and a second and a s The second and a second	n in niteria	en e	
REGULATUR	INFORMATION	DISTRIBUTION STATEM	(FIDS)
AUTH.NAME AUTHÜR BASKIN,K.P. Southern RECIP.NAME RECIPIE	uclear Stati uclear Stati AFFILIATION California	on, Unit 2, Southern on, Unit 3, Southern Edison Co. ON	Californ 05000361
factors & instru	sign Review, mentation pr	per NUREG=0737 Item " to identify signif oblems.Seventeen cor e Condition 19F comp	icant human rective
DISTRIBUTION CODE: B001S TITLE: PSAR/FSAR AMDTS an	COPIES RECE d Related Co	IVED:LTR ENCL rrespondence	SIZE:5
NGTES:J Hanchett 1cy PDR	Documents. E	LD Changler 1cy.	05000361
NRR Scaletti 1cy. J Hanchett 1cy PDR NRR Scaletti 1cy.	Documents. E	LD Changler 1cy.	05000362
RECIPIENT ID CODE/NAME A/D LICENSNG LIC 3R #3 LA		_	COPIES LTTR ENCL 1 0 1 1
INTERNAL: ELD/HDS2 IE/DEP EPDS 35 NRR/DE/CEB 11 NRR/DE/GB 28 NRR/DE/MEB 18 NRR/DE/MEB 18 NRR/DE/GAB 21 NRR/DE/SEB 25 NRR/DFS/LQB 32 NRR/DHFS/LQB 32 NRR/DHFS/PTRB20 NRR/DSI/ASB 27 NRR/DSI/CSB 09 NRR/DSI/CSB 16 NRR/DSI/ICSB 16 NRR/DSI/ICSB 16 NRR/DSI/ICSB 33 RGN5	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	IE FILE IE/DEP/EPLB 36 NRR/DE/EQB 13 NRR/DE/HGEB 30 NRR/DE/MTEB 17 NRR/DE/SAB 24 NRR/DHFS/HFEB40 NRR/DHFS/HFEB40 NRR/DHFS/OLB 34 NRR/DSI/AEB 26 NRR/DSI/CPB 10 NRR/DSI/CPB 10 NRR/DSI/CPB 10 NRR/DSI/ETSB 12 NRR/DSI/FSB 19 NRR/DSI/RSB 23 PLC FILE 04 RM/DDAMI/MIB	1       1         3       3         3       3         2       2         1       1         1       1         1       1         1       1         1       1         1       1         1       1         1       1         1       1         1       1         1       1         1       1         1       1         1       1         1       0
EXTERNAL: ACRS 41 DMB/DSS (AMDTS) LPUR 03 NSIC 05	10 10 1 1 1 1 1 1 1 1	BNL(AMDTS ONLY) FEMA-REP DIV 39 NRC POR 02 NTIS	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$
NOTES:	ځ ځ		

. . . . . .

-----

TOTAL NUMBER OF COPIES REQUIRED: LTTR 61 ENCL 56

ور د ای المحمود بیران در با با مع معموم مدروم از با این و در

.

....

0

## Southern California Edison Company

P. O. BOX 800 2244 WALNUT GROVE AVENUE ROSEMEAD, CALIFORNIA 91770

K. P. BASKIN MANAGER OF NUCLEAR ENGINEERING, SAFETY, AND LICENSING

e }}

August 19, 1982

Director, Office of Nuclear Reactor Regulation Attention: Mr. Frank Miraglia, Branch Chief Licensing Branch No. 3 U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362 San Onofre Nuclear Generating Station Units 2 and 3

Item I.D.1, Control Room Design Review, of NUREG-0737 required SCE to conduct a detailed control room design review to identify significant human factors and instrumentation problems and to establish a schedule approved by the NRC for correcting deficiencies. Corrective actions which were identified and agreed to by both the NRC staff and SCE during the course of the control room design review/audit, along with a schedule for implementation of corrective actions were identified in Supplement No. 1 of the Safety Evaluation Report (SER) for San Onofre Units 2 and 3. Seventeen (17) corrective actions which were scheduled for completion prior to the operation of San Onofre Unit 2 above 5% power were incorporated as part of License Condition (19)f of Operating License No. NPF-10 for San Onofre Unit 2.

SCE has completed the activity associated with the seventeen corrective actions identified in License Condition (19)f. Relative to corrective Action No. 4 which required SCE to "Identify changes to correct control room lighting for optimum operator performance," SCE recently reevaluated control room lighting, subsequent to the following improvements which were implemented as part of the overall control room modification program and which enhanced illumination for optimum operator performance:

- Repainting of control room walls/panels with colors that reduced glare/reflectance and enhanced optimum operator performance and comfort.
- 2. Utilization of anti-glare materials and processes to reduce the glare contribution from annunciators and back lighted switches.
- 3. Replacement of instrument lenses with anti-glare lenses as required.
- Relocation and relettering of labels for consistency, elimination of shadows and improved legibility.
   ROOI



SE

TELEPHONE (213) 572-1401 Mr. Frank Miraglia

Control Room lighting was reevaluated with consideration to the guidelines for normal and emergency lighting discussed in Section 6.1.5.3, "Illumination" of NUREG-0700, "Guidelines for Control Room Design Reviews" which recommend the following illumination levels:

1.	Normal Lighting	Task Illuminance, Footo Min. Recommended		candles <u>Max.</u>	
	Panel Area Seated Operator Stations Reading and Writing Areas	20 50 50	30 75 75	50 100 100	
2.	Emergency Lighting	Minimum	illumination	level of	

Minimum illumination level of 10 footcandles at all work stations in the primary operating area.

The results of the San Onofre Units 2 and 3 Control Room lighting survey for the normal lighting levels are summarized in Enclosure I. The results of the lighting survey for vertical section (A) of both the main control panel and mimic panel showed an average lighting level of 42.9 footcandles consistent with the guidelines of NUREG-0700 for panel areas. The results of the lighting survey for inclined sections (B) and (C) of the main control panel and inclined section (D) of the mimic panel showed average lighting levels of 57.4, 69.5 and 77.5 footcandles respectively. These higher lighting levels are a direct result of the increase in incident light on the panels due to the orientation of the inclined panels. The results for these inclined areas are also considered to be consistent with the guidelines of NUREG-0700 since the illumination levels fall between the recommended quidelines for vertical sections (panel area) and sit-stand sections (seated operator stations). The results for reading and writing areas (Z) showed an average lighting level of 96.9 footcandles consistent with the guidelines of NUREG-0700.

The results of the San Onofre Units 2 and 3 Control Room lighting survey for the emergency lighting level are summarized in Enclosure II. The results of the lighting survey for reading and writing areas (Z) (work stations in the primary working area) showed an average lighting level of 13.8 footcandles consistent with the guidelines of NUREG-0700 for emergency lighting. The average lighting levels for the panel areas are also identified in Enclosure II. The emergency lighting levels in the panel areas did not impair the capability of the operators to obtain clear and discernable readings.

Based on the results of the lighting survey, SCE concludes that the normal and emergency lighting levels in the control room are consistent with the guidelines of NUREG-0700 and that no further lighting modifications are necessary. SCE also considers that the related issues of glare and shadows discussed in Supplement No. 1 of the SER have been resolved as a result of the improvements discussed above which were implemented as part of the overall control room modification program. Mr. Frank Miraglia


SCE considers that the information provided by this letter satisfies the requirements of license condition (19)f and that additional lighting modifications are no longer considered necessary for the first refueling outage.

If you have any questions or comments, please let me know.

Very truly yours,


2P Baston

## SAN ONOFRE UNITS 2 AND 3 CONTROL ROOM SURVEY OF NORMAL LIGHTING LEVELS



## Note

For the main control panel, measurements were taken at levels (A), (B) and (C) as shown on section (XX). For the mimic panel, measurements were taken at levels (A) and (D) as shown on section (YY).



## Note

For the main control panel, measurements were taken at levels (A), (B) and (C) as shown on section (XX). For the mimic panel, measurements were taken at levels (A) and (D) as shown on section (YY).