

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

MA 2

ACCESSION NBR: 8403230074 DOC. DATE: 84/03/20 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern California 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern California 05000362
 AUTH. NAME AUTHOR AFFILIATION
 MEDFORD, M. O. Southern California Edison Co.
 RECIP. NAME RECIPIENT AFFILIATION
 KNIGHTON, G. W. Licensing Branch 3

SUBJECT: Forwards auxiliary feedwater sys monthly outage rept for 840116-0215, including 840112-14 & 15 outages, omitted from last months rept, per License Condition 2.C(26). Next rept will cover period 840216-0315.

DISTRIBUTION CODE: B001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Licensing Submittal: PSAR/FSAR Amdts & Related Correspondence

NOTES: J Hanchett 1cy PDR Documents, ELD Chandler 1cy. 05000361
 J Hanchett 1cy PDR Documents, ELD Chandler 1cy. 05000362

RECIPIENT ID CODE/NAME	COPIES LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES LTR	ENCL
NRR/DL/ADL	1	0	NRR LB3 BC	1	0
NRR LB3 LA	1	0	ROOD, H. 01	1	1

INTERNAL:

ELD/HDS2	1	0	IE FILE	1	1
IE/DEPER/EPB 36	3	3	IE/DEPER/IRB 35	1	1
IE/DQASIP/QAB21	1	1	NRR/DE/AEAB	1	0
NRR/DE/CEB 11	1	1	NRR/DE/EHEB	1	1
NRR/DE/EQB 13	2	2	NRR/DE/GB 28	2	2
NRR/DE/MEB 18	1	1	NRR/DE/MTEB 17	1	1
NRR/DE/SAB 24	1	1	NRR/DE/SGEB 25	1	1
NRR/DHFS/HFEB40	1	1	NRR/DHFS/LQB 32	1	1
NRR/DHFS/PSRB	1	1	NRR/DL/SSPB	1	0
NRR/DSI/AEB 26	1	1	NRR/DSI/ASB	1	1
NRR/DSI/CPB 10	1	1	NRR/DSI/CSB 09	1	1
NRR/DSI/ICSB 16	1	1	NRR/DSI/METB 12	1	1
NRR/DSI/PSB 19	1	1	NRR/DSI/RAB 22	1	1
NRR/DSI/RSB 23	1	1	<u>REG FILE</u> 04	1	1
RGNS	3	3	RM/DDAMI/MIB	1	0

EXTERNAL:

ACRS 41	6	6	BNL (AMDTs ONLY)	1	1
DMB/DSS (AMDTs)	1	1	FEMA-REP DIV 39	1	1
LPDR 03	1	1	NRC PDR 02	1	1
NSIC 05	1	1	NTIS	1	1

NOTES: 2 2

Southern California Edison Company



P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

M.O. MEDFORD
MANAGER, NUCLEAR LICENSING

March 20, 1984

TELEPHONE
(213) 572-1749

Director, Office of Nuclear Reactor Regulation
Attention: Mr. George W. Knighton, Branch Chief
Licensing Branch No. 3
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
Auxiliary Feedwater System Monthly Outage Report
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to License Condition 2.C(26) of Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required monthly report describing any occurrence resulting in the degradation of the Units 2 and 3 Auxiliary Feedwater Systems (AFWS). This report covers the period from January 16, 1984, to February 15, 1984, and also includes outages on January 12, 14, and 15, 1984, which were omitted from last month's report. The component involved, cause of outage, and corrective actions taken to return the equipment to operable status are listed. The durations of the Units 2 and 3 equipment outages are not specified, since both Units were in Modes 4 or 5 during the equipment outages, and the AFWS was not required to be operable per Technical Specifications.

In accordance with License Condition 2.C(26), our next report will cover the period from February 16, 1984, to March 15, 1984.

If there are any questions regarding this report, please contact me.

Sincerely,

RW Krueger for MO Medford

Enclosure

cc: J. B. Martin, (Regional Administrator
U.S. Nuclear Regulatory Commission, Region V)

H. Rood, Project Manager, SONGS 2/3, NRR

A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

8403230074 840320
PDR ADDOCK 05000361
R PDR

*Good
11*

Monthly AFWS Outage Report
January 16, 1984 to February 15, 1984*

Date	Unit	Outage	Duration (hours)	Outage Cause	Corrective Action
1/12/84	3	Design Modification (DCP3-801J)	-	3HV4705, 3HV4706, 3HV4715, and 3HV4730 were taken out of service for installation of anti-rotation plates.	None required.
1/14/84	3	Preventive Maintenance	-	S31305MU128 was taken out of service for repacking.	None required.
1/15/84	3	Design Modification (DCP3-226J)	-	Design change added new sample points to AFWS pump discharge piping.	None required.
1/16/84	3	Corrective Maintenance	-	Check Valve S31301MU003 had steam leaks.	Steam leaks were repaired.
1/17/84	2	Preventive Maintenance	-	2HV4731 taken out of service to change oil and filter.	None required.
1/18/84	3	Component Investigation	-	S31305MP504 was taken out of service to investigate potential problem with unequal motor winding phase to phase resistance.	Motor windings were found to be satisfactory. No corrective actions required.
1/20/84	2	Corrective Maintenance	-	S21305MP140 has leaking turbine casing plugs and damaged insulation on cable for the actuator governor.	Leaking turbine casing plugs were repaired and cable was replaced.
1/26/84	3	Preventive Maintenance	-	S31305MP140 was taken out of service to change oil.	None required.
1/29/84	3	Design Modification (DCP3-1019M)	-	S31305MP141 was taken out of service to modify its miniflow line orifice.	None required.
1/30/84	3	Preventive Maintenance	-	3HV4714 was taken out of service to perform preventive maintenance on Linestarter 3BZ-21.	None required.
1/30/84	3	Corrective Maintenance	-	S31305MR287 (suction line vent valve to S31305MP141) showed indication of valve cap and seat leakage.	Valve was repaired.

*Including three outages omitted from Monthly AFWS Report for December 16, 1983 to January 15, 1984.

Monthly AFWS Outage Report
 January 16, 1984 to February 15, 1984*

Date	Unit	Outage	Duration (hours)	Outage Cause	Corrective Action
1/31/84	3	Corrective Maintenance	-	3HV4730 and 3HV4715 did not show correct position indication locally.	The valves' mechanical dial indicators were adjusted.
2/4/84	3	Preventive Maintenance	-	3HV4731 was taken out of service to change oil and filter.	None required.
2/5/84	3	Preventive Maintenance and Design Modification (DCP3-1398SE)	-	Preventive maintenance was performed on 3A0404, the 4 kV breaker to S31301MP141. Also, a design change to replace the breaker anti-shock spring was implemented.	None required.
2/9/84	3	Preventive Maintenance	-	3HV4714 was taken out of service to change oil and filter.	None required.
2/9/84	3	Preventive Maintenance	-	S31305MP141 was taken out of service to change oil and filter.	None required.
2/15/84	3	Design Modification (DCP3-12570E)	-	S31305MK007 was taken out of service for circuit modifications to reduce circuit noise problems.	None required.