ACCE	LE RATED DIST	<b>TRIBUTI</b> Y INFORMA	ON TION	DEMONSTRATIO	N S	YSTE) S)	4
ACCESSION FACIL:50 AUTH.NA MORGAN,N RECIP.N	N NBR:8902220117 D-362 San Onofre M AME AUTHOR H.E. Southern NAME RECIPIN	DOC.DA Nuclear S AFFILIAT n Califor ENT AFFIL	TE: 8 tatic ION nia E IATIC	89/02/13 NOTARIZED on, Unit 3, Souther Edison Co. DN	): NO n Cali:	[ forn (	DOCKET # )5000362
SUBJECT DISTRIBU TITLE:	: LER 89-002-00:or spurious actuat: UTION CODE: IE22D 50.73 Licensee Eve	n 890113, ion due t COPIES ent Repor	fuel o ina RECEI t (LE	handling isolation dequate loop diagr TVED:LTR <u></u> ENCL <u></u> ER), Incident Rpt,	am. W/8 SIZE etc.	rain A ltr. :	R I D
NOTES:			,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			S
INTERNAL:	RECIPIENT ID CODE/NAME PD5 LA HICKMAN,D ACRS MICHELSON ACRS WYLIE AEOD/DSP/TPAB ARM/DCTS/DAB NRR/DEST/ADE 8H NRR/DEST/ADE 8H NRR/DEST/CEB 8H NRR/DEST/ICSB 7 NRR/DEST/ICSB 7 NRR/DEST/RSB 8E NRR/DEST/RSB 8E NRR/DLPQ/HFB 10 NRR/DCEA/EAB 11 NRR/DCEA/EAB 11 NCCS-ABSTRACT RES/DSIR/EIB RGN5 FILE 01	COPIES LTTR E 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NCL 1 1 1 1 1 1 1 1 1 1 1 1 1	RECIPIENT ID CODE/NAME PD5 PD ACRS MOELLER AEOD/DOA AEOD/ROAB/DSP DEDRO NRR/DEST/ADS 7E NRR/DEST/ESB 8D NRR/DEST/SB 8D NRR/DEST/SGB 9A REG FILE 02 RES/DSR/PRAB	COP LTTR 1 2 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1	IES ENCL 1 2 1 2 1 0 1 1 1 1 1 1 1 1 1	/ A D D S S
EXTERNAL:	EG&G WILLIAMS,S H ST LOBBY WARD NRC PDR NSIC MAYS,G	4 1 1	4 1 1	FORD BLDG HOY,A LPDR NSIC HARRIS,J	1 1 1 .	1 1 1	I D

## NOTE TO ALL "RIDS" RECIPIENTS:

ŧ.

٩

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED! S

A

D

D

S

TOTAL NUMBER OF COPIES REQUIRED: LTTR 45 ENCL 44

					(		LIC	ENSEE	EVENT	RE	PORT	(LE	R)							
Facilit	; Name	(1)											·	Doc	ket Nu	mber (2	2)	Pa	qe (3	)
SAN ONO	FRE NUC	CLEAR (	GENERA	TING	STATION	I. UN	IT 3								51 01		3 6	2 1	of	
Title (	4)									••							<u> </u>	<u> </u>		0 4
FUEL	HANDLIN	IG ISOI	LATION	SYST	TEM TRAI	N "A	" SPURIO	US ACT	UATIC	DN D	UE TO	IN	ADEQU	JATE DE	TAIL O	F INST	RUMENT	LOOP [	IAGRA	М
EVENT DATE (5) LER NUMBER (6)						REPORT DATE (7)					OTHER	FACILI	TIES I	NVOLVED	) (8)					
Month	Day	Year	Year	///	Sequent Numbe	ial	/// Rev	ision mber	Mor	nth	Day	Y	ear	<u> </u>	ames Docket Number(s)					
		-					1/// 1/4	inder	-		1		· · ·		NONE		0 5	0 0	0	
1	13	8 9	8 9		0 0	2	0	0	0	2	11	3 8	9				0 5		01	1 1
0P1	ERATING	ì		THIS	; REPORT	IS	SUBMITTE	D PURS	UANT	TO	THER	EQU	IREME	NTS OF	10CFR					
M01	DE (9)		1	TCHE	20.402(	b)	<u>ore or t</u>	20.	405(c	<u>19)</u> ;)	(11)	Тх	150	73(a)(	$\frac{1}{2}$		73	71(b)		
POWER					20.405(	a)(1	)(i) [	50.	36(c)	(1)			50	.73(a)(	2)(v)		73	.71(c)		
(10)		)   9	i q	—	20.405(	a)(1	$\binom{11}{11}$	50.	36(c)	(2)	(+)		- 50	.73(a)(	2)(vii	)	0t	her (Sp	ecify	'in
11/1/1/	11111	11111	11111		20.405(	a)(1)	)(iv) -	50. 50.	73(a)	(2)	(i) (ii)		- 50	./3(a)( .73(a)(	2)(V11 2)(V1i	1)(A) i)(B)	AD in	stract	below	and
////////	[]]]]]		//////		20.405(	a)(1	)(v) [	50.	73(a)	(2)	(111)		50	.73(a)(	2)(x)	.,(0,		LEXL)		
<u></u>	<u>      </u>	<u> </u>	//////////////////////////////////////																	
							LICENSE	E CONT	ACT F	OR	THIS	LER	(12)	)						
Name																TEL	EPHON	E NUMBE	R	
н. 1	E. Mord	jan, Si	tation	Mana	aer										AREA	CODE	2 6			
			COMPI	.ETE	ONE LIN	E FO	R EACH C	OMPONE	NT FA	ILU	RE DF	SCR	TRFD	IN THI	S REPO	PT (13)	<u> </u>	8 -	6 2	4 1
CALLSE	SVSTE	M C			MANUEAC	T		- ///	//7/					<u> </u>		1		1		
	31310		JMPUNE		TURER	-	TO NPRD	S ///	,,,,,	CAI	USE	S Y :	STEM	COMP	DNENT		AC-	REPORT	ABLE	,,,,,,, ,,,,,,,
								///	////				1		 		<u> </u>		KUS_	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
								///	1111								·			,,,,,, ,,,,,,
	SUPPLEMENTAL REPORT EXPECTED (14)									·····	Month	Dav	Year							
							·				·		_			Expec  Submis	ted			
Yes	(If ye	s, com	nplete	EXPE	CTED_SU	BMIS	SION DAT	Ε)	xx	NO						Date	(15)		1	
ABSTRAC	⊺ (Limi	t to 1	1400 sp	aces	i.e	app	roximate	lv fif	teen	sin	nle-s	nace	e tvn	owritte	an lin	00) (16				┷╼╾┥

At 0801 on 1/13/89, with Unit 3 operating at 99% power, while performing modification work on Containment Purge Isolation System (CPIS) radiation monitor RT-7804, a spurious Fuel Handling Isolation System (FHIS) Train A actuation occurred. Radiation levels in the Fuel Handling Building remained normal, and all FHIS Train A components functioned as required; thus, there is no safety significance to this event. At 0835, FHIS Train A was reset and the ventilation lineup returned to normal.

Power is provided to FHIS Train A monitor RT-7822 via a terminal board which also routes power to RT-7804. When the power lead to RT-7804 was de-terminated to perform the work, power was also removed from the FHIS Train A actuation relay, resulting in the actuation. The technician performing the work was not aware of the power interconnection since the RT-7804 instrument loop diagram, which was utilized to perform the CPIS modification, does not depict the power lead connection to RT-7822. Each radiation monitoring instrument loop diagram was developed from the cabinet wiring diagrams to depict the wiring for a specific monitor, thereby facilitating work on that monitor. As a result, these loop diagrams do not depict power interconnections between monitors, and thus do not have the level of detail necessary to properly plan or perform some types of work activities.

The Engineered Safety Feature Actuation System (ESFAS) radiation monitoring instrument loop diagrams will be amended to depict, where appropriate, power interconnections between monitors. As interim corrective action, appropriate work planners and technicians have been directed to utilize the cabinet wiring diagrams in conjunction with the loop diagrams when planning or performing work on ESFAS radiation monitors.

8902220117 890213 PDR ADOCK 05000362 S PNU

IEad

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

SAN	ONOFRE	NUCLEAR	GENERATION	STATION	DOCKET NUMBER	LER NUMBER	PAGE
UNI	3		<u></u>	"	05000362	89-002-00	<u>2 OF 4</u>

Plant: San Onofre Nuclear Generating Station Unit: Three Reactor Vendor: Combustion Engineering Event Date: 01-13-89 Time: 0801

A. CONDITIONS AT TIME OF THE EVENT:

Mode: 1, Power Operation at 99% power

B. BACKGROUND INFORMATION:

The Fuel Handling Isolation System (FHIS) (EIIS System Code VG) consists of two independent trains of radiation monitors (EIIS Component Code RIT), associated dampers (EIIS Component Code DMP), and recirculation air filtration units (EIIS Component Code AHU). A FHIS actuation is initiated by either a remote manual push-button or in response to high radiation, instrument failure, or loss of power. A FHIS actuation isolates normal ventilation to the Fuel Handling Building (FHB) (EIIS System Code ND) and initiates recirculation.

Radiation monitor cabinet wiring diagrams, which depict the wiring for the cabinets, have historically been utilized by technicians to perform work on the radiation monitors. Since work is typically performed on a per-monitor basis, use of the cabinet wiring diagrams has required the technicians to discriminate the wiring connections applicable to their assigned work from the wiring associated with the other monitors in the cabinet. To facilitate work on the radiation monitors, instrument loop diagrams were developed from the wiring diagrams to depict the wiring schemes for specific monitors.

- C. DESCRIPTION OF THE EVENT:
  - 1. Event:

At 0801 on 1/13/89, while performing modification work on Containment Purge Isolation System (CPIS) (EIIS System Code VA) radiation monitor RT-7804, a spurious FHIS Train A actuation occurred. Specifically, the actuation occurred when the technician performing the work de-terminated the power lead to RT-7804. Radiation levels in the FHB remained normal, and all FHIS Train A components functioned as required. At 0835, following replacement of the power lead, FHIS Train A was reset and the ventilation lineup returned to normal.

2. Inoperable Structures, Systems or Components that Contributed to the Event:

None

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

SAN ONOFRE NUCLEAR GENERATION STATION	DOCKET NUMBER	LER NUMBER	PAGE
UNIT 3	05000362	89-002-00	3 OF 4

3. Sequence of Events:

TIME	ACTION

- 0801 FHIS Train A spurious actuation occurred. All Train A components were verified to actuate as required.
- 0835 FHIS Train A reset and ventilation lineup returned to normal.
- 4. Method of Discovery:

Control room alarms and indications alerted the operators of the FHIS actuation.

5. Personnel Actions and Analysis of Actions:

The operators responded properly to the FHIS actuation by 1) verifying each FHIS Train A component actuated as required, and 2) verifying radiation levels were normal prior to resetting FHIS and returning the ventilation lineup to normal.

6. Safety System Responses:

All FHIS Train A components operated in accordance with design.

## D. CAUSE OF THE EVENT:

1. Immediate Cause:

Power is provided to FHIS Train A monitor RT-7822 via a terminal board which also routes power to RT-7804. When the power lead to RT-7804 was determinated to perform the work, power was also removed from the FHIS Train A actuation relay, resulting in the actuation.

2. Intermediate Cause:

The technician performing the work was not aware of the power interconnection between the monitors since the RT-7804 instrument loop diagram, which was utilized to perform the CPIS modification, does not depict the power lead connection to RT-7822.

3. Root Cause:

Each radiation monitoring instrument loop diagram was developed to include only the circuitry associated with that particular instrument. Consequently, inclusion of power interconnections between instruments was not part of the development criteria for the loop diagrams. As a result, these loop diagrams do not have the level of detail necessary to properly plan or perform some types of work activities, such as the modification work being performed in this instance. LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

SAN	ONOFRE	NUCLEAR	GENERATION	STATION	DOCKET NUMBER	LER NUMBER	PAGE
UNIT	3				05000362	89-002-00	4 OF 4

- E. CORRECTIVE ACTIONS:
  - 1. Corrective Actions Taken:

Until the planned corrective action below is completed, radiation monitoring work planners and technicians have been directed to utilize the cabinet wiring diagrams in conjunction with the loop diagrams when planning or performing work on the Engineered Safety Feature Actuation System (ESFAS) radiation monitors.

2. Planned Corrective Actions:

The ESFAS radiation monitoring instrument loop diagrams will be amended to depict, where appropriate, power interconnections between monitors.

F. SAFETY SIGNIFICANCE OF THE EVENT:

There is no safety significance to this event since radiation levels remained normal and all FHIS Train A components operated in accordance with design.

- G. ADDITIONAL INFORMATION:
  - 1. Component Failure Information:

Not applicable

- Previous LERs on Similar Events: None
- 3. Results of NPRDS Search:

Not applicable

## Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN STATION MANAGER

TELEPHONE (714) 368-6241

February 13, 1989

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Docket No. 50-362 30-Day Report Licensee Event Report No. 89-002 San Onofre Nuclear Generating Station, Unit 3

Pursuant to 10 CFR 50.73(a)(2)(iv), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving a spurious actuation of the Fuel Handling Isolation System. This event had no effect on the health and safety of either plant personnel or the public.

If you require any additional information, please so advise.

Sincerely, HEMorg

Enclosure: LER No. 89-002

cc:

F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)

J. B. Martin (Regional Administrator, USNRC Region V)

Institute of Nuclear Power Operations (INPO)