ACCELERATED DETRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9006050124DOC.DATE: 90/05/31NOTARIZED: NODOCKET #FACIL:50-362San Onofre Nuclear Station, Unit 3, Southern Californ05000362AUTH.NAMEAUTHOR AFFILIATION05000362MORGAN,H.E.Southern California Edison Co.RECIPIENT AFFILIATION

SUBJECT: LER 90-004-00:on 900501, fuel movement performed within spent fuel storage pool w/o concurrent operation of PACU. W/9 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR _ ENCL _ SIZE: 6 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

÷	RECIPIENT ID CODE/NAME PD5 LA KOKAJKO,L.	COPIE LTTR 1 1		RECIPIENT ID CODE/NAME PD5 PD	COPI LTTR 1	
INTERNAL:	ACNW	2	2	ACRS	2	2
	AEOD/DOA	1	1	AEOD/DSP/TPAB	1	1
	AEOD/ROAB/DSP	2	2	DEDRO	ī	1
	NRR/DET/ECMB 9H	1	1	NRR/DET/EMEB9H3	1	1
	NRR/DLPQ/LHFB11	· 1	1	NRR/DLPQ/LPEB10	1	1
	NRR/DOEA/OEAB11	- 1	1	NRR/DREP/PRPB11	2	2
	NRR/DST/SELB 8D	1	1 .	NRR/DST/SICB 7E	1	1
	NRR/DST/SPLB8D1	1	1	NRR/DST/SRXB 8E	ī	1
	REGEFILEE-02	1	1	RES/DSIR/EIB	1.	1
	RGN5 FILE 01	1	1	, ,		
EXTERNAL:	EG&G STUART, V.A	4	.4	L ST LOBBY WARD	1	1
	LPDR	1	1	NRC PDR	1	1
	NSIC MAYS,G	1	1	NSIC MURPHY, G.A	1	1
	NUDOCS FULL TXT	1	1	······································	-	_

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED TOTAL NUMBER OF COPIES REQUIRED: LTTR 36 ENCL 36

R

I

D

S

Α

Ď

D

S

R

Ι

D

S

Α

D

D

S



Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128 SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN STATION MANAGER

May 31, 1990

TELEPHONE (714) 368-6241

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Docket No. 50-362 30-Day Report Licensee Event Report No. 90-004 San Onofre Nuclear Generating Station, Unit 3

Pursuant to 10 CFR 50.73(d), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving the Post Accident Cleanup System. This event had no effect on the health and safety of either plant personnel or the public.

If you require any additional information, please so advise.

Sincerely,

HEMOR

Enclosure: LER No. 90-004

9006050124 900531

PDR.

AXOCK 0500036

P T II 🖸

cc: C. W. Caldwell (USNRC Senior Resident Inspector, Units 1, 2 and 3)

J. B. Martin (Regional Administrator, USNRC Region V)

Institute of Nuclear Power Operations (INPO)

1422

<u> </u>																			
· .								LICE	NSEE E	VENTR	EPORT	(LER)							
Facilit	y Name	(1)												Docket	Numbe	r (2)	F	age (5)
SAN ONO	FRE NU		GENERA	TING	STATION	I IN T	т 3							01 51		01717			
Title (4)			1110	UTATION /									0 5	01.01	0 3 6	1211	of	0 5
	VENENT	05050																	
AS REQU	IRED BY	TECH	RMED W NICAL	SPEC	N THE SPE	INT F	UEL F TO	STOR/	AGE PO	EPPOP	HOUT C	ONCURRI	ENT C	OPERATIC	ON OF	POST ACC	IDENT C	LEANUR	ONIT
	DATE		1		UMBER (6							TE (7)	1	07.07					<u> </u>
Month		Year	Year		Sequenti	al	///	Revis		Month		1	F	acility	/ Name	ILITIES s Do	<u>cket Nu</u>	<u>D (8)</u> mber(s	;)
	Buy	rear		μ	Number	<u> </u>	Ш	Numb	<u>xer</u>	Month	Day	Year	-						
	1		1							-		· .		NONE	· .		5 0 0	0	
0 5	01	90	90	ĺ	0 0			_ 0	0	015	311	910				01	5 0 0	1 01	ΤĹ
	ERATING	3			S REPORT eck one c	IS S	UBMI	TTED	PURSÚ	ANT TO	THER	EQUIREN	1ÉNTS	OF 100	FR				
	DE (9)		6	<u>Cone</u>	20.402(1))	<u>re</u> (120.4	05(c)	(1)	1 150	.73(a)(2)(i	V)	17	3.71(b)		
POWER					20.405(a	0(1)	(i)		50.3	6(c)(1		50).73(a)(2)(\	()		3.71(c)		
		1	10	I—	20.405(a 20.405(a	(1)	(11)	\		6(c)(2 3(a)(2				a)(2)(\			ther (S		
TITIT	11111	min.	\vec{m}		20.405(a	0(1)	(iv)	/	50.7	3(a)(2				a)(2)(\ a)(2)(\			bstract n text)		and
	///////////////////////////////////////		//////		20.405(a)(1)	(v)		50.7	3(a)(2	(iii)	50	0.73	a)(2)()	3	-,			
LICENSEE CONTACT FOR THIS LER (12)																			
Name AREA CODE AREA CODE A																			
<u> </u>	E. More	ian, Si	tation	Mana	ger	_											5 8 -	1 61 2	4 1
			COMPL	ETE	ONE LINE	FOR	EAC	н сом	PONEN	T FAIL	JRE DE	SCRIBED) IN	THIS RE	PORT			+	**
CAUSE	SYSTE	M CO		IT	MANUFAC-	R	EPOR	TABLE	////		AUSE	SYSTEM	1 C	OMPONEN	TM	ANUFAC-	REPOR	TABLE	777777
	<u>.</u>			_	TURER		TON	PRDS							<u> </u>	URER	TON		/////
	<u> </u> [.////	///			_						//////
<u> </u>				·					1111	///									11111
			SUPF	LEME	NTAL REP	ORT	EXPE	CTED	(14)						E	xpected	Month	Day	Year
—																bmission		†́-	t
Yes	(If ye	s, cor	<u>plete</u>	EXPE	CTED SUB	MISS	ION	DATE)		XX NO)				D	ate (15)	1 1		
ABSTRAC	i (L1m1	t to 1	1400 sp	baces	, i.e.,	appr	oxim	ately	' fift	een sir	ngle-sp	bace ty	pewr	itten l	ines)	(16)		÷	++

At 0355 on May 1, 1990, with Unit 3 in Mode 6 and with movement of irradiated fuel occurring in the spent fuel storage pool (SFP), Train A saltwater cooling (SWC) and component cooling water (CCW) systems were declared inoperable in order to perform work on a SWC valve, rendering the Train A post-accident cleanup unit (PACU) (E-370) inoperable. Technical Specification (TS) 3.9.12 requires that with one PACU inoperable, fuel movement within the SFP may proceed provided the other PACU is operable and in operation. Since the Train B PACU (E-371) was not placed in operation and movement of fuel in the SFP was continuing, this represents an operation prohibited by TS 3.9.12. At 1720 on May 1, E-371 was placed in operation when the Control Room Coordinator (CRC) (utility, licensed), who coordinates outage activities on a shutdown unit, recognized that E-371 was required to be in operation in accordance with TS 3.9.12.

Although the work package for the SWC valve contained the requirement to place E-371 in operation during the movement of fuel in the SFP, this requirement was overlooked by both the control room operators (utility, licensed) and the CRC due to inadequate attention to detail.

Appropriate disciplinary action has been administered to the personnel involved. This event will be reviewed with licensed operators, stressing the requirement for SWC/CCW operability to support PACU operability. Appropriate information from this event will be included in the licensed operator requalification program.

There is no safety significance to this event since the Train B PACU unit, E-371, was capable of proper operation if it had been required.

SAN ONOFRE	NUCLEAR GENERATION STATION	DOCKET NUMBER 05000362	LER NUMBER 90-004-00	PAGE 2 OF 5
	Plant: San Onofre Nuclear Gene Unit: Three Reactor Vendor: Combustion En	• .	· ·	
	Event Date: 05-01-90	grieer nig		

Time: 0355

A. CONDITIONS AT TIME OF THE EVENT:

Mode: 6, Refueling

B. BACKGROUND INFORMATION:

1. Fuel Handling Building (FHB) Post-Accident Cleanup Unit (PACU) Filter Systems:

Two PACUs [VG] are provided, one per train of Engineered Safety Features (ESF), to ensure that radioactive material released in the FHB as a result of a fuel handling accident will be minimized. The PACUs recirculate FHB [ND] atmosphere through HEPA filters [FLT] and a charcoal adsorber [ADS] to reduce the particulate and iodine activity levels in the FHB following the event. In addition, the PACUs provide cooling to the FHB to maintain the ambient FHB temperature at a level that permits continuous personnel access and equipment operation. The cooling coil [CLR] provided for this purpose is cooled by component cooling water (CCW) [CC], which is, in turn, cooled by the saltwater cooling (SWC) [BS] system.

2. PACU Technical Specification (TS) Requirements:

TS 3.9.12 requires that with one PACU inoperable, fuel movement within the spent fuel storage pool (SFP) (located in the FHB) or operation of the fuel handling machine over the SFP may proceed provided the other PACU is operable and in operation. With no PACU operable, all operations involving movement of fuel within the SFP must be suspended.

- 3. Administrative Requirements:
 - a. Limiting Condition for Operation Action Requirement (LCOAR) and Equipment Deficiency Mode Restraint (EDMR):

Inoperable equipment which is required by a TS Limiting Condition for Operation (LCO) to be operable is documented by a LCOAR. Inoperable equipment which is required by a TS Limiting Condition for Operation (LCO) to be operable in a mode other than the current plant mode is documented by an EDMR. Specifically, the LCOAR or EDMR identifies the nature of equipment degradation (inoperability), the associated LCO and applicable modes.

SAN ONOFRE NUCLEAR GENERATION STATION	DOCKET NUMBER	LER NUMBER	PAGE
UNIT 3	05000362	90-004-00	3 OF 5

b. Work Authorization Records (WARs):

Work plan requirements, including those related to TS action requirements for removal of a piece of equipment or system from service, are identified in the Work Authorization Record (WAR), LCOAR, and EDMR documents. A work package, which includes the WAR, LCOAR, and EDMR, receives several reviews by responsible personnel (utility, licensed) to verify the accuracy and completeness of these documents. The control room operators (utility, licensed), who perform the final review, are responsible for implementation of the required TS actions.

C. DESCRIPTION OF THE EVENT:

1. Event:

At 0355 on May 1, 1990, with Unit 3 in Mode 6 and with movement of irradiated fuel occurring in the SFP, Train A SWC and CCW systems were declared inoperable in order to perform work in accordance with a WAR on a SWC valve, rendering the Train A PACU (E-370) inoperable. Since the Train B PACU (E-371) was not placed in operation at that time and movement of fuel in the SFP was continuing, this represents an operation prohibited by TS 3.9.12. At 1720, E-371 was placed in operation when the Control Room Coordinator (CRC) (utility, licensed), who coordinates outage activities on a shutdown unit, recognized that E-371 was required to be in operation in accordance with TS 3.9.12.

2. Inoperable Structures, Systems or Components that Contributed to the Event:

Not applicable

3. Sequence of Events:

TIME ACTION

0355

E-370 became inoperable when Train A CCW and SWC declared inoperable in order to perform work on SWC valve; fuel movement in SFP was continuing.

1720

E-371 is placed in operation to comply with requirements of TS 3.9.12.

SAN ONOFRE NUCLEAR GENERATION STATION	DOCKET NUMBER	LER NUMBER	PAGE
UNIT 3	05000362	90-004-00	4 OF 5

4. Method of Discovery:

19

Upon review of a (different) WAR which also referenced the requirements of TS 3.9.12, in conjunction with review of plant status in preparation for shift turnover, the CRC recognized that Train A PACU E-370 was inoperable and that Train B PACU E-371 was required to be in operation during movement of fuel in the SFP.

5. Personnel Actions and Analysis of Actions:

Upon recognition that E-371 was required to be in operation to support fuel movement in the SFP, the CRC properly directed that E-371 be promptly started.

6. Safety System Responses:

Not applicable

- D. CAUSE OF THE EVENT:
 - 1. Root Cause:

Although the WAR on the SWC valve contained the requirement to place E-371 in operation during the movement of fuel in the SFP, this requirement was overlooked by both the control room operators (utility, licensed) and the CRC due to inadequate attention to detail.

- 2. Contributing Causes:
 - a. The EDMR associated with the above WAR did not include TS 3.9.12 as an affected LCO. Had this information been included in the EDMR, the requirement to place E-371 in operation may have been identified.
 - b. Since the filtration capability of a PACU is unaffected by its capacity for cooling the FHB, the dependence of PACU operability upon SWC system operability was not clear. As a result, several control room operators who knew that the Train A SWC and CCW systems were inoperable did not recognize the resultant inoperability of the associated PACU, and thus did not identify the requirement for the operation of E-371 during fuel movement in the SFP.

SAN ONOFRE NUCLEAR GENERATION STATION	DOCKET NUMBER	LER NUMBER	PAGE
UNIT 3	05000362	90-004-00	<u>5 OF 5</u>

E. CORRECTIVE ACTIONS:

1. Corrective Actions Taken:

Upon recognition that E-371 was required to be placed in operation during fuel movement in the SFP, E-371 was promptly started, and proper operation was verified.

Appropriate disciplinary action has been administered to the personnel involved.

2. Planned Corrective Actions:

This event will be reviewed with licensed operators, stressing the requirement for SWC/CCW operability to support PACU operability.

Appropriate information from this event will be included in the licensed operator requalification program.

F. SAFETY SIGNIFICANCE OF THE EVENT:

There is no safety significance to this event since the Train B PACU, E-371, was capable of proper operation if it had been required, as evidenced by its proper operation in response to a manual start signal at 1720.

In addition, even if E-371 had failed to start, there would have been no safety significance to this event. There would have been sufficient time to implement necessary corrective action due to the following: 1) the SFP was at a temperature significantly below its design limit; 2) the FHB was at a temperature significantly below its design limit; and 3) although the CCW system was not in operation, it was never disabled; thus, it remained available to the PACU and could have provided some cooling.

- G. ADDITIONAL INFORMATION:
 - 1. Component Failure Information:

Not applicable

2. Previous LERs for Similar Events:

None

3. Results of NPRDS Search:

Not applicable