

**Operating Experience Smart Sample (OpESS) FY 2009-02**  
**“Negative Trend and Recurring Events Involving Feedwater Systems”**

**Note: This is a public NRC document.**  
**Highlighted hyperlinked documents should have active links.**

**OBJECTIVE:**

To support NRC inspector review of feedwater concerns by providing both main feedwater and related backup systems (auxiliary / emergency feedwater or RCIC/HPCI/CI) inspection guidance and references to recent operating experience (OpE) information related to various feedwater issues. This OpESS provides follow-up for [NRC Information Notice 2008-13: Main Feedwater System Issues and Related 2007 Reactor Trip Data](#).

NOTE: This OpESS is a voluntary inspection sample performed under the baseline program. When performed it should be documented in an inspection report under the baseline inspection procedure selected as described in the REPORTING INSPECTION RESULTS / TIME CHARGES / ADDITIONAL ISSUES section for this OpESS.

**BACKGROUND:**

Based on the recent negative trend information and several feedwater related issues and concerns, the OpE clearinghouse and NRR management directed development of this Operating Experience Smart Sample (OpESS) to supply operating experience and focus inspector attention in this area.

NRR staff review of recent operating experience related to main feedwater identified recurring events and a negative trend issue, [see [NRC Information Notice 2008-13: Main Feedwater System Issues and Related 2007 Reactor Trip Data](#) ]. The staff identified a negative trend related to percentage of 2007 reactor scrams caused by feedwater related events. Specifically, 37% of all scrams were initiated as a result of feedwater related events (typically, feedwater related scrams caused between 15 and 25% of all scrams).

A review of more than 200 NRC main feedwater related findings generally involved either the failure to perform proper preventive maintenance/ maintenance errors or corrective action / maintenance errors more than half (~53%) of the time.

NRR OpE staff also reviewed the backup systems Technical Specification and /or safety-related feedwater system inspection findings and noted 17 - “greater than green” findings. Auxiliary feedwater pumps (at PWR units) were the primary contributor in 14 of 17 - “greater than green” findings.

Additionally, the staff noted potential negative trends in the area of main feedwater system scrams and transients being caused by instrumentation and control (I&C) issues. Specific component area of concern issues were often focused on main feed regulating valve issues. Additionally, there may be a growing area of concern related to digital I&C related issues.

An event that occurred at the Perry site (a BWR unit) on November 28, 2008 also highlights the complications that can arise from these digital I&C related issues and feedwater systems.

Additional background documents with links describing this Perry event and the Special Inspection review of this event are provided in the source documents section below.

**SOURCE DOCUMENTS (with active links):**

- 1) [NRC Information Notice 2008-13: Main Feedwater System Issues and Related 2007 Reactor Trip Data](#) -available in ADAMS ML ML080880115
- 2) The Perry SIT (on digital I&C feedwater trip) Inspection Report can be viewed at ADAMS: [ML080280499](#)

NOTE: Baseline inspection procedures are also considered source documents and are to be used for performing an OpESS. These may include inspection procedures used for various feedwater system alignment inspections, feedwater surveillance testing, post maintenance testing or PI&R corrective action follow-up inspections related to various feedwater issues. Links to these base line procedures are provided in the inspection guidance section below. Inspection hours charged for this OpESS are to the baseline inspection procedure used.

**CORNERSTONES:** Initiating Events (50%), Mitigating Systems (50%)

**APPLICABILITY:** All licensed operating commercial nuclear reactors. This OpESS provides additional information related to events involving Main Feedwater systems for all plants and Technical Specification / safety-related backup feedwater systems: (auxiliary feedwater/emergency feedwater for PWRs) or (RCIC/ Isolation Condenser and HPI systems for BWRs).

**INSPECTION GUIDANCE:**

- [IP-71111.04, "Equipment Alignment"](#)
- [IP-71111.15 "Operability Evaluations"](#)
- [IP-71111.19 "Post Maintenance Testing"](#)
- [IP-71111.22 "Surveillance Testing"](#)
- [IP-71152 "Problem Identification and Resolution"](#)

The above procedures provide baseline inspection program attachments that are used to support various feedwater inspections and follow-up to feedwater related issues. Review, as applicable – (ideally during IP-71111.04, "an Equipment Alignment," for the site specific "safety-related" feedwater systems). The additional feedwater inspection guidance is described below and in the OpESS Attachment.

1) Review the Background and Source Document Sections of this OpESS and the related documents as needed to obtain a general understanding of some of the various feedwater related concerns (i.e., purpose is for inspectors to detect issues on the non-safety main feedwater systems prior to self-revealing transient events). Additionally, it is also desired that this OpESS assist NRC inspectors in detecting issues earlier for important to safety "backup" feedwater related systems, to ensure those system readiness, and thereby help improve plant safety and reduce risk and the number of "greater than green" findings in these areas. Review any licensee corrective action response to: [NRC Information Notice 2008-13: Main Feedwater System Issues and Related 2007 Reactor Trip Data](#).

a.) An additional recent (10/22/2008) issue is described in Event Notice [\(EN\) 44593](#) Pilgrim, "RCIC Inoperability Due to Flow Controller Components with Age Well Beyond Recommended

**Replacement Age.**” In this EN 44593, Pilgrim site stated several of the capacitors installed in the controller were noted to be between 21 to 30 years of age. Industry recommended replacement interval for the capacitors is typically between 7 to 10 years of age. PNPS engineering review in conjunction with Entergy fleet consultation concluded that there is no definitive technical bases to provide a reasonable expectation that the RCIC flow controller function can be assured throughout its mission time due to the capacitor aging concern.

Keep these earlier findings and issues in mind and review these items as needed for similar issues/ concerns at your site.

2) During equipment alignment walkdowns, surveillance testing, post maintenance testing and corrective action followup inspections, as applicable, inspect for similar issues to those noted in the Background Documents and the Source Documents (i.e., similar findings).

3) Review feed regulation valve issues and related licensee related maintenance and corrective actions related to these valves should they occur to verify that necessary corrective actions commensurate with the significance of the issue have been identified and implemented by the licensee.

4) (a) For sites with specific NUREG “risk-based inspection guides” listed on the following page review this guidance for **AFW / EFW systems (PWRs)** or **HPCI systems (BWRs)** provided for “your specific site” as described in the “risk based inspection guide” NUREG.

**NOTE: USE THESE NUREGS WITH CAUTION** as this is “guidance material only.” Realize that these NUREGS were developed in the early 1990’s and may be out of date regarding systems lineups (etc.) and may be in need of revision due to subsequent plant modifications or other changes that may have been implemented since these documents were initially developed. However, the inspection techniques and methodologies derived from these “risk bases inspection guides” should still provide useful inspection insight.

(b) If your “specific” site is not represented by any of these linked NUREG “risk based inspection guides” then review a similar site’s (sister plant/peer group plant) to understand the techniques demonstrated by this “risk based inspection guidance” material which should still provide useful information for inspectors to review and consider during their own site inspections.

Review the appropriate site specific risk-based NUREG inspections guidance for insights, as applicable. **NOTE: USE THESE NUREGS WITH CAUTION** as this is “guidance material only.” Realize that these NUREGS were developed in the early 1990’s and may be out of date.

**For PWR Site(s) /”Risk Based Inspection Guides” (for AFW/EFW systems)–NUREG/CR #**

Arkansas Nuclear One (ANO) - Unit 2 / NUREG/CR-5828  
Beaver Valley / NUREG/CR-5835  
Braidwood and -  
Byron Sites / NUREG/CR-4427  
Callaway/ NUREG/CR-6357  
Catawba/ NUREG/CR-5827  
Comanche Peak/ NUREG/CR-5831  
Cook, D.C./ NUREG/CR-5832  
Crystal River-3/ NUREG/CR-5467  
Diablo Canyon Unit 1/ NUREG/-5616  
Farley, J.M./ NUREG/CR-5617  
Fort Calhoun/ NUREG/CR-5834  
Ginna/ NUREG/CR-5764  
Kewaunee/ NUREG/CR-5821  
McGuire/ NUREG/CR-5830  
North Anna/ NUREG/CR-6837  
Palo Verde/ NUREG/CR-5836  
Point Beach/ NUREG/CR-5898  
Prairie Island Units 1 and 2/ NUREG/CR-5839  
Robinson, H.B./ NUREG/CR-5833  
Saint Lucie Unit-1 / NUREG/CR-5896  
Salem/ NUREG/CR-5761  
San Onofre Unit-2/ NUREG/CR-5766  
South Texas Project/ NUREG/CR-5897  
Summer, V.C./ NUREG/CR-5838  
Three Mile Island Unit 1/ NUREG/CR-5488  
Turkey Point/ NUREG/CR-5633

**For BWR Sites/ Risk Based Inspection Guides (for HPCI systems) – NUREG/CR #**

Browns Ferry/ NUREG/CR-6022  
Dresden Units 2 & 3 / NUREG/CR-5933  
Fermi, Enrico - Unit-2/ NUREG/CR-5959  
Hatch/ NUREG/CR-6014  
Hope Creek/ NUREG/CR-5923  
Pilgrim/ NUREG/CR-5924  
Quad Cities Units 1 and 2/ NUREG/CR-5934  
Susquehanna / NUREG/CR-5932

**Note:** This completes the OpESS inspection, however, other feedwater inspection guidance for consideration by inspectors is also provided in the “**ATTACHMENT**” to OpESS FY2009-02 Negative Trend and Recurring Events Involving feedwater systems.”

## **REPORTING INSPECTION RESULTS / TIME CHARGES / ADDITIONAL ISSUES:**

Document any inspection result findings, as applicable, in an integrated inspection report (i.e., quarterly inspection report/ PI&R or CDBI report) and reference the title/ OpESS number (example: **“Review of Operating Experience Smart Sample: OpESS FY2009-02,” Negative trend and Recurring Events Involving feedwater systems.”** If no findings are identified document completion of the OpESS using the “OpESS number/ title” under the applicable inspection attachment (i.e., 1R04,) stating that no findings of significance were identified.

Inspection time for this OpESS is to be charged to the normal baseline procedure under which it is being documented (along with any routine preparation and documentation charge times).

**ATTACHMENT**  
**(OpESS FY2009-02 “Negative trend and Recurring Events Involving Feedwater Systems  
(additional inspection guidance for consideration)**

1) Consider establishing a site specific “safety-related” feedwater or HPCI inspection notebook (as applicable) that retains important reference information and guidance for use related to their site specific AFW/ EFW (for PWRs) and RCIC / Isolation Condenser/ HPCI (for BWR) system inspections, operability issue reviews, etc. This handbook can be used during new resident training and during turnover at the site. Consider verification and **updating**, as necessary, of the NUREG risk based inspection guides for your specific site; or based on a sister/ Peer group similar plant site listed under the Inspection Guidance Item 4 above of this OPESS. **NOTE: USE THESE NUREGS WITH CAUTION** as this is “guidance material only.” Realize that these NUREGS were developed in the early 1990’s and may be out of date.

The below information provides some general feedwater inspection guidance also for consideration in a feedwater system notebook development.

- 2) Prior to performing baseline inspections on the feedwater systems, inspectors should consider reviewing the licensee CAP documents (perform a search of the licensee CAP for feedwater system related issues) to look for negative feedwater system trends or specific CAP issues that should be examined further. Review Maintenance Rule 10 CFR50.65 documentation [any (a1) status corrective actions status, etc). Look for incomplete actions, inadequate or untimely corrective actions related to feedwater issues.
- 3) Prior to performing baseline inspections on the feedwater systems, inspectors should consider reviewing outstanding (open) work orders, work history / maintenance records, equipment deficiencies, and any temporary system modifications existing on the feedwater system. Review these to ensure they have been appropriately entered into the licensee’s CAP or other appropriate program and have been resolved or are being resolved in a timely manner, appropriate to their level of safety significance.
- 4) Review typical operational parameters based on the licensee procedures /vendor guidance/ for safety-related feedwater design basis and Technical Specification surveillance requirements for the applicable site feedwater system to ensure that it is operable. Review current and past feedwater operating data recorded during testing including applicable system engineer trend analysis data, as necessary.
- 5) To ensure safety-related feedwater system readiness for operation, inspect during routine plant status walkdowns, or during other base line inspections related to the feedwater system the following items, as necessary (refer to IP-71111.04). Some of these may need to be verified by actual observation during licensee operator rounds, or licensee conducted operational testing or surveillance test runs. These feedwater system operability type items typically include, but are not limited to, the following types of operational parameters (which may include minimum/maximum and or “expected”/ normal values), If values are in question ensure licensee addresses them appropriately:
  - a.) Air pressure for air controlled valves properly set
  - b.) Various Tank levels properly maintained:  
i.e., Condensate storage tank level (PWR) or RCIC Storage tank level (BWR)
  - c.) Pump lubricating oil - proper levels
  - d.) Cooling supply alignments for pumps

- e.) Cooling water or keep-warm oil temperatures properly maintained
- f.) TDEFW / RCIC Governor Settings properly maintained
- g.) Turbine Overspeed trip level (in the correct run position)

Additional turbine driven pump note: A risk data review obtained from a Research Report – [“Component Performance Study -- Turbine Driven Pumps \(TDP\) 1998-2006,”](#) identified some statistically significant increasing and decreasing trends. This item provides the figures mentioned below.

Increasing trends included: Standby systems, industry-wide TDP Failure To Run (FTR) > 1Hour trend. (See Figure 3 in link above) and Frequency (events per reactor year) of FTR > 1Hour events, standby TDPs. (see Figure 14 in link above)

These two trends are actually the same increase due to Failure To Run > 1Hour events. There were five Failure To Run > 1Hour events in the standby TDPs. Four of the five events occurred during in the time period FY 2004 to FY 2006. In addition, the run hours associated with Failure To Run > 1 Hour for the standby systems decreased during these same years.

Statistically significant decreasing trends were identified from this TDP study for the following:

- Pooled AFW, HPCI, and RCIC TDP Unavailability (UA) trend. (see Figure 6, in link above)
- Frequency (events per reactor year) of start demands, standby TDPs. (see Figure 9,)
- Standby TDP run hours per reactor critical year of run  $\leq$  1Hour hours. (see Figure 10 in link above)

h.) Check for unusual noises during system operation (that may indicate signs of mechanical trouble) and ensure these are investigated and documented appropriately by the licensee.

i.) Check for unusual smells that may indicate leaks, over-heating, and for any smoke or burned discolored paint, etc. that may indicate problems.

j.) Review the room for proper transient combustible and fire ignition control (i.e., hot work controls).

k.) Check the TDEFW pump / RCIC/ HPCI pumps for fluid/air system or exhaust system leaks (cooling system, steam system, lube oil system, exhaust system, air system and ensure the licensee is aware of and captures these in the appropriate response program (i.e., captured in a CAP or work order/equipment deficiency programs, as applicable).

l.) Verify the steam driven pumps shuts down properly in accordance with licensee procedure (observing for any abnormal conditions, such as excessive vibration, etc.).

m.) Review operator logs and procedures during and following surveillance testing (to ensure they are followed and that they are properly conducted and the necessary operating data is correct. Pay particular attention to any notes of comments recorded in the procedure(s) by operators that may indicate abnormal conditions exist (verify necessary actions such as work orders/ corrective action documents were generated, in response to these notes).

n.) Discuss concerns of feedwater system performance with the appropriate personnel to gain their insights into potential issues, consider discussions with various: Operator(s), Maintenance personnel or System Engineer(s).

t.) Review available trending reports comparing operating logs over extended time that may indicate an impending or slowly developing issue or negative trend.

**6)** During maintenance activities review foreign material exclusion (FME) controls to ensure licensee is maintaining system cleanliness (especially during extended or refueling outages).

**7)** Periodically observe and/or review, as applicable, feedwater related In-Service Testing (IST) vibration data results and discuss this vibration trend analysis with the appropriate engineer(s).

**8)** Consider for review any feedwater related permanent plant modifications (using IP-71111.17) or any related temporary modifications (using IP-71111.23), and review proper use of temporary scaffolding in these areas.

**9)** Review, as necessary, any feedwater system troubleshooting activities to ensure licensee properly identifies the root cause (when needed) under the corrective action process. Diagnostic aids and reference materials that may assist the inspectors in this review may include such items as: Piping and Instrumentation diagrams (P&IDs), equipment drawings, system descriptions, maintenance/work history records, previous operating logs, CAP data base, vendor diagrams/ drawings, manufacturer maintenance manuals including; troubleshooting charts, parts lists, and operating experience data including INPO EPIX data, vendor owner's group alert lists, etc. Also observe /conduct discussions between and with the system engineer(s), maintenance engineer(s), vendor service representatives and various troubleshooting team members and supervisors, as necessary.

**10)** Periodically review any feedwater system health reports (maintenance rule reports, etc), on-line computer monitoring programs, or other unique diagnostic tools licensees use for feedwater systems for any diagnostic or performance trending insights they may provide in following up on feedwater related issues.

**11)** During and/or following painting in the feedwater system pump room(s) verify painting activities do not adversely impact the feedwater system operability.

**12)** Periodically review various feedwater support systems and their capability to support feedwater system operability (i.e., ventilation (heating ventilation and air conditioning), service water or other cooling systems, pump room sumps and drains/ flood control, fire suppression systems, and various electrical power supplies to feedwater system controls and protections (including alternate shutdown functions, as applicable).

**13)** Periodically review specific electrical components and circuits that affect the feedwater systems operation - (i.e., the specific testing of sequence logic controls and relay testing, SI start initiator relays, load shed logic controls and relay testing, as applicable for safety related systems). During surveillance testing of these relays, and other specific components that impact feedwater operation periodically select these surveillances for review (under IP-71111.22, Surveillance Testing and / or IP-71111.20, Refueling and Other Outage Activities, etc.).

**14)** Inspectors should considering developing and retaining other feedwater system checklists and guidance information (updating the risk based inspection guides as discussed in Step 1, as necessary), for inspecting their site specific feedwater (AFW/EFW or HPCI) systems and for



subsequent site turnover information, training of new inspectors, etc., as applicable.

**-END-**