JPG=

Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE ROSEMEAD, CALIFORNIA 91770

M. O. MEDFORD MANAGER, NUCLEAR LICENSING

May 6, 1986

TELEPHONE (818) 302-1749

Director. Office of Nuclear Reactor Regulation G. E. Lear, Director Attention: PWR Project Directorate No. 1

U. S. Nuclear Regulatory Commission

Washington, D.C. 20555

Gentlemen:

Docket No. 50~206 Subject:

Seawall Inspection Report

San Onofre Nuclear Generating Station

Unit 1

References: 1. Letter, Darrell G. Eisenhut, NRC, to Kenneth P. Baskin, SCE, dated November 21, 1984

> 2. Letter, M. O. Medford, SCE, to W. A. Paulson, NRC, dated November 18, 1984

During the return-to-service program on San Onofre Unit 1 in 1984, corrosion of the intake structure rebar was discovered and repaired. In their SER approving plant restart (enclosed with Reference 1), the NRC staff indicated that a field inspection of the seawall should also be performed.

During the current outage an inspection of the seawall was performed. Enclosed is a report on that inspection. The report identifies that minor areas of corrosion were observed but that they will not affect the seawall function for at least 15 years. A monitoring program will be established to monitor future corrosion.

If there are any questions on the enclosure, please let me know.

Very truly yours,

m a ment of

Enclosure

J. B. Martin, NRC Region V, Regional Administrator

F. R. Huey, USNRC Senior Resident Inspector, Units 1, 2 and 3

E. McKenna, USNRC, Integrated Safety Assessment Branch

8605080267 860506

fool Add: Nee Pure-A ADTS , I