Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE ROSEMEAD, CALIFORNIA 91770

M. O. MEDFORD

MANAGER OF NUCLEAR ENGINEERING

AND LICENSING

May 3, 1988

TELEPHONE (818) 302-1749

U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. John B. Martin, Regional Administrator

Dear Sir:

Subject:

Docket No. 50-206 IE Bulletin 88-01

San Onofre Nuclear Generating Station

Unit 1

In response to NRC Bulletin 88-01: "Defects In Westinghouse Circuit Breakers," a review has been conducted and it has been confirmed that Westinghouse DS-206 and DS-416 circuit breakers are utilized at San Onofre Unit 1 in Class 1E applications. The DSL-206, DSL-416 or DS-420 type breakers are not in use at San Onofre Unit 1. These circuit breakers are the subject of the IE Bulletin. Provided as an enclosure are the results of SCE's inspection of the DS-206 and DS-416 circuit breakers at San Onofre Unit 1.

Subscribed on this 3rd day of May, 1988

Respectfully submitted,

m o medford

Subscribed and sworn to before me this day of ______, 1988_.

Notary Public in and for the County of Los Angeles, State of California

OFFICIAL SEAL
C. SALLY SEBO
Notary Public-California
LOS ANGELES COUNTY
My Comm. Exp. Apr. 20, 1990

Enclosure

cc: J. B. Martin, Regional Administrator, NRC Region V

F. R. Huey, NRC Senior Resident Inspector, San Onofre Units 1, 2 and 3

TEII

Response to NRC Bulletin 88-01

SCE Report on Westinghouse DS Breaker Inspections

In accordance with the reporting requirements of this bulletin, the following data includes the breakers of each type inspected, the breakers of each type requiring corrective actions due to pole shaft welds not meeting the acceptance criteria, and the breakers of each type requiring corrective actions due to mechanism alignments not meeting the acceptance criteria. As San Onofre Unit 1 was in a mid-cycle outage, the breaker data contains all short-term and some long-term inspection results. Those breakers awaiting pole shaft replacement are spare breakers and will not be utilized in the plant. A follow-up report will be forwarded within 30 days after completion of the outstanding long-term inspections.

Summary of San Onofre Unit 1 Breaker Inspections

DS-206

Breaker Model	•	•	•	•	•	•	•	•	•	•	DS-206 9 1 4 4 0 7
Breaker Model	•		•	•	•	•	•	•	•	•	_

San Onofre Unit 1 Detailed Breaker Inspection Results

Breaker ID	S1-52-1130 DS-206 Pass Pass Pass
Breaker ID	S1-52-1129 DS-416 Pass Pass Pass
Breaker ID	DS-206
Pole shaft replaced. Long-Term Weld Inspections (Welds 1,4,5,7)	Fail Pass
* * *	
Breaker ID	S1-52-1126 DS-206 Fail
replaced. Long-Term Weld Inspections (Welds 1,4,5,7)	Fail
fusion. Long-Term Alignment Check w/New Shaft	Pass

Short-Term Weld Inspections (Welds 2,3,6)	DS-206
fusion. Pole shaft replaced. Long-Term Weld Inspections (Welds 1,4,5,7) Not Comment: Weld inspections not performed due to unsatisfactory results of short-term inspections.	Performed
	Pass
* * *	
Breaker ID	DS-206
Long-Term Weld Inspections	Pass Pass
* * *	
Breaker ID (Spare)	1-52-1226 DS-206 Fail
Long-Term Weld Inspections	Pass er Report
* * *	
Breaker ID	1-52-1227 DS-206 Fail
Pole shaft replaced. Long-Term Weld Inspections	Pass Pass

Breaker ID											DS-206
replaced. Long-Term Weld Inspections (Welds 1,4,5,7) Comment: Weld 7 failed due to weld size and length of weld.	•			•	•			•		•	Fail
Long-Term Alignment Check w/New Shaft			•					•			Pass
* * *											
Breaker ID									•	•	DS-206
replaced. Long-Term Weld Inspections (Welds 1,4,5,7) Comment: Welds 1 & 7 failed due to weld size and length of weld.	•	•	•	•	•	•		•	٠	•	Fail
Long-Term Alignment Check w/New Shaft		•	•	•	•	•			•	•	Pass
* * *											
Breaker ID		•				•			•	•	DS-416
shaft replaced. Long-Term Weld Inspections (Welds 1,4,5,7) Comment: Weld inspections not performed due to unsatisfactory results		•	•		•	• '	• •		٠	Not	Performed
of short term inspections. Long-Term Alignment Check w/New Shaft				•	•	•	•			•	Pass

* * *

.

Breaker ID (Spare)				. DS-416
Pole shaft to be replaced. Long-Term Weld Inspections (Welds 1,4,5,7) Comment: Welds 1,4,5,7 failed due to weld size. Weld 7 also failed due to lack of fusion.				. Fail
Long-Term Alignment Check w/New Shaft				Later Report
* * *				
Breaker ID (Spare)				. SO#27Y2656B. DS-416
Short-Term Weld Inspections (Welds 2,3,6) Comment: Welds failed due to weld size and length of weld. Pole shaft to be replaced.		• • •	•	. Fail
Long-Term Weld Inspections (Welds 1,4,5,7) Comment: Weld inspections not performed due to unsatisfactory results of short-term weld inspection.	• • •			Not Performed
Long-Term Alignment Check w/New Shaft	• •			Later Report

NM/ACL:0103V