



Southern California Edison Company

P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

F. R. NANDY
MANAGER OF NUCLEAR LICENSING

June 15, 1989

TELEPHONE
(818) 302-1896

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. John B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-206
NRC Bulletin 88-03
San Onofre Nuclear Generating Station
Unit 1

References: 1) NRC Bulletin 88-03, "Inadequate Latch Engagement in HFA Type Latching Relays Manufactured by General Electric (GE) Company," dated March 10, 1988

By Reference 1, the NRC requested that Southern California Edison (SCE) perform inspections of GE latching type HFA relays for inadequate latch engagement and insufficient latch spring tension. SCE completed these actions during the Cycle 10 refueling outage. Provided as an enclosure are the results of SCE's inspection of the GE latching type HFA relays installed in Unit 1.

Respectfully submitted,

By: F. R. Nandy
Manager of Nuclear Licensing

Subscribed and sworn to before me this
15th day of June, 1989.

Handwritten signature of Carol A. Gomez

Notary Public in and for the County of
Los Angeles, State of California



Handwritten initials IE 11

Enclosures

cc: U. S. Nuclear Regulatory Commission, Document Control Desk
F. R. Huey, NRC Senior Resident Inspector, San Onofre Units 1, 2 and 3

8906220144 890615
PDR ADOCK 05000206
PNU

RESPONSE TO NRC BULLETIN 88-03

A. SCE Report on GE Latching Type HFA Relay Inspections

In accordance with the reporting requirements of this bulletin, the following data includes the model number of the latching relay inspected, the number of relays of each type inspected, the number of each type requiring replacement due to interference between the molded contact carrier and the top of the relay armature, and the number of each type requiring replacement due to insufficient spring tension on the latch. As San Onofre Unit 1 was in a refueling outage, the relay data includes all the latching type relays installed in the plant. Spare relays stored in the warehouse and those installed at Units 2 and 3 have previously been inspected.

Summary of San Onofre Inspections

Unit 1 Relay Inspections

Relay Model .....	12HFA154E49F
Quantity .....	8
Passed Latch Interference Inspection .....	5
Failed Latch Interference Inspection .....	3
Passed Spring Tension Inspection .....	6
Failed Spring Tension Inspection .....	2
Failed Both Inspections .....	0
Relay Model .....	12HFA154E22F
Quantity .....	2
Passed Latch Interference Inspection .....	2
Passed Spring Tension Inspection .....	2

Replacement Relay Inspections

Relay Model .....	12HFA154E49F
Quantity .....	5
Passed Latch Interference Inspection .....	5
Passed Spring Tension Inspection .....	5

B. SCE Report on Planned Inspections When Procuring Future GE HFA Relays

In order to ensure future GE HFA relay spares are inspected prior to receipt and installation in the plant, SCE has placed additional checks into the procurement and spare parts process. In the procurement process, a Verification Test Procedure has been incorporated into the Spare Parts Ordering requirements for GE HFA relays such that the manufacturer will perform their own recommended inspections and guarantee the product before delivery. Because of the numerous problems with these relays, SCE has added the subject relays to the Control of Problem Equipment Program to ensure that Type 12HFA relays receive close scrutiny by SCE cognizant organizations prior to installation in the plant.

bu18801