

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN
STATION MANAGER

March 26, 1990

TELEPHONE
(714) 368-6241

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-206
30-Day Report
Licensee Event Report No. 90-004
San Onofre Nuclear Generating Station, Unit 1

Pursuant to 10 CFR 50.73(d), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving the Reactor Coolant System. Neither the health and safety of plant personnel or the public was affected by this occurrence.

If you require any additional information, please so advise.

Sincerely,

Neil Krueger
for H.E. Morgan

Enclosure: LER No. 90-004

cc: C. W. Caldwell (USNRC Senior Resident Inspector, Units 1, 2 and 3)

J. B. Martin (Regional Administrator, USNRC Region V)

Institute of Nuclear Power Operations (INPO)

9004180228 900326
FDR ADCK 05000206
S FDC

IE22
1/1

LICENSEE EVENT REPORT (LER)

Facility Name (1) SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 1
 Docket Number (2) 01501002016
 Page (3) 1 of 01

Title (4) POTENTIAL FOR REACTOR COOLANT SYSTEM LEAKAGE GREATER THAN 6 GPM DUE TO PROCEDURAL INADEQUACY

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Number(s)
0	2	23	91	0	0	0	3	26	91	0
									NONE	01501002016

OPERATING MODE (9) 1
 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)
 POWER LEVEL (10) 091
 20.402(b) _____ 20.405(c) _____ 50.73(a)(2)(iv) _____ 73.71(b) _____
 20.405(a)(1)(i) _____ 50.36(c)(1) _____ 50.73(a)(2)(v) _____ 73.71(c) _____
 20.405(a)(1)(ii) _____ 50.36(c)(2) _____ 50.73(a)(2)(vii) _____ Other (Specify in
 20.405(a)(1)(iii) X 50.73(a)(2)(i) _____ 50.73(a)(2)(viii)(A) Abstract below and
 20.405(a)(1)(iv) X 50.73(a)(2)(ii) _____ 50.73(a)(2)(viii)(B) in text
 20.405(a)(1)(v) _____ 50.73(a)(2)(iii) _____ 50.73(a)(2)(x) _____

LICENSEE CONTACT FOR THIS LER (12)
 Name: H. E. Morgan, Station Manager
 TELEPHONE NUMBER: AREA CODE 714, 368-1624

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS
X	C	B	ISV	B	2	9	5	Y	

SUPPLEMENTAL REPORT EXPECTED (14)
 Yes (If yes, complete EXPECTED SUBMISSION DATE) NO
 Expected Submission Date (15) 041791

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 2/23/90, with Unit 1 in Mode 1 at 91.5% power, during a review of a nonconformance report addressing leakage through letdown orifice isolation valve CV-203 [ISV], it was determined that the potential for a condition prohibited by the basis of Technical Specification (TS) Section 3.1.4 existed. On 3/13/90, during our continuing review of this event, SCE concluded that this also represented a condition not covered by the plant's emergency procedures and subsequently reported it as a non-emergency one-hour report pursuant to 10 CFR 50.72(b)(1)(ii)(C).

San Onofre Unit 1 TS 3.1.4 basis requires that total Reactor Coolant System (RCS) [AB] leakage be limited to 6 gpm for 12 hours during a Station Blackout (SBO). Letdown level control valve LCV-1112 [LCV] is normally considered the RCS leakage boundary for the letdown portion of the Chemical and Volume Control System [CB]. However, during the SBO event postulated by TS 3.1.4 basis, LCV-1112 can not be credited to isolate the letdown system and the containment isolation valves (downstream of LCV-1112) are closed. During this condition, if leakage were to occur through any of the three letdown orifice isolation valves (located between LCV-1112 and the containment isolation valves), relief valve RV-206 might lift (setpoint 485 psig) establishing a leakage path out of the RCS. Were this to occur, it is possible that the TS leakage limit might be exceeded.

The cause of this event was that station procedures, including the Emergency Operating Instruction (EOI), "Loss Of All AC Power," did not adequately consider potential RCS leakage through letdown isolation valves and therefore, did not provide for a positive means (i.e., manual isolation) for meeting the 6 gpm leakage requirement in TS 3.1.4 basis.

As corrective actions, the EOI was revised to require closing a manual isolation valve on the letdown line upstream of the relief valve to ensure positive isolation of letdown. Appropriate training and a drill on the changes to the EOI have been performed.

A revision to this LER will be submitted by 4/17/90, providing a complete discussion of the root cause, corrective actions, and safety significance of this condition.