



LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: C A S 0 S 1; LICENSE NUMBER: 00-000000-000; LICENSE TYPE: 4111; CAT: 5

REPORT SOURCE: L; DOCKET NUMBER: 05000206; EVENT DATE: 010979; REPORT DATE: 020779

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During normal operations, while testing containment isolation valves, the isolation valve on the cooling water from the containment air handling units failed to close. There is no redundant isolation valve in this line, however, the system is closed inside the containment. There were no significant consequences as a result of this failure. This report is per Tech.Spec. 6.9.2-b. A similar event was reported in LER 78-002.

SYSTEM CODE: S D; CAUSE CODE: E; CAUSE SUBCODE: X; COMPONENT CODE: V A L V I O P; COMP. SUBCODE: X; VALVE SUBCODE: Z

LER/RO REPORT NUMBER: 79; EVENT YEAR: 79; SEQUENTIAL REPORT NO.: 001; OCCURRENCE CODE: 03; REPORT TYPE: L; REVISION NO.: 0

ACTION TAKEN: X; FUTURE ACTION: X; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: N; NPRD-4 FORM SUB.: Y; PRIME COMP. SUPPLIER: X; COMPONENT MANUFACTURER: X999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Exact cause undetermined. An Engineering Evaluation of Efcomatic valve operators will be performed with the objective of identifying potential failure modes and implementing corresponding corrective actions. In addition, all Efcomatic valve operators will be inspected for defects and repaired as necessary during 1980 refueling outage.

FACILITY STATUS: E; % POWER: 100; OTHER STATUS: N.A.; METHOD OF DISCOVERY: B; DISCOVERY DESCRIPTION: Valve failed to close

ACTIVITY CONTENT: Z; AMOUNT OF ACTIVITY: N.A.; LOCATION OF RELEASE: N.A.

PERSONNEL EXPOSURES: 000; TYPE: Z; DESCRIPTION: N.A.

PERSONNEL INJURIES: 000; DESCRIPTION: N.A.

LOSS OF OR DAMAGE TO FACILITY: Z; DESCRIPTION: N.A.

PUBLICITY ISSUED: N; DESCRIPTION: N.A.

NAME OF PREPARER: J.M. Curran; PHONE: (714) 492-7700

dupes of 7902130112