

**Enclosure 3**

**Reactor Oversight Process Frequently Asked Questions – November 20, 2013**

**FAQ Log Entering ROP Public Meeting November 20, 2013**

<b>FAQ No.</b>	<b>PI</b>	<b>Topic</b>	<b>Status</b>	<b>Plant/Co.</b>	<b>Point of Contact</b>
13-03	IE03	Quad Cities Animal Intrusion	INTRODUCED 09/11/2013 TENTATIVE FINAL 10/23/2013	Quad Cities Exelon	Jason Smith (Exelon)  Brian Cushman (NRC)
13-04	EP03	Point Beach ANS	INTRODUCED 09/11/2013 Discussed on 10/23/2013	Point Beach NextEra	Gerard Strharsky (NextEra)  James Beavers (NRC)
13-05	IE03	Oyster Creek Downpower	INTRODUCED 09/11/2013 Discussed on 10/23/2013	Oyster Creek Exelon	Dennis Moore (Exelon)  Jeffrey Kulp (NRC)
13-06	MS07	Dresden MSPI	INTRODUCED 09/11/2013 Discussed on 10/23/2013	Dresden Exelon	Joshua Smith (Exelon)  Chuck Phillips (NRC)
13-07	EP01	DEP Scoring Opportunity	INTRODUCED 09/11/2013 Discussed on 10/23/2013	DCPP (Generic)  PGE	Brian Ashbrook (PGE)  Paul Elkmann (NRC)

NEI Contact: James E. Slider, 202-739-8015, [jes@nei.org](mailto:jes@nei.org)

**FAQ 13-03**  
**Quad Cities Animal Intrusion**

**Plant:** Quad Cities

**Date of Event:** June 5, 2013

**Submittal Date:** August 16, 2013

**Licensee Contact:** Jason Smith

**Tel/email:** jason.smith@exeloncorp.com

**NRC Contact:** Brian Cushman

**Tel/email:** brian.cushman@nrc.gov

**Performance Indicator:** Unplanned Power Changes per 7,000 Critical Hours (IE03)

**Site-Specific FAQ (Appendix D)?** No

**FAQ requested to become effective:** when approved

## Question Section

Question #1 -What is considered reasonable for prevention of animal intrusion? Would turning off the lights in a switchyard without motion sensors and an intact boundary still be considered reasonable to prevent animal intrusion?

Question #2 – When does the anticipated outcome of an event apply for PI reporting? If during the review of an event, new information is discovered that validates plant response during the event, can that new information be applied to consider the plant response anticipated even though operators were challenged by unanticipated plant response at the time?

### **NEI 99-02, Rev. 7 Guidance needing interpretation (include page and line citation):**

Page 15, line 19-28

19 Anticipated power changes greater than 20% in response to expected environmental problems  
20 (such as accumulation of marine debris, biological contaminants, or frazil icing) which are  
21 proceduralized but cannot be predicted greater than 72 hours in advance may not need to be  
22 counted unless they are reactive to the sudden discovery of off-normal conditions. However,  
23 unique environmental conditions which have not been previously experienced and could not  
24 have been anticipated and mitigated by procedure or plant modification, may not count, even if  
25 they are reactive. The licensee is expected to take reasonable steps to prevent intrusion of  
26 marine or other biological growth from causing power reductions. Intrusion events that can be  
27 anticipated as part of a maintenance activity or as part of a predictable cyclic behavior would  
28 normally be counted unless the down power was planned 72 hours in advance.

Page 16, line 39-43

39 For an environmental event to be excluded, any of the following may be applied:

- 40 • If the conditions have been experienced before and they exhibit a pattern of
- 41 predictability or periodicity (e.g., seasons, temperatures, weather events, animals, etc.),
- 42 the station must have a monitoring procedure in place or make a permanent modification
- 43 to prevent recurrence for the event to be considered for exclusion from the indicator. If

### **Event or circumstances requiring guidance interpretation:**

On June 5, 2013 an animal (raccoon) caused a fault on a 13.8 kV bus located in the Quad Cities switchyard near Transformer 82, when the animal contacted one phase and part of the metal structure. The Unit 2 reserve aux transformer (RAT) tripped from service, as expected, and a fast bus transfer occurred to

**FAQ 13-03**  
**Quad Cities Animal Intrusion**

preclude a load trip due to undervoltage. This fault resulted in the loss of a bus in the switchyard. By procedure, when this bus is lost, operators are directed to reduce Unit 2 to approximately 85% power for transformer loading concerns on the unit auxiliary transformer (UAT). During the downpower, in response to the loss of the transformer, reduced feedwater temperature was observed by the control room operators. In response to the reduced feedwater heating, power was reduced to about 60% in accordance with approved procedures. Operator monitoring and response was consistent with their training and in accordance with approved station procedures.

Licensee management has determined that this event is not reportable because the transient was initiated by an animal intrusion event and the lower than anticipated final power was not the result of an equipment failure or human performance error.

The NRC resident inspectors consider this event reportable because the licensee began turning off the lights in the switchyard at night. Without lighting, the conditions in the switchyard were no longer reasonable to prevent animal intrusion. Also, by training and annunciator response, the anticipated power reduction for a loss of the Unit RAT would be about 85% power. The loss of feedwater heating, which was unanticipated for this event at the time, was an additional 25% downpower that should be reported as a separate PI occurrence.

**If licensee and NRC resident/region do not agree on the facts and circumstances explain:**

The licensee and the NRC agree on the facts. The NRC and the licensee disagree on the applicability of reporting under the PI.

**The Licensee's Position:**

Reasonable steps were taken to prevent the animal intrusion. The switchyard fence was in good repair and the gates were secured. Operations personnel perform a weekly walkdown of the switchyard and daily rounds in the switchyard on T82. This would identify degraded conditions and any signs of animal intrusion. Also, the switchyard is in a frequently traveled area next to the security checkpoint. A vegetation management program is also in place, which sprays the switchyard to prevent overgrowth. Consistent with the guidance in NEI 99-02 (referenced above) a plant modification was installed after this event. This change added wildlife deterrent devices to both transformers 81 and 82. These devices should prevent recurrence of animal intrusion. Given the level of human activity in the area, material condition of the switchyard, and a history of no animal intrusion issues, the licensee maintains that reasonable steps were taken and in place to prevent animal intrusion.

Of note, the decision to turn off lights in the switchyard was vetted with key stakeholders prior to implementation.

The loss of feedwater heating was due to the voltage transient on the instrument bus, as a direct result of the fault caused by the raccoon. The momentary lowering of voltage caused various feedwater heater solenoid valves to trip, resulting in feedwater heater level control valves unlatching. Operators responded to the transient in accordance with approved procedures.

The loss of feedwater heating could be expected to occur during a fault in the switchyard, depending on where the fault occurs. There have been faults in the past where all heaters have remained latched, and some faults where a partial loss of feedwater heating has occurred. In this event, the fault was sufficient to cause enough of a voltage transient that the feedwater heater latching solenoids dropped out. Operators

## **FAQ 13-03 Quad Cities Animal Intrusion**

are trained on the loss of a Unit RAT and also trained on loss of feedwater heating. The operator responses for these two events are governed by approved procedures. There were no malfunctions of equipment or human performance errors that led to the additional 25% downpower.

### **The NRC's Position:**

The NRC concurs that the switchyard fence was in good repair and there was no food or other materials in the switchyard. Licensee management made a decision to turn the lights in the switchyard off except for times of maintenance. There are no motion detectors in the switchyard. Lights have been on in the switchyard during the night for the purpose of theft deterrent. Licensee management did not assess if the lights in the switchyard also provided a deterrent to the local wildlife. Licensee management made this change to the switchyard lighting during the weekend of June 1, 2013 and on June 5, 2013, an animal causes a switchyard fault.

The NRC agrees that no equipment failed and no human performance errors occurred during this event that contributed to the extra 25% downpower. Indications were received by the control room operators for a loss of a Unit RAT. The additional loss of feedwater heating was unexpected and not anticipated to occur coincident with the loss of a Unit RAT. This fault occurred on the bus that feeds the transformer which resulted in the unlatching of several feedwater level control valves. This new information will be incorporated into operator response procedures and training materials.

It is the position of the NRC that prior to this event, the anticipated final plant condition for a loss of the Unit RAT is 85% power. For future events, with the inclusion of the possibility of partial loss of feedwater heating incorporated, the expected final power level may be lower. But for the purposes of reporting under this PI, the additional 25% power reduction should be reported as an unplanned power change.

### **Potentially relevant existing FAQ numbers:**

ID 237- The response details taking actions outside of pre-planned activities.

## **Response Section**

### **Proposed Resolution of FAQ**

Proposed answer #1 – An intact switchyard fence in a frequently traveled area can be viewed as a reasonable barrier for the prevention of animal intrusion, with or without switchyard lighting being illuminated. Vegetation management practices were in place to ensure there was not an adequate habitat for raccoons or their food source to exist.

Proposed answer #2 – Since the reduction in power was solely due to an animal intrusion event, this event should not be reported, regardless of when the validation of plant response is determined. The plant operated as expected during the transient and the operators responding to the event took appropriate actions in accordance with approved procedures.

**FAQ 13-04**  
**Point Beach Alert & Notification System**

**Plant:** Point Beach 1 and Point Beach 2

**Date of Event:** May 15, 2013

**Submittal Date:** August 14, 2013

**Licensee Contact:** Gerard D. Strharsky

**Tel/email:** 920-755-6557

**NRC Contact:** James Beavers

**Tel/email:** 630-829-9760

**Performance Indicator:** Alert and Notification System Reliability (EP03)

**Site-Specific FAQ (Appendix D)?** Yes, Appendix D page D-1

**32 Kewaunee and Point Beach**

33

34 Issue: The Kewaunee and Point Beach sites have overlapping Emergency Planning Zones (EPZ).  
35 We report siren data to the Federal Emergency Management Agency (FEMA) grouped by criterion  
36 other than entire EPZs (such as along county lines). May we report siren data for the PIs in the  
37 same fashion to eliminate confusion and prevent 'double reporting' of sirens that exist in both  
38 EPZs? Kewaunee and Point Beach share a portion of EPZs and responsibility for the sirens has  
39 been divided along the county line that runs between the two sites. FEMA has accepted this, and  
40 so far the NRC has accepted this informally.

41

42 Resolution: The purpose of the Alert and Notification System Reliability PI is to indicate the  
43 licensee's ability to maintain risk-significant EP equipment. In this unique case, each neighboring  
44 plant maintains sirens in a different county. Although the EPZ is shared, the plants do not share  
45 the same site. In this case, it is appropriate for the licensees to report the sirens they are  
46 responsible for. The NRC Web site display of information for each site will contain a footnote  
47 recognizing this shared EPZ responsibility.

**FAQ requested to become effective when approved.**

**Question Section:**

**NEI 99-02 Guidance needing interpretation (include page and line citation):**

Page D-1 Lines 45 and 46. "In this case, it is appropriate for the licensees to report the sirens they are responsible for."

**Event or circumstances requiring guidance interpretation:**

Point Beach Nuclear Plant (PBNP) personnel have been notified that as a result of the Kewaunee Power Station (KPS) decommissioning actions, KPS will no longer be monitored under the NRC Reactor Oversight Process (ROP). On May 15, 2013 the NRC docketed KPS's certification of permanent defueling. Pursuant to 10 CFR 50.82(a)(1)(ii), the 10 CFR Part 50 license for KPS no longer authorizes operation of the reactor or emplacement or retention of fuel into the reactor vessel, as specified in 10 CFR 50.82(a)(2). All data collection for CDE and INPO shall be counted from the beginning of May until May 15, 2013 @ 1358.

This situation results in a condition where neither KPS nor PBNP are reporting NEI 99-02 ANS PI data for the eight overlapping sirens located in Kewaunee County. The sirens are still the responsibility of and are being maintained by KPS as required by 10CFR50.47 and 10CFR 50 Appendix E. Because KPS retains

**FAQ 13-04**  
**Point Beach Alert & Notification System**

responsibility for the sirens, PBNP is not reporting PI data as outlined in current NEI 99-02 guidance. This condition will exist until PBNP installs new or assumes responsibility for the existing overlapping sirens. PBNP understands that it is the licensee's responsibility to ensure ANS sirens remain available and are not impacted by the KPS decommissioning process. PBNP also understands that KPS will be submitting an exemption that would no longer require a Public Alert and Notification System (ANS siren equipment) when they transition to a fully decommissioned, this is expected to occur one year to seventeen months from the May 15, 2013 permanent defueled date.

PBNP has historically, and will continue to, obtain ANS siren performance and maintenance records and data from KPS for the purpose of monitoring and recording all required information related to overlapping siren performance.

**If licensee and NRC resident/region do not agree on the facts and circumstances explain**

The content of this FAQ has been reviewed with NRC Region III Emergency Preparedness Inspector Mr. James Beavers. Mr. Beavers indicated that he concurs with the facts and circumstances as provided.

**Potentially relevant existing FAQ numbers**

None

**Response Section**

**Proposed Resolution of FAQ**

Until such time as KPS is no longer responsible for the 8 ANS sirens that are co-located in Kewaunee County and are within the PBNP EPZ, PBNP will document siren performance for these 8 sirens in the comments section of the Point Beach Unit 1 and Unit 2 Emergency Preparedness performance indicator (Total sirens-tests), in the INPO Consolidated Data Entry data base. When PBNP becomes responsible for the maintenance and testing of sirens located in Kewaunee County, revise NEI 99-02 Rev. 6 Appendix D to remove the "Kewaunee and Point Beach" plant specific design issue from the document. PBNP will subsequently commence reporting of siren performance for all sirens within the PBNP EPZ as required by the ROP and NEI 99-02.

**If appropriate, provide proposed rewording of guidance for inclusion in next revision.**

No wording change is required.

**FAQ 13-05**  
**Oyster Creek Downpower**

**Plant:** Oyster Creek Nuclear Generating Station

**Date of Event:** 09/28/2012

**Submittal Date:**

**Licensee Contact:** Dennis M Moore      **Tel/Email:** 609-971-4281 dennis.moore@exeloncorp.com

**NRC Contact:** Jeffrey Kulp                      **Tel/Email:** 609-971-4978

Performance Indicator: UNPLANNED POWER CHANGES PER 7,000 CRITICAL HOURS (IE03)

Site-Specific FAQ (Appendix D)? No

FAQ requested to become effective: **when approved.**

### Question Section

NEI 99-02 Guidance needing interpretation (include page and line citation):

Page 13

25      *Unplanned changes in reactor power* are changes in reactor power that are initiated less than 72  
26      hours following the discovery of an off-normal condition, and that result in, or require a change  
27      in power level of greater than 20% of full power to resolve. Unplanned changes in reactor power  
28      also include uncontrolled excursions of greater than 20% of full power that occur in response to  
29      changes in reactor or plant conditions and are not an expected part of a planned evolution or test.

Page 14

10      Equipment problems encountered during a planned power reduction greater than 20% that alone  
11      may have required a power reduction of 20% or more to repair are not counted as part of this  
12      indicator if they are repaired during the planned power reduction. However, if during the  
13      implementation of a planned power reduction, power is reduced by more than 20% of full power  
14      beyond the planned reduction, then an unplanned power change has occurred.

Event or circumstances requiring guidance interpretation:

On September 28, 2012 at 1802- Oyster Creek Nuclear Generating Station (OCNGS) experienced an increase in leakage from a previously identified (<72 hours) salt water leak into the condenser bay from a hole in circulating water piping. The timeline of power changes and event details are as follows:

1855 - Control Room Operators commenced lowering power to allow isolating and draining of the 1A North Condenser waterbox to mitigate the leakage of water into the condenser bay.

1914 – GenManager Ticket Number 1022326 was created to track the emergent downpower to 85%. The ticket begin time was 1901 with an end time of 2259 (the ticket was created, as such, with the intention of merging the repair with the upcoming planned downpower to 73%).

1927 - The power reduction was complete with Reactor Power at 85%.

1943 – The 1A North Condenser waterbox was isolated reducing the leakage to approximately half of the initial leakage.

2110 - Operations commenced draining 1A North waterbox

2147 – Operations completed a pre-job brief for lowering reactor power to 73% for “End of Cycle Rod Maneuvers”

**FAQ 13-05**  
**Oyster Creek Downpower**

2305 – Control Room Operators commenced lowering power from 85% to 73% for “End of Cycle Control Rod conditioning maneuver” (This is the beginning of a planned, >72 hours in advance, downpower to lower power to 73% from 9/28, 2300 until 9/29, 0700 )

9/29, 0015 – Control Room Operators completed lowering power to 73%.

9/29, 0033 – Control Room Operators commenced raising power for “End of Cycle Control Rod conditioning”

9/29, 0041 – The initial repair to the 1A North Condenser waterbox piping was complete reducing the leakage from the waterbox to approximately 1 gpm.

9/29, 0116 – A decision was made to hold the power ascension (with power at 80%) to further assess the salt water leak prior to returning to 100% power

09/29, 0217 – Operations completed a pre-job brief for lowering power to 70% to aid in completing additional circulating water piping repair to reduce or eliminate leakage. (70% was chosen to provide more repair options)

09/29, 0302 – Control Room Operators commenced lowering power from 80% to 70% to “Repair leak Circ Water Leak”

09/29, 0335 – Control Room Operators completed lowering power to 70%

09/29, 0335 to 09/29, 1539 – OCNCS took action, as required, to aid in repairing the circulating water leak.

09/29, 1539 – Circulating water repairs are complete and Control Room Operators commenced raising reactor power from 70% to 100%

09/29, 1843 – Reactor power was returned to 100%

As noted above, Oyster Creek lowered power emergently (<72 hours) due to a salt water leak- with an initial power reduction to 85% (<20% reduction). Power was then lowered to 73% at 0015 in accordance with a planned (>72 hours) power maneuver. After completion of the planned power maneuver, during power ascension (at approximately 80%) a decision was made to lower power to 70% power to facilitate additional repairs to the circulating water system to attempt to eliminate leakage. 70% power was chosen to allow securing of a circulating water pump to increase repair options. (It is important to note that the repair could have been made at a power level above 70%.)

If licensee and NRC resident/region do not agree on the facts and circumstances explain:

**NRC Position**

The description of the event and subsequent plant response is accurate as presented.

The NRC resident inspection staff does not agree that the guidance provided in NEI 99-02 excludes the duration of a downpower from consideration when determining whether a downpower should count against this performance indicator. NEI 99-02 revision 6, page 14, lines 10-14 state:

“Equipment problems encountered during a planned power reduction greater than 20% that alone may have required a power reduction of 20% or more to repair are not counted as part of this indicator if they are repaired during the planned power reduction. However, if during the implementation of a planned power reduction, power is reduced by more than 20% of full power beyond the planned reduction, then an unplanned power change has occurred.”

**FAQ 13-05**  
**Oyster Creek Downpower**

The NRC resident inspection staff determined that this downpower should count for the following reasons:

- The initial downpower was due to address an off-normal condition (the leak on the circulating water piping) and occurred approximately 4 hours before scheduled power reduction for control rod conditioning.
- The licensee reduced power by a total of 30% to perform the repair and resolve the equipment problem.
- The equipment problem was not repaired during the planned power reduction.

**Licensee Position**

An emergent downpower to 85% was initiated to address circulating water piping leak. The emergent downpower was scheduled to coincide with a planned downpower to 73% for End of Cycle Rod Maneuvers (rod pattern adjustments). Repairs commenced during the emergent downpower and continued into the planned power reduction significantly reducing the leakage (to approximately 1 gpm). The emergent downpower was < 20 and therefore outside the scope of the performance indicator.

During power ascension from the planned power reduction for rod pattern adjustments, a decision was made to halt the power ascension at 80%, reduce power to 70%, and perform additional repairs to further reduce or eliminate leakage from the circulating water piping repair prior to returning to 100% power.

- The power reduction to 70% was outside of the preplanned evolution which ended at 0033 on 9/29/12
- The power reduction to 70% was < 20% below the previous power level of 80%
- A power reduction to 70% was not required for the additional repairs
- Power level had not been restored to 100% following completion of the planned power reduction.

Potentially relevant existing FAQ numbers: None

**Response Section**


Proposed Resolution of FAQ

The emergent and preplanned power reduction should be evaluated as two power reductions as opposed to one continuous power reduction to 73%. The power reduction from 80 to 70 should not be counted as an unplanned power reduction since it was not >20% from the preplanned or the previous power level.

If appropriate, provide proposed rewording of guidance for inclusion in next revision.

FAQ 13-05  
Oyster Creek Downpower

Attachment 1 - Reactor Power vs Time



Lowered Power due to a leak in the Circulating Water system (unplanned)

Lowered power as part of a planned (>72 hours) rod pattern adjustment

Commenced raising power due to completion of rod pattern adjustment

Lowered power due to need to continue Circulating Water pipe repair

Completed Circulating Water pipe repair and raised power

**FAQ 13-06  
Dresden MSPI**

Plant:	<u>Dresden Units 2 &amp; 3</u>		
Date of Event:	<u>5/22/12 &amp; 6/10/12</u>		
Submittal Date:	<u>8/30/13</u>		
Licensee Contact:	<u>Joshua Smith</u>	Tel/Email:	<u>815-416-3848 / Joshua.Smith3@exeloncorp.com</u>
NRC Contact:	<u>Chuck Phillips</u>	Tel/Email:	<u>630-829-9752 / Charles.Phillips@nrc.gov</u>

Performance Indicator: **MSPI**

Site-Specific FAQ (Appendix D)? **No**

FAQ requested to become effective **when approved**.

### Question Section

NEI 99-02 Guidance needing interpretation (include page and line citation):

#### **Per NEI 99-02, Rev. 6 under Unplanned Unavailable Hours on page F-5:**

“Unplanned unavailable hours: These hours include elapsed time between the discovery and the restoration to service of an equipment failure or human error (such as a misalignment) that makes the train unavailable. Time of discovery of a failed monitored component is when the licensee determines that a failure has occurred or when an evaluation determines that the train would not have been able to perform its monitored function(s). In any case where a monitored component has been declared inoperable due to a degraded condition, if the component is considered available, there must be a documented basis for that determination, otherwise a failure will be assumed and unplanned unavailability would accrue. If the component is degraded but considered operable, timeliness of completing additional evaluations would be addressed through the inspection process. **Unavailable hours to correct discovered conditions that render a monitored component incapable of performing its monitored function are counted as unplanned unavailable hours.** An example of this is a condition discovered by an operator on rounds, such as an obvious oil leak, that was determined to have resulted in the equipment being non-functional even though no demand or failure actually occurred. Unavailability due to mis-positioning of components that renders a train incapable of performing its monitored functions is included in unplanned unavailability for the time required to recover the monitored function.”

#### **Per NEI 99-02, Rev. 6 under Planned Unavailable Hours on page F-5:**

“Planned unavailable hours: These hours include time a train or segment is removed from service for a reason other than equipment failure or human error. **Examples of activities included in planned unavailable hours are preventative maintenance, testing, equipment modification, or any other time equipment is electively removed from service to correct a degraded condition that had not resulted in a loss of function.** Based on the plant history of previous three years, planned baseline hours for functional equipment that is electively removed from service but could not be planned in advance can be estimated and the basis documented. When used in the calculation of UAI, if the planned unavailable hours are less than the baseline planned unavailable hours, the planned unavailable hours will be set equal to the baseline value.”

**FAQ 13-06  
Dresden MSPI**

**Per NEI 99-02, Rev. 6 under Train Unavailable Hours on page F-5:**

“Train unavailable hours: The hours the train was not able to perform its monitored function while critical. Fault exposure hours are not included; unavailable hours are counted only for the time required to recover the train’s monitored functions. **In all cases, a train that is considered to be OPERABLE is also considered to be available.** Unavailability must be by train; do not use average unavailability for each train because trains may have unequal risk weights.”

**Per NEI 99-02, Rev. 6 under Unavailability on page 31:**

“Unavailability is the ratio of the hours the train/system was unavailable to perform its monitored functions (as defined by PRA success criteria and mission times) due to planned and unplanned maintenance or test during the previous 12 quarters while critical to the number of critical hours during the previous 12 quarters. (Fault exposure hours are not included; unavailable hours are counted only from the time of discovery of a failed condition to the time the train’s monitored functions are recovered.) Time of discovery of a failed monitored component is when the licensee determines that a failure has occurred or when an evaluation determines that the train would not have been able to perform its monitored function(s). **In any case where a monitored component has been declared inoperable due to a degraded condition, if the component is considered available, there must be a documented basis for that determination, otherwise a failure will be assumed and unplanned unavailability would accrue.** If the component is degraded but considered operable, timeliness of completing additional evaluations would be addressed through the inspection process.”

**Event or circumstances requiring guidance interpretation:**

On 5/22/12 at Dresden Unit 2 and 6/10/12 at Dresden Unit 3, minor steam leaks were discovered on elbows for the High Pressure Coolant Injection (HPCI) System Drain Pot Line. The purpose of this line is to provide a drainage path for any condensation that forms at steam isolations while the system is in standby. The line is isolated from the system upon initiation and not required for the system to perform its safety functions. This line of piping is ASME Code Class 2 piping and, per the Dresden Technical Requirements Manual (TRM), requires the structural integrity be restored or the component isolated immediately if the boundary is not in conformance. In order to isolate this portion of piping, the inboard and outboard steam isolation valves (2301-4/5) must be closed, thus isolating the entire HPCI system from steam and making it unavailable. The system remained operable and available prior to the steam supply valves being closed.

When reporting the unavailability for the Mitigating System Performance Index (MSPI), Dresden Station considered this unavailability to be Planned Unavailability based on the definitions provided in NEI 99-02 referenced above. The station counted the unavailability as planned since the system was still capable of performing its monitored function with the leak; i.e. the leaking component is not a monitored component and the monitored function of providing a source of high pressure make-up water to the Reactor Vessel (per the Reactor Oversight Program MSPI Bases Document for Dresden Nuclear Generating Station, Rev. 9, Nov. 2011 under Section 2.2) was not lost. This aligns with the above section from NEI 99-02 discussing unplanned unavailable hours.

On 4/25/13, a Regional NRC Inspector questioned the station on how it applied the MSPI unavailability. The NRC Inspector believes that the station did not remove the equipment from service electively due to

**FAQ 13-06**  
**Dresden MSPI**

the TRM requirement and, therefore, the unavailability should be counted as unplanned per the above section from NEI 99-02 discussing planned unavailable hours.

**If licensee and NRC resident/region do not agree on the facts and circumstances explain:**

The facts and circumstances are agreed upon. The only point of contention is whether the unavailability detailed above should be counted as planned or unplanned based on the interpretation of NEI 99-02.

## Response Section

### **Proposed Resolution of FAQ**

Revise the sections of NEI 99-02 that affect the interpretation of planned versus unplanned unavailability to make it clear that anytime there is not a failure of a monitored component /function, the unavailability is considered to be planned.

NEI 99-02, Rev. 6, page F-5, beginning at line 24:

*Planned unavailable hours:* These hours include time a train or segment is removed from service for a reason other than **a condition within the train/segment boundary that renders the train/segment unavailable**. Examples of activities included in planned unavailable hours are preventive maintenance, testing, equipment modification, or any other time **equipment is removed** from service to correct a degraded condition that had not resulted in loss of function. Based on the plant history of previous three years, planned baseline hours for functional equipment **that is removed from service** but could not be planned in advance (**e.g., predictive maintenance**) can be estimated and the basis documented. When used in the calculation of UAI, if the planned unavailable hours are less than the baseline planned unavailable hours, the planned unavailable hours will be set equal to the baseline value.

*Unplanned unavailable hours:* These hours include elapsed time between the discovery and the restoration to service of an equipment failure, **condition** or human error (such as a misalignment) **that results in a loss of function. Time of discovery is when the licensee** determines that a failure has occurred or when an evaluation determines that the **train/segment** would not have been able to perform its monitored function(s). In any case where a monitored component has been declared inoperable due to a degraded condition, if the component is considered available, there must be a documented basis for that determination, otherwise a failure will be assumed and unplanned unavailability would accrue. If the component is degraded but considered operable, timeliness of completing additional evaluations would be addressed through the inspection process. Unavailable hours to correct discovered conditions that render a monitored component incapable of performing its monitored function are counted as unplanned unavailable hours. An example of this is a condition discovered by an operator on rounds, such as an obvious oil leak, that was determined to have resulted in the equipment being non-functional even though no demand or failure actually occurred. Unavailability due to mis-positioning of components that renders a train incapable of performing its monitored functions is included in unplanned unavailability for the time required to recover the monitored function.

**FAQ 13-07**  
**Correctly Scoring Classification Opportunities (DCPP)**

**Plant:** DCP

**Date of Event:**

**Submittal Date:** April 23, 2013

**Contact:** Brian Ashbrook

**Tel/email:** 805.545.6279 bka4@pge.com

**NRC Contact:**

**Tel/email:**

**Performance Indicator:** EP01, Drill/Exercise Performance

**Site-Specific FAQ (Appendix D)?** No

**FAQ requested to become effective:** when approved

### Question Section

**NEI 99-02 Guidance needing interpretation (include page and line citation):**

Page 44, Lines 19 & 20:

“Timely means:

- classifications are made consistent with the goal of 15 minutes once available parameters reach an Emergency Action Level (EAL)...”

**Event or circumstances requiring guidance interpretation:**

In a license operator requalification simulator session with a simulated earthquake at T=0, the shift manager (SM) emergency coordinator declared to the operations shift at T=7 minutes an Unusual Event (UE). After declaring the event, the SM requested additional information from the operations shift and after additional information was presented to the SM, the SM changed the classification level to the correct classification level, Alert, at T=10 minutes.

The scenario expectation was that only an Alert would be declared, although both the UE EAL threshold and Alert thresholds were exceeded. Because guidance is not clear on how to evaluate a scenario where a subsequent classification is made within 15 minutes of the conditions being available, the licensee reached out to industry subject matter experts. The results were as follows:

- Three individuals concluded: 2 for 2 – the UE declaration was a process error and critiqued, but the Alert declaration was timely and accurate, as was the Alert declaration.
- Three individuals concluded: 2 for 3 – the UE declaration was an unexpected and inaccurate declaration based on the available indications at the time. If the Earthquake Force Monitor (EFM) had been looked at it, it would have been noted that it indicated greater than the Alert level threshold, 0.2g, at 1055.
- One individual concluded: 3 for 4 – the UE was accurate based on the information known at the time; the UE notification was not done and therefore, not timely. The Alert classification and notification were both timely and accurate.
- One individual concluded: 3 for 3 successful opportunities. The UE was accurate based on the information available to the SM at the time. The Alert classification was timely and accurate within 15 minutes of the first indication of an earthquake. The notification was timely and accurate because it was within 15 minutes of the first declaration.

**FAQ 13-07**  
**Correctly Scoring Classification Opportunities (DCPP)**

The licensee reviewed current guidance and industry input and graded the Alert classification as a pass. The SM was remediated through the corrective action program for the UE declaration. The results were 2 for 2 (timely and accurate Alert classification and timely Notification within 15 minutes of the Unusual Event declaration).

During Diablo Canyon's Evaluated Exercise week, the NRC reviewed the performance indicator per NRC Inspection Procedure 71151. The inspectors concluded the result was 1 for 2 successful opportunities. This conclusion, different from all 4 industry conclusions, appears to be based on guidance where a subsequent and correct EAL is not recognized within 15 minutes of availability. The reason that the classification is not an opportunity is that the appropriate classification level was not attained in a timely manner. However, in the scenario at DCPP, the correct EAL was recognized within 15 minutes.

This condition and others, such as when a scenario is designed where a developer may ramp a process value through a lower emergency classification trigger point (T=0) to a final higher value classification, the lower emergency classification is declared and then modified to the higher classification all within 15 minutes, prompt the need for consistent guidance on how these conditions are scored to ensure the extent of all possible conditions is considered once in this FAQ.

**What is the NRC resident inspector's position?**

The NRC's EP inspector believed the Alert classification is not counted in the PI and graded the scenario as 1 for 2 (inaccurate UE declaration, timely and accurate notification)

**Potentially relevant existing FAQ numbers**

None

Response Section

**Proposed Resolution of FAQ:**

Count as a successful opportunity the subsequent classification recognized and declared accurately within 15 minutes of the original initiating condition and/or when conditions became available to operators. Critique and enter the inadvertent or inaccurate classification in the station's corrective action program. Revise NEI 99-02 as shown below.

**Proposed revision to NEI 99-02, Rev. 6, page 46, added to the existing paragraph beginning on line 43:**

If the accurate and expected classification is recognized within 15 minutes of the original initiating condition or when conditions became available to operators, then the final classification shall be considered a success and shall be the only opportunity considered in the performance indicator. Any unexpected classification shall be entered in the station's corrective action program and is considered a non-opportunity.

**NRC Response**

TBD

**Updated NRC Responses to  
Reactor Oversight Process Frequently Asked Questions – November 20, 2013**

**FAQ 13-03**  
**Quad Cities Animal Intrusion**  
**(Final Response)**

**Plant:** Quad Cities

**Date of Event:** June 5, 2013

**Submittal Date:** August 16, 2013

**Licensee Contact:** Jason Smith

**Tel/email:** jason.smith@exeloncorp.com

**NRC Contact:** Brian Cushman

**Tel/email:** brian.cushman@nrc.gov

**Performance Indicator:** Unplanned Power Changes per 7,000 Critical Hours (1E03)

**Site-Specific FAQ (Appendix D)?** No

**FAQ requested to become effective:** when approved

## Question Section

Question #1 -What is considered reasonable for prevention of animal intrusion? Would turning off the lights in a switchyard without motion sensors and an intact boundary still be considered reasonable to prevent animal intrusion?

Question #2 – When does the anticipated outcome of an event apply for PI reporting? If during the review of an event, new information is discovered that validates plant response during the event, can that new information be applied to consider the plant response anticipated even though operators were challenged by unanticipated plant response at the time?

### **NEI 99-02, Rev. 7 Guidance needing interpretation (include page and line citation):**

Page 15, line 19-28

19 Anticipated power changes greater than 20% in response to expected environmental problems  
20 (such as accumulation of marine debris, biological contaminants, or frazil icing) which are  
21 proceduralized but cannot be predicted greater than 72 hours in advance may not need to be  
22 counted unless they are reactive to the sudden discovery of off-normal conditions. However,  
23 unique environmental conditions which have not been previously experienced and could not  
24 have been anticipated and mitigated by procedure or plant modification, may not count, even if  
25 they are reactive. The licensee is expected to take reasonable steps to prevent intrusion of  
26 marine or other biological growth from causing power reductions. Intrusion events that can be  
27 anticipated as part of a maintenance activity or as part of a predictable cyclic behavior would  
28 normally be counted unless the down power was planned 72 hours in advance.

Page 16, line 39-43

39 For an environmental event to be excluded, any of the following may be applied:

- 40 • If the conditions have been experienced before and they exhibit a pattern of  
41 predictability or periodicity (e.g., seasons, temperatures, weather events, animals, etc.),  
42 the station must have a monitoring procedure in place or make a permanent modification  
43 to prevent recurrence for the event to be considered for exclusion from the indicator. If

### **Event or circumstances requiring guidance interpretation:**

On June 5, 2013 an animal (raccoon) caused a fault on a 13.8 kV bus located in the Quad Cities switchyard near Transformer 82, when the animal contacted one phase and part of the metal structure. The Unit 2 reserve aux transformer (RAT) tripped from service, as expected, and a fast bus transfer occurred to

**FAQ 13-03**  
**Quad Cities Animal Intrusion**  
**(Final Response)**

preclude a load trip due to undervoltage. This fault resulted in the loss of a bus in the switchyard. By procedure, when this bus is lost, operators are directed to reduce Unit 2 to approximately 85% power for transformer loading concerns on the unit auxiliary transformer (UAT). During the downpower, in response to the loss of the transformer, reduced feedwater temperature was observed by the control room operators. In response to the reduced feedwater heating, power was reduced to about 60% in accordance with approved procedures. Operator monitoring and response was consistent with their training and in accordance with approved station procedures.

Licensee management has determined that this event is not reportable because the transient was initiated by an animal intrusion event and the lower than anticipated final power was not the result of an equipment failure or human performance error.

The NRC resident inspectors consider this event reportable because the licensee began turning off the lights in the switchyard at night. Without lighting, the conditions in the switchyard were no longer reasonable to prevent animal intrusion. Also, by training and annunciator response, the anticipated power reduction for a loss of the Unit RAT would be about 85% power. The loss of feedwater heating, which was unanticipated for this event at the time, was an additional 25% downpower that should be reported as a separate PI occurrence.

**If licensee and NRC resident/region do not agree on the facts and circumstances explain:**

The licensee and the NRC agree on the facts. The NRC and the licensee disagree on the applicability of reporting under the PI.

**The Licensee's Position:**

Reasonable steps were taken to prevent the animal intrusion. The switchyard fence was in good repair and the gates were secured. Operations personnel perform a weekly walkdown of the switchyard and daily rounds in the switchyard on T82. This would identify degraded conditions and any signs of animal intrusion. Also, the switchyard is in a frequently traveled area next to the security checkpoint. A vegetation management program is also in place, which sprays the switchyard to prevent overgrowth. Consistent with the guidance in NEI 99-02 (referenced above) a plant modification was installed after this event. This change added wildlife deterrent devices to both transformers 81 and 82. These devices should prevent recurrence of animal intrusion. Given the level of human activity in the area, material condition of the switchyard, and a history of no animal intrusion issues, the licensee maintains that reasonable steps were taken and in place to prevent animal intrusion.

Of note, the decision to turn off lights in the switchyard was vetted with key stakeholders prior to implementation.

The loss of feedwater heating was due to the voltage transient on the instrument bus, as a direct result of the fault caused by the raccoon. The momentary lowering of voltage caused various feedwater heater solenoid valves to trip, resulting in feedwater heater level control valves unlatching. Operators responded to the transient in accordance with approved procedures.

The loss of feedwater heating could be expected to occur during a fault in the switchyard, depending on where the fault occurs. There have been faults in the past where all heaters have remained latched, and some faults where a partial loss of feedwater heating has occurred. In this event, the fault was sufficient to cause enough of a voltage transient that the feedwater heater latching solenoids dropped out. Operators

**FAQ 13-03**  
**Quad Cities Animal Intrusion**  
**(Final Response)**

are trained on the loss of a Unit RAT and also trained on loss of feedwater heating. The operator responses for these two events are governed by approved procedures. There were no malfunctions of equipment or human performance errors that led to the additional 25% downpower.

**The NRC's Position (Resident Inspector's Comments):**

The NRC concurs that the switchyard fence was in good repair and there was no food or other materials in the switchyard. Licensee management made a decision to turn the lights in the switchyard off except for times of maintenance. There are no motion detectors in the switchyard. Lights have been on in the switchyard during the night for the purpose of theft deterrent. Licensee management did not assess if the lights in the switchyard also provided a deterrent to the local wildlife. Licensee management made this change to the switchyard lighting during the weekend of June 1, 2013, and on June 5, 2013, an animal causes a switchyard fault.

The NRC agrees that no equipment failed and no human performance errors occurred during this event that contributed to the extra 25% downpower. Indications were received by the control room operators for a loss of a Unit RAT. The additional loss of feedwater heating was unexpected and not anticipated to occur coincident with the loss of a Unit RAT. This fault occurred on the bus that feeds the transformer which resulted in the unlatching of several feedwater level control valves. This new information will be incorporated into operator response procedures and training materials.

It is the position of the NRC that prior to this event, the anticipated final plant condition for a loss of the Unit RAT is 85% power. For future events, with the inclusion of the possibility of partial loss of feedwater heating incorporated, the expected final power level may be lower. But for the purposes of reporting under this PI, the additional 25% power reduction should be reported as an unplanned power change.

**Potentially relevant existing FAQ numbers:**

ID 237- The response details taking actions outside of pre-planned activities.

## **Response Section**

**Proposed Resolution of FAQ**

Proposed answer #1 – An intact switchyard fence in a frequently traveled area can be viewed as a reasonable barrier for the prevention of animal intrusion, with or without switchyard lighting being illuminated. Vegetation management practices were in place to ensure there was not an adequate habitat for raccoons or their food source to exist.

Proposed answer #2 – Since the reduction in power was solely due to an animal intrusion event, this event should not be reported, regardless of when the validation of plant response is determined. The plant operated as expected during the transient and the operators responding to the event took appropriate actions in accordance with approved procedures.

## **NRC Final Response**

The staff reviewed IEEE Standard 1264-1993 (R2009), "IEEE Guide for Animal Deterrents for Electrical Power Supply Substations" to identify reasonable methods to prevent animal intrusion. The main methods identified in the standard are physical barriers, increased insulation, and other deterrents (fake predatory animals, disturbing noises, chemical repellents, and screening). The staff agrees that

**FAQ 13-03**  
**Quad Cities Animal Intrusion**  
**(Final Response)**

an intact switchyard fence in a frequently traveled area can be viewed as a reasonable barrier for the prevention of animal intrusion, with or without lighting.

Since the event has not been experienced previously at Quad Cities and the intrusion event could not have been anticipated 72 hours in advance, the following exclusion in NEI 99-02 is applicable:

**NEI 99-02, Revision 7 (Page 15, Lines 19-25)**

Anticipated power changes greater than 20% in response to expected environmental problems (such as accumulation of marine debris, biological contaminants, or frazil icing) which are proceduralized but cannot be predicted greater than 72 hours in advance may not need to be counted unless they are reactive to the sudden discovery of off-normal conditions. However, unique environmental conditions which have not been previously experienced and could not have been anticipated and mitigated by procedure or plant modification, may not count, even if they are reactive.

The staff agrees that this event should not be counted against the PI. The licensee is expected to take adequate corrective action to prevent similar intrusion events in the future.

This FAQ is effective immediately.

**FAQ 13-04**  
**Point Beach Alert & Notification System**

**Plant:** Point Beach 1 and Point Beach 2

**Date of Event:** May 15, 2013

**Submittal Date:** August 14, 2013

**Licensee Contact:** Gerard D. Strharsky

**Tel/email:** 920-755-6557

**NRC Contact:** James Beavers

**Tel/email:** 630-829-9760

**Performance Indicator:** Alert and Notification System Reliability (EP03)

**Site-Specific FAQ (Appendix D)?** Yes, Appendix D page D-1

**32 Kewaunee and Point Beach**

33

34 Issue: The Kewaunee and Point Beach sites have overlapping Emergency Planning Zones (EPZ).  
35 We report siren data to the Federal Emergency Management Agency (FEMA) grouped by criterion  
36 other than entire EPZs (such as along county lines). May we report siren data for the PIs in the  
37 same fashion to eliminate confusion and prevent 'double reporting' of sirens that exist in both  
38 EPZs? Kewaunee and Point Beach share a portion of EPZs and responsibility for the sirens has  
39 been divided along the county line that runs between the two sites. FEMA has accepted this, and  
40 so far the NRC has accepted this informally.

41

42 Resolution: The purpose of the Alert and Notification System Reliability PI is to indicate the  
43 licensee's ability to maintain risk-significant EP equipment. In this unique case, each neighboring  
44 plant maintains sirens in a different county. Although the EPZ is shared, the plants do not share  
45 the same site. In this case, it is appropriate for the licensees to report the sirens they are  
46 responsible for. The NRC Web site display of information for each site will contain a footnote  
47 recognizing this shared EPZ responsibility.

**FAQ requested to become effective when approved.**

**Question Section:**

**NEI 99-02 Guidance needing interpretation (include page and line citation):**

Page D-1 Lines 45 and 46. "In this case, it is appropriate for the licensees to report the sirens they are responsible for."

**Event or circumstances requiring guidance interpretation:**

Point Beach Nuclear Plant (PBNP) personnel have been notified that as a result of the Kewaunee Power Station (KPS) decommissioning actions, KPS will no longer be monitored under the NRC Reactor Oversight Process (ROP). On May 15, 2013 the NRC docketed KPS's certification of permanent defueling. Pursuant to 10 CFR 50.82(a)(1)(ii), the 10 CFR Part 50 license for KPS no longer authorizes operation of the reactor or emplacement or retention of fuel into the reactor vessel, as specified in 10 CFR 50.82(a)(2). All data collection for CDE and INPO shall be counted from the beginning of May until May 15, 2013 @ 1358.

This situation results in a condition where neither KPS nor PBNP are reporting NEI 99-02 ANS PI data for the eight overlapping sirens located in Kewaunee County. The sirens are still the responsibility of and are being maintained by KPS as required by 10CFR50.47 and 10CFR 50 Appendix E. Because KPS retains

**FAQ 13-04**  
**Point Beach Alert & Notification System**

responsibility for the sirens, PBNP is not reporting PI data as outlined in current NEI 99-02 guidance. This condition will exist until PBNP installs new or assumes responsibility for the existing overlapping sirens. PBNP understands that it is the licensee's responsibility to ensure ANS sirens remain available and are not impacted by the KPS decommissioning process. PBNP also understands that KPS will be submitting an exemption that would no longer require a Public Alert and Notification System (ANS siren equipment) when they transition to a fully decommissioned, this is expected to occur one year to seventeen months from the May 15, 2013 permanent defueled date.

PBNP has historically, and will continue to, obtain ANS siren performance and maintenance records and data from KPS for the purpose of monitoring and recording all required information related to overlapping siren performance.

**If licensee and NRC resident/region do not agree on the facts and circumstances explain**

The content of this FAQ has been reviewed with NRC Region III Emergency Preparedness Inspector Mr. James Beavers. Mr. Beavers indicated that he concurs with the facts and circumstances as provided.

**Potentially relevant existing FAQ numbers**

None

## **Response Section**

**Proposed Resolution of FAQ**

Until such time as KPS is no longer responsible for the 8 ANS sirens that are co-located in Kewaunee County and are within the PBNP EPZ, PBNP will document siren performance for these 8 sirens in the comments section of the Point Beach Unit 1 and Unit 2 Emergency Preparedness performance indicator (Total sirens-tests), in the INPO Consolidated Data Entry data base. When PBNP becomes responsible for the maintenance and testing of sirens located in Kewaunee County, revise NEI 99-02 Rev. 6 Appendix D to remove the "Kewaunee and Point Beach" plant specific design issue from the document. PBNP will subsequently commence reporting of siren performance for all sirens within the PBNP EPZ as required by the ROP and NEI 99-02.

**If appropriate, provide proposed rewording of guidance for inclusion in next revision.**

No wording change is required.

**NRC Response [Received December 2, 2013]**

NSIR/DPR Head Quarters does not support the proposed revision to the counting of the common KPS and PBNP ANS sirens. 10 CFR 50.47(b)(5) states the following:

Procedures have been established for notification, by the licensee, of State and local response organizations and for notification of emergency personnel by all organizations; the content of initial and followup messages to response organizations and the public has been established; **and means to provide early notification and clear instruction to the populace within the plume exposure pathway Emergency Planning Zone have been established.** [Emphasis added]

NUREG-0654 II.E.6 states:

Each organization shall establish administrative and physical means, and the time required for notifying and providing prompt instructions to the public within the plume exposure pathway

**FAQ 13-04**  
**Point Beach Alert & Notification System**

Emergency Planning Zone. (See Appendix 3.) **It shall be the licensee's responsibility to demonstrate that such means exist, regardless of who implements this requirement.** It shall be the responsibility of the State and local governments to activate such a system. [Emphasis added]

This means the licensee is responsible for the ANS availability regardless who maintains it, or owns it. Not requiring PBNP to include the availability of the common sirens in their quarterly ANS PI data would leave them essentially unaccounted for, hence PBNP may not be meeting the intent of 10 CFR 50.47 (b)(5).

**NRC Proposed Resolution of FAQ**

PBNP is responsible for the ANS availability regardless of who maintains or owns it, hence PBNP should add the additional 8 sirens to the denominator of their ANS PI data evaluation and each sirens availability status to the numerator.

**FAQ 13-07 (Proposed)  
Correctly Scoring Classification Opportunities (DCPP)**

**Plant:** DCP

**Date of Event:**

**Submittal Date:** April 23, 2013

**Contact:** Brian Ashbrook

**Tel/email:** 805.545.6279 bka4@pge.com

**NRC Contact:**

**Tel/email:**

**Performance Indicator:** EP01, Drill/Exercise Performance

**Site-Specific FAQ (Appendix D)?** No

**FAQ requested to become effective:** when approved

### Question Section

**NEI 99-02 Guidance needing interpretation (include page and line citation):**

Page 44, Lines 19 & 20:

“Timely means:

- classifications are made consistent with the goal of 15 minutes once available parameters reach an Emergency Action Level (EAL)...”

**Event or circumstances requiring guidance interpretation:**

In a license operator requalification simulator session with a simulated earthquake at T=0, the shift manager (SM) emergency coordinator declared to the operations shift at T=7 minutes an Unusual Event (UE). After declaring the event, the SM requested additional information from the operations shift and after additional information was presented to the SM, the SM changed the classification level to the correct classification level, Alert, at T=10 minutes.

The scenario expectation was that only an Alert would be declared, although both the UE EAL threshold and Alert thresholds were exceeded. Because guidance is not clear on how to evaluate a scenario where a subsequent classification is made within 15 minutes of the conditions being available, the licensee reached out to industry subject matter experts. The results were as follows:

- Three individuals concluded: 2 for 2 – the UE declaration was a process error and critiqued, but the Alert declaration was timely and accurate, as was the Alert declaration.
- Three individuals concluded: 2 for 3 – the UE declaration was an unexpected and inaccurate declaration based on the available indications at the time. If the Earthquake Force Monitor (EFM) had been looked at it, it would have been noted that it indicated greater than the Alert level threshold, 0.2g, at 1055.
- One individual concluded: 3 for 4 – the UE was accurate based on the information known at the time; the UE notification was not done and therefore, not timely. The Alert classification and notification were both timely and accurate.
- One individual concluded: 3 for 3 successful opportunities. The UE was accurate based on the information available to the SM at the time. The Alert classification was timely and accurate within 15 minutes of the first indication of an earthquake. The notification was timely and accurate because it was within 15 minutes of the first declaration.

**FAQ 13-07 (Proposed)**  
**Correctly Scoring Classification Opportunities (DCPP)**

The licensee reviewed current guidance and industry input and graded the Alert classification as a pass. The SM was remediated through the corrective action program for the UE declaration. The results were 2 for 2 (timely and accurate Alert classification and timely Notification within 15 minutes of the Unusual Event declaration).

During Diablo Canyon's Evaluated Exercise week, the NRC reviewed the performance indicator per NRC Inspection Procedure 71151. The inspectors concluded the result was 1 for 2 successful opportunities. This conclusion, different from all 4 industry conclusions, appears to be based on guidance where a subsequent and correct EAL is not recognized within 15 minutes of availability. The reason that the classification is not an opportunity is that the appropriate classification level was not attained in a timely manner. However, in the scenario at DCPP, the correct EAL was recognized within 15 minutes.

This condition and others, such as when a scenario is designed where a developer may ramp a process value through a lower emergency classification trigger point (T=0) to a final higher value classification, the lower emergency classification is declared and then modified to the higher classification all within 15 minutes, prompt the need for consistent guidance on how these conditions are scored to ensure the extent of all possible conditions is considered once in this FAQ.

**What is the NRC resident inspector's position?**

The NRC's EP inspector believed the Alert classification is not counted in the PI and graded the scenario as 1 for 2 (inaccurate UE declaration, timely and accurate notification)

**Potentially relevant existing FAQ numbers**

None

Response Section

**Proposed Resolution of FAQ:**

Count as a successful opportunity the subsequent classification recognized and declared accurately within 15 minutes of the original initiating condition and/or when conditions became available to operators. Critique and enter the inadvertent or inaccurate classification in the station's corrective action program. Revise NEI 99-02 as shown below.

**Proposed revision to NEI 99-02, Rev. 6, page 46, added to the existing paragraph beginning on line 43**

*[In NEI 99-02, Rev. 7, "clean version", see page 48, lines 31-35]:*

If the accurate and expected classification is recognized within 15 minutes of the original initiating condition or when conditions became available to operators, then the final classification shall be considered a success and shall be the only opportunity considered in the performance indicator. Any unexpected classification shall be entered in the station's corrective action program and is considered a non-opportunity.

**NRC Response [Rec'd Dec. 2, 2013]**

The DEP PI statistic is intended to be a test of the licensee's decision maker's ability to make an accurate and timely declaration of an emergency event occurring on site. For this to happen the PI affords 15

**FAQ 13-07 (Proposed)**  
**Correctly Scoring Classification Opportunities (DCPP)**

minutes from the time the information is available to the decision maker, to the point the declaration decision needs to be completed. 10 CFR 50 Appendix E.IV.C.2 states:

By June 20, 2012, *nuclear power reactor licensees shall establish and maintain the capability to assess, classify, and declare an emergency condition within 15 minutes after the availability of indications to plant operators that an emergency action level has been exceeded and shall promptly declare the emergency condition as soon as possible following identification of the appropriate emergency classification level. Licensees shall not construe these criteria as a grace period to attempt to restore plant conditions to avoid declaring an emergency action due to an emergency action level that has been exceeded.* Licensees shall not construe these criteria as preventing implementation of response actions deemed by the licensee to be necessary to protect public health and safety provided that any delay in declaration does not deny the State and local authorities the opportunity to implement measures necessary to protect the public health and safety.

It is the expectation of the NRC staff that once the licensee decision maker announces the declaration, the decision has been made and should be evaluated base on its accuracy and timeliness.

**NRC Proposed Resolution of FAQ**

The DEP opportunity would be counted as a failure because the declaration was announced incorrectly as a NOUE. The EAL announcement ends the declaration portion of the DEP test.

**Proposed revision to NEI 99-02, Rev. 6, page 46, added to the existing paragraph beginning on line 43 [In NEI 99-02, Rev. 7, "clean version", see page 48, lines 31-35]:**

A DEP declaration opportunity is considered complete, for both accuracy and timeliness, when the licensee decision maker announces the declaration. Once the declaration is announced it may not be changed for the purpose of determining the DEP PI opportunity success or failure.