JRC FORM 366 **U.S. NUCLEAR REGULATORY COMMISSION** (7.77) LICENSEE EVENT REPORT •\_\_\_\_\_ CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 2 0 0 - 0 0 0 0 - 0 0 <u>3</u> 4 <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>4</u> <u>57</u> LICENSE NUMBER <u>25</u> <u>26</u> <u>LICENSE TYPE</u> <u>30</u> <u>57</u> CON'T 
REPORT
L
6
0
5
0
0
2
6
1
7
0
4
2
6
7
9
8
0
8
1
5
7
9
9
8
0
8
1
5
7
9
9
8
0
8
1
5
7
9
9
9
8
0
8
1
5
7
9
9
8
0
8
1
5
7
9
9
8
0
8
1
5
7
9
9
8
0
8
1
5
7
9
9
9
75
REPORT DATE
80
9

50
60
60
60
EVENT DATE
74
75
REPORT DATE
80
9
9
9
80
9
9
9
80
9
9
9
80
9
9
9
9 0 1 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During shutdown for the 1979 refueling outage, small pin hole leaks were discovered 0 2 on four canopy seal welds (1 lower and 3 middle canopy seal welds). Similar leaks 0 3 were discovered and repaired during the 1976 and 1978 refueling outages. (Ref. 04 HBR2-RO-76-20 and HBR2-RO-78-04) Due to the minute leakage occurring from the 0 5 defects, no adverse consequences resulted from the occurrence. 0 6 0 7 0 8 SYSTEM CAUSE COMP VALVE SUBCODE CAUSE CODE SUBCODE COMPONENT CODE SUBCODE CODE | C | (13) R D R V ΙE Z [(15) E (12)  $C \mid 1 \mid$ CI (14) ZI (11) (16) 12 13 18 OCCURRENCE REVISION REPORT SEQUENTIAL EVENT YEAR CODE TYPE REPORT NO. NO. LER/RO 19 0 | 1 X 1 REPORT 0 1 1 NUMBER 28 ACTION FUTURE TAKEN ACTION EFFECT ON PLANT SHUTDOWN METHOD ATTACHMENT SUBMITTED NPRD-4 PRIME COMP. COMPONENT HOURS (22 FORM SUB. MANUFACTURER SUPPLIER Y 23 B (18) X IZ 0 0 00 Ζ (21) (25) (26) 36 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Pin hole leaks found at locations K6, L5, M6, & N7 are believed to possibly be the 10 result of weld degradation taking place in areas where a minimum amount of filler metal 1 1 might have been deposited during the original welding process. The defects were 1 2 repaired and non-destructive examination of all repair welds performed. In addition, 1.3 the repair welds were pressure tested. 1 4 80 9 METHOD OF DISCOVERY FACILITY OTHER STATUS DISCOVERY DESCRIPTION (32) % POWER H (28) Outage inspection B (31) 0 0 0 NA 80 ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) RELEASED\_OF RELEASE Z 33 Z 34 NA NA 45 80 10 11 PERSONNEL EXPOSURES 44 DESCRIPTION (39) NUMBER TYPE 0 0 0 37 Z 38 NA 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 NA 8 (40 80 11 12 LOSS OF OR DAMAGE TO FACILITY (43) 7908210 422 TYPE DESCRIPTION (42) NA Ζ 9 10 PUBLICITY NRC USE ONLY DESCRIPTION (45) ISSUED 917-92 Z (44) NA 0 68 80 69 8 10 GРО 919-383-4524 rmd R. B. Starkey, Jr. NAME OF PREPARER ... PHONE .

SUPPLEMENTARY INFORMATION FOR REPORTABLE OCCURRENCE 79-11

## I. Cause Description & Analysis:

On April 26, 1979, while inspecting the reactor vessel head, small pinhole leaks were found on four canopy seal welds. The canopy seal welds are tertiary reactor coolant pressure boundaries. The degradation of a reactor coolant pressure boundary constitutes a reportable occurrence in accordance with Technical Specification Paragraph 6.9.2.a.3. The locations of the weld defects are as follows:

- 1. Lower canopy seal at location K6
- 2. Middle canopy seal at location L5
- 3. Middle canopy seal at location M6
- 4. Middle canopy seal at location N7

The defects are apparently the result of weld degradation since leaks have not been found at any other location on the vessel head stub assemblies.

The failures are located in the filler material and heat affected zones of the seal welds. It is believed that the configuration of the consummable inserts used in the original Robinson canopy seal welds might have resulted in a minimum amount of filler metal being deposited in some locations. The defects could also be related to interpass temperature control or gas purge problems that might have been encountered. Furthermore, the failures may be related to a thermal cycling which these welds might undergo during reactor heat up and cool down.

All failures which have occurred to date are local to the canopy seal welds and in no way indicate a concern with the load bearing machined and threaded region of the mechanism.

The machined and threaded surfaces of each vessel head stub assembly provide primary and secondary pressure boundaries, respectively, for the reactor coolant. The threaded portions of the seal are forged or cast. The threaded region consists of ACME threads which are chrome plated and conservatively designed. The seal welds contain only the minute leakage that might occur past the machined and threaded joint. Therefore, the pinhole leaks do not result in any adverse effects to plant operation or to the public health and safety.

## II. Corrective Action:

The weld defects were repaired April 27 through May 2, 1979. All welds passed liquid penetrant examinations; however, during plant pressurization • (at approximately 400 psig) leaks were found within the repairs of the mechanisms at locations K6 and L5. Upon investigation it was discovered that a small area in the K6 repair weld had apparently undergone excessive grinding and then ruptured upon pressurization. The repair weld leak on

## REPORTABLE OCCURRENCE 79-11 (Continued)

L5 was located at the end of the repair weld where total fusion of the filler and base metals had not been achieved.

These failures were subsequently repaired May 26 through May 30, 1979. Both repair welds passed liquid penetrant examination; however, upon pressure testing (at approximately 2335 psig) K6 failed again. This second repair failure consisted of two linear indications on either side of the repair weld. This was viewed as unique since linear indications had not been previously observed. It was these unique indications that lead to the belief regarding the consumable insert as discussed above. This failure was again repaired June 12 through June 20, 1979. However, several procedure changes were incorporated which are believed to ensure the repair weld integrity.

The indications were ground and holes drilled at each end of the indications so as to inhibit any further growth of the defect. In addition, the canopy was flushed with hot water for an extended length of time prior to the Argon purge so as to remove any boric acid which might have been deposited in the canopy. Following the weld repair, several beads were overlaid  $180^{\circ}$  around the canopy seal so as to add an extra quantity of weld metal at the defect and  $90^{\circ}$  to each side of it. The weld was liquid penetrant tested following each step in the weld repair. The weld repair passed the subsequent pressure testing.

## III. Corrective Action to Prevent Further Occurrence:

NSSS supplier is continuing its investigation of this type failure in an effort to identify the precise failure mechanism. Further corrective action will be contingent upon the results of this investigation.