

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: West Branch Regional Medical Center 2463 South M-30 West Branch, MI 48661 REPORT NUMBER(S) 03017321/2014001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-17321	4. LICENSE NUMBER(S) 21-18892-01	5. DATE(S) OF INSPECTION 06/13/2014
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED 87131	7. INSPECTION FOCUS AREAS 03.01 - 03.09
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 2120	2. PRIORITY 3	3. LICENSEE CONTACT Mathew Maack, M.D., RSO	4. TELEPHONE NUMBER (989) 345-3660
--------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: 06/13/2017

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine inspection of a small community hospital authorized for radioactive materials under 10 CFR 35.100, 35.200, and 35.300. The licensee was authorized to perform activities at two locations, the main hospital (2463 S. M-30) and the cancer center (2431 S. M-30). The licensee employed 2 full time technologists who performed approximately 160 diagnostic studies per month; primarily cardiac stress tests, bone, renal, gastric emptying, and lung scans. The licensee received unit doses from a local nuclear pharmacy and 60 millicuries of bulk technetium-99m daily. The licensee also performed 2-4 thyroid uptake or ablations per year using I-131 at the main hospital. The licensee utilized a consultant health physics service who performed quarterly audits of the radiation safety program.

OBSERVATIONS AND FINDINGS

Licensed material was observed adequately secured within the hot lab during the inspection and was not readily accessible to members of the general public. Interviews conducted with the technologists revealed an adequate level of understanding of radiation safety practices and emergency procedures. The inspector reviewed dose calibrator daily checks, quarterly linearity and annual accuracy checks, package receipt surveys, daily and weekly surveys, waste handling and disposal records, and radiation safety committee meeting minutes. Licensee staff demonstrated daily dose calibrator checks, well counter, and daily and weekly surveys. The inspector observed several cardiac stress test injections of Tc-99m, and a package receipt survey. The licensee exchanged badges on a quarterly basis and used a NVLAP approved vendor. Records reviewed indicated that the maximum exposures were 58 millirem (mrem) deep-dose equivalent (DDE) and 160 mrem shallow-dose equivalent (SDE) for 2014 through March 25; and 472 mrem DDE and 1310 mrem SDE for 2013. Independent measurements taken in the hot lab, imaging and unrestricted areas were comparable to the licensee's survey data.

The inspector verified that corrective actions to a violation involving the failure to conduct semi-annual inventory of sealed brachytherapy sources were being implemented. In addition, on December 18, 213, the licensee disposed of all I-125 brachytherapy seeds in its possession and amended its license to remove authorization for 35.400 activities

No violations of regulatory requirements were identified.