

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company
H. B. Robinson Unit 2

Docket No.: 50-261
License No.: DPR-23

During the NRC inspection conducted on December 26, 1993, - January 22, 1994, violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure For NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violations is are listed below:

- A. Technical Specification 6.5.1.1, Procedures, Tests, and Experiments requires, in part, that written procedures be established, implemented, and maintained covering the activities recommended in Appendix A of Regulatory Guide 1.33, Rev 2., 1978, including general procedures for the control of maintenance activities.

Maintenance Management Manual Procedure, MMM-001, Maintenance Administration Program, requires the use of adequate debris intrusion control measures be employed during the performance of maintenance activities.

Contrary to the above, inadequate debris intrusion control measures were employed on November 15, 1993, during paint stripping efforts in the A Emergency Diesel Generator room. As a result, steel shot, which was being used to strip paint, was introduced into the Emergency Diesel Generator as well as its associated generator control and current transformer cubicles.

This is a severity Level IV violation (Supplement I).

- B. 10 CFR 19.11 (a)(4)(e) requires, in part, that the response to a violation involving radiological working conditions be posted within 2 days of it's dispatch to the NRC.

Contrary to the above, on January 5, 1994, the inspectors detected that the licensee's response to violations 50-261/93-26-01 and 93-26-03 which involved radiological working conditions had been dispatched on December 29, 1993, but had not been posted as required.

This is a Severity Level V violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, Carolina Power and Light Company is hereby required to submit a written statement or explanation to the U. S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the

Carolina Power and Light Company
H. B. Robinson Unit 2

2

Docket No.: 50-261
License No.: DPR-23

corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Atlanta, Georgia
this 18th day of February 1994