

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8805270014 DOC. DATE: 88/05/20 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
 AUTH. NAME AUTHOR AFFILIATION
 LOFLIN, L. I. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards corrected Figure 15.6.2-10 from Westinghouse rept
 discussing LOCA analysis in support of 880507 requested
 amend to License DRR-23.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 LA	1 0	PD2-1 PD	5 5
	LO, R	1 1		
INTERNAL:	ARM/DAF/LFMB	1 0	NRR/DEST/ADS 7E	1 1
	NRR/DEST/CEB 8H	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/RSB 8E	1 1
	NRR/DOEA/TSB 11	1 1	NRR/PMAS/ILRB12	1 1
	NUDDCS-ABSTRACT	1 1	OGC 15-B-18	1 0
	<u>REG FILE</u> 01	1 1	RES/DE/EIB	1 1
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		



Carolina Power & Light Company

SERIAL: NLS-88-129

MAY 20 1988

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
SUBMITTAL OF CORRECTED INFORMATION

Gentlemen:

Carolina Power & Light Company's (CP&L) license amendment request dated May 7, 1988 transmitted a supporting report by Westinghouse Electric Corporation discussing the small break loss-of-coolant accident analysis (CPL-88-538, dated May 5, 1988). The continuing review by CP&L led to discussions with Westinghouse regarding the correctness of the Figure 15.6.2-10 included therein. It was discovered that due to an administrative error, the wrong plot was included in the report. The correct Figure 15.6.2-10 for the 1.5-inch break is attached. Please note that this is an administrative error only and does not impact the calculations or the results of the analysis. The other figures and information transmitted in the referenced report were checked, and we have found no other errors.

Questions regarding this matter may be referred to Mr. R. W. Prunty at (919) 836-7318.

Yours very truly,

for L. I. Loflin
Manager
Nuclear Licensing Section


JSK/crs (037CRS)

Attachment

cc: Dr. J. Nelson Grace
Mr. R. Lo
Mr. L. Garner (NRC - HBR)

8805270014 880520
PDR ADDCK 05000261
P PDR

A001
1/1



H. B. ROBINSON UNIT 2
CORE HEAT TRANSFER COEFFICIENT
1.5-INCH COLD LEG BREAK - 100% POWER

FIGURE 15.6.2-10