NRC FORM 195				MMISSION DOCKET NUMBER 50-26/	
NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL				FILE NUMBER INCIDENT REPORT	
TO: Mr N C Moseley	FROM: Carolina Pwr & Light Co Raleigh, NC		CO DATE OF DOCUMENT 2-23-77		
			Banks	DATE RECEIVED 2-28-77	
LETTER NOTORIZED		PROP	INPUT FORM	NUMBER OF COPIES RECEIVED	
☐ ORIGINAL MUNCLASSIFIED MCOPY				lcc	
DESCRIPTION		ENCLOSURE			
Ltr trans the following:		concerning brip	Report (RO# 77-1) on 1-24-77 ping of "B" Boric Acid Transfer h pump motor temperature cut-out .(40 cys encl rec'd)		
PLANT NAME:			V. Charles Controlling		
H B Robinso	on #1		DONO: EMM212-		
·			NOTE: IF PERSONNEL EXPOSURE IS INVOLVED		
			SEND DIRECTLY TO KREGER/J. COLLINS		
				•	
		, FOR ACTION	INFORMATION 3-2	-77 ehf	
BRANCH CHIEF:	Reic				
W/3 CYS FOR ACTION	7	·	<u> </u>		
LIC. ASST.: Zwe		etzig			
ACRS 16 CYS HOLDING/SENT AS CAT B 3/2/77					
INTERNAL DISTRIBUTION					
REG FILE		INTERNAL	713TRIBOTION		
NRC PDR	+				
I & E (2)					
MIPC					
SCHROEDER/IPPOLITO					
HOUSTON					
NOVAK/CHECK					
GRIMES CASE			 		
BUTLER					
HANAUER					
TEDESCO/MACCARY					
EISENHUT					
BAER					
SHAO VOLLMER/BUNCH					
KREGER/J. COLLINS	 				
AREGER/5 COLLETO					
EXTERNAL DISTRIBUTION				CONTROL NUMBER	
LPDR: Hartsuille, SC					
TIC:				- 1 n/h 0 n	
NSIC:				2680 ₂₆₁	
			 	a a 4	
			 		



Carolina Power & Light Company

February 23, 1977

FILE: NG-3513 (R)

Mr. Norman C. Moseley, Director U. S. Nuclear Regulatory Commission Region II, Suite 818 230 Peachtree Street, N.W. Atlanta, Georgia 30303

Dear Mr. Moseley:

FEB 28 1977 FR

SERIAL:

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2

DOCKET 50-261

LICENSE NO. DPR-23

LICENSEE EVENT REPORT 77-1

In accordance with Section 6.9.2.b of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Yours very truly,

A James Charles I V Charles I am

H. R. Banks

Manager

Nuclear Generation

WH:kd

Attachment

cc: Messrs. W. G. McDonald

E. Volgenau

2080



1. Report No.: 50-261/77-1

2a. Report Date: February 17, 1977

2b. Occurrence Date: January 24, 1977

- 3. Facility: H. B. Robinson Unit No. 2, Hartsville, S. C. 29550
- 4. Identification of Occurrence: At 0747 and 0810 hours on January 24, 1977, "B" Boric Acid Transfer Pump tripped on thermal overload and was subsequently taken out of service. This constitutes a Reportable Occurrence with Technical Specifications Paragraph 6.9.2.b.2.
- 5. Conditions Prior to Occurrence: No unusual conditions prevailed prior to the occurrence. The plant was operating at steady state and 100% power. "B" Boric Acid Transfer Pump was re-circulating "B" Boric Acid Tank.
- 6. Description of Occurrence: At 0747 hours on January 24, 1977, "B" Boric Acid Transfer Pump tripped on thermal overload while re-circulating "B" Boric Acid Tank. Heat trace temperature indicated 155°F. The overload was reset and the pump re-started at 0805. A pump discharge pressure of 106# was obtained. At 0810, "B" Boric Acid Transfer Pump again tripped on thermal overload. At 0830, "A" Boric Acid Transfer Pump was aligned to the blender and to re-circulate with the boron injection tank. "B" Boric Acid Pump was taken out of service per OWP CVC-7. Investigation revealed that the "B" pump balance line was plugged with partially solidified boric acid. The balance line was cleaned, and "B" Boric Acid Transfer Pump was re-started at 1252. A discharge pressure of 108# was observed with heat tracing temperature of 180°F. The pump operated satisfactorily and was returned to normal service.
- 7. Designation of Apparent Cause of Occurrence: The apparent cause through investigation was that the "B" Boric Acid Transfer Pump's balance line (re-circulates to cool and lubricate the motor) was plugged with partially solidified boric acid. The loss of cooling flow across the rotor caused the pump to trip on thermal overload. The balance line was cleaned and the pump operated satisfactorily afterwards.
- 8. Analysis of Occurrence: The failure of "B" Boric Acid Transfer Pump was due to equipment malfunction. Corrective action was considered adequate to prevent subsequent failures. There were not any adverse effects to plant operation or to public health and safety.
- 9. <u>Corrective Action</u>: The balance line on the "B" Boric Acid Transfer Pump was cleaned and the pump re-started with satisfactory operation.
- 10. Failure Data: No similar failure had occurred.



Carolina Power & Light Company

February 23, 1977

FILE: NG-3513 (R)

SERIAL: NG-77-200

Mr. Norman C. Moseley, Director U. S. Nuclear Regulatory Commission Region II, Suite 818 230 Peachtree Street, N.W. Atlanta, Georgia 30303

Dear Mr. Moseley:

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET 50-261 LICENSE NO. DPR-23 LICENSEE EVENT REPORT 77-1

In accordance with Section 6.9.2.b of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Yours very truly,

B́anks Manager

Nuclear Generation

WH:kd

Attachment

cc: Messrs. W. G. McDonald

E. Volgenau

CONTROL BLOCK: BE PRINT ALL REQUIRED INFORMATIONS LICENSEE LICENSE **EVENT** NAME LICENSE NUMBER TYPE 3 1 | Η В REPORT TYPE REPORT REPORT DATE CATEGORY DOCKET NUMBER 10 0 | 5 1 0 1 CON'T 0 6 0 I L **EVENT DESCRIPTION** During normal operation "B" Boric Acid Transfer Pump tripped due to high pump motor 0 2 89 Unit was operating at 100% power with "A" Boric Acid Transfer 03 temperature cut-out. 80 89 Pump available. The re-circulating line which cools and lubricates the motor was 04 ัลิจี found plugged with partially solidified boric acid. The line was cleaned, and the 05 80 8 9 No similar occurrence had occurred. (HBR RO 77-1) pump returned to normal service. 0 6 80 PRIME COMPONENT COMPONENT CAUSE COMPONENT CODE SUPPLIER MANUFACTURER VIOLATION CODE CODE N C | 3 | 0 | 0N P \mathbf{E} P U M PXX 8 9 10 CAUSE DESCRIPTION The "B" Boric Acid Transfer Pump's re-circulating line which cools and lubricates the ОΒ 7 8 motor was found plugged with partially solidified boric acid. The line was cleaned 0 9 80 8 9 and the pump returned to normal service after satisfactory operation. 10 80 8 9 METHOD OF **EACH ITY** DISCOVERY DESCRIPTION OTHER STATUS % POWER DISCOVERY STATUS Operator Surveillance Α 0 0 NA Ε 80 45 13 FORM OF CONTENT AMOUNT OF ACTIVITY LOCATION OF RELEASE RELEASE RELEASED NA Z NA 45 80 10 11 PERSONNEL EXPOSURES DESCRIPTION TYPE NUMBER NA 0 0 0 \mathbf{Z} 80 12 PERSONNEL INJURIES DESCRIPTION NUMBER NA 0 0 0 90 12 OFFSITE CONSEQUENCES NA 80 LOSS OR DAMAGE TO FACILITY DESCRIPTION NA 80 10 **PUBLICITY** NΛ 80 ADDITIONAL FACTORS 80 80 (803) 332-1351 NAME: J. B. McGirt PHONE:

GPO 881 - 667

1. Report No.: 50-261/77-1

2a. Report Date: February 17, 1977

2b. Occurrence Date: January 24, 1977

- 3. Facility: H. B. Robinson Unit No. 2, Hartsville, S. C. 29550
- 4. Identification of Occurrence: At 0747 and 0810 hours on January 24, 1977, "B" Boric Acid Transfer Pump tripped on thermal overload and was subsequently taken out of service. This constitutes a Reportable Occurrence with Technical Specifications Paragraph 6.9.2.b.2.
- 5. <u>Conditions Prior to Occurrence</u>: No unusual conditions prevailed prior to the occurrence. The plant was operating at steady state and 100% power. "B" Boric Acid Transfer Pump was re-circulating "B" Boric Acid Tank.
- 6. Description of Occurrence: At 0747 hours on January 24, 1977, "B" Boric Acid Transfer Pump tripped on thermal overload while re-circulating "B" Boric Acid Tank. Heat trace temperature indicated 155°F. The overload was reset and the pump re-started at 0805. A pump discharge pressure of 106# was obtained. At 0810, "B" Boric Acid Transfer Pump again tripped on thermal overload. At 0830, "A" Boric Acid Transfer Pump was aligned to the blender and to re-circulate with the boron injection tank. "B" Boric Acid Pump was taken out of service per OWP CVC-7. Investigation revealed that the "B" pump balance line was plugged with partially solidified boric acid. The balance line was cleaned, and "B" Boric Acid Transfer Pump was re-started at 1252. A discharge pressure of 108# was observed with heat tracing temperature of 180°F. The pump operated satisfactorily and was returned to normal service.
- 7. Designation of Apparent Cause of Occurrence: The apparent cause through investigation was that the "B" Boric Acid Transfer Pump's balance line (re-circulates to cool and lubricate the motor) was plugged with partially solidified boric acid. The loss of cooling flow across the rotor caused the pump to trip on thermal overload. The balance line was cleaned and the pump operated satisfactorily afterwards.
- 8. Analysis of Occurrence: The failure of "B" Boric Acid Transfer Pump was due to equipment malfunction. Corrective action was considered adequate to prevent subsequent failures. There were not any adverse effects to plant operation or to public health and safety.
- 9. <u>Corrective Action</u>: The balance line on the "B" Boric Acid Transfer Pump was cleaned and the pump re-started with satisfactory operation.
- 10. Failure Data: No similar failure had occurred.