

Dresden Nuclear Power Station

6500 North Dresden Road Morris, IL 60450 815 942 2920 Telephone www.exeloncorp.com

10 CFR 50.73

SVPLTR # 14-0050

September 5, 2014

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Dresden Nuclear Power Station, Unit 2

Renewed Facility Operating License No. DPR-19

NRC Docket No. 50-237

Subject:

Licensee Event Report 237/2014-002-01, Unit 2 Reactor Scram due to Main

Power Transformer Failure

Enclosed is Licensee Event Report 237/2014-002-01, Unit 2 Reactor Scram due to Main Power Transformer Failure. This is an interim report which describes an event which is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A), any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B).

There are no regulatory commitments contained in this submittal.

Should you have any questions concerning this letter, please contact Mr. Glen Morrow at (815) 416-2800.

Respectfully,

Shane M. Marik Site Vice President

Dresden Nuclear Power Station

Enclosure Licensee Event Report 237/2014-002-01

cc: Regional Administrator – NRC Region III

NRC Senior Resident Inspector - Dresden Nuclear Power Station

TE22 NKK

APPROVED BY OMB: NO. 3150-0104 NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION EXPIRES: 01/31/2017 (02-2014) Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported tessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections LICENSEE EVENT REPORT (LER) Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and (See Page 2 for required number of Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB digits/characters for each block) control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection. 1. FACILITY NAME 2. DOCKET NUMBER 3. PAGE 05000237 1 OF 3 Dresden Nuclear Power Station, Unit 2 4. TITLE Unit 2 Reactor Scram due to Main Power Transformer Failure 5. EVENT DATE 6. LER NUMBER 7. REPORT DATE 8. OTHER FACILITIES INVOLVED FACILITY NAME DOCKET NUMBER SEQUENTIAL MONTH DAY YEAR YFAR MONTH DAY YEAR NUMBER FACILITY NAME DOCKET NUMBER 2014 -002 04 12 2014 - 01 09 05 14 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply) 9. OPERATING MODE 20.2201(b) 20.2203(a)(3)(i) 50.73(a)(2)(i)(C) 50.73(a)(2)(vii) 20.2201(d) 20.2203(a)(3)(ii) 50.73(a)(2)(ii)(A) 50.73(a)(2)(viii)(A) 1 20.2203(a)(1) 20.2203(a)(4) 50.73(a)(2)(ii)(B) 50.73(a)(2)(viii)(B) 20.2203(a)(2)(i) 50.36(c)(1)(i)(A) 50.73(a)(2)(iii) 50.73(a)(2)(ix)(A) 10. POWER LEVEL 20.2203(a)(2)(ii) 50.36(c)(1)(ii)(A) 50.73(a)(2)(iv)(A) 50.73(a)(2)(x) 20.2203(a)(2)(iii) 50.36(c)(2) 50.73(a)(2)(v)(A) 73.71(a)(4) 20.2203(a)(2)(iv) 50.46(a)(3)(ii) 50.73(a)(2)(v)(B) 73.71(a)(5) 100 20.2203(a)(2)(v) 50.73(a)(2)(i)(A) 50.73(a)(2)(v)(C) OTHER Specify in Abstract below or in NRC Form 366A 20.2203(a)(2)(vi) 50.73(a)(2)(i)(B) 50.73(a)(2)(v)(D) 12. LICENSEE CONTACT FOR THIS LER ICENSEE CONTACT TELEPHONE NUMBER (Include Area Code) Glen Morrow - Regulatory Assurance Manager 815-416-2800 13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT REPORTABLE MANU-REPORTABLE MANIL SYSTEM COMPONENT CAUSE COMPONENT CAUSE SYSTEM FACTURER TO EPIX FACTURER TO EPIX X EL **XFMR** S125 14. SUPPLEMENTAL REPORT EXPECTED 15. EXPECTED MONTH DAY YEAR SUBMISSION YES (If yes, complete 15. EXPECTED SUBMISSION DATE) 01 80 2015 DATE ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) On April 12th, 2014 at 1012 CDT, an automatic reactor protection system actuation due to failure of the main power transformer. All control rods inserted to their full-in position. Following the reactor trip, all systems operated as expected.

This event is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A), any event or condition that resulted in manual or automatic actuation of any of the system listed in paragraph (a)(2)(iv)(B).

NRC FORM 366A (02-2014)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB: NO. 3150-0104

EXPIRES: 01/31/2017

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NFC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
Dresden Nuclear Power Station, Unit 2	05000237	YEAR	SEQUENTIAL NUMBER	REV NO.	2	OF	3
		2014	- 002 -	01			

NARRATIVE

PLANT AND SYSTEM IDENTIFICATION

Dresden Nuclear Power Station (DNPS), Unit 2, is a General Electric Company Boiling Water Reactor with a licensed maximum power level of 2957 megawatts thermal. The Energy Industry Identification System codes used in the text are identified as [XX].

A. Plant Conditions Prior to Event:

Unit: 02

Event Date: 04-12-2014

Mode Name: Power Operation

Event Time: 1012 hours CDT Power Level: 100 percent

B. Description of Event:

Reactor Mode: 1

On April 12th, 2014 at 1012 CDT, an automatic reactor protection system [JC] actuation due to failure of the main power transformer [EL]. All control rods [AA] inserted to their full-in position. Following the reactor trip, all systems operated as expected.

This event is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A), any event or condition that resulted in manual or automatic actuation of any of the system listed in paragraph (a)(2)(iv)(B).

C. Cause of Event:

The cause of this event is under investigation and will be reported in a supplemental notification.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION (02-2014) LICENSEE EVENT REPORT (LER) CONTINUATION SHEET								
1. FACILITY NAME	2. DOCKET	6. LER NUMBER				3. PAGE		
Dreader Nuclear Dever Chatian Unit O	05000037	YEAR	SEQUENTIAL NUMBER	REV NO.	•	OF	0	
Dresden Nuclear Power Station, Unit 2	05000237	2014	- 002 -	01	3	OF	3	

NARRATIVE

D. <u>Safety Analysis</u>:

Following the actuation, all other systems responded as expected, therefore, this event is of low safety significance.

E. <u>Corrective Actions</u>:

Corrective actions will be developed during the ongoing root cause investigation.

F. <u>Previous Occurrences</u>:

Previous occurrences will be identified through the root cause investigation.

G. <u>Component Failure Data</u>:

Manufacturer	Model	S/N	Туре
Siemens	ELIN	1731658	TDQ-A27D9K-99