

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Oakwood Cardiovascular Associates 22060 Beech Street Dearborn, MI 48124 REPORT NUMBER(S) 2015-001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-35146	4. LICENSE NUMBER(S) 21-32196-01	5. DATE(S) OF INSPECTION February 27, 2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
 (Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ryan Craffey / Luis Nieves		3/10/15
BRANCH CHIEF	Aaron McCraw		3/12/15

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Oakwood Cardiovascular Associates 22060 Beech Street Dearborn, MI 48124 REPORT NUMBER(S) 2015-001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-35146	4. LICENSE NUMBER(S) 21-32196-01	5. DATE(S) OF INSPECTION February 27, 2015
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS All
--	--------------------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Gregory Pitt, BS, CNMT - RSO	4. TELEPHONE NUMBER (734) 365-8030
---------------------------------	----------------------	---	---

Main Office Inspection Next Inspection Date: No change
 Field Office Inspection _____
 Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine inspection of a cardiology group authorized to use byproduct material for diagnostic administrations of radiopharmaceuticals at its facilities in Dearborn and Brownstown, Michigan. The licensee normally conducted studies Mondays through Fridays at its Dearborn location, with the exception of Tuesday afternoons, when the licensee's nuclear medicine technologist (the RSO) conducted studies at the Brownstown location instead.

However, prior to opening for business on February 17, 2015, the licensee's Dearborn facility flooded when a fire water pipe burst between the second and third floors, directly above the nuclear medicine lab on the first floor. The licensee canceled its receipt of unsealed material for the day, and, in consultation with its medical physics consultant, removed all sealed sources of material from the Dearborn facility and transferred them to Brownstown. The licensee anticipated that it would be four to six weeks before it could return to the Dearborn facility to assess the damage to its imaging cameras. In the mean time, the licensee intended to reschedule as many patients as possible for studies at the Brownstown location.

PERFORMANCE OBSERVATIONS

The inspectors toured the licensee's Dearborn facility under supervision of the contract restoration company to evaluate the condition of the facility following the flood. Independent surveys of the nuclear medicine area and of debris removed from the lab found no unsecured sealed sources or readings which would indicate the presence of residual contamination. The inspectors interviewed the RSO by telephone to discuss the licensee's plans for restoration.

No violations of NRC requirements were identified as a result of this inspection. Since no principal activities were observed during this inspection, the due date for the next inspection should remain unchanged.