former Remainder					Attachment #5 page 1 of 8						
form 01077	, (R7-89)		·	•			FORM	101.1	R	EVISION	13
		CEE	RTIFICATIO		NGINEE						
STAT								-	EOWE	E)	
							•				
		0455 a						•			2N)
		CONSISTING OF:				INFOR	WATIO	I ONL	ě.		
PAGE	ES	7			THRO	UGH	Z	<u> </u>			· · · ·
TOTA	AL ATTACI		NE	тс	DTAL MIC	ROFICHE	ATTACH	MENTS	NON	E	
ΤΟΤΑ	AL VOLUN	1ES						10 🗙			
		·	TYPEII		REQUEN		NA				
ESTA	ABLISHED	EERING CALCU PROCEDURES, NHAS BEEN ORI	THE QUAL	ITY HAS E	BEEN AS	SURED AN	ND I CERT	FIFY THAT	RDANCE	WITH OVE	
	GINATED	\frown) and a le	eso:				118/	93_		
	CKED BY		TON CHI	QUIV				<u> 25-93</u>		•	
	ROVED B		-		2	DA	те	28-	- 93		
		ECHNICAL SERV		ON	$\overline{}$	DA	TE				
	· .	TECHNICAL SE	•			DA	TE			<u> </u>	
MICI	ROFICHE	ATTACHMENT L	IST: 🗆 Yes	X No	SEE F	ORM 101	.4				
REV. NO.	CALCULATION PAGES (VOL)		ATTA	CHMENTS (VOL)	VOLU	IMES	ORIG	СНКД	APPR `	ISSUE DATE
		DELETED ADDED	REVISED	DELETED	ADDED	DELETED	ADDED	DATE	DATE	DATE	REC'D DATE
		· · · · · · · · · · · · · · · · · · ·									
		<u> </u>	· .	•·							
	· · · · · · · · · · · · · · · · · · ·										
1		1						1		1	
·											
		ļ						 			
		. ·									
		· · ·								· · ·	
		· · ·									
		951117	· · ·								

(

Attachment # 5 page 2 of 8

Form 101.2 Revision 1 26164 (R9-89)

.

ź

File/Calculation No. 05C - 4995

REVISION DOCUMENTATION SHEET

Revision Number	Review Frequency Changed Yes/No	Revision Description							
· · · · · · · · · · · · · · · · · · ·		· · ·							
	· · ·								
·									
		· · · · · · · · · · · · · · · · · · ·							
·									
	· 	1							
· · · · · · · · · · · · · · · · · · ·	·								
	· · · · · · · · · · · · · · · · · · ·								
	· ·								

Attachment # 5 page 3 of 8

CALCULATION/ANALYSIS INFORMATION SHEET (SHEET 1 OF 2)

CALCULATION (ANALYSIS NO. OSC - 4995 ORIGINATOR: the Jourdam DATE 1/20/93 CHECKER: HHP HHP DATE Chese PIRS add PROBLEM: Q. 0 Α. Su من 100 to circuiting failures 1. QT ∇ Keowel 99 • • • 0 29 0 虹 20 of the manuel Δ موہ QA-1 RELATION TO QA CONDITION: в. DESIGN METHODS: 101 с. $\langle \gamma \rangle$ 0 4 5 por PAGE NO. 1

Attachment # 5 page \$ of 8 CALCULATION/ANALYSIS INFORMATION SHEET (SHEET 2 OF 2) CALCULATION (ANALYSIS NO. 056-4995 ORIGINATOR. Or DATE OI ZO/93 DATE 1-25-93 CHECKER: HJH APPLICABLE CODES AND STANDARDS (NAME, NUMBER, DATE, D. REVISION): N/A OTHER DESIGN CRITERIA: KEOWEE DBD Ε. 055-0254.00-00-2005 RELATED SAR CRITERIA (PSAR OR FSAR, PAGE, AMENDMENT): F. FSAR CHAPTER 8 TECHNICAL SPECIFICATIONS 3.7.1 and 3.7.2 - - - - - - PAGE NO. ATTACHMENT 1 CALCULATIONS: -G. - - - .. - PAGE NO. N/A ASSUMPTIONS: H REFERENCES: - - - - - - - - - - - PAGE NO. ATTACHMENT 1 I. CONCLUSION: - - - - - - - - - - - - - PAGE NO. ATTACH MENT 1 J. PAGE NO. 2.___

1990 - 1997 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999			Attachm	mt #5 page 5 0
	· ·		RING DEPARTMENT EVALUATION	OSC-4995 ATTACHMENT 1 PAGE1064
Station:	Oconee	Unit:1, 2,	<u>& 3</u> PIR Number: <u>0-09</u>	2-455 & 490
Structure, sy	stem, or compon	ent (SSC) in question:	Emergency Power Sy	stem
	<u>dro Unit 2</u>		· · · · · · · · · · · · · · · · · · ·	
Design basi:	s references applik	cable:0SS-0254.0	0-00-2005	
Technical S	pecification section	ns applicable: 3.7	·.1	
The SSC in	question is recom	mended to be:		m
		CONDITIONALLY OPE		This more upit of
FSAR chang	ge required	res X No	10 CFR 50.59 Evaluation	on required Yes X
Summary/Co	omments:			
This evaluin its vo	uation address ltage regulato	er system.		with failed circuitry
relay 90X	1C failed to p	nick up and activa	te the automatic reg	
regulator	for Keowee Un	it 2 from perform	ing its function.	prevented the manual
equipment Keowee un sidered o	manufacturers it regulator a perable.	s concludes that b are required to be	operable for that K	, and discussion with matic) features of the eowee unit to be con-
performin ing the t lator whi regulator Therefore be operab	g the safety f he Keowee unit le the auto re is out could , both the mar le to account	function of the re ts. However, cert egulator is out or have adverse impa nual and automatic for single failur	gulator during a des ain failure modes wi within the auto reg ct on the Oconee Eme features of the reg e consideration.) is fully capable of ign Basis Event requir thin the manual regu- ulator while the manua rgency Power System. Julator are required to
Further d	etails of this	s evaluation are c	locumented in Calcula	tion #OSC-4995.
				·
Originated	by: DADO	Mullion :	Rue Proc Byng Date	:
		(udenwork)	Date	10/13/92
Reviewed	() n			: 10/13/12
Approved I	by: 1	·		•

Attachment # 5 page 6 of 8

OSC-4995 ATTACHMENT 1 PAGE 2 OF 4

EVALUATION

KEOWEE VOLTAGE REGULATOR AND POSTULATED VOLTAGE PROBLEMS

As a result of the failure of relay 90XIC to automatically pick up (and place the KEOWEE #2 GENERATOR voltage regulator in AUTO) an analysis was performed to determine specific failure modes of the KEOWEE voltage regulators and static excitation systems.

BASIC SYSTEM DESCRIPTION

The voltage regulator and excitation system, which is installed on each of the Keowee generators, is the Westinghouse type WTA solid state regulator and TRINISTAT static excitation system.

This type of system precludes the inherent problems associated with exciter generators and rotary amplifiers by utilizing a portion of the generator output (for main field excitation) via an excitation transformer and silicon control rectifiers (thyristers) and by the application of solid state components for the regulator.

The main field rectifiers (trinistat power units) consist of eight individual sections six of which are required to supply full load excitation at rated power factor. Further, the firing (control) system to the trinistat power units are comprised of two separate (redundant) circuits.

The operation of the system is such that a manually operated base adjuster is pre-set to establish an excitation level which corresponds to generator no load voltage. Once actuated the AUTO voltage regulator functions to oppose or aid (BUCK/BOOST) the base value to automatically maintain the generator output voltage at the value selected by the auto voltage regulator.

A "BASE FOLLOWING" feature automatically adjusts the BASE ADJUSTER rheostats when the regulator is in the AUTO MODE such that if the auto regulator is lost (or removed from service) a "bumpless" transition to the manual regulator (BASE ADJUST) occurs.

Also, the ranges of operation are such that the generator output voltage will be automatically maintained (from no load to full load values) if the base adjust output goes to zero during automatic regulator operation. However, for the base adjust output to completely fail, in this manner, both of the redundant firing circuits must go to zero.

Other features of the WTA regulator enhance overall reliability further by providing limiting, compensating and protective functions which act to protect both the Keowee generators and connected devices from the potential damaging effects of postulated regulator/excitation system malfunctions.

These features include:

- 1. Maximum excitation limiter.
- 2. Minimum excitation limiter.
- 3. Volts per Hertz limiter and protection
- 4. Reactive droop compensation.

Attachment # 5 page 8 of 8

OSC-4995 ATTACHMENT 1 PAGE 3 OF 4

5. Reactive line drop compensation.

6. Resistive line drop compensation.

7. Field overcurrent protection.

8. AC overvoltage protection.

9. Loss of potential protection.

POSTULATED PROBLEMS

1. UNDERVOLTAGE

Various regulator malfunctions were considered which could result in Keowee generator output voltage decreasing to unacceptable values during emergency operation.

As noted, in the previous section, the built-in redundance of the field rectifiers (trinistats) and the firing circuits auctioneering feature greatly reduces the likelihood that a single component failure will result in less than acceptable generator output voltage.

Also, there exists adequate undervoltage protection in the Oconee Emergency Power Switching logic systems which is independent of the Keowee voltage regulator/excitation systems.

However, because of the nature of the particular relay failure (90XIC) which resulted in the regulator not shifting into AUTO (on a normal Keowee startup), this scenario was postulated to occur during a Keowee emergency start and subsequent automatic loading.

During this analysis the KEOWEE no load saturation curve (obtained from the generator manufacturer's instruction book) was utilized to determine generator voltage under various design basis loading conditions. These values were then input into the ASDOP program which resulted in verifying adequate voltage under conditions where the Keowee unit was loaded with the base adjuster at the pre-set position and the auto regulator failed to engage.

2. OVERVOLTAGE

Because of the limiters and protective devices provided with the Keowee voltage regulator/excitation system malfunctions which result in high generator output voltage are very unlikely.

However, because the field overcurrent protective feature, which trips the applicable Keowee unit during normal operation, is bypassed during emergency operation this particular scenario was considered.

Postulated malfunctions analyzed were ones that would result in the trinistat firing circuits in the regulator output going high while assuming that the excitation limiters and auto regulator had no effect on limiting the voltage to acceptable values.

No malfunctions were identified that could occur as the result of any one single failure..

Mr. Don Kimmel and Mr. Richard Mummert of the Westinghouse Facility in Asheville, North Carolina were consulted in an attempt to determine resultant voltage levels, under the conditions described, and their knowledge or credibility of such malfunctions actually occurring.

Attachment #5 page 8 of 8

OSC-4995 ATTACHMENT 1 PAGE 4 OF 4

Mr. Don Kimmel (704-687-3320) performed an in-depth analysis utilizing the generator no load saturation curve, field resistances at various temperatures, excitation transformer saturation data and information concerning the potentially damaging overheating effects of prolonged over excitation to the generator field and stator.

Mr. Kimmel's conclusion was that, if the conditions postulated could credibly occur, generator voltage would rise to higher than normal values. He also noted that he considered this to be a hypothetical situation which he had not seen (or been aware of occurring) in his experience with the Westinghouse WTA regulator. Mr. Kimmel's experience with Westinghouse voltage regulator/excitation equipment includes research and development as well as field and manufacturing work.

Mr. Mummert agreed with Mr. Kimmel's assessment and also noted that no one single failure could result in regulator responses as postulated.

CONCLUSIONS

The Westinghouse WTA voltage regulator and trinistat excitation systems are highly reliable with between three and four hundred units in operation dating to the mid 1960's.

Because of the utilization of the KEOWEE generators as system peaking units and as the emergency on-site sources of auxiliary power to the Oconee Nuclear Station certain protective features are defeated (bypassed) during emergency operation of the units.

This is accomplished to increase reliability when the units are called upon as emergency sources to Oconee.