U.S. NUCLEAR REGULATORY COMMISSION (07-2012) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION								
Belle, MI	ed MANNHALTUR Marios Ri 10. 65013	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTION				
030-17987		24-20121-01		7/22/15				
Regulatory Commission	n examination of the activities conduct on (NRC) rules and regulations and th sentative records, interviews with pers	e conditions of your	license. The inspection consist	ed of selective examination	ons of			
1. Based on	the inspection findings, no violations v	vere identified.						
2. Previous v	2. Previous violation(s) closed.							
The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.								
	Non-cited violation(s) were discuss	sed involving the follo	owing requirement(s):					
cited in ac with 10 Cl	s inspection, certain of your activities, cordance with NRC Enforcement Poli FR 19.11. s and Corrective Actions)							
		atement of Corre						
corrective actions is r	ithin 30 days, the actions described by made in accordance with the requirem lance will be achieved). I understand t	ents of 10 CFR 2.20	1 (corrective steps already taker	n, corrective steps which v	will be taken,			
TITLE	PRINTED NAME		SIGNATURE		DATE			
LICENSEE'S REPRESENTATIVE								
NRC INSPECTOR	E.L. Kulzer	8	- Lauha		7/22/15			
BRANCH CHIEF	ARRONT. McCRAN		Di	1	7/30/15			
NRC FORM 591M PART	1 (07-2012)				1			

NRC FORM 591M PART 3			II S NII	CLEAR REGULATORY COMMISSION				
(07-2012) Docket File Information								
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION								
1. LICENSEE/LOCATION INSPECT	ED:		2. NRC/REGIONAL OFFICE					
Kingsford Manufacturing	Company		Region III					
21200 Maries Road 314	y		U. S. Nuclear Regulatory Commission					
Belle, MO 65013			2443 Warrenville Road, Suite 210					
			Lisle, IL 60532-4352					
REPORT NUMBER(S) 15-01								
3. DOCKET NUMBER(S)	3. DOCKET NUMBER(S)		5)	5. DATE(S) OF INSPECTION				
030-17987		24-20121-01	7/22/2015					
6. INSPECTION PROCEDURES USED		7. INSPECTION FOCUS AREAS						
1P 87124		03.01 through 03	3.07	·				
SUPPLEMENTAL INSPECTION INFORMATION								
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTAC	Т	4. TELEPHONE NUMBER				
03121	5	Justin Dent		(573) 859-5514				
✓ Main Office Inspec	Main Office Inspection Next Inspection Date: 7/22/2020							
Field Office Inspection								
Temporary Job Site Inspection								
		PROGRAM S	COPE					
This was a routine inspection of facility that produces charcoal briquettes. The licensee possessed 33 Ronan Model SA-1 gauges. Currently, the RSO was involved with use and oversight of the devices.								
On October 3, 2012, the facility has used Ronan to dispose of the six Kay-Ray Model 7062 and two Ronan gauges at Thermo Fisher Scientific in Texas. Leak testing was completed before these gauges were sent off site for disposal.								
The licensee was not authorized to remove and/or relocate gauges. The licensee does not perform any service or maintenance activities on its gauges; these services were performed by the manufacturer.								
Performance Observations								
The plant facility was toured and observed the gauges in conjunction with the licensee's current inventory. Proper lock-out and leak test procedures were also adequately described. Interviews conducted with plant workers revealed that under no circumstances would a vessel be entered without RSO supervision of lock-out/tag-out procedures. The inspector observed proper signs at each of the gauges. The inspector verified that the gauges are leak tested at three-year frequencies in accordance with manufacturers specifications. The inspector verified that the inventories and shutter checks were performed at required frequencies.								
No violations of NRC requirements were identified during the inspection.								