



Mr. J. W. Hampton Vice President, Oconee Site Duke Power Company P.O. Box 1439 Seneca, SC 29679

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION RELATING TO TENDON SURVEILLANCE REPORT, OCONEE NUCLEAR STATION, UNIT 3 (TAC NO. M93942)

Dear Mr. Hampton:

۴.

On October 11, 1995, you submitted report entitled, "Unit 3 Reactor Building Post-tensioning System Sixth Surveillance." During our review of this report, the NRC staff has determined that additional information is needed. The specific details of the staff's request for this additional information is provided in the enclosure to this letter. Your response to this request for additional information is requested by February 23, 1996.

This requirement affects nine or fewer respondents and, therefore, it is not subject to the Office of Management and Budget review under P.L. 96-511.

If you have questions regarding this matter, contact me at (301) 415-1495.

Sincerely, Original signed by:

Patrick D. Milano, Sr. Project Manager Project Directorate II-2 Division of Reactor Projects-I/II Office of Nuclear Reactor Regulation

Docket No. 50-287

Enclosure: As stated

cc w/encl: See next page

<u>Distribution:</u>

| Docket File | CPTan |
|----------------|-----------------|
| PUBLIC | OGC |
| PD 2-2 Reading | ACRS |
| SVarga | RCrlenjak, RII |
| JZwolinski | EMerschoff, RII |
| LWiens | - |
| LBerry | |
| PMilano | |
| | |

PDR

| - | DOCUMENT NAME: G:\OCONEE\OC93942.RAI To receive a copy of this document, indicate in the box C=Copy w/o attachment/enclosure E=Copy with attachment/enclosure N = No copy | | | | | | | |
|------------------|---|------------------------|----------------------------|------------|------------------------------|--|------|--|
| | | LA:PD2-2 | PM:PD2-2 E PMilano 00 m | : (A)PD:Pl | 2-2 N | | K | |
| | DATE | 1 /1 7/96 | 01//8/96 | | <i>u</i> 1 <i>119</i> 196 | | | |
| 9601 PDR P | 23039 ADOCI | 1 960119 K 05000287 | OFFIC | IAL RECOR | | | CELL | |

AA3



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

January 19, 1996

Mr. J. W. Hampton Vice President, Oconee Site Duke Power Company P.O. Box 1439 Seneca, SC 29679

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION RELATING TO TENDON SURVEILLANCE REPORT, OCONEE NUCLEAR STATION, UNIT 3 (TAC NO. M93942)

Dear Mr. Hampton:

On October 11, 1995, you submitted report entitled, "Unit 3 Reactor Building Post-tensioning System Sixth Surveillance." During our review of this report, the NRC staff has determined that additional information is needed. The specific details of the staff's request for this additional information is provided in the enclosure to this letter. Your response to this request for additional information is requested by February 23, 1996.

This requirement affects nine or fewer respondents and, therefore, it is not subject to the Office of Management and Budget review under P.L. 96-511.

If you have questions regarding this matter, contact me at (301) 415-1495.

Sincerely,

Patrick D. Milano, Sr. Project Manager Project Directorate II-2 Division of Reactor Projects-I/II Office of Nuclear Reactor Regulation

Docket No. 50-287

Enclosure: As stated

cc w/encl: See next page

Mr. J. W. Hampton Duke Power Company

cc:

Mr. Paul R. Newton Duke Power Company, PB05E 422 South Church Street Charlotte, North Carolina 28242-0001

J. Michael McGarry, III, Esquire Winston and Strawn 1400 L Street, NW. Washington, DC 20005

Mr. Robert B. Borsum B&W Nuclear Technologies Suite 525 1700 Rockville Pike Rockville, Maryland 20852-1631

Manager, LIS NUS Corporation 2650 McCormick Drive, 3rd Floor Clearwater, Florida 34619-1035

Senior Resident Inspector U. S. Nuclear Regulatory Commission Route 2, Box 610 Seneca, South Carolina 29678

Regional Administrator, Region II U. S. Nuclear Regulatory Commission 101 Marietta Street, NW. Suite 2900 Atlanta, Georgia 30323

Max Batavia, Chief Bureau of Radiological Health South Carolina Department of Health and Environmental Control 2600 Bull Street Columbia, South Carolina 29201

County Supervisor of Oconee County Walhalla, South Carolina 29621 Oconee Nuclear Station

Mr. Ed Burchfield Compliance Duke Power Company Oconee Nuclear Site P. O. Box 1439 Seneca, South Carolina 29679

Ms. Karen E. Long Assistant Attorney General North Carolina Department of Justice P. O. Box 629 Raleigh, North Carolina 27602

Mr. G. A. Copp Licensing - EC050 Duke Power Company 526 South Church Street Charlotte, North Carolina 28242-0001

Dayne H. Brown, Director Division of Radiation Protection North Carolina Department of Environment, Health and Natural Resources P. O. Box 27687 Raleigh, North Carolina 27611-7687

REQUEST FOR ADDITIONAL INFORMATION

OCONEE NUCLEAR STATION, UNIT 3

TENDON SURVEILLANCE REPORT

In the Summary section of report, "Unit 3 Reactor Building Post-1. tensioning System Sixth Surveillance," it was stated that the mean liftoff force for each surveillance tendon group (hoop, vertical and dome) exceeded required values. In Table 3 the report appears to indicate that. for tendons which were detensioned and retensioned, the "as-left" forces are larger than "as-found" forces. However, Section 3.5 states that "(f)ollowing wire removal the relaxed tendons were retensioned, as closely as possible to the same stress level indicated by the lift-off force data obtained during this surveillance." If the "as-left" forces are larger than the "as-found" forces, the tendon prestress losses are either reduced or eliminated and the lift-off forces in the associated subsequent tendon surveillances will probably not be below the required values. While there is no mention of the required value for each group of tendons, the force-time plots in the report indicate that 7.00 kips per wire is the required values for all tendons. Each tendon in each group has undergone 2 detensionings and retensionings and 4 lift-offs during the 6 surveillances performed to date.

Based on its observations, the NRC staff requests that:

- a. A re-analysis of the lift-off data from all the surveillances be performed that modifies, if applicable, each lift-off force by the difference between "as-found" and "as-left" values obtained from preceding surveillances.
- b. All lift-off force data be plotted on a graph similar to that shown in Figure 2 of Regulatory Guide (RG) 1.35.1 and including the minimum required value (MRV) identified for each group of tendons. The values to be plotted are the individual data obtained without averaging or taking mean values. On the basis of the plotted data, a regression analysis should be performed for each group of tendons to establish the trend of the prestress force.
- c. Indicate how the MRV is determined for each group of tendons.
- d. Provide all the data used in the above regression analysis.
- 2. The analysis of the data indicated above may remedy some of the deficiencies resulting from using pre-selected tendons for surveillance. Although the Technical Specifications requirement for using the pre-selected tendons was approved by the NRC, the staff has found that, by using randomly selected tendons for each surveillance, the lift-off forces obtained are more representative of the actual tendon force. In view of this fact, the NRC staff encourages licensees to use the randomly selected tendons for surveillance as proposed in RG 1.35, Revision 3. Indicate whether you plan to adopt such an approach for the next scheduled tendon surveillance at Oconee.

Enclosure

- 3. In Table 2 of the report, the shim thicknesses at both ends of a tendon are listed. Discuss the significance of this information. Were the tendon elongations recorded during the retensioning along with the force measurements? If so, provide them. Elongations can be used to check the corresponding force measurement, especially if the retensioning is accomplished in two or more steps.
- 4. In Table 1 of the report, grease in the amounts of 18 and 15 gallons was shown to have been added for tendons 23V14 and 45V16, respectively. The NRC staff does not completely agree with the explanation given for these excessive amounts. Therefore, provide the rational as to why it occurs only in vertical tendons. The voids in the grease give rise to two concerns: (1) the tendon may be subjected to corrosion and (2) the voids may result from the leakage of the grease into the concrete which may affect the concrete strength.

- 2 -