

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7901040160 DOC. DATE: 78/12/29 NOTARIZED: NO
 FACIL: 50-287 OCONEE #3, DUKE POWER CO.
 AUTH. NAME AUTHOR AFFILIATION
 PARKER, W.O. DUKE POWER CO.
 RECIP. NAME RECIPIENT AFFILIATION
 O'REILLY, J.P. **REG. 2, ATLANTA, OFF. OF THE DIRECTOR

DOCKET #
05000287

SUBJECT: Forwards LER#78-017/03L-0.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: _____
 TITLE: INCIDENT REPORTS

NOTES: _____

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	05 BC	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 HANAUER	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 COLLINS	0	0	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 HOUSTON	0	0
	26 VOLLMER	1	1	E JORDAN/IE	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	27 ACRS	16	16			

TOTAL NUMBER OF COPIES REQUIRED: LTR 43 ENCL 43

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

December 29, 1978

TELEPHONE: AREA 704
373-4063


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

RE: Oconee Unit 3
Docket No. 50-287

Dear Mr. O'Reilly:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station Technical Specifications, please find attached Reportable Occurrence Report RO-287/78-17.

Very truly yours,



William O. Parker, Jr.

KRW:scs
Attachment

cc: Director, Office of Management Information
and Program Control

REGULATORY DOCKET FILE COPY

7901040166

A002
5/11

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | S | C | N | E | E | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 28 30 37 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CONT
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 7 | 7 | 1 | 1 | 2 | 9 | 7 | 8 | 8 | 1 | 2 | 2 | 9 | 7 | 8 | 9
7 8 60 61 68 69 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

0 2 | EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
On November 29, 1978 ES Analog Channels A and C were tripped due to
0 3 | apparent drift in the narrow-range pressure transmitters . Channel A was
0 4 | tripped at 0810 and returned to service at 1230 and Channel C was tripped at
0 5 | 1345 and returned to service at 1445. Sufficient operability and redundancy
0 6 | were available except as noted in the attached report and which will be
0 7 | described in RO-287/78-18.

0 9 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE
I | B | E | G | I | N | S | T | R | U | T | Z
9 10 11 12 13 18 19 20

17 | LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.
7 | 8 | 7 | 8 | 0 | 1 | 7 | 0 | 3 | L | 0
21 22 23 24 25 26 27 28 29 30 31 32

1 0 | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
The cause of the transmitter malfunctions was apparently temperature or
1 1 | humidity transients in the penetration room. This is a recurring problem.

1 2 | _____
1 3 | _____
1 4 | _____

1 5 | FACILITY STATUS | % POWER | OTHER STATUS (30) | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION (32)
E | 28 | 0 | 9 | 9 | 29 | NA | A | 31 | Routine instrument surveillance
7 8 9 10 12 13 44 46 48

1 6 | ACTIVITY CONTENT | AMOUNT OF ACTIVITY (35) | LOCATION OF RELEASE (36)
Z | 33 | Z | 34 | NA | NA | 36
7 8 9 10 44 45

1 7 | PERSONNEL EXPOSURES | DESCRIPTION (39)
0 | 0 | 0 | 0 | 37 | Z | 38 | NA
7 8 9 11 12 13

1 8 | PERSONNEL INJURIES | DESCRIPTION (41)
0 | 0 | 0 | 0 | 40 | NA
7 8 9 11 12

1 9 | LOSS OF OR DAMAGE TO FACILITY | DESCRIPTION (43)
Z | 42 | NA
7 8 9 10

2 0 | PUBLICITY ISSUED | DESCRIPTION (45) | NRC USE ONLY
N | 44 | NA
7 8 9 10 68 69 80