

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9302220153 DOC. DATE: 93/02/11 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 AUTH. NAME AUTHOR AFFILIATION
 HAMPTON, J.W. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Provides steam generator tube plugging & repair 30 day rept
 & category C-3 examination results, as specified in 921231
 ltr & requested during NRC telcon on 930106.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 63
 TITLE: OR Submittal: General Distribution

NOTES: *see Rpts*

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-3 LA		1	1		PD2-3 PD		1	1
	WIENS, L		2	2					
INTERNAL:	ACRS		6	6		NRR/DET/ESGB		1	1
	NRR/DOEA/OTSB11		1	1		NRR/DST/SELB 7E		1	1
	NRR/DST/SICB8H7		1	1		NRR/DST/SRXB 8E		1	1
	NUDOCS-ABSTRACT		1	1		OC/LFMB		1	0
	OGC/HDS2		1	0		REG-FILE 01		1	1
EXTERNAL:	NRC PDR		1	1		NSIC		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 21 ENCL 19

omb-2

Duke Power Company
Oconee Nuclear Generation Department
P.O. Box 1439
Seneca, SC 29679

J.W. HAMPTON
Vice President
(803)885-3499 Office
(704)373-5222 FAX



DUKE POWER

February 11, 1993

U.S. Nuclear Regulatory Commission
Attention Document Control Desk
Washington, DC 20555

Subject: Duke Power Company
Oconee Nuclear Station
Docket No. 50-269
Unit 1, EOC 14 Refueling Outage
Steam Generator Tube Plugging and Repair 30 Day Report

Pursuant to Oconee Technical Specification 4.17.6(a), the following is the report on the number of tubes plugged or repaired during the Unit 1, EOC 14 Refueling Outage. In addition, information specified in our letter dated December 31, 1992 for the notification to NRC of Category C-3 examination results and as requested by NRC during the telephone conference on January 6, 1993, is also provided.

One hundred thirty-nine (139) tubes were removed from service by plugging in the "A" OTSG. Four hundred seventy-three (473) were removed from service by plugging in the "B" OTSG. No tubes were sleeved in either OTSG. The plugging of these tubes was completed January 13, 1993.

The higher than normal numbers of tubes plugged during this outage were attributed to an inspection transient resulting from not using a 5 to 1 signal to noise ratio which had been used during past examinations. This was concluded by normalizing bobbin eddy current data between EOC-13 and EOC-14 of the 40% or greater through wall calls from EOC-14. These were then compared on the basis of voltage change, phase angle change, and a combination of both. The result of these comparisons are as follows:

- 1) The majority of voltage increases were 0.5 volts or less (Figures 1 and 2). The average growth was 0.383 volts for OTSG "A" and 0.134 volts for OTSG "B". This growth rate is within the error for the eddy current signal calibration method used. Indications having a voltage increase of 1 volt or more was 4.0% for OTSG "A" and 3.7% for OTSG "B". The average growth for this population was 5.79 volts for "A" and 3.46 volts for "B".

9302220153 930211
PDR ADOCK 05000269
P PDR

A001
1/11

- 2) The phase component of the signal did not prove to be a reliable indicator of growth for the majority of the population. This is attributed to the influence of signal noise on the phase of the signal. No meaningful patterns could be identified.
- 3) The number of tubes showing an increase in voltage in combination with a decrease in phase angle was small compared to the total population. One tube in OTSG "A" and eight in OTSG "B" met this criteria.

The comparisons addressed above show the growth for the bobbin coil signal components was within expected bounds and typical of past inspections.


Motorized Rotating Pancake Coil (MRPC) confirmed the presence of 40% of those bobbin indications inspected in OTSG "A" and 55.6% of the indications inspected in OTSG "B".

MRPC sizing was performed and showed 69 or 16% of the indications in OTSG "A" and 129 or 12.7% of the indications in OTSG "B" had an axial length of greater than 1/2". The number of indications with an axial extent greater than 1/2" and a circumferential extent greater than 30 degrees were 41 in OTSG "A" and 98 in OTSG "B". The complete results of the MRPC sizing study are included as attachments to this report.

As supported from the data above, the signals are typical of degradation we have seen in past examinations. The growth rate for this degradation is still small and typical of past examinations. Based on the above and historical data which indicates tube leaks in the Ocone OTSGs have occurred predominately in the lane and wedge regions as a result of high cycle fatigue, no corrective actions will be taken. The future OTSG examinations will be performed using our normal examination sampling plan.

If you have any questions or need further information you may contact M. E. Patrick at (803) 885-3292.

Very truly yours,


J. W. Hampton

Attachment

U. S. Nuclear Regulatory Commission
Page 3

xc: Mr. L. A. Wiens
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. S. D. Ebnetter
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission

Mr. P. E. Harmon
Senior NRC Resident Inspector
Oconee Nuclear Station

Mr. Heyward G. Shealy
Bureau of Radiological Health
SC Dept. of Health & Environmental Control
2600 Bull St.
Columbia, SC 29201