

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9703070062 DOC. DATE: 97/02/27 NOTARIZED: NO
 FACIL: 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.
 AUTH. NAME AUTHOR AFFILIATION
 BOND, R.T. Duke Power Co.
 HAMPTON, J.W. Duke Power Co.
 RECIPIENT NAME RECIPIENT AFFILIATION

DOCKET #
05000270

SUBJECT: LER 96-006-01: on 951211, NRC insp of plant implementation of GL 89-10 identified issue w/Anchor/Darling double disc gate valves. Caused by deficient design analysis, unanticipated interaction of components. Procedures revised. W/970227 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 8
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD2-2 PD	1 1	LABARGE, D	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	FILE CENTER	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 25 ENCL 25

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T

Duke Energy Corp.
Oconee Nuclear Site
P.O. Box 1139
Seneca, SC 29679

J. W. Hampton
Vice President
(864) 885-3199 Office
(864) 885-3564 Fax



DUKE POWER

February 27, 1997

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
Licensee Event Report 270/96-06, Revision 1
Problem Investigation Process Nos.:
3-096-2331, 2-096-2571

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d),
attached is Licensee Event Report 270/96-07, concerning
the past inoperability of containment isolation valves.

This is a supplemental report. It is being submitted in
accordance with 10 CFR 50.73 (a) (2) (ii). This event is
considered to be of no significance with respect to the
health and safety of the public.

Very truly yours,

J. W. Hampton, Vice President
Oconee Nuclear Site

/fts

Attachment

07000
9703070062 970227
PDR ADOCK 05000270
S PDR



11
Ie 2

Document Control Desk

February 27, 1997

Page Two

cc: Mr. Luis A. Reyes
Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

Mr. D. E. LaBarge
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Mr. M. A. Scott
NRC Resident Inspector
Oconee Nuclear Station

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Oconee Nuclear Station, Unit Two	DOCKET NUMBER (2) 05000 270	PAGE (3) 1 OF 6
--	---------------------------------------	---------------------------

TITLE (4)
Containment Isolation Valves Technically Inoperable Due To Deficient Design Analysis

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER(S)
12	11	96	96	06	01	02	27	97	Oconee, Unit Three	05000 287
										05000

OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR (Check one or more of the following) (11)									
POWER LEVEL (10) 0	20.402(b)			20.405(c)			50.73(a)(2)(iv)			73.71(b)
	20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)			73.71(c)
	20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vii)			OTHER (Specify in
	20.405(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(viii)(A)			Abstract below and
	20.405(a)(1)(iv)			X 50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)			in Text, NRC Form
20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)			366A)	

LICENSEE CONTACT FOR THIS LER (12)									
NAME R. T. Bond, Safety Review Manager							TELEPHONE NUMBER		
							AREA CODE (864)		NUMBER 885-3043

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)				EXPECTED SUBMISSION DATE (15)			MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)				X	NO				

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)

In December 1995, a NRC inspection of Oconee's implementation of Generic Letter 89-10 identified an issue with Anchor/Darling double disc gate valves. As a result, a Duke calculation using EPRI methodology concluded that the valve's disc wedges have to be installed in a preferred direction. During the recent shutdown of all three Oconee Nuclear Station units, an inspection of these type valves identified four containment isolation valves that had the wedges installed in the non-preferred direction. These valves were determined to be technically inoperable from the date of installation. The root cause of this event is determined to be a deficient Design Analysis, Unanticipated interaction of components. Corrective actions included reassembly with the disc lower wedges in the preferred direction and revising applicable valve maintenance procedures to provide proper guidance on installing wedges in the preferred direction during reassembly.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Oconee Nuclear Station, Unit Two	270	96	06	01	2 OF 6

BACKGROUND

2FDW-103, 3FDW-103 and 2FDW-104 are motor operated valves that are the outside containment penetration isolation valve for the Steam Generator shell drain lines. During normal operating conditions these valves remain closed and are only opened during startups and shutdowns.

2HP-20 is a motor operated valve that is an inside containment isolation valve for the Reactor Coolant seal return line. During normal operating conditions this valve is in the open position.

In the event of a design basis accident, the Engineered Safeguard System [EIIS:JE] will automatically close these valves and block the operation of the opening circuit on low Reactor Coolant System [EIIS:AB] pressure or high Reactor Building pressure.

EVENT DESCRIPTION

Late in 1994, EPRI issued a report on Motor Operated Valve Performance Prediction Methodology.

Oconee Nuclear Station (ONS) had a vendor perform valve analysis using portions of the EPRI methodology. This analysis showed that Anchor/Darling double disc gate valves could meet the thrust prediction for theoretical flow isolation. The orientation of the valve disc used in this analysis was believed to be more severe than was applicable at ONS.

Between December 4 and 15, 1995, the NRC performed an inspection to verify that ONS met the intent of Generic Letter 89-10 (Safety-Related Motor Operated Valve and Surveillance Program). During this inspection, the NRC requested that ONS use the EPRI methodology to address hard seat contact on Anchor/Darling double disc gate valves. This was identified as an Inspector Follow-up Item (IFI). As a result of the IFI, ONS Engineering initiated a formal calculation as part of the design basis documentation for Anchor/Darling double disc gate valves.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Oconee Nuclear Station, Unit Two	270	96	06	01	3 OF 6

On March 15, 1996, the NRC issued a Safety Evaluation Report on the EPRI methodology report, which basically approved its use as "state-of-the-art" for valve analysis.

The ONS Engineering calculation was approved on July 22, 1996, and concluded that these valves' lower wedges are required to be installed toward the downstream side (the preferred direction) except for Unit 1, 2, and 3's SSF-97 which can perform its intended function in the non-preferred direction. As a result, work orders were initiated to inspect all affected Anchor/Darling double disc gate valves during the next outage of sufficient length.

On November 12, 1996, with Unit 3 shutdown for a Refueling Outage, an inspection of 3FDW-103 identified that the wedges were installed in the non-preferred direction. As a result, a Problem Investigation Process (PIP) report was initiated and an operability evaluation began.

On November 26, 1996, with Unit 2 shutdown due to a forced outage, an inspection of 2HP-20 identified that the wedges were installed in the non-preferred direction. As a result, another PIP report was initiated and an operability evaluation began.

On December 3, 1996, the wedges on 2HP-20 were removed and reinstalled in the preferred direction.

On December 4, 1996, the wedges on 3FDW-103 were removed and reinstalled in the preferred direction.

On December 11, 1996, the operability evaluation concluded that 3FDW-103 had been technically inoperable since it was installed on December 9, 1989. Therefore, the valve may not have been capable of providing containment isolation during an Engineering Safeguards actuation.

On December 23, 1996, the operability evaluation concluded that 2HP-20 had been technically inoperable since it was installed on March 5, 1992. Therefore, the valve may not have been capable of providing containment isolation during an Engineering Safeguards actuation.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Oconee Nuclear Station, Unit Two	270	96	06	01	4 OF 6

On January 4, 1997, the wedges on 2FDW-103 and 2FDW-104 were inspected and found to be in the non-preferred direction. The wedges were removed and reinstalled in the preferred direction.

On January 6, 1997, the operability evaluation concluded that 2FDW-103 and 2FDW-104 had been technically inoperable since their installation on April 1, 1988. Therefore, these valves may not have been capable of providing containment isolation during an Engineering Safeguards actuation.

All of the other Anchor/Darling double disc gate valves were inspected and found to be in the preferred direction.

CONCLUSIONS

The root cause of this event is determined to be a Deficient Design Analysis, unanticipated interaction of components. At the time these valves were installed, the vendor indicated that there was not a preferred direction. Therefore, it was not known that the Anchor/Darling double disc gate valves had to be installed with the wedges in a preferred direction. This was not clear until the completion of the EPRI testing. It is concluded that if this information had been known at the time these valves were installed, the preferred direction of the wedges could have been properly ensured.

This event is considered to be non-recurring. No corrective action can be taken to assure that industry operating experience, improving technology, testing methods, and/or analytical models do not reveal previously unknown equipment problems. Duke Power's Operating Experience Program is intended to assure evaluation of new industry information for potential impact on equipment/systems at Duke's Nuclear Power Stations.

This event did not involve an equipment failure and is not NPRDS reportable. There were no radiological overexposures, radioactive releases, or personnel injuries associated with this event.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Oconee Nuclear Station, Unit Two	270	96	06	01	5 OF 6

CORRECTIVE ACTIONS

Immediate

None

Subsequent

1. All applicable Anchor/Darling double disc gate valves were inspected to ensure that the wedges were in the preferred direction.
2. Wedges on affected valves were placed in the preferred direction.
3. All applicable procedures have been revised to provide proper guidance on installing wedges in the preferred direction during reassembly.

Planned

None

Because correction of the valve disc configuration is complete and there are no planned corrective actions, none of the corrective actions contained in this report are considered an NRC commitment.

SAFETY ANALYSIS

The Anchor Darling valves in this event are containment isolation valves. The safety significance of this event is the potential for failure of the affected valves to close on demand following an accident. Postulating failure of these valves due to this condition, with an assumed single failure of the remaining containment boundary, could result in a postulated uncontrolled release in excess of the allowed containment leakage limits.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Oconee Nuclear Station, Unit Two	270	96	06	01	6 OF 6

2HP-20 is the inside containment isolation valve in the reactor coolant pump seal return line. In order to lose containment integrity following an accident, 2HP-21, the outside containment isolation valve, would also have to fail to close. 2HP-21 has a pneumatic operator, which fails closed on loss of air.

The potential failure of valve 2HP-20 does not increase the probability of any PRA core damage sequence (such as LOCA outside of containment). This is because the High Pressure Injection [EIIS:BG] makeup system could keep up with any flow out of 2HP-20.

As stated above, 2HP-21 could be used to isolate any containment leakage through 2HP-20.

3FDW-103, 2FDW-103 and 2FDW-104 are outside containment isolation valves in the Steam Generator blowdown line. The inside boundary is the Steam Generator, associated Feedwater and Main Steam piping. These valves are only open during start-ups and shutdowns, when Reactor Coolant System pressure is reduced. A release through blowdown valves (3FDW-103, 2FDW-103 and 2FDW-104) is unlikely because, for this to happen, these valves would have to be open during a failure of the inside boundary. As stated above, they are only open during startup and shutdown.

There were no releases of radioactive material involved with this incident. The health and safety of the public were not affected.