



Clinton Power Station
8401 Power Road
Clinton, IL 61727

U-604240
August 24, 2015

10CFR50.73
SRRS 5A.108

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555-0001

Clinton Power Station, Unit 1
Facility Operating License No. NPF-62
NRC Docket No. 50-461


Subject: Licensee Event Report 2015-004-00

Enclosed is Licensee Event Report (LER) 2015-004-00: Trip of Emergency Reserve Auxiliary Transformer Static VAR Compensator Causes Positive Secondary Containment Pressure Following Lightning Strike on 138 kV Offsite Source. This report is being submitted in accordance with the requirements of 10 CFR 50.73.

There are no regulatory commitments contained in this report.

Should you have any questions concerning this report, please contact Mr. Jeffrey Cunningham, Regulatory Assurance Manager, at (217) 937-2800.

Respectfully,


for M. Newcomer
Mark M. Newcomer
Site Vice President
Clinton Power Station

JLP/cas

Enclosure: Licensee Event Report 2015-004-00

cc: Regional Administrator – NRC Region III
NRC Senior Resident Inspector - Clinton Power Station
Office of Nuclear Facility Safety – Illinois Emergency Management Agency

Handwritten initials "JED" and "NRR" in the bottom right corner of the page.



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Clinton Power Station, Unit 1	2. DOCKET NUMBER 05000461	3. PAGE 1 OF 3
--	-------------------------------------	--------------------------

4. TITLE
Trip of Emergency Reserve Auxiliary Transformer Static VAR Compensator Causes Positive Secondary Containment Pressure Following Lightning Strike on 138 kV Offsite Source

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
06	25	2015	2015	004	00	08	24	2015		05000
									FACILITY NAME	DOCKET NUMBER
										05000

9. OPERATING MODE	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)			
1	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
10. POWER LEVEL	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT Jeffrey Cunningham, Regulatory Assurance Manager	TELEPHONE NUMBER (Include Area Code) 217-937-2800
--	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On 6/25/15 at 0301 CDT, the Main Control Room received numerous annunciators that indicated a trip of the Emergency Reserve Auxiliary Transformer (ERAT) Static VAR Compensator (SVC) caused by a voltage transient on the 138 kV offsite source due to thunderstorms in the area. The Division 1 Safety Bus was manually aligned from the reserve source to its normal source. As a result of the voltage transient, the Division 1 Fuel Building Ventilation (VF) system isolation dampers closed causing a trip of VF supply and exhaust fans. With no running VF fans, secondary containment differential pressure rose to slightly greater than 0 inches water gauge which exceeded the Technical Specification (TS) requirement of greater than 0.25 inches vacuum water gauge. Secondary Containment differential pressure was restored within TS requirements at 0320 CDT by reopening the VF isolation dampers and restarting the VF supply and exhaust fans. The ERAT SVC was returned to service at 0457 CDT. ENS notification 51179 was made at 0927 ET in accordance with 10 CFR 50.72(b)(3)(v)(C). This event is being reported as a condition that could have prevented fulfillment of a safety function under 10 CFR 50.73(a)(2)(v)(C).



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
		YEAR	SEQUENTIAL NUMBER	REV NO.		
Clinton Power Station, Unit 1	05000461	2015	- 004	- 00	2	OF 3

NARRATIVE

PLANT AND SYSTEM IDENTIFICATION

General Electric -- Boiling Water Reactor, 3473 Megawatts Thermal Rated Core Power Energy Industry Identification System (EIS) codes are identified in text as [XX].

EVENT IDENTIFICATION

A. Plant Operating Conditions Before the Event

Unit: 1 Event Date: 06/25/2015 Event Time: 0301 Central Daylight Time
 Mode: 1 Mode Name: Power Operation Reactor Power: 99 percent

B. DESCRIPTION OF EVENT

On 6/25/15 at 0301 CDT, the Main Control Room received numerous annunciators that indicated a trip of the Emergency Reserve Auxiliary Transformer (ERAT)[XFMR] Static VAR Compensator (SVC)[COMP] caused by a voltage transient on the 138 kV offsite source due to thunderstorms in the area. The Division 1 Safety Bus [BU] was manually aligned from the reserve source to its normal source. As a result of the voltage transient, the Division 1 Fuel Building Ventilation (VF) system isolation dampers [DMP] closed causing a trip of VF supply and exhaust fans [FAN]. With no running VF fans, secondary containment differential pressure rose to slightly greater than 0 inches water gauge which exceeded the Technical Specification (TS) requirement of greater than 0.25 inches vacuum water gauge. Secondary Containment differential pressure was restored within TS requirements at 0320 CDT by reopening the VF isolation dampers and restarting the VF supply and exhaust fans. The ERAT SVC was returned to service at 0457 CDT.

This condition required an eight-hour Event Notification under 10 CFR 50.72(b)(3)(v)(C). Event Notification #51179 was made at 0927 ET.

This issue was entered into the Clinton Power Station corrective action program under Issue Report (IR) 2519380.

C. CAUSE OF EVENT

An investigation was performed by Ameren and found that the South Bloomington substation breakers and the Clinton Route 54 breakers opened and reclosed as designed. A phase-to-ground fault was discovered and it was determined that the most apparent cause of loss of the 138kV line was due to a lightning strike.

D. SAFETY CONSEQUENCES

There were no actual safety consequences related to this event. This event resulted in the loss of secondary containment pressure for about 19 minutes, from 0301 to 0320 on 6/25/15, due to the VF supply and exhaust fans tripping off. Secondary Containment differential pressure was greater than the 0.25 inches vacuum required by TS 3.6.4.1. The VF supply and exhaust fans were restarted manually during this period and the differential pressure was restored to within limits.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Clinton Power Station, Unit 1	05000461	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 3
		2015	- 004	- 000	

NARRATIVE

This event is considered to be reportable as a loss of safety function under 10 CFR 50.72(b)(3)(v)(C) and 10 CFR 50.73(a)(2)(v)(C) as an event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to control the release of radioactive material.

E. CORRECTIVE ACTIONS

No failed or malfunctioning equipment resulted from this event. All equipment functioned as designed. As a result, no corrective actions were necessary.

F. PREVIOUS SIMILAR OCCURRENCES

Licensee Event Report 2012-001-00: Loss of Secondary Containment Differential Pressure Due to Transformer Trip, dated October 26, 2012

Licensee Event Report 2013-008: Failure of Division 1 Transformer Leads to Isolation of Instrument Air Supply to Containment, Lowering Scram Pilot Air Header Pressure, and Manual Scram, dated February 3, 2014

Licensee Event Report 2014-001-00: Premature Failure of Air Supply Solenoid Results in Isolation of Fuel Building Ventilation System and Loss of Secondary Containment Differential Pressure, dated March 20, 2014

G. COMPONENT FAILURE DATA

None