

**Virginia Electric and Power Company  
Surry Power Station  
5570 Hog Island Road  
Surry, Virginia 23883**

December 11, 2015

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555-0001

Serial No.: 15-544  
SPS: JSA  
Docket No.: 50-280  
License No.: DRP-32

Pursuant to 10CFR50.73, Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to Surry Power Station Unit 1.

Report No. 50-280/2015-003-00

This report has been reviewed by the Station Facility Safety Review Committee and will be forwarded to the Management Safety Review Committee for its review.

Very truly yours,



N. L. Lane  
Site Vice President  
Surry Power Station

Enclosure

Commitment contained in this letter: None

cc: U.S. Nuclear Regulatory Commission, Region II  
Marquis One Tower, Suite 1200  
245 Peachtree Center Ave., NE  
Atlanta, GA 30303-1257

NRC Senior Resident Inspector  
Surry Power Station

*JE22*  
*MR*



**LICENSEE EVENT REPORT (LER)**

(See Page 2 for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

<b>1. FACILITY NAME</b> Surry Power Station, Unit 1	<b>2. DOCKET NUMBER</b> 05000 - 280	<b>3. PAGE</b> 1 OF 3
--	--	--------------------------

**4. TITLE**  
Unit 1 Reactor Trip Due to Loss of Main Generator Field

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
10	13	2015	2015	- 003	- 00	12	11	2015	FACILITY NAME	DOCKET NUMBER 05000

<b>9. OPERATING MODE</b>	<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)</b>			
N	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
100	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

**12. LICENSEE CONTACT FOR THIS LER**

LICENSEE CONTACT N. L. Lane, Site Vice President	TELEPHONE NUMBER (Include Area Code) (757) 365-2001
---	--

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
B	TB	EXC	S366	Y					

<b>14. SUPPLEMENTAL REPORT EXPECTED</b> <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	<b>15. EXPECTED SUBMISSION DATE</b>	MONTH	DAY	YEAR
--	-------------------------------------	-------	-----	------

**ABSTRACT** (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On October 13, 2015 at 1815 hours, with Unit 1 at 100 percent power and Unit 2 at 93.5 percent power at the end of life coastdown, Unit 1 experienced a reactor trip initiated from a turbine trip by main generator trip. The main generator trip was due to a loss of the main generator field that caused a loss of field protection relay to trip.

All three auxiliary feedwater pumps automatically started on low-low steam generator water level providing flow to the steam generators. Main steam trip valves were closed due to primary cooldown in accordance with emergency operating procedures and the plant was stabilized using steam generator power operated relief valves. The direct cause of the loss of main generator field of the Unit 1 generator was an electrical fault in the main generator exciter spacer coupling. Corrective actions to prevent recurrence will be implemented through the corrective action program when the root cause evaluation is completed.

This report is being submitted pursuant to 10CFR50.73(a)(2)(iv)(A) as an event that resulted in the automatic actuation of the Reactor Protection System and the Auxiliary Feedwater System.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Surry Power Station	05000 - 280	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 3
		2015	- 003	- 00	

**NARRATIVE**

**1.0 DESCRIPTION OF THE EVENT**

On October 13, 2015 at 1815 hours, with Unit 1 at 100 percent power and Unit 2 at 93.5 percent power at the end of life coastdown, Unit 1 experienced a reactor trip initiated from a turbine trip by main generator trip. The main generator trip was due to a loss of the main generator field [EISS-TB] that caused a loss of field protection relay to trip.

Automatic systems responded to the reactor/turbine trip as designed. All three auxiliary feedwater (AFW) pumps [EISS-BA-P] automatically initiated on low-low steam generator (SG) water level providing flow to the SGs [EISS-AB-SG]. Following the reactor trip, reactor coolant system (RCS) temperature fell below the nominal temperature of 547 degrees Fahrenheit and reached a minimum of 542 degrees Fahrenheit. The lower temperature was due to the expected opening of at least one SG power operated relief valve (PORV) [EISS-AB-RV], injection of AFW flow, valve alignment of gland steam being supplied by main steam versus auxiliary steam and leakby of a moisture separator reheater steam supply control valve [EISS-SB-FCV]. Due to the primary cooldown, the main steam trip valves [EISS-SB-ISV] were closed at 1836 hours as directed by emergency operating procedures and the plant was stabilized using SG PORVs. AFW was subsequently secured by procedural guidance and Unit 1 was placed in hot shutdown using normal operating procedures.

At 2120 hours, a four-hour report was made pursuant to 10CFR50.72(b)(2)(iv)(B) due to valid automatic actuation of Reactor Protection Systems and an eight-hour report was made pursuant to 10CFR50.72(b)(3)(iv)(A) due to automatic actuation of the AFW system.

This report is being submitted pursuant to 10CFR50.73(a)(2)(iv)(A) as an event that resulted in the automatic actuation of the Reactor Protection System and the AFW system.

**2.0 SIGNIFICANT SAFETY CONSEQUENCES AND IMPLICATIONS**

This event resulted in no safety consequences or implications. There was no testing or surveillances in progress when the reactor trip occurred. Appropriate operator actions were taken in accordance with emergency operating procedures and the unit was quickly brought to a stable condition. Station equipment relied upon to mitigate the event responded as designed. Therefore, the health and safety of the public were not affected.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
Surry Power Station	05000 - 280	YEAR	SEQUENTIAL NUMBER	REV NO.	3	OF	3
		2015	- 003	- 00			

**NARRATIVE**

**3.0 CAUSE**

The direct cause of the loss of main generator field of the Unit 1 generator was an electrical fault in the main generator exciter spacer coupling. Disassembly of the generator exciter found damage to the electrical connections between the exciter, spacer coupling and generator. The electrical fault was caused by a poor connection between one of the main generator exciter coupling butterfly leads and axial lead. The poor connection was due to a deficiency in the assembly process when the connection was last assembled during a refueling outage in May 2015.

**4.0 IMMEDIATE CORRECTIVE ACTION(S)**

Following the reactor trip, control room operators acted promptly to place the unit in a safe, shutdown condition in accordance with emergency operating procedures.

**5.0 ADDITIONAL CORRECTIVE ACTIONS**

A root cause evaluation (RCE) team was assembled to determine the cause of this event and to recommend corrective actions. The leakby of the moisture separator reheater steam supply control valve has been repaired and Engineering is evaluating the valve alignment of gland steam being supplied by main steam versus auxiliary steam.

**6.0 ACTIONS TO PREVENT RECURRENCE**

Additional corrective actions to prevent deficiencies during the assembly process will be identified when the RCE is completed and will be implemented through the corrective action program.

**7.0 SIMILAR EVENTS**

None

**8.0 MANUFACTURER/MODEL NUMBER**

Siemens Westinghouse/Mark III

**9.0 ADDITIONAL INFORMATION**

Unit 2 was at 93.5 percent power at the end of life coastdown and remained unaffected by the Unit 1 reactor trip.