

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 9136

FILE: INCIDENT REPORT FILE

FROM: Duke Power Co. Charlotte, N.C. William O. Parker		DATE OF DOC 8-19-75	DATE REC'D 8-27-75	LTR	TWX	RPT XX	OTHER
TO:		ORIG 1 Signed	CC	OTHER	SENT AEC PDR SENT LOCAL PDR		XXX XXX
CLASS	UNCLASS XX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-270		

DESCRIPTION:
Letter trans the following.....

PLANT NAME: Oconee # 2

ENCLOSURES:
Abnormal Occurrence # 75-15, on 8-5-75,
Concerning Failure of amplifier in Reactor
Protective System Channel D Power Imbalance
circuit.....

(1 Copy Enclosure Received)

FOR ACTION/INFORMATION

SAB 8-29-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

DO NOT REMOVE

ACKNOWLEDGED

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Walhalla, S.C.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST S. Sheppard		
** SEND ONLY TEN DAY REPORTS		

DUKE POWER COMPANY

Regulatory

File Cy.

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

August 19, 1975

Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303




Re: Oconee Unit 2
Docket No. 50-270

Dear Mr. Moseley:

Pursuant to Section 6.2 and 6.6.2 of the Oconee Nuclear Station
Technical Specifications, please find attached Abnormal Occurrence
Report A0-270/75-15.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr.



ROS:vr
Attachment

cc: Mr. Roger S. Boyd

DUKE POWER COMPANY
OCONEE UNIT 2

Report No.: AO-270/75-15

Report Date: August 19, 1975

Occurrence Date: August 5, 1975

Facility: Oconee Unit 2, Seneca, South Carolina

Identification of Occurrence: Failure of amplifier in Reactor Protective System Channel D power imbalance circuit

Conditions Prior to Occurrence: Trip recovery in progress

Description of Occurrence:

On August 5, 1975, during surveillance testing of Oconee Unit 2 Reactor Protective System (RPS) Channel D, it was noted that a faulty amplifier in the power imbalance circuit of the power-imbalance-flow trip function had resulted in a trip setpoint less conservative than allowed by Technical Specification 2.3. For this test, RPS Channel D was placed in manual bypass, leaving the system in a two-out-of-three logic. Power and imbalance test signals were set and a flow test signal then decreased to establish a trip point. Because of the faulty amplifier in the imbalance circuit, the trip point decreased to 109.5×10^6 lbs/hr rather than the required trip point of 110×10^6 lbs/hr. RPS Channel D was left in manual bypass since a replacement amplifier was not immediately available. The last periodic test of RPS Channel D was completed on July 9, 1975.

Designation of Apparent Cause of Occurrence:

A faulty amplifier was determined to be the apparent cause of this occurrence. This was the first failure of this component and is regarded as a random failure.

Analysis of Occurrence:

This amplifier is part of the power imbalance circuit of the power-imbalance-flow trip function. The failure of this amplifier resulted in a trip point less conservative than required; however, a trip of two of the three remaining RPS channels would have performed this function if necessary. It is concluded that the health and safety of the public was not affected.

Corrective Action:

The faulty amplifier will be replaced as soon as a replacement is available. Until that time, RPS Channel D will remain in manual bypass. The Oconee periodic surveillance program is considered adequate to identify random failures of this nature.

AUG 21 9 32 AM '75

U.S.A.E.O.
REGULATORY OPERATIONS
REGION II
ATLANTA, GA.

[Faint, mostly illegible text body of the document]