

**NRC DISTRIBUTION FOR PART 50 DOCUMENT MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 7428

FILE: INCIDENT REPORT FILE

FROM: Duke Power Co. Charlotte, N.C. William O. Parker, Jr		DATE OF DOC 7-9-75	DATE REC'D 7-11-75	LTR xxx	TWX	RPT	OTHER
TO: Mr. Norman C. Moseley		ORIG no	CC 1	OTHER	SENT AEC PDR <u>xxxx</u> SENT LOCAL PDR <u>xx</u>		
CLASS	UNCLASS xxxxxxx	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-269		

DESCRIPTION:

Ltr trans the following:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME:
Oconee #1

ENCLOSURES:

Abnormal Occurrence #75-7 on 6-24-75 concerning high reactor coolant system leakage
.....

FOR ACTION/INFORMATION 7-14-75 JGB

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	✓ PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO ** STELLO ** HOUSTON ** NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON ** GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	---	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <u>Walhalla, S.C.</u>	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
5 - ACRS SENT TO LIC ASST		
** SEND ONLY TEN DAY REPORTS		

*Abm. locum (4) ✓
(misc. memos re. plant)*

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

File Copy

TELEPHONE: AREA 704
373-4083

July 9, 1975



Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Re: Oconee Unit 1
Docket No. 50-269

Dear Mr. Moseley:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station
Technical Specifications, please find attached Abnormal Occurrence
Report A0-269/75-7.


Very truly yours,

A handwritten signature in dark ink, appearing to read "William O. Parker, Jr." with a stylized flourish at the end.

William O. Parker, Jr.

ROS:vr
Attachment

cc: Mr. Angelo Giambusso



DUKE POWER COMPANY
OCONEE UNIT 1

Report No.: AO-269/75-7

Report Date: July 9, 1975

Occurrence Date: June 24, 1975

Facility: Oconee Unit 1, Seneca, South Carolina

Identification of Occurrence: High Reactor Coolant System leakage

Conditions Prior to Occurrence: Unit at full power

Description of Occurrence:

On June 24, 1975, the control operator identified a decreasing level in the Oconee Unit 1 letdown storage tank (LDST). Leakage detection systems indicated a reactor coolant leak of approximately 40 gpm outside of the Reactor Building and a reactor shutdown was initiated. An investigation determined that the reactor coolant letdown line relief valve (HP-43) had lifted and was discharging water to the miscellaneous waste holdup tank. A small portion of the water discharged through valve HP-43 was released to the Auxiliary Building as a result of a valve plug on the downstream side of the relief valve being blown out. The relief valve was found to have lifted because the inlet valve to the purification demineralizer (HP-9) had closed, blocking the letdown flow path. A bypass around the demineralizer was opened allowing valve HP-43 to reseat and stop the leakage.

Designation of Apparent Cause of Occurrence:

Valves 1HP-9 and 2HP-12, inlet to spare purification demineralizer from Unit 1 and outlet from spare purification demineralizer to Unit 2 respectively, are interlocked to prevent crossconnecting Units 1 and 2 through the purification demineralizer. The position limit switch on valve 2HP-12 failed and simulated an open position. This caused valve 1HP-9 to close. The resulting blockage of the Unit 1 letdown flow path caused a pressure increase and relief valve actuation.

The small plug on the downstream side of relief valve HP-43 had previously been lockwired in place. The cause of the plug failure could not be determined.

Analysis of Occurrence:

This incident resulted in a leakage rate of approximately 40 gpm, most of which went into a waste holdup tank. This leakage was well within the makeup capacity of the system. It was calculated that the small portion of the leakage released to the Auxiliary Building resulted in a total of 7.78 curies of gaseous activity being released, which is less than 0.016 percent of the total annual release limit. It is concluded that the health and safety of the public were not affected.

Corrective Action:

The limit switch on valve 2HP-12 was replaced. It was found that the switch was wet and had shorted. The limit switch location is being changed to prevent a recurrence.