

**NRC DISTRIBUTION FOR PART 50 DOCK MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 7663

FILE: INCIDENT REPORT FILE

FROM: Duke Power Co. Charlotte, N. C. William O. Parker, Jr.			DATE OF DOC 7-14-75	DATE REC'D 7-18-75	LTR XX	TWX	RPT	OTHER
TO: Norman C. Moseley			ORIG NONE	CC	OTHER	SENT AEC PDR <u>XXX</u>		SENT LOCAL PDR <u>XXX</u>
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D		DOCKET NO:		
	XXX			1		50-287		

DESCRIPTION:
Ltr. trans the following.....

PLANT NAME: Oconee # 3

ENCLOSURES:
Unusual Event # 75-8, on 6-14-75, concerning
Failure of personwl hatch interlocks.....

(1 cy. Encl. rec'd)

ACKNOWLEDGED
DO NOT REMOVE

FOR ACTION/INFORMATION

VCR 7-19-75

- | | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L)
W/ Copies | SCHWENCER (L)
W/ Copies | ZIEMANN (L)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (L)
W/ Copies | STOLZ (L)
W/ Copies | DICKER (E)
W/ Copies | LEAR (L)
W/ Copies |
| PARR (L)
W/ Copies | VASSALLO (L)
W/ Copies | KNIGHTON (E)
W/ Copies | SPELS
W/ Copies |
| KNIEL (L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | |

INTERNAL DISTRIBUTION

- | | | | | |
|--|---|--|--|--|
| REG FILE
NRC PDR
OGC, ROOM P-506A
GOSSICK/STAFF
CASE
GIAMBUSO
BOYD
MOORE (L)
DEYOUNG (L)
SKOVHOLT (L)
GOLLER (L) (Ltr)
P. COLLINS
DENISE
REG OPR
FILE & REGION (2)
MIPC/PE (3)
STEELE | TECH REVIEW
SCHROEDER
MACCARY
KNIGHT
PAWLICKI
SHAO
**STELLO
**HOUSTON
**NOVAK
ROSS
IPPOLITO
TEDESCO
J. COLLINS
LAINAS
BENAROYA
VOLLMER | DENTON
**GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | LIC ASST
R. DIGGS (L)
H. GEARIN (L)
E. GOULBOURNE (L)
P. KREUTZER (E)
J. LEE (L)
M. RUSHBROOK (L)
S. REED (E)
M. SERVICE (L)
S. SHEPPARD (L)
M. SLATER (E)
H. SMITH (L)
S. TEETS (L)
G. WILLIAMS (E)
V. WILSON (L)
R. INGRAM (L)
M. DUNCAN (E) | A/T IND.
BRAITMAN
SALTZMAN
MELTZ

PLANS
MCDONALD
CHAPMAN
DUBE (Ltr)
E. COUPE
PETERSON
HARTFIELD (2)
KLECKER
EISENHUT
WIGGINTON

F. WILLIAMS
HANAUER |
|--|---|--|--|--|

EXTERNAL DISTRIBUTION

- | | | |
|---------------------------------------|--------------------------------|---|
| 1 - LOCAL PDR <i>Thalhalla - S.C.</i> | 1 - NATIONAL LABS | 1 - PDR-SAN/LA/NY |
| 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB |
| 1 - NSIC (BUCHANAN) | 1 - CONSULTANTS | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | NEWMARK/BLUME/AGBABIAN | 1 - AGMED (RUTH GUSSMAN)
Rm B-127 GT |
| 1 - Newton Anderson | | 1 - J. D. RUNKLES, Rm E-201
GT |
| 5 - ACRS SENT TO LIC ASST | <i>Sheppard</i> | |
| ** SEND ONLY TEN DAY REPORTS | | |

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

July 14, 1975


Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Re: Oconee Unit 3
Docket No. 50-287

Dear Mr. Moseley:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station
Technical Specifications, please find attached Unusual Event Report
UE-287/75-8.



Very truly yours,



William O. Parker, Jr.

ROS:vr
Attachment

cc: Mr. Angelo Giambusso



DUKE POWER COMPANY
OCONEE UNIT 3

Report No.: UE-287/75-8

Report Date: July 14, 1975

Event Date: June 14, 1975

Facility: Oconee Unit 3, Seneca, South Carolina

Identification of Event: Failure of personnel hatch interlocks

Conditions Prior to Event: Unit in cold shutdown

Description of Event:

During a maintenance outage for Oconee Unit 3, it was determined that the interlock mechanism on the personnel hatch had failed. Administrative controls were taken to assure that both doors were not opened simultaneously even though containment integrity was not required.

Designation of Apparent Cause of Event:

Each door of the personnel hatch has a gear which is rotated by the door handwheel. A pawl mechanism, in conjunction with this gear, creates a ratchet mechanism to prevent rotation of the door handwheel should the opposite door be open. The pawls are raised from or lowered on the gear by motion of the opposite door transmitted through a cable and linkage mechanism. The apparent cause of this event was a pinched cable which restricted movement of the pawls.

Analysis of Event:

The unit was in cold shutdown at the time of this incident; hence, containment integrity was not required. In addition to the action taken to prevent simultaneous opening of the doors, a control room alarm also monitors the status of the personnel hatch doors. It is concluded that the health and safety of the public was not affected.

Corrective Action:

The interlocks were adjusted and the personnel hatch was returned to service. The interlocks were tested approximately 15 times to verify operability.

Failure Data:

A previous failure of the personnel hatch interlocks on Oconee Unit 3 was experienced and reported as UE-287/75-3.