

A08/24/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL 50-287

REC: OREILLY J P
NRC

ORG: PARKER W O
DUKE PWR

DOC DATE: 08/18/78
DATE RCVD: 08/23/78

DOCTYPE: LETTER NOTARIZED: NO COPIES RECEIVED
SUBJECT: LTR 1 ENCL 1
FORWARDING LICENSEE EVENT REPT (RO 50-287/78-012) ON 08/04/78 CONCERNING ARC
WELD FILLER WIRES UTILIZED IN THE CONSTRUCTION OF THE PRESSURE VESSEL WAS
UNKNOWINGLY MIXED BY THE SUPPLIER WITH A SHIPMENT OF MN-NO-NI FILLER WIRE.

PLANT NAME: OCONEE - UNIT 3

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: u

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

NOTES:

- 1. M. CUNNINGHAM - ALL AMENDMENTS TO FSAR AND CHANGES TO TECH SPECS

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#4 BC**W/4 ENCL

INTERNAL:	REG FILE**W/ENCL	NRC PDR**W/ENCL
	I & E**W/2 ENCL	MIPC**W/3 ENCL
	I & C SYSTEMS BR**W/ENCL	EMERGENCY PLAN BR**W/ENCL
	NOVAK/CHECK**W/ENCL	EEB**W/ENCL
	AD FOR ENG**W/ENCL	PLANT SYSTEMS BR**W/ENCL
	HANAUER**W/ENCL	AD FOR PLANT SYSTEMS**W/ENCL
	AD FOR SYS & PROJ**W/ENCL	REACTOR SAFETY BR**W/ENCL
	ENGINEERING BR**W/ENCL	VOLLMER/BUNCH**W/ENCL
	KREGER/J. COLLINS**W/ENCL	POWER SYS BR**W/ENCL
	K SEYFRIT/IE**W/ENCL	

EXTERNAL: LPDR'S
WALHALLA, SC**W/ENCL
TIC, LIZ CARTER**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+2P+1P

CONTROL NBR: 782350260

***** THE END *****

A0/4
R

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

August 18, 1978

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

RECEIVED
REGULATORY SERVICES UNIT

1978 AUG 21 PM 4 55

RECEIVED DISTRIBUTION
SERVICES UNIT

Reference: Oconee Unit 3
Docket No. 50-287

Dear Mr. O'Reilly:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station Technical Specifications, please find attached Reportable Occurrence Report RO-287/78-12.

Very truly yours,

William O. Parker Jr. by WAT
William O. Parker, Jr.

RLG:scs
Attachment

cc: Director, Office of Management
Information and Program Control

REGULATORY DOCKET FILE COPY

782350260

1002
S.11

Duke Power Company

Oconee Unit 3

Report No: 50-287/78-12

Report Date: August 18, 1978

Occurrence Date: August 4, 1978

Facility: Oconee Unit 3, Seneca, South Carolina

Identification of Occurrence: Atypical submerged arc weld filler wires utilized in construction of reactor vessel.

Condition Prior to Occurrence: 100% Full Power

Description of Occurrence:

On August 4, 1978, B&W, the Oconee Unit 3 NSSS vendor, informed Duke Power Company that as a result of chemical analyses performed on archive weldments, they had discovered that weld filler wire atypical of the submerged arc weld filler wires utilized in the construction of nuclear pressure vessels was unknowingly mixed by the supplier with a shipment of Mn-Mo-Ni filler wire. The atypical weld wire has high silicon and low nickel contents which are outside of the typical range for the Mn-Mo-Ni filler wire specified by B&W. The nickel content was 0.1% (typically 0.6%) and the silicon content was 1.0% (typically 0.5%). As this atypical material may be present in the Oconee 3 vessel, correspondingly appropriate changes to the heatup and cooldown limits for Unit 3 were prepared by B&W and are implemented at Oconee. These limits are more restrictive than those currently in the Oconee Technical Specifications.

Cause of Occurrence:

B&W's supplier of submerged arc weld filler wire provided weld wire with an atypical material composition which may have been utilized in the construction of the pressure vessel.

Analysis of Occurrence:

There are no directly applicable irradiation data for the atypical weldment although other applicable data exists, and welds of this wire possesses a higher than normal unirradiated reference temperature. Welds prepared from the atypical weld wire exhibit a very adequate Charpy Upper Shelf Energy. This wire mixture (Mn-Mo-Ni filler wire plus the atypical filler wire) may have been used in the construction of the reactor vessel. The weld locations where the wire mixture may have been used are: inlet and outlet nozzles to nozzle belt; upper shell to lower shell; dutchman to lower head. A technical evaluation has been performed by B&W on the reactor vessel assuming the atypical material is in the locations mentioned. This fracture mechanics evaluation has

Analysis of Occurrence (Continued):

demonstrated that the structural integrity of the reactor vessel has not been compromised by the possible presence of the atypical material. However, with the atypical weld material assumed to be present, the operation of the unit is governed by more restrictive pressure-temperature operating limits. These limits are currently in use for Unit 3.

Corrective Action:

Unit 3 operation will continue with the pressure-temperature limits provided by B&W, which are more restrictive than those in the Technical Specifications.

