

**From:** Loomis, Thomas R:(GenCo-Nuc) <thomas.loomis@exeloncorp.com>  
**Sent:** Wednesday, February 24, 2016 8:21 AM  
**To:** Chereskin, Alexander  
**Cc:** Villar, Enrique:(GenCo-Nuc)  
**Subject:** [External\_Sender] Draft for 1100 Discussion  
**Attachments:** 10CFR50 55(a) Evaluation 2016-02-23 1700 DRAFT .docx

Alex

Here is an unverified draft for discussion at the 1100 call.

Thanks  
Tom

This Email message and any attachment may contain information that is proprietary, legally privileged, confidential and/or subject to copyright belonging to Exelon Corporation or its affiliates ("Exelon"). This Email is intended solely for the use of the person(s) to which it is addressed. If you are not an intended recipient, or the employee or agent responsible for delivery of this Email to the intended recipient(s), you are hereby notified that any dissemination, distribution or copying of this Email is strictly prohibited. If you have received this message in error, please immediately notify the sender and permanently delete this Email and any copies. Exelon policies expressly prohibit employees from making defamatory or offensive statements and infringing any copyright or any other legal right by Email communication. Exelon will not accept any liability in respect of such communications. -EXCIP

February XX, 2016

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

Calvert Cliffs Nuclear Power Plant, Unit 1  
Facility Operating License No. DPR-53  
NRC Docket No. 50-317

Subject: Report Concerning Dissimilar Metal Weld Indication on Pressurizer Safety Relief Nozzle to Safe End Weld

Examinations performed during the current refueling outage at Calvert Cliffs Nuclear Power Plant, Unit 1 have identified a change from previous examinations in an axial indication in a pressurizer safety relief nozzle to safe end dissimilar metal weld that was mitigated by the Mechanical Stress Improvement Process (MSIP®) in 2006. These examinations were performed to meet ASME Code Case N-770-1 and 10 CFR 50.55a(g)(5)(ii)(F) requirements.

10 CFR 50.55a(g)(6)(ii)(F)(6) states the following: "For any mitigated weld whose volumetric examination detects growth of existing flaws in the required examination volume that exceed the previous IWB-3600 flaw evaluations or new flaws, a report summarizing the evaluation, along with inputs, methodologies, assumptions, and causes of the new flaw or flaw growth is to be provided to the NRC prior to the weld being placed in service other than modes 5 or 6."

This report satisfies this requirement. Please note that the conclusions presented herein are preliminary as the station will be performing a root cause evaluation for this issue.

The station is examining all twenty-seven (27) dissimilar metal (DM) butt welds within the scope of ASME Code Case N-770-1 during the current refueling outage using Section XI, Appendix VIII UT examination techniques. The affected weld will be repaired by full structural weld overlay during the current outage.

There are no regulatory commitments in this letter. If you have any questions concerning this letter, please contact Tom Loomis at (610) 765-5510.

Respectfully,

---

James Barstow  
Director - Licensing & Regulatory Affairs  
Exelon Generation Company, LLC

Attachment: Report Concerning Dissimilar Metal Weld Indication on Pressurizer Safety Relief Nozzle to Safe End Weld

Report Concerning Dissimilar Metal Weld Indication  
on Pressurizer Safety Relief Nozzle to Safe End Weld  
Page 1

cc: Regional Administrator, Region I, USNRC  
USNRC Senior Resident Inspector, CCNPP  
USNRC Project Manager [CCNPP]  
S. T. Gray, State of Maryland

DRAFT

**Purpose of Evaluation:**

During examinations performed to meet ASME Code Case N-770-1 and 10 CFR 50.55a(g)(6)(ii)(F) requirements, a change was observed from previous examinations in an axial indication in a pressurizer safety relief nozzle to safe end dissimilar metal butt weld that was mitigated by the Mechanical Stress Improvement Process (MSIP®) in 2006.

10 CFR 50.55a(g)(6)(ii)(F)(6) states: "For any mitigated weld whose volumetric examination detects growth of existing flaws in the required examination volume that exceed the previous IWB-3600 flaw evaluations or new flaws, a report summarizing the evaluation, along with inputs, methodologies, assumptions, and causes of the new flaw or flaw growth is to be provided to the NRC prior to the weld being placed in service other than modes 5 or 6."

**Evaluation**

ISI Weld 4-SR-1006-1, (pressurizer safety relief nozzle to safe end weld), also designated as line 4" CC10-1006 (W1) and 18-405A, was examined as required by the Inservice Inspection (ISI) Program during refueling outage CC1R23 per ASME Code Case N-770-1, Inspection Item E and 10CFR50.55a(g)(6)(ii)(F). The examination was a fully encoded phased array ultrasonic examination (PAUT) and was qualified to ASME Code Section XI, Mandatory Appendix VIII, Performance Demonstration for Ultrasonic Examination Systems, to detect and length and depth size circumferential and axial flaws within the specified examination volume from the outside surface. The examination met all additional industry NEI 03-08 guidance for examination of dissimilar metal piping welds susceptible to Primary Water Stress Corrosion Cracking (PWSCC). Full examination coverage was achieved to meet the requirements of ASME Code Case N-770-1 as conditioned by 10CFR50.55a as indicated in Table 1 below.

**Table 1**


**Required Volumetric Examination Coverage Achieved – 2016 Exams**

<b>Applicable Material</b>	<b>Circumferential Flaw Coverage</b>	<b>Axial Flaw Coverage</b>	<b>Combined Coverage Assessment</b>
PWSCC Susceptible (Inconel Alloy 82/182)	100%	100%	100%
SA-182 F-316 SS Safe-end	100%	100%	100%
Carbon Steel SS Clad Nozzle (SA-508, CL 2)	100%	100%	100%

The evaluation of the recorded UT data identified one axially oriented defect indication, which is contained within the weld material, exhibiting characteristics indicative of PWSCC. The measured depth of the indication was 81.6% through-wall including clad thickness. In addition, eight indications characterized as embedded fabrication flaws were detected during the data evaluation. See Figure 1 for a graphic representation of the indications in this weld as reported in 2010 along with an approximation of the 2016 flaw characteristics. To confirm that the flaw has changed since the last examination, another NDE vendor performed a manual encoded phased array UT examination and confirmed that the flaw was ID connected and had a through-wall extent of 67.2%.

**Figure 1**

**Annotated Figure 6-1 from 2010 EPRI Report Showing 2016 Flaw Approximate Size and Location**



This weld was mitigated by a mechanical stress improvement process (MSIP®) application in 2006. UT examination prior to the application of MSIP® identified an axial flaw in the same location as the 2016 flaw but was reported to be 8% through-wall and was acceptable per IWB-3500. UT examination immediately following the MSIP® application confirmed the indication was still present and at the same 8% through-wall depth. Inservice examinations in 2010 also reported the same through wall depth.


**Inputs**

Following the examination in 2006 and application of MSIP® a flaw evaluation of the axial flaw was performed and submitted to the NRC. A non-linear finite element analysis using the ANSYS Program was performed for the application of MSIP®. This analysis confirmed that an axial PWSCC flaw of 8% depth would be contained within the compressive hoop stress zone of

the post MSIP® stress profile at operating conditions. The post MSIP® stress profile is compressive from the ID of the pipe wall to an extent of approximately 50% of the through-wall depth. As shown in Figure 2, the hoop stress then becomes tensile out to the OD, reaching tensile stress values of about 55 ksi at 80% through-wall and reducing to about 44 ksi at the OD of the pipe.

**Figure 2**  
**2006 Post MSIP®+Operating Stress Calculated Hoop Stress Through Wall at Nominal Flaw Position (Path along butter/weld interface)**


<b>PATH DIST</b> (inch)	<b>HOOP STRESS</b> (psi)
0.000	2,278
0.068	-1,124
0.135	-7,546
0.203	-24,114
0.271	-42,931
0.338	-47,583
0.406	-49,002
0.473	-47,203
0.541	-34,280
0.609	-20,561
0.676	-8,410
0.744	-815
0.812	4,423
0.879	8,477
0.947	23,657
1.014	52,552
1.082	54,937
1.150	52,411
1.217	50,809
1.285	47,982
1.353	44,350



The results of the phased array encoded NDE examination performed in 2010 show that the axial flaw is widest at the ID (lower  $\sim 1/3^{\text{rd}}$  of the flaw), narrower in the center  $\sim 1/3^{\text{rd}}$  of the flaw and becomes wider in the top  $\sim 1/3^{\text{rd}}$  of the flaw (see Figure 3 below). The PWSCC flaw indication is narrower and consequently produces a weaker reflection in the middle through-wall range of the flaw where the compressive stress is the highest.

**Figure 3**

**2016 Axial Flaw Characteristics**



**Methodologies**

The fabrication and examination history of weld 4-SR-1006-1 was reviewed to confirm fabrication repairs, construction examination and inservice examination results. The inservice examinations from 2006 (pre- and post-MSIP<sup>®</sup>), 2010, and 2016 were reviewed to confirm if the flaw observed in 2016 was present and not called in the previous years. See Table 2 for a summary of exams performed. The post-MSIP<sup>®</sup> stress profiles were reviewed both in 2006 and 2010 to confirm the extent of the compressive stress region and effectiveness of the MSIP<sup>®</sup> application. Physical measurements were also performed in 2010 to confirm the MSIP<sup>®</sup> parameters were met.



**Table 2**

**4-SR-1006-1 DM Weld Inspection History**

Year	Radiography	Visual	Liquid Penetrant	Manual UT	Auto UT	Comments
1972	Yes		Yes			ASME III; 1 PT surface repair
1973		Yes	Yes	Yes		ASME XI Pre-Service Exam
1980			Yes	Yes		ASME XI Inservice Exam
2004		Yes				MRP-139
2006		Yes		Yes	Yes*	MRP-139, conventional manual & auto encoded pre- and post-MSIP
2010		Yes		Yes	Yes	MRP-139, manual PAUT, conventional auto encoded; surface preparation
2016		Yes		Yes	Yes	Code Case 770-1, Automated Encoded PAUT, confirmed with Manual Encoded PAUT

\* Circumferential scans only. Used for sizing of axial indication.

**Assumptions**

1. The MSIP® process was applied correctly.
2. The initially identified flaw pre-MSIP® had a greater through wall axial extent than characterized by the UT examination in 2006 (i.e. beyond the allowed 30% through wall extent).

**Causes of New Flaw/Flaw Growth**

Please note that the conclusions presented herein are preliminary as the station will be performing a root cause evaluation for this issue.

Three potential causes of the change in axial flaw through-wall extent from previous examinations were investigated:

- 1) The MSIP® application was ineffective allowing the existing axial flaw to grow,
- 2) A new indication developed in the weld, or
- 3) Prior NDE did not detect a pre-existing flaw larger than 30% through-wall prior to MSIP® (either ~80% through-wall or some value between ~30% and 80%)

The first potential cause was ruled out due to extensive reviews of the MSIP® implementation documentation and by obtaining independent field measurements to confirm the required parameters were met. The second potential cause was ruled out since the MSIP® application was found to have been performed correctly. It is not plausible that a new ID flaw could initiate and grow through the compressive stress region to the currently observed flaw depth. Also, this axial indication is in the same location as the previously identified axial indication just with a larger through-wall extent, so it would not be considered a new flaw.

The third potential cause is considered to be the most likely cause for the change in the axial indication's through wall extent from 2010 to 2016. The data collected in 2016 was reviewed by Exelon, EPRI and inspection vendor NDE personnel. After this review, the 2006 inspection vendor personnel reviewed the pre-MSIP® and post-MSIP® data collected in 2006 as well as the data collected in 2010. The team came to a consensus that the 2016 reported flaw is ID connected, the NDE data quality is good and the proper techniques were used.

The 2016 examination technique included a larger aperture search unit, additional angles, lower frequency, and enhanced focusing. This data imaged the previously reported axial flaw, but with a much deeper extent. After carefully reviewing the data it was determined that this optimized technique may have provided sufficient data to detect the connection of the flaws that were previously seen in the other examinations. Adjacent fabrication flaws and a potential repair area made depth sizing more difficult.

Due to limitations with the data collection during the 2006 pre-MSIP® examination, the upper portion of the flaw may not have been detected. After the MSIP®, the data quality was improved and some indications above the ID connected flaw were identifiable that were not in the pre-MSIP® data, but there was no clear connection between the two, thus they were treated as two unrelated indications. The stress profile indicates that the material between the inside surface connected flaw and the fabrication flaw is in compression, which could potentially reduce or eliminate the ultrasonic responses. This would produce the appearance that they are not connected. If this is true, the flaw would actually be much larger than originally thought and potentially the tip could have been outside of the compression zone which could allow continued flaw growth.