

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8006110096 DOC. DATE: 80/06/05 NOTARIZED: NO
 FACIL: 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co.
 AUTH. NAME: AUTHOR AFFILIATION
 LEWIS, S. R. Duke Power Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 Region 2, Atlanta, Office of the Director

DOCKET #
 05000287

SUBJECT: LER 80-008/03L-0: on 800507, shutdown was initiated when reactor protective sys channel B was lost due to inverter failure. Caused by blown fuses. Power to ac vital instrumentation restored manually & fuses replaced.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: Incident Reports

NOTES: M. Cunnennham - All amendments to
FSAR + changes to TELH specs

ACTION:	RECIPIENT		COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR ENCL	LTR ENCL	ID CODE/NAME		LTR ENCL	LTR ENCL
INTERNAL:	05 BC	4	4		02 NRC PDR	1	1
	09 I&E	2	2		11 MPA	3	3
	15 NOVAK/KNIEL	1	1		16 EEB	1	1
	17 AD FOR ENGR	1	1		18 PLANT SYS BR	1	1
	19 I&C SYS BR	1	1		20 AD PLANT SYS	1	1
	22 REAC SAFT BR	1	1		23 ENGR BR	1	1
	24 KREGER	1	1		25 PWR SYS BR	1	1
	26 AD/SITE ANAL	1	1		27 OPERA LIC BR	1	1
	28 ACCIDENT ANALYS	1	1		29 AUX SYS BR	1	1
	AD/ORP-DOR	1	1		AEOD	10	10
	BERLINGER, C.	3	3		DOUG MAY-TERA	1	1
	HANAUER, S.	1	1		JORDAN, E./IE	1	1
EXTERNAL:	03 LPDR	1	1		04 NSIC	1	1
	29 ACRS	16	16				

JUN 13 1980

DUKE POWER COMPANY
OCONEE UNIT 3

Report Number: RO-287/80-8

Report Date: June 5, 1980

Occurrence Date: May 7, 1980

Facility: Oconee 3, Seneca, South Carolina

Identification of Occurrence: Power Lost to RPS Channel B

Conditions Prior to Occurrence: 100% Full Power

Description of Occurrence:

At 0916 on May 7, 1980, static inverter 3DIB, which supplies power from 125 VDC instrumentation and control power panelboard 3DIB to AC vital instrumentation power panelboard 3KVIB, tripped while Oconee 3 was operating at 100% full power. At 0920 on May 7, power was restored to panelboard 3KVIB by manually bypassing static inverter 3DIB. However, one of the loads lost when power was interrupted was Reactor Protection System (RPS) Channel B. Since RPS Channel C had already been bypassed for testing, a shutdown was initiated at 0923 pursuant to Oconee Nuclear Station Technical Specification 3.5.1, which requires that a minimum of three of the four RPS channels be available. At 0930 RPS Channel B and the other lost loads were reset, and the unit was returned to 100% full power by 0950. On May 8 static inverter 3DIB was returned to service. At 1354 on May 9, the inverter again tripped. A power reduction was initiated but was terminated at 1402 after the inverter was again bypassed and RPS Channel B was reset. On May 16 power to panelboard 3KVIB was momentarily lost when an attempt was made to return the inverter to service. RPS Channel B was again reset, and inverter 3DIB was returned to service.

Apparent Cause of Occurrence:

Static inverter 3DIB tripped on May 7 due to a blown fuse. When the same fuse blew on May 9, an examination of all the logic boards in the inverter was made to identify any faulty components. A failed transistor was discovered, and it apparently had begun breaking down when the original inverter failure occurred, then cooled and operated properly for two days before failing completely. On May 16, a fuse blew when an attempt was made to transfer power to panelboard 3KVIB from the regulated AC power supply back to inverter 3DIB. The switch immediately reverted to the regulated AC line. It is possible that a bypass switch may have been closed when the transfer was attempted, allowing power to be supplied from both sources in parallel, and causing the fuse to blow.

Analysis of Occurrence:

A unit shutdown was initiated as required by Technical Specification 3.5.1 when power to RPS Channel B was lost, since RPS Channel C had already been bypassed for testing. Although the inverter failure caused a loss of the loads from panelboard 3KVIB, the remaining three AC vital instrumentation power panelboards

Analysis of Occurrence (Continued)

were in service, and sufficient instrumentation was available for a safe and controlled shutdown. In addition, power to panelboard 3KVIB was interrupted only briefly each time, since timely manual action was taken to bypass the inverter. However, this incident resulted in initiation of a shutdown as required by a limiting condition for operation, and must therefore be reported pursuant to Technical Specification 6.6.2.1.b(2), although it was considered to be of no significance with respect to safe operation, and the health and safety of the public were not affected.

Corrective Action:

The immediate corrective action was to bypass the inverter and reset the loads which were lost from panelboard 3KVIB. After the first occurrence, the fuse was replaced and the logic voltage and inverter wiring were checked. The examination of the logic boards after the second occurrence revealed the faulty transistor. After repairs were made the inverter was tested for four days before being returned to service. A further investigation revealed that the Ocone 3 inverters operate at higher temperatures than those for Ocone 1 and 2. An evaluation of possible effects on premature aging of components will be made.

EXHIBIT A

8006110096