

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION-NBR: 9609110005      DOC.DATE: 96/08/29      NOTARIZED: NO  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.  
 AUTH.NAME                      AUTHOR AFFILIATION  
 WILKIE, L.V.                    Duke Power Co.  
 HAMPTON, J.W.                  Duke Power Co.  
 RECIP.NAME                    RECIPIENT AFFILIATION

DOCKET #  
05000269

SUBJECT: LER 96-008-00: on 951106, declared emergency core cooling check valve inoperable. Caused by long term wear due to vibration. Scheduled valves for replacement in upcoming refueling outages. W/960829 ltr.

DISTRIBUTION CODE: IE22T    COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 PD	1 1	LABARGE, D	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	<del>FILE CENTER</del>	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	2 2
	NOAC MURPHY, G.A	1 1	NOAC POORE, W.	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM  
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

C  
A  
T  
E  
G  
O  
R  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T

Duke Power Company  
Oconee Nuclear Site  
P.O. Box 1439  
Seneca, SC 29679

J. W. HAMPTON  
Vice President  
(864)885-3499 Office  
(864)885-3564 Fax



**DUKE POWER**

**August 29, 1996**

**U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555**

**Subject: Oconee Nuclear Station Unit 1  
Docket Nos. 50-269, -270, -287  
Licensee Event Report 269/96-08, Revision 0  
Problem Investigation Process No.: 1-O95-1392**

**Gentlemen:**

**Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 269/96-08, concerning a potentially past inoperable valve in a High Pressure Injection Emergency Core Cooling System flow path.**

**This report is being submitted in accordance with 10 CFR 50.73 (a) (2) (v). This event is considered to be of no significance with respect to the health and safety of the public.**

**Very truly yours,**

  
**J. W. Hampton**

**/fts**

**Attachment**

**cc: Mr. S.D. Ebner  
Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St., NW, Suite 2900  
Atlanta, GA 30323**

**INPO Records Center  
700 Galleria Parkway  
Atlanta, GA 30339-5957**

**Mr. D. E. LaBarge  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Washington, D.C. 20555**

**Mr. M. Scott  
NRC Resident Inspector  
Oconee Nuclear Station**

9609110005 960829  
PDR ADOCK 05000269  
S PDR

*JE 22*  
*1/1*

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Oconee Nuclear Station, Unit 1	DOCKET NUMBER (2) 05000 269	PAGE (3) 1 of 1
---	--------------------------------	--------------------

TITLE (4)  
Emergency Core Cooling Check Valve Inoperable due to Wear

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER(S)
11	06	95	96	08	00	08	29	96		05000

OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR (Check one or more of the following) (11)																				
POWER LEVEL (10) 0	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 20.405(c)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 73.71(b)	<input type="checkbox"/> 73.71(c)	<input type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A)

LICENSEE CONTACT FOR THIS LER (12)		TELEPHONE NUMBER	
NAME Lanny V. Wilkie, Safety Review Manager		AREA CODE (864)	885-3518

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	
B	BG	V	V085	N						

SUPPLEMENTAL REPORT EXPECTED (14)				EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
Y	YES (f yes, complete EXPECTED SUBMISSION DATE)			NO		10	30	96

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)

On November 6, 1995, Unit 1 was at cold shutdown for a refueling outage. During a test, 1HP-153, a Velan Stop Check valve in a High Pressure Injection (HPI) Emergency Core Cooling System injection path, failed to pass the required flow rate. The valve was inspected, cleaned and polished internally, and successfully retested prior to unit restart. Valve 1HP-153 had previously failed a flow test on May 6, 1995, while Unit 1 was at cold shutdown. At that time, it was retested without maintenance and passed. If 1HP-153 is considered past inoperable from May 6 to Nov. 6, 1995, single failure of another HPI component could have prevented mitigation of certain small break LOCA scenarios. A past operability evaluation is in progress and is expected to find the valve operable. However, the evaluation is being performed by a vendor and has not been completed in the expected time frame. Management decided to make this report assuming the valve was past inoperable. A retraction or supplement will be issued after the operability evaluation is completed. The cause of the apparent failure is long term wear due to vibration. The valves in this application are scheduled for replacement in upcoming refueling outages.