

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S | C | N | E | E | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T  
01 | R | P | O | R | T | S | O | U | R | C | E | L | 8 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 9 | 7 | 0 | 1 | 9 | 1 | 1 | 9 | 7 | 1 | 8 | 8 | 1 | 0 | 0 | 4 | 7 | 1 | 8 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During the annual calibration check on the BWST level indication instrument  
03 | strings it was determined that one of the two channels was inoperable (out-of-  
04 | calibration). The error (~ 2 ft.) could have allowed the BWST level to be  
05 | below the required level without giving appropriate alarms. Adequate redundant  
06 | sources of borated water were available to mitigate potential accidents so  
07 | that no adverse effect on public health and safety could have resulted.

08 | \_\_\_\_\_

09 | I | E | 11 | E | 12 | X | 13 | I | N | S | T | R | U | 14 | T | 15 | Z | 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 | L | E | R / R | O | R | E | P | O | R | T | N | U | M | B | E | R | 7 | 8 | 21 | 22 | 0 | 2 | 3 | 24 | 25 | 26 | 27 | 0 | 1 | 28 | 29 | T | 30 | 31 | 0 | 32  
18 | E | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 1 | 0 | 0 | 0 | 37 | Y | 23 | Y | 24 | L | 25 | B | 0 | 4 | 5 | 26 | 47  
13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause for the channel inoperability was an error in the differential  
11 | pressure transmitter. No apparent cause for the transmitter being out of  
12 | calibration has been determined. The components causing the error were  
13 | recalibrated.

14 | \_\_\_\_\_

15 | H | 28 | 0 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Observed During Annual Test | 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36 | LOCATION OF RELEASE | 38  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 | 0 | 0 | 0 | 0 | 37 | NA | 38  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 | 0 | 0 | 0 | 0 | 40 | NA | 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PERSONNEL INJURIES NUMBER DESCRIPTION

19 | Z | 42 | NA | 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 | N | 44 | NA | 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PUBLICITY ISSUED DESCRIPTION

7810200170  
NAME OF PREPARER K. R. Wilson PHONE: (704) 373-8197