

CENTRAL FILES

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

June 26, 1979

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

79 JUN 29 A 8:45

USNRC REGION II
ATLANTA, GA

Re: RII:JPO
50-269
50-270
50-287

Dear Mr. O'Reilly:

This letter supplements the response to IE Bulletin 79-04 for Oconee Nuclear Station provided by my letter of May 30, 1979.

The modification to cross-connect the high pressure injection (HPI) headers necessitated reanalysis of the piping which had 1500 psi Velan check valves installed. This reanalysis, which was performed with the correct check valve weights, indicated that support modifications were required. These support modifications were made during the installation of the cross-connect modification.

It is expected that similar support modifications will be required for Oconee Units 1, 2 and that they will be made during the installation of the HPI cross-connect modification.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr.

by [Signature]

RLG:scs

*002
CCP*

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Construction Inspection
Washington, D. C. 20555

790330
OFFICIAL COPY

7908070 735 *Q*