

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7911070466 DOC. DATE: 79/10/31 NOTARIZED: NO
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 AUTH. NAME: LEWIS, S.R. AUTHOR AFFILIATION: Duke Power Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director

DOCKET #
05000269

Reportable Occurrence

SUBJECT: LTR 79-029/03L-1: on 790902, reactor vessel head flange was leaking. Caused by improper installation of incorrect O-rings. Procedures revised to assure use of correct O-rings.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+3
 TITLE: Incident Reports

NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR & CHANGES TO TECH SPECS.

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		L	T		L	T
	05 BC <i>ORB #4</i>	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACIDENT ANLYS	1	1
	29 AUX SYS BR	1	1	E JORDAN/IE	1	1
	HANAUER, S.	1	1	STS GROUP LEADR	1	1
	TMI-H STREET	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

NOV 9 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 48 ENCL 48

cf
A04

DUKE POWER COMPANY
OCONEE UNIT 1

Report Number: RO-269/79-29

Report Date: October 31, 1979

Occurrence Date: September 2, 1979

Facility: Oconee Unit 1, Seneca, South Carolina

Identification of Occurrence: Reactor Vessel Head Flange Leak

Conditions Prior to Occurrence: Hot Shutdown

Description of Occurrence:

On September 2, 1979, during an inspection of the Oconee 1 Reactor Building while the unit was in hot shutdown in anticipation of returning to power operation, water was observed to be draining from around the insulation on the reactor vessel. The insulation was removed, and steam was found to be leaking from the reactor vessel head flange. Cooldown of the unit was initiated at 0830 on September 3. On September 8, 1979, the reactor vessel head was removed, and the head flange was inspected. The inspection revealed that incorrect O-rings were in use, and that they had been installed improperly. No damage to the reactor vessel was observed, but the improper installation of the O-ring clips resulted in some small impressions on the head flange. The impressions were honed and contoured, and proper O-rings were installed prior to resetting the reactor vessel head.

Apparent Cause of Occurrence:

The reactor vessel head flange leakage resulted from improper installation of the O-ring clips during the refueling outage in September of 1978. Thermal cycling of the unit caused the clips to cut into the sealing surface, allowing slight leakage. The clips were not installed in accordance with the O-ring replacement procedure. Adding to confusion in the installation was the fact that incorrect O-rings were used. This error resulted when Duke Power Company provided to the supplier specifications which called for O-rings requiring sixteen clips rather than the type normally used at Oconee, which requires twelve clips. The supplier prepared manufacturing drawings from the inaccurate specifications, and Duke Power Company mistakenly approved those drawings.

Analysis of Occurrence:

Although slight impressions in the reactor vessel head flange resulted from improper installation of the O-ring clips, this was corrected, and no other damage was observed. The leakage was very slight, and was discovered at an early stage. If the leakage had not been discovered prior to startup of the unit, it would have been detected by the normal leakage monitoring methods before a serious degradation of the reactor coolant system boundary resulted. The leakage resulted in shutdown of the unit in accordance with Oconee Nuclear Station Technical Specification 3.1.6.2. The incident therefore resulted in conditions leading to a shutdown required by a limiting condition for operation, and must be reported pursuant to Technical Specification 6.6.2.1.b(2), although it did not affect safe operation of the unit or the health and safety of the public.

7911070 466

Corrective Action:

Correct O-rings were installed using the proper procedure, eliminating the source of the reactor vessel head leakage. The remaining incorrect O-rings in stock were destroyed to assure that no attempt would be made to install them in the future. In addition, the installation procedure has been revised to state explicitly the type of O-rings to be used and the correct method for installing them. The procedures have been reviewed with the responsible personnel to assure complete understanding. These steps should preclude the possibility of a recurrence of such an incident.

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S | C | N | E | E | 1 | 2 | 0 | 0 | - | 10 | 10 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 1 | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 34

CONT
011 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 16 | 19 | 7 | 0 | 19 | 10 | 2 | 7 | 9 | 8 | 1 | 10 | 13 | 1 | 7 | 9 | 9
7 8 REPORT SOURCE 60 61 COCKET NUMBER 62 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | During an inspection of the Reactor Building prior to startup of the unit,
013 | the reactor vessel head flange was discovered to be leaking slightly. The
014 | leakage was minor and was completely contained within the Reactor Building.
015 | If it had not been discovered prior to startup it would have been detected by
016 | normal leakage monitoring methods before serious degradation of the pressure
017 | boundary resulted. Thus, the incident did not affect safe operation of the
018 | unit or the health and safety of the public.

09 | C | A | 11 | A | 12 | C | 13 | V | E | S | I | S | E | L | 14 | A | 15 | Z | 16
7 8 SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 14 COMPONENT CODE 15 16 COMP. SUBCODE 17 18 VALVE SUBCODE 19 20
17 | 7 | 9 | 21 | 0 | 2 | 19 | 24 | 0 | 3 | 29 | 30 | L | 31 | 1 | 32
17 LER/RD REPORT NUMBER 21 EVENT YEAR 24 SEQUENTIAL REPORT NO. 27 OCCURRENCE CODE 29 REPORT TYPE 31 REVISION NO. 32
A | 18 | G | 19 | C | 20 | Z | 21 | 0 | 3 | 30 | Y | 22 | Y | 24 | L | 25 | U | 10 | 7 | 10 | 25
23 ACTION TAKEN 24 FUTURE ACTION 25 EFFECT ON PLANT 26 SHUTDOWN METHOD 27 HOURS 28 ATTACHMENT SUBMITTED 29 NPRA FORM SUB. 30 PRIME COMP. SUPPLIER 31 COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 | The head flange leakage resulted from improper installation of incorrect O-
111 | rings. The incorrect O-rings were supplied because inaccurate specifications
112 | were provided to the manufacturer by Duke Power. The installation procedure
113 | has been revised to assure that the correct O-rings are used and that they
114 | are properly installed.

15 | G | 29 | 0 | 0 | 0 | 29 | NA | B | 31 | Routine Reactor Building Inspection
7 8 FACILITY STATUS 9 10 % POWER 11 12 OTHER STATUS 13 14 METHOD OF DISCOVERY 15 16 DISCOVERY DESCRIPTION 17 18

16 | Z | 33 | Z | 34 | NA | NA
7 8 ACTIVITY CONTENT 9 10 RELEASED OF RELEASE 11 12 AMOUNT OF ACTIVITY 13 14 LOCATION OF RELEASE 15 16

17 | 0 | 0 | 0 | 37 | Z | 38 | NA
7 8 PERSONNEL EXPOSURES NUMBER 9 10 TYPE 11 12 DESCRIPTION 13 14

18 | 0 | 0 | 0 | 40 | NA
7 8 PERSONNEL INJURIES NUMBER 9 10 DESCRIPTION 11 12

19 | Z | 42 | NA
7 8 LOSS OF OR DAMAGE TO FACILITY TYPE 9 10 DESCRIPTION 11 12

20 | N | 44 | NA
7 8 PUBLICITY ISSUED 9 10 DESCRIPTION 11 12 NRC USE ONLY 13 14

NAME OF PREPARER S. R. Lewis

PHONE: (704) 373-8285