## REGULATOR REPORMATION DISTRIBUTION STITEM (RIDS)

ACCESSION NBR	8005200555 DOC.DA	TE: 80/05/13 NOTARIZED: NO	DOCKET #
FACIL:50-269	Oconee Nuclear Static	on, Unit 1, Duke Power Co.	05000269
AUTH.NAME	AUTHOR AFFILIAT	ION	, i ini
LEWIS, S.R.	Duke Power Co.		
RECIP, NAME	RECIPIENT AFFIL		
	Region 2, Atla	nta, Office of the Director	

- SUBJECT: LER 80=011/01T=0:on 800429,comparing startup procedure heatup curve w/Tech Specs,curve was incorrect on nonconservative side.Caused by personnel error misplacing Unit 1 curve w/Unit 2 procedure.Procedure revised.
- DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR LENCL L SIZE: 371 TITLE: Incident Reports

# NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR CHANGES TO TECH

						SPECS
RECIPIENT			RECIPIENT			36663
ID CODE/NAME	LITR	ENCL	ID CODE/NAME	LTTR	ENCL	
05 BC ORB #4	4	4		-	м "	
01 REG ETTE	1	1	02 NRC PDR	×1	1	
09 18E	2	2		3	3	
14 TAZEDO	1	1		1	1	
	i	1		1	. 1	
	<b>1</b> .	1		1	1	
	1	ī		· <b>1</b> ·	1	
	1	1		1	ī	
	1	1		1.	i -	
27 OPERA LIC BR	1	1		ī	1	
29 AUX SYS BR	1.	1		ī	1	
AEOD	10	10		3.	3	
DOUG MAY-TERA	1	1		1	1	
JORDAN, E./IE	1	1		-	-	
03 LPDR	1	1	04 NSTC	1	1	
29 ACRS	16	16	v t stway.	+	A 1	
	ID CODE/NAME 05 BC ORB #4 01 REG FILE 09 I&E 14 TA/EDO 16 EEB 18 PLANT SYS BR 20 AD PLANT SYS 23 ENGR BR 25 PWR SYS BR 27 OPERA LIC BR 29 AUX SYS BR AEOD DOUG MAY-TERA JORDAN, E./IE 03 LPDR	ID CODE/NAME LTTR 05 BC ORB #4 01 REG FILE 1 09 ISE 14 TA/EDO 1 16 EEB 18 PLANT SYS BR 1 20 AD PLANT SYS BR 1 23 ENGR BR 1 25 PWR SYS BR 1 25 PWR SYS BR 1 27 OPERA LIC BR 1 29 AUX SYS BR 1 AEOD DOUG MAY-TERA 1 03 LPDR 1 1 1 1 1 1 1 1 1 1 1 1 1	ID CODE/NAME LITR ENCL 05 BC ORB #4 01 REG FILE 1 1 09 I&E 14 TA/EDO 16 EEB 1 1 16 EEB 1 1 17 DPLANT SYS BR 1 1 20 AD PLANT SYS BR 1 1 23 ENGR BR 1 1 25 PWR SYS BR 1 1 27 OPERA LIC BR 1 1 29 AUX SYS BR 1 1 29 AUX SYS BR 1 1 10 10 DOUG MAY-TERA 1 1 10 10 11 11 11 11 12 11 12 12 12 12	IDCODE/NAME OF BC ORB #4LTTR ENCL 4IDCODE/NAME01REG1102NRCPDR09I&E2211MPA14TA/EDO1115NOVAK/KNIEL16EEB1117ADFOR18PLANTSYSBR119I&CSYS20ADPLANTSYS1122REAC23ENGRBR1124KREGER25PWRSYSBR1126AD/SITE27OPERALICBR128ACDENTANAL27OPERALICBR1AD/ORP-DORAEOD1010BERLINGER, C.DOUGMAY-TERA1JORDAN, E./IE1104NSIC	IDCODE/NAMELTTRENCLIDCODE/NAMELTTR05BCBCBCBCCA44401REGFILE1102NRCPDR109I&E2211MPA314TA/EDO1115NOVAK/KNIEL116EEB1117ADFORENGR18PLANTSYSBR119I&CSYSBR20ADPLANTSYS122REACSAFTBR123ENGRBR1124KREGER1123ENGRBR1126AD/SITEANAL125PWRSYSBR1126AD/SITEANAL127OPERALICBR1128ACDENTANLYS129AUXSYSBR11AD/ORP-DOR11AEOD1010BERLINGER, C.3333DOUGMAY-TERA11104NSIC103LPDR1104NSIC1	IDCODE/NAME OSLTTRENCLIDCODE/NAME CODE/NAMELTTRENCL05BCORS#4444401REG11102NRCPDR1109I&E2211MPA3314TA/EDO1115NOVAK/KNIEL1116EEB1117ADFORENGR116EEB1117ADFORENGR1116EEB1119I&CSYSBR1120ADPLANTSYSBR1122REACSAFTBR1120ADPLANTSYSBR1124KREGER11123ENGRBR1126AD/SITEANAL11124KREGER1128ACDENTANLYS11127OPERALICBR11AD/ORP-DOR11129AUXSYSBR11AD/ORP-DOR1114EOD1010BERLINGER, C.33333DOUGMAY-TERA111111103LPDR11104NSIC11

 DUKE POWER COMPANY OCONEE UNIT 1

Report Number: RO-269/80-11

Report Date: May 13, 1980

Occurrence Date: April 29, 1980

Facility: Oconee 1, Seneca, South Carolina

Identification of Occurrence: Procedural Heatup Curves Non-Conservative with Respect to Technical Specifications

Conditions Prior to Occurrence: 72% Full Power

### Description of Occurrence:

On April 29, 1980 the heatup curve in the Oconee 1 controlling procedure for unit startup was discovered to be less conservative than the Oconee Nuclear Station Technical Specification heatup curve for Oconee 1, Figure 3.1.2-1A, when the two curves were compared. The heatup and cooldown curves in use in the startup and shutdown procedures for all three units were then checked, and it was determined that the heatup curve in the Oconee 2 startup procedure was incorrect, but was more conservative than the corresponding Technical Specification curve. The Oconee 3 heatup curve and the cooldown curves for all three units were correct. An investigation of the eight Oconee 1 heatups which have been made since March 19, 1979, when the Technical Specification heatup curve was last revised, revealed that the heatup limitations were exceeded on two occasions. On August 4, 1979, the Technical Specification curve was exceeded by 5°F in the worst case, and on July 18, 1979, it was exceeded by 25°F in the worst case. The Oconee 1 startup procedure heatup curve was redrawn and approved on April 29, 1980, within three hours of discovery of the error.

#### Apparent Cause of Occurrence:

On April 18, 1980, a revision to the Oconee 1 startup procedure incorporating the revised Technical Specification heatup curve was approved. On May 23, 1979 the startup procedures for both Oconee 1 and Oconee 2 were rewritten. The Oconee 2 heatup curve was mistakenly replaced with the new Oconee 1 curve, and the previous Oconee 1 curve was reincorporated into the Oconee 1 procedure.

#### Analysis of Occurrence:

The Technical Specification curve which was in effect prior to March 19, 1980 was valid for up to 4.0 effective full power years (EFPY). Due to the procedural error which resulted in retaining this curve after May 23, 1979, the revised Figure 3.1.2-1A was exceeded twice at approximately 3.8 EFPY. Thus, the procedural curve based on the outdated Technical Specification curve still provided acceptable limiting conditions for operation, although it was not as conservative as the approved curve. This incident constituted operation of a unit when a parameter subject to a limiting condition for operation was less conservative than the least conservative aspect of the limiting condition for operation established in Technical Specification 3.1.2, and must therefore be reported pursuant to Technical Specification 6.6.2.1.a(2). However, this incident is not considered to be significant with respect to safe operation, and the health and safety of the public were not affected.

-2-

#### Corrective Action:

The Oconee 1 startup procedure was revised to incorporate the correct heatup curve. The heatup and cooldown curves for the other two units were also checked for accuracy. A review of all Oconee 1 heatups which were made using the incorrect procedure was completed to assure that no unacceptable operating conditions had occurred. In addition, the responsibility for redrawing the heatup and cooldown curves for the procedures has been more clearly delineated to provide further assurance that the curves are prepared correctly.

8005200555 NRC FORM 366 U. S. NUCLEAR REGULATORY COMMISSION (7.77) LICENSEE EVENT REPORT EXHIBIT A CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) J(I) CONT 5 0 0 0 2 6 9 7 0 4 2 9 8 0 8 0 5 1 3 8 0 9 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 0 1 SOURCE L ارفكا EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) As a result of the comparison of the Oconee 1 startup procedure heatup curve 0 2 to Technical Specification Figure 3.1.2-1A on April 29, 1980, the procedure 03 04 curve was discovered to be incorrect in the non-conservative direction. А review of the eight Oconee 1 heatups since the procedure was last revised 0 5 0 6 revealed two instances when the current curve was exceeded at approximately 3.8 EFPY. However, the procedure curve was valid for up to 4.0 EFPY. 0 7 Thus. this incident was not considered to be significant with respect to safe 0 8 operation, and the health and safety of the public were not affected. CAUSE CAUSE COMP. SUBCODE VALVE SUBCODE COMPONENT CODE 09 ZI Z 114 (12)  $Z \mid Z \mid Z \mid$ A Z (15) Z (16) 13 18 19 3 SEQUENTIAL OCCURRENCE LERIRO EVENT YEAR REPORT REVISION. REPORT NO. CODE NQ. 8 0 01 0 1 1 1 T 01 NUMBER 28 ACTION FUTURE TAKEN ACTION SHUTDOWN METHOD EFFECT SUBMITTED PRIME COMP. COMPONENT HOURS (22) FORM SUB. SUPPLIER MANUFACTURER ZI Z (20) \_(18)\_\_\_(19) 10 1 0 0 0 01 Z ZZZZ (25) 38 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The Oconee 1 and Oconee 2 startup procedures were both revised on May 23, 1979, 10 111 | and the newly-revised Oconee 1 heatup curve was mistakenly placed in the Oconee 2 procedure. The outdated heatup curve was reincorporated into the 1 2 Oconee 1 procedure. The Oconee 1 procedure has been corrected, and responsi-bility for redrawing the heatup and cooldown curves has been more clearly 14 delineated. 80 METHOD OF OTHER STATUS (30) DISCOVERY DESCRIPTION (32) E 3 0 7 2 3 NA A [31] Procedure 9 10 ACTIVITY CONTENT 13 80 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA NA 10 11 PERSONNEL EXPOSURES 80 NUMBER DESCRIPTION (39) TYPE 0 0 0 J J Z 38 1 7 NA 11 PERSONNEL INJURIES 80 DESCRIPTION (41) NUMBER NA 0 0 0 (40) 1 8 LOSS OF OR DAMAGE TO FACILITY (43) 80 NA Z (42) 9 10 PUBLICITY 80 DESCRIPTION (45) NA NRC USE ONLY SUED 0 S. R. Lewis NAME OF PREPARER PHONE: (704) 373-8285