

**CURTISS -
WRIGHT**

4600 East Tech Drive
Cincinnati, Ohio 45245
(513) 528-7900

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

SUBJECT: INTERIM 10 CFR PART 21 REPORT REGARDING DISPOSITION OF A
NONCONFORMANCE ON STRUTHERS-DUNN RELAY PART NUMBER
B255XCXPFHSC125V FOR PSEG NUCLEAR LLC

This letter serves as an interim report in accordance with 10 CFR 21.21 pertaining to a potential deviation associated with Struthers-Dunn relays P/N B255XCXPFHSC125V supplied to PSEG Nuclear LLC. Based upon information obtained from PSEG, a defect may exist with the reset coil of the Struthers-Dunn relay listed above. Preliminary observations indicate the reset coil had shorted (opened) during operation, and that no other sub-components of the relay are believed to be associated with this failure. PSEG is aware of Curtiss-Wright's investigation into this failure.

Evaluation of reportability in accordance with 10 CFR Part 21 is not able to be completed within the 60-day evaluation period due to the need for additional time to collect and evaluate the necessary information. It is currently expected that the evaluation of this defect will be completed by July 22, 2016.

If you have any questions pertaining to this information, please contact Timothy Franchuk, Director of Quality Assurance, at 513-201-2176.

Sincerely,



Timothy Franchuk
Director, Quality Assurance
Nuclear Division
Curtiss-Wright

cc: Regional Administrator, USNRC, Region II

IEZD
NRR