#### **Briefing on Indian Point Baffle Bolt Inspections**

April 19, 2016

TAIL


Protecting People and the Environment

**Enclosure 1** 



2


## **Baffle-former assembly**



Function of baffle-former assembly is to direct coolant flow through the core. It also provides lateral support to the core during a seismic event or loss-of-coolant accident (LOCA).




.



Stainless steel bolts are 5/8" dia. x ~2" long and attach the baffle plates to the former plates to form the baffle assembly Baffle-former bolt head 10-18-10 Tack weld Locking tab

3

## **Potential consequences**




4

- No impact from a few bolt failures
- Large numbers of failed bolts could cause:
  - Flow leakage through gaps between adjacent plates
    - Fuel degradation (baffle jetting erosion)
    - Increased core bypass flow (less fuel cooling)
  - Baffle plates impacting fuel assemblies during LOCA event, potentially leading to grid deformation

## **Baffle-Former Bolt Inspections – Regulatory Basis – First 40 years**

#### 10 CFR 50.55a "Codes and Standards"

- Incorporates by Reference ASME Code, Section XI
- Section XI mandates general visual condition examination of reactor vessel internals (RVI) every 10 years
- All PWRs have been performing every 10 years during the first 40 years of operation



- Guidance for PWR RVI aging management program is based on NRC-approved topical report MRP-227-A
- To manage aging of RVI, IP2 committed to enhanced inspections following MRP-227-A, consistent with NRC guidance

•

# MRP-227-A Inspection Requirements for Baffle-Former Bolts

- Ultrasonic (UT) Examination
- Initial (baseline) inspection between 25-35 effective full power years
- 100% of bolts
- Inspect every 10 years thereafter

Nestrybon

 All PWRs with baffle-former bolts must perform these inspections (most PWR designs)

ZP2 - off

## 2016 Indian Point Results

#### **Entergy Unit 2 Activities**

- Conducted visual examination of 1232 baffle-edge bolts
- Conducted ultrasonic and visual examination of 832 baffleformer bolts
- Results:
  - All baffle edge-bolts were acceptable
  - (227) total baffle-former bolt identified as failed
    - 182 ultrasonic testing failures
    - 31 visually identified as protruding
    - 14 inaccessible, conservatively assumed failed
- Bolts to be sent out for analysis by Westinghouse and LPI, an independent engineering firm

#### 2016 Indian Point Activities

#### Indian Point Unit 2 (IP2)

- Removing degraded bolts using mechanical extraction and Electrical Discharge Machining (EDM) tools
- Developing plans to replace baffle-former bolts
- Developing safety evaluation of as-found condition
- Developing analysis to support baffle-former assembly return to service (if not all bolts are replaced)

#### Indian Point Unit 3 (IP3)

- Developing evaluation of baffle-former assembly considering information from IP2
- Evaluating schedule for future baffle bolt examinations, currently planned in 2019

#### NRC Inspections to Ensure Safety Of Indian Point Unit 2

Evaluated Entergy's Inservice Inspection to verify their examination methods/acceptance criteria were appropriate

- Baseline Inspections being planned and implemented to:
  Verify Entergy completes bolt replacement and analyses that ensure the baffle-former assembly will perform intended safety functions
  - Review Entergy's evaluation of the as-found conditions to independently assess the safety significance and whether there were prior performance issues

## NRC Inspections to Ensure Safety Of Indian Point Unit 3

NRC staff's current assessment is that IP3 is safe to operate
 Smaller number of failed bolts expected because:

- IP3's baffle-former bolts are exposed to less radiation than those in IP2
- Less operating time than IP2
- No current indication of fuel leaks which would indicate significant problems with baffle-former bolts
   Analysis for other Westinghouse plants have demonstrated

significant margin regarding the total number of required bolts Will reassess IP3 functionality based on results of IP2 analysis currently in progress

- Resident Inspectors onsite to independently assess if conditions change
- NRC will review Entergy's evaluation of IP3 and their plans for future baffle-former assembly exams

Protecting People and the Environment

11

# **Operating Experience – Inspection Results**

- Only one plant found broken baffle-former bolts via Section XI visual inspections
- Over 12,000 baffle-former bolts ultrasonically inspected to date
- Only 3.6% defective (potentially cracked)
- Excluding IP2 results, 2% defective
- Several plants of similar age or older to IP2 have inspected
- These older plants have found no more than 10% defective bolts

Protecting People and the Environment

lind

# Industry Response

- Entergy will perform root cause analysis
- Results will be shared with the industry through the EPRI Materials Reliability Program (MRP)
- EPRI considers MRP-227-A a living program
- Changes can be made in response to operating experience

# NRC Response

- Region I and NRR monitoring IP2 analysis, repair and root cause, and IP3 implications
- Decide if regulatory action needed based on:
  - Operating experience with baffle-former bolt inspections
  - IP2 root cause analysis results
  - Operability of IP2 under all design basis conditions with asfound defective bolts
- Potential actions could include acceleration of baseline inspection schedule, shorten reinspection interval, or no change
- Could implement through modification to guidance, or generic communication if warranted by safety impact