

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8502050613 DOC. DATE: 85/02/01 NOTARIZED: NO DOCKET #
 FACIL: 50-275 Diablo Canyon Nuclear Power Plant, Unit 1, Pacific Ga 05000275
 50-323 Diablo Canyon Nuclear Power Plant, Unit 2, Pacific Ga 05000323
 AUTH. NAME AUTHOR AFFILIATION
 SHIFFER, J.D. Pacific Gas & Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 KNIGHTON, G.W. Licensing Branch 3

SUBJECT: Forwards responses to NRC Allegations 1430 & 1431 re pipe supports raised during 850114-17 piping audit. Based on analysis results, location or type of support precluded as cause for overstress.

DISTRIBUTION CODE: B021D COPIES RECEIVED: LTR. 1 ENCL. 27 *on encl* SIZE: 25
 TITLE: OR/Licensing Submittal: Combined General Distribution

NOTES: J Hanchett 1cy PDR Documents. 05000275
 OL: 09/22/81
 J Hanchett 1cy PDR Documents. 05000323

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	NRR LB3 BC 05	1 1	NRR LB3 LA	1 0
	SCHIERLING, H 01	1 1		
INTERNAL:	ACRS 29	8 <u>05</u>	ADM/LFMB	1 0
	ELD/HDS2	1 0	NRR/DE/CEB 09	1 1
	NRR/DE/MTEB	1 1	NRR/DHFS DEPY12	1 1
	NRR/DHFS/HFEB16	1 1	NRR/DHFS/LGB	1 1
	NRR/DL DIR	1 0	NRR/DL/ORAB	1 0
	NRR/DL/SSPB	1 0	NRR/DSI/ADRS	1 0
	NRR/DSI/AEB 28	1 1	NRR/DSI/CPB 11	1 1
	NRR/DSI/CSB 10	1 1	NRR/DSI/ICSB 18	1 1
	NRR/DSI/METB 13	1 1	<u>NRR/DSI/PSB 21</u>	1 1
	NRR/DSI/RSB 25	1 1	<u>REG FILE</u> 04	1 1
	RGNS	1 1	RM/DDAMI/MIB	1 0
EXTERNAL:	LPDR 03	2 2	NRC PDR 02	1 1
	NSIC 06	1 1	PNL GRUEL, R	1 1
NOTES:		1 1		

THE UNIVERSITY OF CHICAGO
DEPARTMENT OF CHEMISTRY
58 CHEMISTRY BUILDING
CHICAGO, ILLINOIS 60637
TEL: 773-936-3700

RECEIVED
JAN 10 1964

TO: DIRECTOR, NATIONAL BUREAU OF STANDARDS
WASHINGTON, D.C. 20535

FROM: DR. J. H. GOLDSTEIN, CHICAGO
DR. R. F. W. WILSON, CHICAGO

SUBJECT: POLYMERIZATION OF VINYL MONOMERS
BY CATIONIC MECHANISM

1. INTRODUCTION
2. EXPERIMENTAL
3. RESULTS AND DISCUSSION
4. CONCLUSIONS
5. REFERENCES

ACKNOWLEDGMENT
This work was supported by the National Science Foundation under Grant No. CHE-60000.

REFERENCES
1. J. H. Goldstein, R. F. W. Wilson, J. Polym. Sci., 1963, 12, 123.
2. J. H. Goldstein, R. F. W. Wilson, J. Polym. Sci., 1963, 12, 135.
3. J. H. Goldstein, R. F. W. Wilson, J. Polym. Sci., 1963, 12, 147.

PACIFIC GAS AND ELECTRIC COMPANY

PG&E + 77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

JAMES D. SHIFFER
VICE PRESIDENT
NUCLEAR POWER GENERATION

February 1, 1985

PGandE Letter No.: DCL-85-041

Mr. George W. Knighton, Chief
Licensing Branch No. 3
Division of Licensing
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555


Re: Docket No. 50-275, OL-DPR-80
Docket No. 50-323
Diablo Canyon Units 1 and 2
NRC Allegations 1430, 1431, and 1432

Dear Mr. Knighton:

During the NRC Staff piping audit on Diablo Canyon Unit 2 conducted on January 14-17, 1985, the Staff requested a written response to NRC Allegations 1430, 1431, and 1432 raised by C. Stokes related to pipe supports. Enclosed are PGandE's responses to these allegations. The response to Allegation 1432 was previously provided to Mr. H. Polk, NRR, on January 17, 1985.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelope.

Sincerely,


for J. D. Shiffer

Enclosure

cc: R. T. Dodds
J. B. Martin
H. E. Schierling
Service List

8502050613 850201
PDR ADDCK 05000275
PDR

B021
1/27

1944
1945
1946
1947

1948
1949
1950
1951
1952

1953
1954
1955
1956
1957

1958
1959


ENCLOSURE

NRC Allegation #1430


It is alleged that:

The first of my concerns involves the placement of rigid supports near elbows. Two cases come to mind --


- (1) A branch line being subjected to axial buckling, or tensile stress.



From the NRC and PGandE documents, it is impossible to tell if NRC or PGandE looked at this potential problem.



I am concerned about the 15,000 feet of pipe qualified soley (sic) by span rule. (Reference page 5 of IDVP re-evaluation in proposed SSER). This appears to have been overlooked.



Response:

This allegation raises the following questions:

- i) For a branch line, was the placement of the first support from the header piping done correctly?
- ii) Did the 15000 feet of small bore piping qualified by the span method correctly consider the issue in (i) above?

In Unit 1, the location and type of the first support on a branch line in each direction from the header pipe is based on the following:

- a) The branch piping between this support and the connection to the header pipe has sufficient flexibility to accommodate seismic and thermal displacements of the header pipe.
- b) The branch piping has stresses less than the code allowable stress when subjected to the header displacements.
- c) The support load is of reasonable value (about 300 lbs or less for small bore piping).

The small bore piping sample program was specifically designed to include the design considerations of piping and equipment seismic anchor movement (SAM) and thermal anchor movement (TAM). The sample program analysis results provided the basis for accepting the 15,000 feet of small bore piping and supports for the SAM design consideration. However, the sample program results caused verification of all small bore piping subjected to large SAM from equipment. Further, all stainless steel piping above 165⁰F and carbon steel piping above 200⁰F was computer analyzed (using ME101), thereby eliminating the possibility of any TAM-related problems. These analyses would preclude either the location or the type of support as the cause for piping overstress.



Sections 3.3.3, 5.2, and 5.3 of the IDVP Interim Technical Report 61 thoroughly investigated the above aspects of the span method.


For Unit 2, all Class 1 piping was analyzed by computer addressing SAM and TAM, as applicable.



NRC Allegation #1431

It is alleged that:

The second concern is placement through the construction tolerance of six inches for the location of a pipe support on piping. This factor must be considered in combination with a special support configuration. But the pipe stress group had separated the two supports when we received them at the pipe support group. As a result, they improperly were considered in isolation. I am aware of this happening at least once because I corrected it:



This pair of supports are usually shown on the stress isometric drawings as being at the same location. It is a special case where the pipe must be seismically restrained but allowed to move for thermal reasons. It is possible by using the six-inch construction tolerance to place the snubber (see above) on the opposite side of the rigid restraint. As a result, when the pipe moves, the snubber clamp binds on the rigid restraint, either causing the restraint to fail or the pipe to overstress. This is also applicable to a spring-can and as rigid restraint in the lateral direction.

Response:

This allegation describes a possibility of interference between a pipe support and external structural steel or between two adjacent pipe supports due to the Construction Group's use of the six-inch pipe support installation tolerance.

During the pipe support design phase, it is not always possible to identify all interferences. Hence, walkdowns were performed to provide added assurance that the systems are installed such that they will perform their intended design function.



Mr. Stokes appears to be concerned that pipe supports separated by six inches or less were only considered in isolation. This is not so. All adjacent pipe support hardware which was known at the time of design was considered. Only supplementary steel which was subsequently installed could not be considered. Mr. Stokes also appears to be concerned that in certain circumstances use of a 6-inch tolerance criterion could result in pipe overstress. In either case, the potential interference or the condition of overstress would be identified during the walkdown program, thereby, eliminating any potential overstress condition.

All conditions of improper location of supports or overstress were identified and corrected according to appropriate procedures as part of the various piping walkdown programs that were performed at the Diablo Canyon site. (References: Project Procedure P-36, "Walkdown of Piping During Hot Functional," and Project Instructions I-50, "Stress Walkdown for Design Class I Systems.")

Attached are examples from these walkdowns identifying and correcting such interferences.

ATTACHMENT I

Heatup Walkdown Problem Report #15-1


Problem Description: Pipe clamp of support #15-115SL interferes with steel of support #575-188R due to thermal growth of the pipe.

Resolution: Both supports redesigned to resolve this problem.

ATTACHMENT II

Stress Walkdown Problem Resolution #220

Problem Description: Pipe support #74-2V interferes with 1-inch diameter heat-traced pipe due to thermal growth of the line.



Resolution: Pipe clamp offset to avoid interference with the heat-traced pipe. Insulation on pipe at north notched to avoid interference due to offset of clamp.

ATTACHMENT III


Stress Walkdown Problem Report #1034

Problem Description: Interference between coupling and steel of pipe support due to thermal growth of the line.

Resolution: Support steel to be notched to avoid the interference.

ATTACHMENT IV


This is an excerpt from the referenced Hot Piping Walkdown Report addressing the thermal growth concern.



NRC Allegation #1432

It is alleged that:

Issues which the ACRS discussed on Friday, July 13, 1984, involve the radial expansion of large bore lines. There is a construction tolerance of 1/16-inch on a side with a 1/6-inch tolerance, for a total gap of 3/16-inch maximum. Many of the large bore lines, such as Main Steam, Residual Heat Removal (RHR), and Reactor Coolant System (RCS), which are subjected to high pressure and temperature, will expand more than the 3/16-inch maximum (zero-inch possible) and bind up in the support, rather than slide through as intended.



The approximate radial expansion of this line can be one inch. This line will grow in length and diameter roughly at the same uniform rate. It will therefore lock up at approximately only one inch of the axial growth. It still has three inches more to go. I estimated four inches movement as a conservative assumption in Figure 4, because at the meeting on Friday Mr. Shipley admitted movements of six inches in some lines. Two possibilities are likely. -- (1) the pipe stronger than the support - support fails, (2) support stronger than pipe -- pipe fails.

Response:


This allegation raises the concern that the radial expansion of high temperature piping, such as main steam piping, may be greater than the gap (3/16-inch) around the pipe at frame-type supports. This would result in the pipe binding in the support and causing overstress of the pipe or support.

The 3/16-inch clearance provided for supports in the restrained direction is adequate to accommodate radial thermal growth of the main steam and residual heat removal piping without closing the gaps, assuming maximum line temperature.



The hot functional and power ascension testing programs have verified that the actual gaps provided in the field are adequate to permit radial expansion of the pipe and permit axial movement of the pipe without binding. The final report on the results of the hot piping walkdown was submitted to the NRC on December 20, 1984 (PGandE letter No. DCL-84-382). Attachment IV is excerpted from the referenced Hot Piping Walkdown Report addressing the thermal growth concern. The NRC also participated in the physical inspections (walkdowns) during the Unit 2 Hot Functional Test Program.

For Unit 1, as noted in SSER-25 (page 2-2), the NRC concluded that in satisfaction of Item 5 of License Condition 2.C.(11) the actual thermal movements are in reasonable agreement with calculated movements.



ATTACHMENT I

Heatup Walkdown Problem Report

Heatup Walkdown Package Number: 15 Problem No.: 15-1

Piping System Description:.. STEAM GEN 3 BLOWDOWN OUTSIDE CONTAINMENT

Analysis Number of Piping Where Problem is Located: 1-113
(1st only one)

Describe Problem: PIPE CLAMP ON 15-115 SL IS UP AGAINST STEEL
OF ADJACENT HANGER S75-188R, CAUSING AN UNINTENTIONAL AXIAL
RESTRAINT. THE CALCULATED MOVEMENT IS 1.6" AXIALLY.
CLAMP SHOULD BE RELOCATED 1 3/4" N.W. TO ALLOW THIS MOVEMENT.
(REMOVE INSULATION FIRST TO DETERMINE IF PIPE CONFIGURATION WILL
ALLOW MOVING CLAMP) (.80" NORMAL, .88" DILATION, 1.60" ACCIDENT
WITH DILATION) RHN '2-3-84

Temperature: ALL LEVELS 160°

By: Stephen Beckey 1-31-84
Date


[Signature] 2-1-84
Date


Resolution: Move clamp on 115 SL 5" downstream to other
side of 188R. KAP 2-10-84 REDESIGNS FOR ABOVE SUPPORTS
ISSUED TO RESOLVE INTERFERENCE. ISSUE DATE 2-10-84
PER DCI-EP-17476 RO

By: Ken Palmer 2-24-84
Date

DC Tatequin
9/11/84
ALL PAPER WORK
COMPLETE 2-24-84
[Signature]

Handwritten notes on the left margin: "Check photo", "Cope Plate", "Support from 115 SL", "of 188R".







- LEGEND**
- NODAL POINT
 - FIXED END
 - PAINED END
 - SPRING HANGER
 - SNUBBER

ANALYSIS 1-113
REV. 2

REF. PG# E DWG.
NO. 445877.



DETAIL A-A



DESIGN VERIFICATION	
CLIENT	DCPO
JOB NO.	9999-OR0
CALCIPROB NO.	1-113
BY: AJ	DATE: 5-1-83
CHKD: [Signature]	DATE: 5-2-83

20-019
-78

DIABLO CANYON NUCLEAR
POWER PLANT UNIT #1
STEAM GENERATOR BLOWDOWN
PIPING FROM PENT. 39 TO
FLOOR ANCHOR AT EL. 140'-0"
(SHT. 1 OF 1)



11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

AREA GE

LINE 1-K16-1042-2½ V P E

HANGER SYMBOL

57S
188R

EL 100'-0"

(STM. GEN. BD)


⊥ (H) REST

LOC ON DWG 500057

76-11-2


DESIGN CLASS I
CODE CLASS E'

CALLED NORTH




LOCATION PLAN

⊗ NO WELD



SECTION B-B




SECTION D-D

UPGRADED TO CL I
REQUIREMENTS
AS BUILT REQUIRED

NO OF ASSEMBLIES REQUIRED 1

NO	REQD	MATERIALS PER ASSEMBLY			
1	1	L 3" x 3" x 3/8" — 2'-0 1/8" LONG (CUT TO FIT)			
2	1	TS 4" x 2" x 1/4" — 0'-10 1/2" LONG			
3	1	TS 4" x 3" x 1/4" — 0'-11 1/2" LG.			
4	1	L 3" x 3" x 3/8" — 0'-7" LONG DELETED			
5	2	MT 2 x 6.5 — 0'-3" LONG (FIELD GROUND TO FIT EXISTING TEE)			
6	1	L 3" x 3" x 3/8" — 1'-1 1/2" LONG (CUT ONE LEG OFF)			
7	1	L 3" x 3" x 3/8" — 3'-4 7/8" LONG (CUT TO FIT)			
8	1	2 1/2" PIPE CLAMP (FIG 212)			
9	2	3/4" φ SHELL TYPE CONCRETE FASTENER W/BOLT			
10	1	R 1/2" x 10" — 0'-10" LONG			
12	1	L 3" x 3" x 3/8", 4'-11" LG (CUT TO FIT)	15	1	R 1/2" x 3" x 5" LG.
13	1	1 3/4" x 3" x 1/2" THK FISH R	DSGN		DRAWING NO
14	1	3" x 3" x 1/2" THK FISH R	DWN GR 4/15/80		049262
			CHKD SJ 4/18/82		

RM INDEXED REV.



AREA GE

EL 100'-0"

LINE I-K16-1042-2 1/2 VP

(STM. GEN. BD.)


PLATE SYMBOL

L(H) REST

LOC ON DWG 500057



76-111 REV 3-76



ELEV. VIEW A-A

INDEXED REV. ...

DSGN
DWN SH 4/15/80
CHKD 4/18/80

DRAWING NO
049262



76-11-1 Rev 3-76

AREA GE

LINE 1-K16-1042-2 1/2" V P E

DANGER SYMBOL




EL 100'-0"

(STM. GEN. DD.)

L (H); REST

LOC ON DWG 500057



EL. 113'-0"

EL. 109'-2"
2 1/2" PIPE
(REF)


SECTION C-C

INDEXED REV.

DSGN	DRAWING NO	
DWN GH 4/6/80	049262	
CHKD SJ 4/18/80		

PROJECT: DIABLO CANYON UNIT: /

SHEET NO OF SHTS PG & E CO



76-146 (82)

AREA <u>1-GE</u>	LINE <u>1-K16-1042-2 1/2 IP-E</u>	HANGER SYMBOL <u>1, H RESTRAINT</u>
EL <u>100'-0"</u>	<u>STM GEN 1-3 BLOW TNK HDR</u>	LOC ON DWG <u>500057</u>



REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
4	8-16-82	AS BUILT PER M.E. LEPPKE MEMO DATED 6-1-82.	JS	JS	JEB	MS	JEB	JEB
5	12-10-82	CHANGED SUPPORT DESIGN CLASS II TO CLASS I ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION DCN. DCI-E-P-5060 UPGRADED TO DESIGN CLASS I	J.L	J.L	RE	dkk	DAVE CRYER (BRC)	JPS
6	5-7-83	REVISED TO INCORPORATE FCT # 692 NO FIELD WORK REQUIRED	KP	ST	D. Patel	ED	RKC	DJC
7	8-16-83	REVISED TO INCORPORATE FCT # 3290 C, AND REMOVED MVMT DATA ON SMT 204. NO FIELD WORK REQUIRED.	J.L	J.L	PI.	JRF	ASM	JPS
8	2/10/84	DELETED ITEM-4, REVISED ITEMS 2 & 3, ADDED ITEM 15. APPROVED FOR CONSTRUCTION PER DCN, DC-1-E-P-17470. GENERIC DCN	E.L.	ST	RKC	J	EJ	JPS

NOTES:


SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 4 SHEETS)

<u>204</u>	<u>204 A</u>	<u>204 B</u>	<u>204 X</u>																
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20

DSGN <u>JS</u>	DRAWING NO
DWN <u>JS</u>	<u>049262</u>
CHKD <u>JEB</u>	

PROJECT: <u>DIABLO CANYON</u>	UNIT: <u>ONE</u>	204X OF	SHS	P G & E CO	7
					ISSUE
					REV

PM INDEXED BY



71-16 Rev 3-76

AREA 1 GE

EL 100'-0"



LINE 1-K16-1042-2 1/2" P
 STM. GEN. 1-3 BLOW DN
 TK. HDR. M.S. SVS. 04

REGISTER SYMBOL
 Y SNUBBER



LOC ON DWG 500057

DESIGN CLASS I
 CODE CLASS E
 CALLED NORTH




ELEV. VIEW. A-A

NO	REQD	MATERIALS PER ASSEMBLY
1		DELETED
2		DELETED
3		DELETED
4	1	C.S. PL. 1/2" x 5" x 5" LG.
5	1	M4 X 13, 3'-6 1/4" LG.
6	1	C.S. PL. 3/4" x 14 1/2" x 11 1/2" LG.
7	4	3/4" Φ H&TI SHELL TYPE ANCHOR
8		DELETED
9		DELETED

DSGN EFT
 DWN C DELUCA
 CHKD JPN

DRAWING NO
 049313

DIAGN



AREA 1GE



SEE SHT 136

HANGER SYMBOL
Y SNUBBER




EL 100'-0"


LOC ON DWG 500057




VIEW F-F
(SNB. OMITTED FOR CLARITY)



SECT. C-C




OFFSET DETAIL



SECT. E-E
ITEMS 5, 6, 7, 14 & 16
OMITTED FOR CLARITY

NO	REQD	MATERIALS PER ASSEMBLY
10		DELETED
11	1	PSA-10 NF (SER. #14577) W/PSA NFR.B. C.S. = 3 5/8"; H.S. = 2 1/2"
12	1	TRANS. KIT FOR PSA-10 W/2" SCH. 80 EXT. PIPE (LENGTH BY FIELD)
13	1	SPC-14-025 FOR PSA-10 (1" PH PIN)
14	2	C.S. PL. 1/2" x 3" x 11 1/2"
15		DELETED
16	4	C.S. PL. 1/2" x 3" x 4 3/4" LG.

PROJECT: DIABLO	DSGN EPT	DRAWING NO	049313
	DWN C. DELUCA		
	CHKD JBL		
DATE: 10/10/80	DATE: 10/10/80	DATE: 10/10/80	DATE: 10/10/80



76-1483(4-87)

AREA 1-GE

LINE 1-K16-1042-2 1/2 V E
 STM. GEN. 1-3 BLOWN DN
 T.K. HDR. MS SYS 04

HANGER SYMBOL
 Y SNUBBER



EL 100'-0"


LOC ON DWG 500057

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
A	02/10/84	EXIST. ITEM # 13 SSC-14-025, REPLACED BY SPC-14-025 TO AVOID INTERFERENCE WITH SUPPORT NO. 575-198R DUE TO SYSTEM HEAT UP. APPROVED FOR CONSTRUCTION PER DCN-DC-1-E-P-17476/REV.0 GENERIC DCN.	VK	ST	hlg	gms	gms	cg

NOTES:

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 3 SHEETS)

136	136A	136X																	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
DSGN V KATCOOL											DRAWING NO								
DWN ST											049313								



STRESS WALKDOWN PROBLEM RESOLUTION

Package No. 8-110-3-Y-A

Problem No. 220

System No. 10

Line No. SI-119-8

Analysis No. 8-110 R3

Building AUX

Building(s) AUX

Key INT. - SUPPORT

Fuel Load Required? yes

no

Walkdown Team Ralph Noristering
Alan Hugh Bursale

Date 8-24-83

Date 8-24-83

Item for Resolution: 74/2V WILL HIT A 1" ϕ .
HEAT TRACED PIPE @ \approx el. ~~97'7"~~ 97'7".
SI-119-8 MOVES 1/4" SOUTH. SEE ATTACHED
SKETCH.

Disposition Requested From: Engineering Construction

GC to cope ^{insulation} ~~with~~ and offset pipe clamp
as described on the attached drawing.

Final Resolution: DCTateorian 8/25/83

Issued to Mosely 9/30
Support complete

MR

By: WR Ball Dept. Mech

Date: 10-12-83


Walkdown: E H Borsley
R Noristering

Date: 10-25-83

Date: 10-25-83


Approved by: DC Tateorian

Date: 1/15/84



PG&E MEGH & NU. ENG. DEPT.
DIABLO CANYON PROJECT
ANALYSIS ISSUE

ANAL. NO. 8-110 REV. 3
CASE ALL
ANALYST P. SMITH 7/5/83
CHECKER G. RAQUELSANTOS 7/7/83
APPROVED S. CHITNIS DATE 7/8/83




DIABLO CANYON NUCLEAR
POWER PLANT UNIT NO. 1
PART OF RHR, SAFETY
INJECTION AND
CONTAINMENT SPRAY.

ANALYSIS 8-110
PGE REF. DWG NO.
446542
446546
446541


ANALYSIS 8-110

- LEGEND**
- FIXED SUPPORT
 - X PINNED SUPPORT
 - NODAL POINT
 - X SNUBBER
 - X SPRING




SUBJECT _____

MADE BY ASB DATE 8/23/83 CHECKED BY _____ APPROVED BY _____



* CUT INSULATION AND MOVE ROD HANGER (CLAMP) $\frac{1}{2}$ ' NORTH
ON UPPER 1" ϕ LINE



ATTACHMENT III

STRESS WALKDOWN PROBLEM REPORT

Package No. W049-05-01-C
Unit No. 2
System No. 9

Problem No. 1034
Priority No. 400
Line No. 2-56-3866-2-7

Analysis No. W049-05-RO1

Building CONTAINMENT

Walkdown Team ALLEN J. MAHNCKE


Date 8-8-84

ROBERT YAZDANI

Date 8-9-84

Item for Resolution:

2-2" interference exist between coupling & D.L.S. RESTRAINT. ALSO DLS RESTRAINT IS NOT INDICATED ON ISOMETRIC.



Disposition Requested From:

SFHO

SFHO TO EVALUATE THE D.L. SUPPORT AND UNINTENTIONAL AXIAL RESTRAINT IN N-W DIRECTION.

4/1/84

Final Resolution: CON. HFT

Predicted displacements are .15" (HFT), 1.07" (Normal), 2.5" (Accident), all in direction of DLS. DLS is not in analysis. Delate DLS. *7/1/84*

THIS IS OPEG SCOPE. PLS. SEND TO OPEG P/S GROUP FOR RESOLUTION *Magan*

By: K. S. AHAND Dept. MT SWE

Date: 11/08/84


Walkdown Team: _____

Date: _____

Approved by: _____

Date: _____

Stress Walkdown Group Leader




SUPPORT SK2216-99

MEMBER 3180 TO 0 AT NODES 3199

LOADING CONDITION NO.		F(KIPS)	FX(KIPS)	FY(KIPS)	FZ(KIPS)	MX(IN-K)	MY(IN-K)	MZ(IN-K)
104	THNMAX	0.0000	-0.0000	0.0000	-0.0000	0.000	-0.000	-0.000
105	THNMIN	0.0013	-0.0000	0.0013	-0.0000	0.000	-0.000	-0.000
204	THAMAX	0.0001	-0.0001	0.0000	-0.0001	0.000	-0.000	-0.000
205	THAMIN	0.0044	-0.0000	0.0044	-0.0000	0.000	-0.000	-0.000
206	THMAX	0.0001	-0.0001	0.0000	-0.0001	0.000	-0.000	-0.000
207	THMIN	0.0044	-0.0000	0.0044	-0.0000	0.000	-0.000	-0.000
5	UH+THNMX+DE+SA	0.0975	-0.0001	-0.0975	-0.0001	-0.000	-0.000	-0.000
6	UH+THNMX-DE+SA	0.0515	0.0001	-0.0515	0.0000	0.000	0.000	0.000
7	UH+THMX+DDF+SA	0.1040	-0.0003	-0.1040	-0.0002	-0.000	-0.000	-0.000
8	UH+THMN-DDF+SA	0.0419	0.0002	-0.0419	0.0001	0.000	0.000	0.000
9	UH+(HOS+SAM)	0.2996	-0.0002	-0.2996	-0.0001	-0.000	-0.000	-0.000
10	UH-(HOS+SAM)	0.1494	0.0002	0.1494	0.0001	0.000	0.000	0.000



		DX(INCHES)	DY(INCHES)	DZ(INCHES)	RX(RADS)	RY(RADS)	RZ(RADS)
104	THNMAX	-0.000	0.000	-0.000	0.000026	-0.000003	-0.000000
105	THNMIN	-0.189	0.000	-0.208	0.000000	-0.002829	-0.000000
204	THAMAX	-0.000	0.000	-0.000	0.000126	-0.000003	-0.000000
205	THAMIN	-0.892	0.000	-0.983	0.000000	-0.013389	-0.000000
206	THMAX	-0.000	0.000	-0.000	0.000126	-0.000003	-0.000000
207	THMIN	-0.892	0.000	-0.983	0.000000	-0.013389	-0.000000
5	UH+THNMX+DE+SA	0.929	-0.001	0.379	0.000496	0.005532	0.000000
6	UH+THNMX-DE+SA	-1.108	-0.001	-0.584	-0.000974	-0.008294	-0.000000
7	UH+THMX+DDF+SA	1.800	-0.000	0.733	0.001168	0.010038	0.000000
8	UH+THMN-DDF+SA	-2.683	-0.001	-1.712	-0.001546	-0.023360	-0.000000
9	UH+(HOS+SAM)	2.400	0.001	0.965	0.001317	0.010258	0.000000
10	UH-(HOS+SAM)	-2.391	-0.003	-0.964	-0.001821	-0.010188	-0.000000

ANALYSIS 11/2/83
 REV. 1
 PAGE 2 OF 5
 SECTION 11



AREA <u>2G</u>	LINE <u>2-52-3002-4</u> E	HANGER SYMBOL 6 Y & H _L -RESTR.
EL. <u>100'-0"</u>	NOS. <u>2-K-3243-3</u> E	LOC. ON DWG. <u>500906</u>


DESIGN CLASS II
CODE CLASS E



NO. OF ASSEMBLIES REQUIRED 1

NO.	REQD	MATERIALS
1	1	L 4" x 3 1/2" x 1/2" (3 MEMBERS) T.L. = 6'-2" (2) 4" LG. EA. (1) 5'-6" LG.
2	2	L 3" x 3" x 3/8", B 5/8" LG. EA.
3	1	L 3" x 3" x 3/8", O-11 5/8" LG.
4	2	SHIM PL 3" x 1/2", 4" LG.
5	1	STIFF. PL 3" x 1/2", 3 1/2" LG.

REV 1: ADDED ITEMS 2 TO 5. APPROVED FOR CONST. *[Signature]*



ATTACHMENT IV

SECTION 2

THERMAL RADIAL EXPANSION OF LARGE DIAMETER PIPING WITH REGARD TO POTENTIAL BINDING DUE TO RIGID SUPPORT GAP CLOSURE

2.0 Description of Program, Development, and Followup Information

On large diameter hot piping a concern may exist that due to the small clearances in the restrained direction of a rigid frame-type pipe support, the radial expansion of the pipe may be sufficient to close the gaps and result in the pipe binding within the restraint. At Diablo Canyon the only piping where this condition may exist is the feedwater, main steam, and diesel engine exhaust lines.

The diesel engine exhaust lines were addressed as a part of the design process in that all of the frame type restraints were replaced by sway struts where this concern does not exist.

The feedwater and main steam lines have thermal diametric growths of approximately 1/16" and 1/8", respectively. Because these growths are about the size of the seismic gap typically designed into a pipe support, no special reviews were undertaken. However, this issue is addressed as a part of the piping walkdowns in that if the pipe was to bind it would become apparent by virtue of the actual piping movements being different than predicted. As a result, the binding problem would be identified and corrective action taken.

In fact, this happened during the Unit 2 hot Functional testing on the main steam piping. As a result of observing one pipe support to be binding, the walkdown team undertook a special review to walkdown all of the frame-type supports on main steam to see if any others were binding. As a result, approximately eight such supports were modified to provide increased clearance.

A cold walkdown of feedwater piping and supports will be performed prior to fuel load to assure the existence of sufficient gaps. The hot walkdown of this piping will occur during power ascension and will consider hot support gaps, as well as piping deflections and clearances.

In summary, the normal design review process and the existing walkdown programs will ensure that this potential binding condition will not occur in the final accepted piping and pipe support configuration.

