REGULATERY INFORMATION DISTRIBUTION SYSTEM (RIDS)

| ACCESSION NBR: | 8708030226 | DOC. DATE: | 87/07/28 | NOTARIZED |): NO | | DOCKET # |
|----------------|---------------|-------------|-------------|-----------|---------|----|----------|
| FACIL: 50-323 | Diablo Canyon | Nuclear Po | ower Plant, | Unit 2, | Pacific | Ga | 05000323 |
| AUTH. NAME | AUTHOR A | FILIATION | | | | | |
| WILSON, S. D. | Pacific G | as & Electi | ric Co. | | | | |
| SHIFFER, J. D. | Pacific G | as & Electi | ric Co. 🍐 | | | | |
| RECIP. NAME | RECIPIEN | AFFILIAT | ION | | | | |

SUBJECT: LER 85-029-00: on 850827, controlled leakage exceeding limit of Tech Spec 3.4.6.2 occurred. Caused by improper installment of reactor coolant pump seal injection flow measurement orifices, cited on 870629. Orifices corrected. W/870728 ltr.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR ____ ENCL ____ SIZE: ______ TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

13

| | RECIPIENT | COPI | ES | RECIPIENT | COPI | IES | |
|-----------|----------------|------|------|-----------------|------|------|--|
| | ID CODE/NAME | LTTR | ENCL | ID CUDE/NAME | LIIR | ENCL | |
| | PD5 LA | 1 | 1 | PD5 PD | 1 | 1 | |
| | TRAMMELL,C | 1 | 1 | | × | | |
| INTERNAL: | ACRS MICHELSON | 1 | 1 | ACRS MOELLER | 2 | 2 | |
| | AEOD/DOA | 1 | 1 | AEOD/DSP/NAS | 1 | 1 | |
| • | AEOD/DSP/ROAB | 2 | 2 | AEOD/DSP/TPAB | 1 | 1 | |
| • | DEDRO | 1 | 1 | NRR/DEST/ADE | 1 | 0 | |
| | NRR/DEST/ADS | 1 | 0 | NRR/DEST/CEB | 1 | 1 | |
| | NRR/DEST/ELB | 1 | 1 | NRR/DEST/ICSB | 1 | 1 | |
| | NRR/DEST/MEB | 1 | 1 | NRR/DEST/MTB | 1 | 1 | |
| | NRR/DEST/PSB | 1 | 1 | NRR/DEST/RSB | 1 | 1 | |
| | NRR/DEST/SGB | 1 | 1 | NRR/DLPQ/HFB | 1 | 1 | |
| | NRR/DLPQ/QAB | 1 | 1 | NRR/DOEA/EAB | 1 | 1 | |
| | NRR/DREP/RAB | 1 | 1 | NRR/DREP/RPB | 2 | 2 | |
| | NRE PMASKILRB | 1 | 1 | NRR/PMAS/PTSB | 1 * | 1 | |
| | REG FILE 02 | 1 | 1 | RES DEPY GI | 1 | 1 | |
| | RES TELFORD, J | 1 | 1 | RES/DE/EIB | 1 | 1 | |
| | RGN5 FILE 01 | 1 | 1 | | | | |
| EXTERNAL: | EG%G GROH, M | 5 | 5 | H ST LOBBY WARD | 1 | 1 | |
| | LPDR | 2 | 2 | NRC PDR | 1 | 1 | |
| | NSIC HARRIS, J | 1 | 1 | NSIC MAYS, G | 1 | 1 | |

. . .

.

| · . | | |
|-----|--|---|
| 1 | LICENSEE EVENT REPORT (LER) | |
| ه ' | PACILITY NAME (1) | (2) PAGE (3) |
| | DIABLO CANYON UNIT 2 | 13121311 0F 1014 |
| | CONTROLLED LEAKAGE IN EXCESS OF TECHNICAL SPECIFICATION LIMIT | .5 CAUSED |
| | EVENT DATE (8) LER NUMBER (8) REPORT DATE (7) OTHER FACILITIES INVOLVED (8) | DOCKET NUMBERIS |
| | | |
| | | |
| | 0 8 2 7 8 5 8 5 0 2 9 0 0 0 7 2 8 8 7 | |
| | MODE (3) 2 | |
| | Tower 50.73(a)(2)(1) | |
| | CTHER (Specify in Abstract below and in Test, NRC Form | |
| | LICENSEE CONTACT FOR THIS LER (12) | |
| | | TELEPHONE NUMBER |
| | | |
| | COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) | |
| | CAUSE SYSTEM COMPONENT WANDFAC REPORTABLE TO MPADS | |
| | | |
| | | |
| | | |
| | | |
| | ABSTRACT (16) | |
| | · · | - |
| | On August 27, 1985, Unit 2 entered Mode 2 (Startup), with controlled leak exceeding the limit of Technical Specification (TS) 3.4.6.2. Plant perso performing Surveillance Test Procedure (STP) M-54, "Measurement of Reactor Pump Seal Injection Flow," were unaware that two of the four flow measure orifices (FE-144 and FE-115) had previously been installed backwards in t coolant pump (RCP) seal injection lines. On June 29, 1987, the incorrect installation was discovered by Instrumentation and Controls technicians. Engineering Department determined that the reversed orifice plates had ca erroneous RCP seal injection flowrate indication approximately 20 percent less than the actual flowrate for each of the two seal injection lines. | <pre>kage pnnel pr Coolant ement the reactor t The aused an t (1.5 gpm)</pre> |
| | The orifices were installed correctly and the flow measurement surveillant the RCP seal injection lines was completed July 2, 1987. | nce test of |
| | The cause of this event was lack of adequate detail in the written instruor orifice installation. | uctions for |
| | All flow measurement orifices that provide data for TS-related surveilla were inspected to verify proper orientation. Four other orifice plates installed backwards. These incorrect installations did not adversely af surveillance tests or system performance. The Work Planning Center will written work instruction for proper installation of orifice plates. | nce tests were found fect any TS provide |
| | 1567S/0051K B708030224 B70728 PDR ADDCK 05000323 S PDR | 5620 |

--· ·

. **)**

1 r .

· ·

1

| UICENSEE EVENT F | Form 366A LICENSEE EVENT REPORT (LER) TEXT CONTINUATION LICENSEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED OMB NO, 3150-01 EXPIRES: 8/31/68 | | | | | | | | | |
|---|---|-----------|----------|--|--|--|--|--|--|--|
| FACILITY NAME (1) | DOCKET NUMBER (2) | LER NU | WBER (6) | PAGE (3) | | | | | | |
| : | | YEAR SEQU | NUMBER | | | | | | | |
| DIABLO CANYON UNIT 2 | 0 5 0 0 0 3 2 | 3 8 5 _ 0 | 2 9 0 0 | 0 2 OF 0 4 | | | | | | |
| TEXT (If more space is required, use additional NRC Form 366A's) (17) | | | | <u>1 </u> | | | | | | |
| I. Initial Conditions | | | • | | | | | | | |

Unit 2 was in Mode 2 (Startup).

II. <u>Description of Event</u>

A. Event:

On August 27, 1985, Unit 2 entered Mode 2 (Startup), with controlled leakage exceeding the limit of Technical Specification (TS) 3.4.6.2. Plant personnel performing Surveillance Test Procedure (STP) M-54, "Measurement of Reactor Coolant Pump Seal Injection Flow," were unaware that two of the four flow measurement orifices (FE-144 and FE-115) had previously been installed backwards in the reactor coolant pump (RCP) seal injection lines. Controlled leakage is defined as the seal water flow supplied to the RCP seals.

On June 29, 1987, the incorrect installations were discovered by Instrumentation and Controls personnel while the unit was in Mode 4 (Hot Shutdown) during a refueling outage. The Engineering Department determined that the reversed orifice plates had caused an erroneous RCP seal injection flowrate indication approximately 20 percent (1.5 gpm) less than the actual flowrate for each of the two seal injection lines. It was determined that since the orifice plates were incorrectly installed, results of the monthly required STP M-54 had been adversely affected four times, exceeding the 40 gpm controlled leakage limit of TS 3.4.6.2.

The orifices were installed correctly and the flow measurement surveillance test of the RCP seal injection lines was completed July 2, 1987.

B. Inoperable structures, components or systems that contributed to the event:

None

3

C. Dates and approximate times for major occurrences:

| 1. | June - | July | 1985: | The | flow | meas | ureme | nt o | rifices | on | RCP | 2–1 | | |
|----|--------|------|-------|------|------|-------|--------|------|---------|-----|-------|-----|----|-----|
| | | | | and | 2-4 | were | rever | sed | during | mai | ntena | nce | on | RCP |
| | | | | seal | inj | ectio | on lin | es. | - | | | | | |

2. August 27, 1985, December 7, 1985, January 24, 1986, and March 28, 1986:
Event dates - STP M-54 was performed to determine RCP seal injection flow. The "as left" data combined with the reversed orifice error exceeded the 40 gpm controlled leakage criteria of TS 3.4.6.2.

1567S/0051K

, • • ۲-۱ . .

.

~

1.

I c .

| NRC For (9-83) | m 36fA | • | LICENSEE EVEN | T REPOI | RT (LER) TEXT CONTINU | ATION | U.S. NUCLEAR I APPROVE EXPIRES: 8 | REGULATORY COMMIS D OMB NO. 3150-0104 1/31/88 | SION |
|-------------------|-----------|--|---|---|---|--|--|---|------|
| FACILIT | Y NAME | (1) | | | DOCKET NUMBER (2) | LER / | NUMBER (6) | PAGE (3) | |
| | DIAB | LO CAI | NYON UNIT 2 | | 0 15 10 10 10 312 3 | 8 ₁ 5 _ 0 | | 0 0 1 3 OF 0 | 14 |
| TEXT (#) | more spec | e is require | d, use additional NRC Form 366A'sI (17) | | | | <u></u> | | |
| | | | 3. June 29, 1987 | : | Discovery date – In FE-144 and FE-115 i maintenance. | correct i dentified | nstallation I during cor | of rective | |
| | | | 4. July 2, 1987: | | The orifices were in flow-measurement sur seal injection line | nstalled rveillanc s was com | correctly a ce test of t pleted. | nd the he RCP | |
| | i. | D. | Other systems or s | econdar | y functions affected | • | | | |
| | | - | None | | • | | | ų | |
| | | Ε. | Method of discover | y: | | | t | | |
| | | | An Instrumentation installation durin | and Co g maint | ntrols technician di enance on the associ | scovered ated flow | the incorre transmitte | ct rs. | |
| | | F. | Operator actions: | | - | | | _ | |
| | | | Not required | | | | | · | |
| | | G. | Safety system resp | onses: | | | | | |
| | | L | None required | | | | | | |
| | III. | <u>Caus</u> | <u>e of Event</u> | | · · · | | | • | |
| | | Α. | Immediate cause: | | | , | | | |
| | | | RCP seal injection installed backward 1.5 gpm less than caused the control exceeded. | n flow n Is which actual lled lea | heasurement orifices a caused indicated fl flowrate for each of kage limit of TS 3.4 | FE-115 ar owrate to the two .6.2 to b | nd FE-144 we be approxi orifices. be inadverte | re mately This ntly | |
| | | Β. | Root cause: | • | | | | | |
| | | | Adequate detail wa proper installatio | is not p on and c | provided in the writt prientation of a flow | en instru measuren | uctions to e nent orifice | nsure • | |
| | IV. | <u>Anal</u> | ysis of Event | _ | | | | | |
| • | | An e inje at n Anal test conc inje | ngineering analysis ction flow in exces ormal operating pre ysis Report and sur ing were used to de luded that the mini ction tank would ha | was co s of th ssure. veillar termine mum saf ve beer | nducted to determine e TS limit on the re Graphical data prov ice test data from ce the safety injectio ety injection flowra met. Thus, no safe | the effe quired sa ided in i ntrifugal n flowrai te throug ty~consec | ect of RCP s afety inject the Final Sa I charging p te margin. gh the boron quences or | eal ion flow fety ump It was | |
| | 1567 | ، ۱۳۵۱ S/005 | IK | | s evenu. | · | | | |

-

η

+

.

•

•

÷ . ۲. · · ·

.

| 19-831 LICENSEE EVENT | LICENSEE EVENT REPORT (LER) TEXT CONTINUATION | | | | | | |
|---|---|-----------|----------------------|--------------------|-----|--------|--|
| FACILITY NAME (1) | DOCKET NUMBER (2) | | LER NUMBER (6 | ;} | PAG | GE (3) | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| DIABLO CANYON UNIT 2 | 0 5 0 0 0 3 2 3 | 8 5 | _0 2 9 | _0_0 | 0 4 | DF 0 4 | |
| TEXT (If more space is required, use additional NRC Form 366A's) (17) | ······································ | · · · · · | | | ··· | | |

V. <u>Corrective Actions</u>

- A. The Work Planning Center will provide adequate written instruction for proper installation of orifice plates.
- B. The Mechanical Maintenance department and the Work Planning Center will conduct a training session on the written instructions for orifice installation.
- C. The Training Department will include orifice installation instructions at the quarterly maintenance training seminar and in the Quality Control Specialist training program.
- D. All flow measurement orifices that provide data for TS-related surveillances were inspected to verify proper orientation. Four other orifice plates were found to be installed backwards. These incorrect installations did not adversely affect any TS surveillance tests or system performance.
- VI. Additional Information
 - A. Failed components:

None

B. Previous LERs on similar events:

None

NRC FORM 366A (9-83)

.

•

· ·

· .

PACIFIC GAS AND ELECTRIC COMPANY

PGrie -

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

JAMES D. SHIFFER VICE PRESIDENT NUCLEAR POWER GENERATION

July 28, 1987

PGandE Letter No.: DCL-87-183

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D.C. 20555

Re: Docket No. 50-323, OL-DPR-82 Diablo Canyon Unit 2 Licensee Event Report 2-85-029-00 Improper Installation of Reactor Coolant Pump Seal Injection Orifices Caused Controlled Leakage in Excess of Technical Specification Limit

Gentlemen:

Pursuant to 10 CFR 50.73(a)(2)(i), PGandE is submitting the enclosed Licensee Event Report concerning the improper installation of reactor coolant pump seal injection orifices which caused controlled leakage in excess of the Technical Specification limit.

This event has in no way affected the public's health and safety.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelope.

Sincerely, Shiffer

Enclosure

cc: L. J. Chandler J. B. Martin P. P. Narbut B. Norton CPUC Diablo Distribution INPO

1567S/0051K/DY/1714

DC2-87-TN-N082

и ,

r · · · чарана и страна и стр И страна и стр

.

、 • , . ۰. ۲۰

ç