

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9205040024 DOC. DATE: 92/04/24 NOTARIZED: NO DOCKET #  
 FACIL: 50-323 Diablo Canyon Nuclear Power Plant, Unit 2, Pacific Ga 05000323  
 AUTH. NAME AUTHOR AFFILIATION  
 HUG, M.T. Pacific Gas & Electric Co.  
 RUEGER, G.M. Pacific Gas & Electric Co.  
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 91-006-01: on 910926, leakage of approx 1.3 gpm noted from diaphragm valves CVCS-2-8471 & CVCS-2-548 in charging pump suction line. Caused by personnel error. Preventive maint program will be revised. W/920424 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 7  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD5 LA	1 1	PD5 PD	1 1
ROOD, H	1 1		
INTERNAL: ACNW	2 2	ACRS	2 2
AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
AEOD/ROAB/DSP	2 2	NRR/DET/EMEB 7E	1 1
NRR/DLPQ/LHFB10	1 1	NRR/DLPQ/LPEB10	1 1
NRR/DOEA/OEAB	1 1	NRR/DREP/PRPB11	2 2
NRR/DST/SELB 8D	1 1	NRR/DST/SICB8H3	1 1
NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
REG FILE 02	1 1	RES/DSIR/EIB	1 1
RGN5 FILE 01	1 1		
EXTERNAL: EG&G BRYCE, J.H	3 3	L ST LOBBY WARD	1 1
NRC PDR	1 1	NSIC MURPHY, G.A	1 1
NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 32 ENCL 32

R  
I  
D  
S  
/  
A  
D  
D  
S  
/  
A  
D  
D  
S

AO-4  
llp



Pacific Gas and Electric Company

77 Beale Street  
San Francisco, CA 94106  
415/973-4684

Gregory M. Rueger  
Senior Vice President and  
General Manager  
Nuclear Power Generation

April 24, 1992

PG&E Letter No. DCL-92-086



U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

Re: Docket No. 50-323, OL-DPR-82  
Diablo Canyon Unit 2  
Licensee Event Report 2-91-009-01  
10 CFR 100 Dose Limits Potentially Exceeded in the Event of a  
Design Basis Loss of Coolant Accident Recovery as a Result of  
Valve Leakage

Gentlemen:

Pursuant to 10 CFR 50.73(a)(2)(ii)(B), PG&E is submitting the enclosed revision to Licensee Event Report (LER) 2-91-009-00. This revision is being submitted to report the results of PG&E's investigation into the root cause of this event and the determination of applicable corrective actions.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Gregory M. Rueger'.

Gregory M. Rueger

cc: Ann P. Hodgdon  
John B. Martin  
Philip J. Morrill  
Harry Rood  
CPUC  
Diablo Distribution  
INPO

DC2-91-TN-N087

Enclosure

5714S/85K/PJT/2246

Handwritten initials or a signature in the bottom right corner of the page.



# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) <b>DIABLO CANYON UNIT 2</b>										DOCKET NUMBER (2) <b>0 5 0 0 0 3 2 3</b>						PAGE (3) <b>1</b> OF <b>6</b>							
TITLE (4) <b>10 CFR 100 DOSE LIMITS POTENTIALLY EXCEEDED IN THE EVENT OF A DESIGN BASIS LOSS OF COOLANT ACCIDENT RECOVERY AS A RESULT OF VALVE LEAKAGE</b>																							
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)													
MON	DAY	YR	YR	SEQUENTIAL NUMBER			REVISION NUMBER			MON	DAY	YR	FACILITY NAMES				DOCKET NUMBER (S)						
09	26	91	91	-	0	0	9	-	0	1	04	24	92					0 5 0 0 0					
OPERATING MODE (9) <b>N</b>			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR: (11)																				
POWER LEVEL (10) <b>0 0 0</b>			<input checked="" type="checkbox"/> 10 CFR <u>50.73(a)(2)(i)(B)</u> <input type="checkbox"/> OTHER - _____ (Specify in Abstract below and in text, NRC Form 366A)																				
LICENSEE CONTACT FOR THIS LER (12)																							
<b>MARTIN T. HUG, SENIOR REGULATORY COMPLIANCE ENGINEER</b>												TELEPHONE NUMBER											
												AREA CODE <b>805</b>			NUMBER <b>545-4005</b>								
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																							
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC													
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)			MONTH			DAY			EAR		
<input type="checkbox"/> YES (if yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO																							

## ABSTRACT (16)

On September 26, 1991, with Unit 2 defueled, leakage of approximately 1.3 gallons per minute (gpm) was identified from diaphragm valves CVCS-2-8471 and CVCS-2-548 in the charging pump suction line during the performance of a hydrostatic test. The diaphragms in both valves were replaced and the valves tested satisfactory.

On October 4, 1991, at 1645 PDT, an evaluation of the leakage discovered September 26, 1991, determined that the control room and exclusion area boundary 10 CFR 100 dose limits could be potentially exceeded during the design basis recirculation phase of loss of coolant accident (LOCA) recovery. On October 4, 1991, at 1800 PDT, a four-hour, non-emergency report was made to the NRC in accordance with 10 CFR 50.72(b)(2)(i).

The root cause of body-to-bonnet leakage in valve CVCS-2-8471 was personnel error in that the valve was not included in the plant preventive maintenance program. The root cause of body-to-bonnet leakage from valve CVCS-2-548 could not be determined.

The preventive maintenance program will be revised to include diaphragm replacement frequency and bolt torquing for diaphragm valves.



# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)
DIABLO CANYON UNIT 2	0 5 0 0 0 3 2 3	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2   OF   6	
		91	- 0 0 9	- 0 1		

TEXT (17)

## I. Plant Conditions

Unit 2 was defueled at the time of the event as part of the Unit 2 fourth refueling outage.

## II. Description of Event

### A. Event:

#### Summary

On October 4, 1991, at 1645 PDT, with Unit 2 defueled, an evaluation determined that leakage from valves CVCS-2-548 and CVCS-2-8471 could have resulted in the control room (NA) and exclusion area boundary 10 CFR 100 dose limits being exceeded during the recirculation phase of recovery from a design basis loss of coolant accident (LOCA). CVCS-2-548 and CVCS-2-8471 are located in the chemical and volume control system (CVCS) (CB).

#### Discussion

On September 26, 1991, a hydrostatic test was performed during a scheduled refueling outage, following installation of a new valve in the CVCS. The hydrostatic test pressurized the charging pump (BQ)(P) suction line portion of the CVCS.

During the performance of the hydrostatic test, diaphragm valves CVCS-2-548 (CB)(V) and CVCS-2-8471 (CB)(V) were identified to be leaking. The identified leakage was coming from between the valve body and bonnet on both valves. Leakage from both valves was estimated to be approximately 1.3 gallons per minute (gpm) total.

CVCS-2-548 and CVCS-2-8471 are located in the boric acid blender (CB) (MIX) room on the 100 foot elevation of the auxiliary building (NF). Both valves are pressurized during post-LOCA recirculation. The boric acid blender room ventilation exhausts to the plant vent without passing through charcoal filters (VF)(FLT). Therefore, any radioactive material that may be released as a result of leakage from these valves would be released to the plant vent filtered only by HEPA filters.

On October 4, 1991, at 1645 PDT, evaluation of the hydrostatic test data was performed to confirm the leak rates and post-LOCA recirculation pressure. The evaluation determined that leakage from CVCS-2-548 and CVCS-2-8471 could have resulted in the control room and exclusion area boundary 10 CFR 100 dose limits being exceeded during the recirculation phase of recovery from a design basis LOCA.



# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)	
DIABLO CANYON UNIT 2	0 5 0 0 0 3 2 3	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		91	-	0 0 9			
		3	OF	6			

TEXT (17)

On October 4, 1991, at 1800 PDT, a four-hour, non-emergency report was made to the NRC in accordance with 10 CFR 50.72(b)(2)(i).

Similar tests were performed during previous Units 1 and 2 refueling outages, but no similar problems were identified.

**B. Inoperable Structures, Components, or Systems that Contributed to the Event:**

Leakage through CVCS-2-548 and CVCS-2-8471 caused the event.

**C. Dates and Approximate Times for Major Occurrences.**

1. September 26, 1991: Event date - CVCS-2-8471 and CVCS-2-548 were observed to be leaking during the performance of a hydrostatic test.
2. October 4, 1991, 1645 PDT: Discovery date - The results of an evaluation indicated that the leak from CVCS-2-548 and CVCS-2-8471 could cause the control room and exclusion area boundary 10 CFR 100 dose limits to potentially be exceeded during the recirculation phase of LOCA recovery.
3. October 4, 1991, 1800 PDT: A four-hour, non-emergency report was made to the NRC in accordance with 10 CFR 50.72(b)(2)(i).

**D. Other Systems or Secondary Functions Affected:**

None.

**E. Method of Discovery:**

Test engineers observed leakage while performing a hydrostatic test.

**F. Operators Actions:**

None.

**G. Safety System Responses:**

None.



# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)	
DIABLO CANYON UNIT 2	05000323	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER					
		91	-	009	-	01	4	OF	6

TEXT (17)

## III. Cause of the Event

### A. Immediate Cause:

The immediate cause of the plant being outside of its design basis was body-to-bonnet leakage from CVCS-2-548 and CVCS-2-8471.

### B. Root Cause:

1. The root cause of body-to-bonnet leakage in CVCS-2-8471 was personnel error in that the valve was not included in the plant preventive maintenance (PM) program. Since the valve was not included in the PM program, the diaphragm's service life was exceeded.
2. Although the specific root cause of body-to-bonnet leakage from CVCS-2-548, which was included in the PM program, could not be determined, the failure to include vendor recommendations on retorquing bonnet bolts in the PM program may have been a factor in the root cause.

## IV. Analysis of the Event

A leak of 1.3 gpm in the auxiliary building filtered only by HEPA filters could potentially have resulted in control room operator thyroid dose exceeding the 10 CFR 50 Appendix A General Design Criteria 19 limit over the 30-day duration of the design basis LOCA.

However, post-LOCA emergency response procedures provide for use of self-contained breathing apparatus (SCBAs) and potassium iodide prophylaxis, which would mitigate control room operator thyroid dose. Control room radiation conditions would be monitored by area radiation monitors located in the control room. Although the monitors are design Class II, they are powered from Class 1E power supplies. The area radiation monitors would provide sufficient indication to allow control room operators to don SCBA equipment or take additional corrective measures.

A leak of 1.3 gpm from the auxiliary building filtered only by the HEPA filters could potentially have resulted in exceeding the 10 CFR 100 2-hour site boundary dose limit to the thyroid.



# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)					PAGE (3)	
DIABLO CANYON UNIT 2	0 5 0 0 0 3 2 3	YEAR		SEQUENTIAL NUMBER		REVISION NUMBER	5   OF   6	
		91	-	0 0 9	-	0 1		

TEXT (17)

A design basis LOCA dose analysis contains many conservative assumptions, particularly with regards to source term (i.e. fuel damage), therefore an analysis was performed by PG&E using "expected case" LOCA assumptions (no fuel damage). The analysis determined that a 1.3 gpm leak would result in a 2-hour site boundary thyroid dose of approximately 0.5 rem, which is well below the 10 CFR 100 limit. Therefore, public health and safety were not affected by this event.

## V. Corrective Actions

### A. Immediate Corrective Actions:

The diaphragms for CVCS-2-548 and CVCS-2-8471 were replaced and the valves were successfully tested to assure that body-to-bonnet leakage did not occur.

### B. Corrective Actions to Prevent Recurrence:

1. Maintenance Procedure M-51.7, "Grinell Diaphragm Valve Maintenance," will be revised to include vendor recommendations on diaphragm replacement frequency and bolt torquing for diaphragm valves.
2. A review of installed diaphragm valves was made to ensure that all applicable valves are included in the diaphragm replacement PM program.

## VI. Additional Information

### A. Failed Components:

None.

### B. Previous LERs on Similar Events:

LER 1-90-010-00 Control Room Post-LOCA Habitability Design Basis Potentially Exceeded Due to Leakage Through a Vibration Induced Crack in CVCS Piping

This LER addressed the leakage of post-LOCA coolant into the charging pump rooms. The leakage would have resulted in exceeding the control room design basis dose limit. The cause of the event was determined to be a high cycle fatigue crack in the suction line of the nonsafety-related charging pump.



# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)	
DIABLO CANYON UNIT 2	0 5 0 0 0 3 2 3	YEAR		SEQUENTIAL NUMBER		REVISION NUMBER	
		91	-	0 0 9	-	0 1	6   OF   6

TEXT (17)

The corrective actions for the event included repairing the crack, adding additional supports to the suction line, and revising emergency procedures to assure that the auxiliary building ventilation system (VF) is in the safeguards mode of operation, and consequently, exhaust from the charging pump rooms is filtered, after a LOCA.

These corrective actions would not have prevented the leakage from CVCS-2-548 and CVCS-2-8471. The requirement for assuring that the auxiliary building ventilation system is in the safeguards mode would not have prevented the control room or exclusion area boundary dose limit from being exceeded in the event of a LOCA because the boric acid blender room is not part of the safeguards ventilation flowpath.

