

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9208110296 DOC. DATE: 92/08/06 NOTARIZED: NO DOCKET #
 FACIL: 50-275 Diablo Canyon Nuclear Power Plant, Unit 1, Pacific Ga 05000275
 AUTH. NAME AUTHOR AFFILIATION
 THIERRY, R.L. Pacific Gas & Electric Co.
 RUEGER, G.M. Pacific Gas & Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 92-006-00: on 920702, discovered one location on diesel fuel oil piping below min wall thickness requirement. Caused by general corrosion due to degradation in coal tar coating. Areas of corrosion repaired or replaced. W/920806 ltr.


DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: //
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	PD5 LA	1	1	PD5 PD	1	1
	ROOD, H	1	1			
INTERNAL:	ACNW	2	2	ACRS	2	2
	AEOD/DOA	1	1	AEOD/DSP/TPAB	1	1
	AEOD/ROAB/DSP	2	2	NRR/DET/EMEB 7E	1	1
	NRR/DLPQ/LHFB10	1	1	NRR/DLPQ/LPEB10	1	1
	NRR/DOEA/OEAB	1	1	NRR/DREP/PRPB11	2	2
	NRR/DST/SELB 8D	1	1	NRR/DST/SICB8H3	1	1
	NRR/DST/SPLB8D1	1	1	NRR/DST/SRXB 8E	1	1
	REGISTRATION 02	1	1	RES/DSIR/EIB	1	1
	RGN5 FILE 01	1	1			
EXTERNAL:	EG&G BRYCE, J.H	2	2	L ST LOBBY WARD	1	1
	NRC PDR	1	1	NSIC MURPHY, G.A	1	1
	NSIC POORE, W.	1	1	NUDOCS FULL TXT	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!



Pacific Gas and Electric Company

77 Beale Street
San Francisco, CA 94106
415/973-4684

Gregory M. Rueger
Senior Vice President and
General Manager
Nuclear Power Generation

August 6, 1992

PG&E Letter No. DCL-92-180



U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Re: Docket No. 50-275, OL-DPR-80
Docket No. 50-323, OL-DPR-82
Diablo Canyon Units 1 and 2
Licensee Event Report 1-92-006-00
Diesel Fuel Oil Transfer System Degradation Due to General
Corrosion

Gentlemen:

PG&E is submitting the enclosed voluntary Licensee Event Report concerning the degradation of piping in the diesel fuel oil system. This report is submitted for information purposes only as described in Item 19 of Supplement 1 to NUREG-1022.

PG&E management recognizes the need to comprehensively review corrosion issues, and has directed that a plan be developed to identify other systems with piping or conduit which may be susceptible to similar corrosion mechanisms.

This event has in no way affected the health and safety of the public.

Sincerely,

A handwritten signature in black ink, appearing to read 'Gregory M. Rueger'. The signature is fluid and cursive, with a long horizontal stroke at the end.

Gregory M. Rueger

cc: Ann P. Hodgdon
John B. Martin
Philip J. Morrill
Harry Rood
CPUC
Diablo Distribution
INPO

DC2-92-TN-N028

Enclosure

1043S/85K/SDL/2246

9208110296 920806
PDR ADDCK 05000275
S PDR

JE22



LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) DIABLO CANYON UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 2 7 5 1	PAGE (3) 1 OF 10
--	---	-----------------------------------

TITLE (4) **DIESEL FUEL OIL TRANSFER SYSTEM DEGRADATION DUE TO GENERAL CORROSION**

EVENT DATE (6)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)					
MON	DAY	YR	YR	SEQUENTIAL NUMBER		REVISION NUMBER	MON	DAY	YR	FACILITY NAMES			DOCKET NUMBER (8)		
07	02	92	92	-	0 0 6	-	0 0	08	06	92	DIABLO CANYON UNIT 2			0 5 0 0 0 3 2 3	
			0 5 0 0 0												

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR: (11)	
POWER LEVEL (10) 1 0 0	<input checked="" type="checkbox"/> 10 CFR <input type="checkbox"/> OTHER - <input type="checkbox"/> VOLUNTARY (Specify in Abstract below and in text, HRC Form 366A)	

LICENSEE CONTACT FOR THIS LER (12)		TELEPHONE NUMBER	
RAYMOND L. THIERRY, SENIOR REGULATORY COMPLIANCE ENGINEER		AREA CODE 805	545-4004

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		
C	D E	P S P		N							

SUPPLEMENTAL REPORT EXPECTED (14) <input checked="" type="checkbox"/> YES (if yes, complete EXPECTED SUBMISSION DATE) NO	EXPECTED SUBMISSION DATE (15)	MONTH 09	DAY 15	YEAR 92
---	-------------------------------	--------------------	------------------	-------------------

ABSTRACT (16)

This voluntary LER is submitted for information purposes only as described in Item 19 of Supplement 1 to NUREG-1022.

On July 2, 1992, ultrasonic testing identified one location on DFO Train 0-1 piping that was below the minimum wall thickness requirement; this piping was subsequently replaced. However, subsequent engineering evaluation based on preliminary information concluded that the piping would have remained operable under all design basis loading conditions.

The root cause of the event was general corrosion due to a degradation or breakdown in the coal tar coating exposing the pipe to standing water and saltwater air environment.

Corrective actions include development and implementation of a repair program to repair and/or replace the remaining areas of corrosion on the DFO piping.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)	
		YEAR	-	SEQUENTIAL NUMBER	-	REVISION NUMBER	-	2	OF 10
DIABLO CANYON UNIT-1	0 5 0 0 0 2 7 5	92	-	0 0 6	-	0 0	2	OF 10	

TEXT (17)

I. Plant Conditions

Units 1 and 2 were in Mode 1 (Power Operation) at 100 percent power.

II. Description of Event

A. Summary:

On June 21, 1992, corrosion was discovered on piping (DE)(PSP) associated with diesel fuel oil (DFO) Train 0-1 (DE)(PSP) and the two fire suppression system carbon dioxide (CO₂)(KQ)(PSP) lines contained in pipe trenches located in the Unit 2 west buttress area trench. Immediate visual inspection of the corroded areas determined the pipe to be operable. On June 23, 1992, at 0240 PDT, DFO Train 0-2 was removed from service for the tie in of new Emergency Diesel Generator (EDG) 2-3 (EK)(GEN).

On July 2, 1992, ultrasonic testing identified one location on DFO Train 0-1 piping that was below the minimum wall thickness requirement; this piping was subsequently replaced.

On July 8, 1992, plant management conservatively determined that, because the corrosion experienced by the DFO system piping must have required a significant period of time to degrade below a minimum wall condition, Technical Specification (TS) 3.8.1.1 action g. may not have been met. In addition, since DFO Train 0-2 was removed from service on June 23, 1992, at 0240 PDT, and DFO Train 0-1 may have been inoperable due to the minimum wall conditions, TS 3.8.1.1 action h. may not have been met.

Subsequent engineering evaluation based on preliminary information concluded that the piping would have remained operable under all design basis loading conditions.

B. Background:

The DFO system supplies fuel oil to the Units 1 and 2 EDGs. There are two redundant DFO pipe trains, 0-1 and 0-2. These two trains each consist of a 40,000 gallon underground DFO storage tank (DE)(TK), a fuel oil transfer pump (DE)(P), and associated piping, filters (DE)(FLT), and valves (DE)(V) (refer to Figure 1).

The DFO transfer system supplies DFO from the underground storage tanks to the individual EDG day tanks (DE)(TK). The day tanks have a capacity of 572 gallons, but contain a minimum of 200 gallons of DFO for each EDG at all times. Each EDG uses approximately 200 gallons per hour at a full load.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) DIABLO CANYON UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 2 7 5	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		92	- 0 0 6	- 0 0	3	of

TEXT (17)

TS 3.8.1.1 action statements g. and h. govern the DFO transfer system. With one supply train of the DFO storage and transfer system inoperable, action g. requires that the inoperable supply train must be restored to operable status within 72 hours or be in at least Mode 3 (Hot Standby) within the next 6 hours and be in Mode 4 (Hot Shutdown) within the following 6 hours. With both supply trains of the DFO storage and transfer systems inoperable, action h. requires that one supply train must be restored to operable status within 1 hour or be in at least Mode 3 within the next 6 hours and be in Mode 5 (Cold Shutdown) within the following 30 hours.

TS 4.8.1.1.3.e requires visual examination of accessible DFO piping during an operating pressure leak test at least once every 10 years. Surveillance Test Procedure (STP) M-91, "Diesel Fuel Oil Transfer System, Piping and Component Inspection," implements this 10-year visual inspection for DFO piping leakage, but does not specifically require inspecting all DFO piping for corrosion. STP M-91 is performed every 5 years in accordance with administrative requirements.

STP M-9A, "Diesel Engine Generator Routine Surveillance Test," requires a series of EDG tests to be performed on a frequency ranging from 1 test per 7 days to 1 test per 31 days, depending upon the number of valid starts. The tests performed under STP M-9A determine the overall operability of a single EDG and verifies that the DFO trains transfer fuel.

STP P-12B1 (P-12B2), "Routine Surveillance Test of Diesel Fuel Oil Transfer Pump 0-1 (0-2)," requires testing of the DFO transfer pumps on a quarterly basis.

C. Event Description:

On February 2, 1990, STP M-91 was performed and corrosion was identified on DFO Train 0-1. In early May 1990, the corroded area was cleaned, inspected, and recoated. The maintenance engineer documented that there was no damage to the pipe due to corrosion or pitting. However, as a result of this event, the frequency of STP M-91 was changed from 10 to 5 years in August 1991.

On June 18, 1992, corrosion was discovered in auxiliary saltwater (ASW) annubar piping (BA)(PSP). The ASW system piping, DFO system piping, and the CO₂ piping are found in a common area in one location of the DFO pipe trench.

On June 21, 1992, a work crew was inspecting the DFO trenches to determine the extent of an acid/caustic spill in the Unit 2 west buttress. Corrosion was found on DFO Train 0-1 system piping and two fire suppression system CO₂ lines. Design Engineering performed an immediate evaluation of the worst corroded areas identified by the work



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
DIABLO CANYON UNIT 1	0 5 0 0 0 2 7 5	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 10
		92	- 0 0 6	- 0 0	

TEXT (17)

crew. The piping was concluded to be operable and an inspection plan was formulated to mechanically clean the corroded areas and non-destructively examine the piping to determine remaining wall thickness.

On June 23, 1992, during implementation of the inspection plan, corrosion was identified on DFO Train 0-2 and additional corrosion areas were identified on the two CO₂ lines. Again, based upon the findings of the visual inspections and selective ultrasonic testing (UT) of the DFO line, these pipes were evaluated to be operable.

On June 23, 1992, at 0240 PDT, DFO Train 0-2 was removed from service and TS 3.8.1.1 action g. was entered for the tie-in of EDG 2-3 to DFO Train 0-2 (with the addition of EDG 2-3, Units 1 and 2 will each have three dedicated EDGs). As part of the tie-in activities, an operational pressure test was performed on the pipe train. The previously identified areas of corrosion were observed and no leakage was identified.

On June 24, 1992, at 0320 PDT, DFO Train 0-2 was returned to service and TS 3.8.1.1 action g. was exited.

On June 24, 1992, a comprehensive inspection plan was developed to evaluate the condition of the piping and associated supports on both trains of the DFO system. The plan involved a complete visual inspection of each DFO train from the transfer pump vaults to the EDG day tank level control valves (DE)(LCV), including pipe supports (DE)(PSP)(SPT), and UT inspection of the worst corrosion areas to verify wall thickness.

On June 25, 1992, at 0230 PDT, DFO Train 0-1 was removed from service and TS 3.8.1.1 action g. was entered to tie-in EDG 2-3 to DFO Train 0-1. Also on June 25, 1992, the visual inspection plan for DFO Train 0-1 was implemented. As part of the tie-in activities, an operational pressure test of the pipe was performed. The exposed sections of the train were walked down and no leakage was identified. This walkdown included the section of pipe that later was found to be below minimum wall thickness requirements.

On June 26, 1992, at 0224 PDT, DFO Train 0-1 was returned to service and TS 3.8.1.1 action g. was exited.

On June 29, 1992, the visual inspections were completed. The visual inspections identified 6 areas on the DFO Train 0-1 for UT examination.

On July 2, 1992, at 0500 PDT, DFO Train 0-1 was cleared and drained for UT testing. At 1700 PDT, one location on DFO Train 0-1 was identified as being below the minimum wall thickness requirement. DFO Train 0-1 was conservatively declared inoperable.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
DIABLO CANYON UNIT 1	0 5 0 0 0 2 7 5	92	- 0 0 6	- 0 0	5	of 10	

TEXT (17)

On July 3, 1992, at 0500 PDT, the repair plans for DFO Train 0-1 were implemented. At 1700 PDT, the visual inspection plan for DFO Train 0-2 piping for the Unit 2 EDGs was initiated. This visual examination determined that the Train 0-2 section of piping had the worst corrosion of the DFO piping. Since the UT examination did not identify concerns with the other areas tested, the validity of the visual examination was confirmed.

On July 4, 1992, at 1300 PDT, the section of pipe with below minimum wall thickness on DFO Train 0-1 was replaced and the train was declared operable.

On July 4, 1992, at 1500 PDT, the visual inspection of the portion of DFO Train 0-2 supplying the Unit 2 EDGs was completed and 7 areas were chosen for UT examinations.

On July 5, 1992, at 1100 PDT, the UT tests on DFO Train 0-2 were completed and no areas of pipe were found below minimum wall thickness. At 1200 PDT, the inspection of the portion of DFO Train 0-2 supplying the Unit 1 EDGs began. At 2300 PDT, the visual inspection for Train 0-2 supply piping for Unit 1 was completed and 5 areas were chosen for UT testing.

On July 6, 1992, at 1200 PDT, the UT tests were completed and no areas were found below the minimum wall thickness requirements.

On July 8, 1992, plant management conservatively determined that because the corrosion on the DFO system piping had required a significant period of time to degrade below a minimum wall condition, TS 3.8.1.1 action g. may not have been met for an indeterminate period of time and action h. may not have been met for the period when DFO Train 0-2 was removed from service.

Between July 8, 1992, at 0700 PDT, and July 13, 1992, the CO₂ supply line inspections were implemented and all lines were determined to meet the minimum wall thickness requirements.

Inspections of the DFO and CO₂ pipe supports were also performed at the same time as the pipe wall thickness inspections. As a result of the inspections, two of the DFO pipe supports on DFO Train 0-1 and one CO₂ pipe support were determined to be degraded. A conservative engineering analysis was performed and determined that the degraded supports would not affect the operability of the piping.

D. Inoperable Structures, Components, or Systems that Contributed to the Event:

None.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) DIABLO CANYON UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 2 7 5	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		92	- 0 0 6	- 0 0	6	OF

TEXT (17)

E. Dates and Approximate Times for Major Occurrences:

1. June 21, 1992: Corrosion was discovered on the DFO piping.
2. June 23, 1992, at 0240 PDT: TS 3.8.1.1 action g. was entered for DFO Train 0-2 for EDG 2-3 tie-in.
3. June 24, 1992, at 0320 PDT: DFO Train 0-2 was returned to service and TS 3.8.1.1 action g. was exited.
4. June 25, 1992, at 0230 PDT: TS 3.8.1.1 action g. was entered for DFO Train 0-1 for EDG 2-3 tie-in and subsequent pipe pressure test.
5. June 26, 1992, at 0224 PDT: DFO Train 0-1 was returned to service and TS 3.8.1.1 action g. was exited.
6. July 2, 1992, at 1700 PDT: Event Date. DFO Train 0-1 was found below minimum wall thickness. TS 3.8.1.1. action g. was entered.
7. July 4, 1992, at 1400 PDT: Corroded section of DFO Train 0-1 pipe was replaced. TS 3.8.1.1 action g. was exited.
8. July 8, 1992: Discovery date. An evaluation conservatively determined that TS 3.8.1.1 actions g. and h. may not have been met.

F. Other Systems or Secondary Functions Affected:

Corrosion was also discovered on ASW and CO₂ system piping.

G. Method of Discovery:

On June 21, 1992, a work crew was inspecting the DFO trenches to determine the extent of an acid/caustic spill in the Unit 2 west buttress area. Corrosion was found on DFO Train 0-1 system piping and two fire suppression system CO₂ lines.

H. Operator Actions:

None.

I. Safety System Responses:

None.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) DIABLO CANYON UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 2 7 5	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
		92	- 0 0 6	- 0 0	7 of 10

TEXT (17)

III. Cause of the Event

A. Immediate Cause:

The immediate cause of the event was DFO Train 0-1 piping below minimum wall thickness requirements.

B. Root Cause:

The root cause of the event was general corrosion due to a degradation or breakdown in the DFO piping coal tar coating, which exposed the pipe to a standing water and saltwater air environment. Standing water seeping through the coating corroded the pipe, especially at the water/air interface. As the iron oxide rust formed, it expanded in volume (at a volumetric ratio of approximately 7 to 1). This bulging or blistering further degraded the coal tar and accelerated the corrosion process. The standing water was due to inadequate drainage caused by plugging of the trench drains due to flow blockage by pipe supports and external debris.

A supplemental LER will be issued to report any additional information on the root cause.

C. Contributory Cause:

1. The existing DFO inspection procedure does not provide instructions on how to identify corrosion and only requires inspection of accessible DFO transfer piping.
2. Initial application and maintenance of the coal tar protective coating on the underside of piping was inadequate.

IV. Analysis of the Event

A portion of the DFO Train 0-1 piping was found severely corroded and has been replaced. This section of corroded pipe was judged to have the worst corrosion of both DFO trains. Preliminary examination of the corroded section found some areas below the required minimum pipe wall thickness and numerous small pits that were very nearly through-wall. The pits are considered to not have affected operability; this was demonstrated when the piping was pressurized without any indication of leakage on June 25, 1992, during tie-in of EDG 2-3.

An analysis is being performed to evaluate the effect of the degraded pipe wall condition on the integrity of the DFO piping. The analysis is considering the remaining pipe wall thickness and the design load conditions, including seismic loads. A preliminary engineering evaluation concluded that the piping would have remained operable under all design



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) DIABLO CANYON UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 2 7 5	LER NUMBER (6)			PAGE (3) 8 of 10
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
		92	- 0 0 6	- 0 0	

TEXT (17)

basis loading conditions. Therefore, system operability was never compromised. The final results of the analysis will be submitted in a supplemental LER.

Based on the above, it is concluded that this event did not adversely affect the health and safety of the public.

V. Corrective Actions

A. Immediate Corrective Actions:

1. The section of pipe below minimum wall thickness requirements on DFO Train 0-1 was replaced.
2. The trenches containing the DFO trains have been cleaned to minimize standing water. In addition, interim measures are being taken to minimize further pipe support corrosion until Corrective Action to Prevent Recurrence #1 below is completed.
3. Visual inspection of both trains of the DFO transfer system has been completed, along with UT examination on the worst areas of corrosion.
4. Additional visual, UT, and/or radiography examination of both DFO trains and associated pipe support contact areas is ongoing to establish a comprehensive basis for adequacy of the piping.

B. Corrective Actions to Prevent Recurrence:

1. A program will be developed and implemented to repair and/or replace the remaining areas of corrosion on the DFO piping. The program will also address the following issues:
 - improving the protective coating
 - improving the drainage in the trenches
 - minimizing standing water in trenches
 - improving the surveillance program
2. A plan is being developed for a comprehensive review to identify other systems with piping and conduit that may be susceptible to similar corrosion mechanisms.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) DIABLO CANYON UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 2 7 5	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
		92	- 0 0 6	- 0 0	9 of 10

TEXT (17)

VI. Additional Information

A. Failed Components:

The carbon steel piping in the DFO transfer system was found corroded below minimum wall thickness requirements.

B. Previous Similar LERs:

None.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) DIABLO CANYON UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 2 7 5	LER NUMBER (6)			PAGE (3) 10 OF 10
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
		92	- 0 0 6	- 0 0	

TEXT (17)

Figure 1
DFO Transfer System

