	q ,						ENSEE	EVE	NT	REP	ORT	(L	<b>R</b>						<i></i>
,	ı I	•	1									•							
FACILITY N	AME (1)	0.044			1			н					0				7 5 1	GE (3) OF	9
TITLE (4)	IMPR	DPER L	ISE (	F SU	RGE S	UPPR	ESSION D	IODE	S ON	TH	E POS	T-A		ENT	SAMP	LING	SYSTEM D	UE T	0
	PERS	ONNEL	ERRO	R															
EVENT DAT	TE (6) DAY	YR	YR		LER NUN	ABER (8)	REVISION	REPOR MON	DATE	(7) YR		F	ACULTY N	AMES	FACILI	DOCK	ET NUMBER (S)		
$\left  \cdot \right $	,				NUMBE	R	NUMBER										5 0 0 0	) 3	2 3
11	06	92	92	- (	2	6 -	0 1	03	05	93	DIAB		CANY	<u>on u</u>		2 0	5000		
OPERATIN MODE (9)	G	3	THIS	REPORT	IS SUBM	ITTED P	URSUANT TO T	HE REQU		NTS OF	10 CFR	: ()				<u> </u>			
POWER LEVEL (10)	$\begin{array}{c c} & 3 \\ \hline \\$																		
			1		•			(Speci	fy iı	n Abs	tract	bel	ow and	in 1	text,	NRC Fo	rm 366A)		
XC98336	0.382.14						UCENS	EE CONT	ACT FO	RTHIS	LER (12)	•			<u> </u>				
	DAVID SOKOLSKY, SENIOR NUCLEAR GENERATION ENGINEER  AREA CODE 415 973-9717														17				
				-	COMP	LETE ON	UNE FOR EACH	- I COMPO	NENT F	AILURE	DESCRIBI	ED IN '	THIS REPO	ORT (13	4. )	15	97	5-97	17
CAUSE	SYSTEM	I COM	PONENT	. M	ANUFAC- TURER	RE T	O NPRDS		4.8 9.8	CAUSE	SYST	EM	COMPON	IENT	MAN T	IUFAC- URER	REPORTABLE TO NPRDS		
		1					200 200 200						<b>i i</b>			1			ÌX.
															Mi				
	-		8	JPPLEME	NTAL REP	ORT EXP	ECTED (14)	r					EXPEC	TED		MONTH	DAY	_ _	YEAR
	YES (	if yes,	comp	lete	EXPECTE	D SUB	MISSION D	ATE)	x	NO			DATE	(15)					
ABSTRACT	I   YES (if yes, complete EXPECTED SUBHISSION DATE) X NOEXPECTEDNOABSTRACT (16)On November 6, 1992, at 1745 PST, with Unit 1 in Mode 3 (Hot Standby) at 0 percent power and Unit 2 in Mode 1 (Power Operation) at 100 percent power, PG&E determined that surge suppression diodes used in electrical control circuitry for several solenoid valves were not adequate for operation under post-accident conditions and that diode failure could impact operability of the post-accident conditions and that diode failure could impact operability of the post-accident sampling system (PASS). Technical Specification 6.8.4.e implies that the PASS should be operable. A one-hour, non-emergency report was made to the NRC for Units 1 and 2 on November 6, 1992, at 1803 PST, in accordance with 10 CFR 50.72(b)(1)(ii)(B).The root cause for this event was personnel error, cognitive, in that the design engineers did not take the required steps to assure that all equipment (diodes) could function in the conditions required (high radiation and/or steam).The diodes were removed from the affected solenoid valves. Class I solenoid valves with diodes in post-accident harsh environments are being reviewed to ensure that secondary (nonsafety-related) functions will be operable when required. Design Class II equipment needed to be operable in post-accident harsh environments will be reviewed for operability. The applicable drawing and Design Criteria Memoranda now contain guidance regarding use of components in post- accident harsh environments.												<i>t</i>						
60065			7303 7DR	1201 ADC	70 9 ICK (	7303 )500	05 0275 9DR	ţŦ		 U				<del>.</del>	<u></u>		<u>,</u> ,-		L.

,

6006S/85K

,

.

• 11 1 L. . 'n • "

`

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	-	Ľ	ER NUMBER	(6)			PAGE (	3)
		YEAR	2	SEQUENTIAL NUMBER	2358 2210	REVISION NUMBER			
DIABLO CANYON UNIT 1	0 5 0 0 0 2 7	5 92	<u> </u>	0 2 6	_	0 1	2	OF	9

### I. <u>Plant Conditions</u>

Units 1 and 2 have operated in all modes and at various power levels with the condition described below. At the time of discovery of the event, Unit 1 was in Mode 3 (Hot Standby) at 0 percent power and Unit 2 was in Mode 1 (Power Operation) at 100 percent power.

### II. Description of Event

A. Summary:

On November 6, 1992, at 1745 PST, with Unit 1 in Mode 3 (Hot Standby) at O percent power and Unit 2 in Mode 1 at 100 percent power, PG&E determined that surge suppression diodes used in electrical control circuitry for several solenoid valves were not adequate for operation under post-accident conditions and that diode failure could impact operability of the post-accident sampling system (PASS) (IP). Technical Specification (TS) 6.8.4.e implies that the PASS should be operable. A one-hour, non-emergency report was made to the NRC for Units 1 and 2 on November 6, 1992, at 1803 PST, in accordance with 10 CFR 50.72(b)(1)(ii)(B).

### B. Background:

NUREG-0578, "TMI-2 Lessons Learned Task Force Status Report and Short Term Recommendations," was issued on July 1, 1979. NUREG-0737 "Clarification of TMI Action Plan Requirements," was issued on October 31, 1980. The NUREGs require the following:

- Capability to promptly obtain a sample under accident conditions without incurring a radiation exposure to any individual in excess of 5 rem to the whole body and 75 rem to the extremities.
- Capability to promptly quantify certain radionuclides in the sample that are indicators of the degree of core (AC) damage. Such radionuclides are noble gases (which indicate cladding (AC) failure), iodines and cesiums (which indicate high fuel temperatures), and nonvolatile isotopes (which indicate fuel melting). The combined time for sampling and analysis should be 3 hours or less from the time a decision is made to take a sample.
- Procedures shall be provided to perform boron and chloride chemical analyses assuming a highly radioactive initial sample (Regulatory Guide 1.4 source term).

On February 26 and March 13, 1981, PG&E submitted documentation of actions to be taken at Diablo Canyon Units 1 and 2 to implement items from NUREG-0578 and 0737, which included a discussion of the actions

-. • . •

.

î

# LICENSEL EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)		DOCKET NUMBER (2)		L	ER NUMBER	(6)		1	PAGE (3)
			YEAR	ій.	SEQUENTIAL NUMBER		revision Number		
DIABLO CANYON UNIT 1	-	0 5 0 0 0 2 7 5	92	_	026	-	0 1	3	of 9
TEXT (17)		- <u>-</u>						•	

PG&E was taking to install a PASS for each unit to meet the requirements of NUREG-0737, Item II.B.3, "Post Accident Sampling Capability." As noted in the PG&E submittals, the PASS was design Class II (i.e., nonsafety-related).

In Supplemental Safety Evaluation Report (SSER) 14, page 3-12, issued April 1981, the NRC stated that "based on our evaluation, we find that the design meets the requirements of NUREG-0578, 0737 and Regulatory Guide 8.8 and is therefore acceptable."

Further, TS 6.8.4.e, "Administrative Controls, Post Accident Sampling," requires a program for (a) training of personnel, (b) procedures for sampling and analysis, and (c) provisions for maintenance of sampling and analysis equipment, as required in Item 2 in Generic Letter 83-37, "NUREG-0737 Technical Specifications."

C. Event Description:

During implementation of the corrective actions for LER 1-92-015, "Inadequate Maintenance of Hosgri Report Commitments" (DCL-92-198, dated September 11, 1992), reactor coolant system (RCS) (AB) hot leg sample inlet valves 9351A and 9351B (IP)(SMV) were reviewed for seismic qualification. These air-operated valves are used to obtain an RCS sample during normal and post-accident operation. In addition, these valves provide the capability to obtain an RCS sample to verify boron concentration after a postulated Hosgri earthquake. While NUREG-0737 did not require seismic qualification of the PASS, a previous commitment in the Hosgri Report required that valves 9351A and 9351B be seismically qualified to ensure the capability to collect the RCS sample for boron concentration measurement after a Hosgri earthquake.

Solenoid valves SV-371 and SV-372 provide control air to the operators for valves 9351A and 9351B. When the electrical control circuitry for SV-371 and SV-372 was reviewed, surge suppression diodes across their leads were identified inside containment (NH). Although the PASS is design Class II and would not require formally documented environmental qualification (EQ) under PG&E's 10 CFR 50.49 program, the valves are required to be operable in post-accident conditions.

Because the diodes were not capable of long-term operation in a harsh environment, a review was conducted to determine which PASS sample lines are required for post-accident use. In addition to SV-371 and SV-372, solenoid valves SV-381 and SV-382 for residual heat removal (RHR) (BP) outlet sample valves 9353A and 9353B, which are located outside containment in a harsh (radiation-only) environment, were also identified as having diodes across their leads. On October 28, 1992, PG&E management was apprised that a concern existed. Design changes were issued on November 2 (Unit 1) and November 5 (Unit 2) to remove the solenoid valve diodes while investigation continued.

•

.

i ž \* 1

### LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

DIABLO CANYON UNIT 1 $0 5 0 0 2 7 5$ 92 - $0 2 6$ - $0 1 4 ^{OF}$	FACILITY NAME (1)		DOCKET NUMBER (2)		Ľ	ER NUMBER	(6)			PAGE (	3)
DIABLO CANYON UNIT 1 0 5 0 0 2 7 5 92 - 0 2 6 - 0 1 4  0	un an		-	YEAR	*	SEQUENTIAL NUMBER	Ŵ	REVISION NUMBER	4		
	DIABLO CANYON UNIT 1	•	0 5 0 0 0 2 7 5	92	_	0 2 6	_	0 1	4	OF	9

PG&E determined that if the diodes were subjected to a harsh environment, the solenoid valves may not be capable of operation, thus preventing operation of the associated sample valves. Therefore, the PASS might not have been able to collect post-accident RCS hot leg and RHR outlet samples, contrary to system design basis. On November 6, 1992, at 1745 PST, PG&E conservatively determined that although the PASS was design Class II, TS 6.8.4.e implies that the PASS should be operable; therefore, the PASS was considered to be outside of its system design basis. Therefore, a one-hour, non-emergency report was made to the NRC for Units 1 and 2 on November 6, 1992, at 1803 PST, in accordance with 10 CFR 50.72(b)(1)(ii)(B).

Further investigation following identification of the diode issue determined that an additional concern existed. Solenoid valve SV-327 for the outside containment isolation valve (CIV) 9356B on the RCS hot leg sample line and SV-314 for outside CIV FCV-681 on the sample return line were found to have diodes across their leads. In addition, solenoid valve SV-312 for FCV-679 (a non-PASS outside CIV) was found to be electrically tied to SV-314 for FCV-681; failure of the SV-312 diode could also affect operation of FCV-681. These diodes outside containment are exposed to a radiation environment only after initiation of RHR recirculation. While failure of the diodes would not prevent the CIVs from performing their containment isolation safety function, their failure could prevent re-opening of the valves to obtain post-accident samples (9356B), or return samples to containment (FCV-681). Design changes were issued on November 13 to remove the three solenoid valve diodes for each unit.

D. Inoperable Structures, Components, or Systems that Contributed to the Problem:

None.

E. Dates and Approximate Times for Major Occurrences:

1.	February 26 and March 13, 1981:	PG&E letters to the NRC committed to NUREGS 0578/0737.
2.	April 1981:	NRC issued SSER 14 accepting PG&E's PASS design.
3.	October 28, 1992:	Diodes on SV-371, 372, 381, and 382 were determined to not be adequate for post-accident conditions.
4.	November 6, 1992 at 1745 PST:	Event/Discovery Date: Diodes were

determined to impact PASS

operability.

*,* .

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY' NAME (1)		····· ··· ··· ··· ····················	DOCK	ET NUM	BER (2	)		Ţ		Ľ	ER N	MBER	(6)			PAGE (	3)
· ·						•	·	ſ	YEAR	X	SEO M	uential Mder	Š	revision Number			
DTAR	۵۵ ۵	NYON UNIT 1		5 I N.	Inti	n   2	171	5	92		01	216	,	011	5	OF	.9
TEXT (17)	.0 07		101	510						1	<u>     </u>	210					
њ , , , , , , , , , , , , , , , , , , ,	× -	5. November 6, 1992, at 1	803 P	ST:	On ma ac 50	ie-h ide :cor 0.72	our, for danc (b)(	, n Un Ce 1 (1)	on-e its with (ii)	mer 1 a 10 (B)	rge and ) C	ncy 2 i FR	rer n	oort	was	•	
	F.	Other Systems or Secondary	/ Fun	ctio	ns A	ffe	cted	:			ı						
		None.					,	,			÷		•			•	
	G.	Method of Discovery:							-								-
•		This event was identified valves 9351A and 9351B as Valves 9351A and 9351B are enable obtaining an RCS 1 concentration. While rev the diodes were noted and identified concerns with of Section VI of this LER).	duri a pa e req iquid iewin furt diode	ng a rt o sam g tho her s in	rev f LE d to ole e as inve a p	iew R 1 be for soc sti	for -92- sei ver iate gate -acc	`se 01! smi ifi d s id ide	eism 5 con ical icat sole beca ent	ic rre ly ion ñoi use env	qua qua dua d d vir	a]if ive alif bo valv f ot onme	ica act iec ror e c her	tion ions to ircu (see	´of • itr:	y, <sup>2</sup>	I
	H.	Operator Actions:												•			
		None.			1				-								4 1
	Ι.	Safety System Responses:										۴,		5			
		None.	-	*			1				·	,					,
III.	<u>Cau</u>	<u>se of the Event</u>	•	\$													Ŧ
· .	Α.	Immediate Cause:	٠		,		-				•.						
• •		Use of surge suppression of operation under post-accide	diode dent	s in cond	the itio	PA	SS t	hat	t we	re	no	t ad	lequ	iate '	for		
	В.́	Root Cause:															
•		Personnel error, cognitive the required steps to asso in the conditions required design practice has been and minimize contact pitt the PASS, design engineers harsh environment, which of function.	e, in ure t d (hi to in ing. s did could	tha hat gh r stal How not res	t th all adia l di ever rec ult	e d equ ode , a ogn in	esig ipme n an s to t th ize loss	in e id/o ie i that o	engi (di or s educ time at d f PA	nee ode tea of ioc SS	ers (es) (ele) fil les li(	did cou ctro ctro nsta cou quid	nd itar itar ild ild sa	ot ta func dard noi: noi: tion fail mpli:	ke PG se of in ng	n &E a	

۴.

. , 1 , . . •

LICENSEL EVENT REPORT	(LER) TEXT CONTINUATION
-----------------------	-------------------------

2

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
	~	YEAR SEQUENTIAL REVISION NUMBER NUMBER	
DIARLO CANVON UNIT 1			6  0F  9
н — — — — — — — — — — — — — — — — — — —			
C. Contributory Cause:			
The following contrib	utory causes were identifi	ed:	
1. The original PASS Sampling System," components would b environment.	Design Criteria Memorandum did not explicitly identif e required to operate in a	n (DCM) M-28, "Post-LC Fy that some PASS a post-accident harsh	DCA
2. The Diablo Canyon solenoid valve dio guidance regarding environments.	electrical design drawing de installation details di use of diodes in post-acc	that shows typical id not have adequate cident harsh	
3. While the primary containment isolat their safety-relat secondary nonsafet was not adequately	function of the affected on ion valves was adequately ed isolation function cou y-related PASS sampling for reviewed.	design Class I reviewed to assure th Id be completed, the Inction of these valve	nat es
4. PG&E design Class environment was no sufficient assuran under post-acciden	II PASS equipment in a posit adequately reviewed to a contract the equipment wou it conditions.	st-accident harsh ensure that there was ld be able to operate	
IV. <u>Analysis of the Event</u>			
The diodes were mounted a DC solenoid valves that s discussed in detail becau essential to the collecti valves, 9356B, FCV-679, a valves, 9351A and B and 9 Valves 9351A and 9351B ar are located outside conta are assumed to fail worst associated fuses (IP)(FU) Failure of the diode "ope circuit and has no affect	cross the solenoid coils ( upport the PASS operation, se they represent the set on and return of RCS post- nd FCV-681, are outside CD 353A and B, are used only e located inside containme inment. For post-accident -case to complete short, w to blow and remove the po n" simply removes the dioc on system operability.	(IP)(CL) for PG&E-supp Seven of the valves that are considered t accident samples. The Vs. The remaining for for obtaining samples ent and 9353A and 9353 conditions, the dioc which could cause the ower source (IP)(JX). de from the solenoid	are are be aree our BB les
Prior to their removal, t affect on the ability of CIVs are located outside (radiation-only) environm	he existence of the diodes the CIVs to close to isola of containment and will be ent after the onset of RHM	would not have had a te containment. Thes subject to a harsh recirculation. Alth	iny se iough

(radiation-only) environment after the onset of RHR recirculation. Although diodes would be expected to survive for up to 1 hour of radiation exposure at the exposure rates postulated for their location, all of the CIVs would have already closed on the appropriate isolation signal prior to initiation of RHR recirculation. Should a valve not already be closed, diode failure (short) will cause the valve to go to its designed fail-safe closed

6006S/85K

4

·

. .

.

. .

# LICENSE EVENT REPORT (LER) TEXT CONTINUATION

• • •		
FACILITY' NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)
2		YEAR SEQUENTIAL REVISION NUMBER NUMBER
DIABLO CANYON UNIT 1	. 0 5 0 0 0 2 7 5	92 - 0 2 6 - 0 1 7 9

position.

Diode short-circuit failure could have prevented subsequent operation of the valves for PASS sampling purposes. Failure of 9351A and B and 9356B to open would have prevented collection of an RCS hot leg sample via this path. Failure of 9353A and B to open would have prevented collection of a sample from the RHR outlet. Failure of FCV-681 to open (and FCV-679 because it is electrically tied to 681) would have prevented returning the liquid samples to containment. While other methods for disposing of sample fluids may exist (e.g., the post-LOCA sample collection tank), there is no proceduralized method for use, and radiological concerns would have to be resolved before they could be used. Therefore, it is conservatively assumed that the capability to return a sample might not have been available.

The PASS is not safety-related. The liquid sampling capability is used to obtain detailed information on the condition of the reactor fuel, fuel cladding, and coolant, not directly for accident mitigation. A number of other indications of core conditions exist, including the reactor vessel level indication system, the subcooled margin monitor (JD), and incore thermocouples (JD); these systems are environmentally qualified. Sample collection is in accordance with Emergency Procedure RB-14, "Core Damage Assessment Procedure." By this procedure, a preliminary assessment of clad failure/core damage would have already been completed using available information, for example, containment area radiation monitors (IK)(MON) and containment hydrogen monitors (IK)(MON) (both are environmentally qualified). A containment air sample would have been obtained for PASS analysis (all valves in this path are qualified). RCS boron concentration may be calculated using tank [refueling water storage tank (BP)(TK), accumulator tank (BP)(ACC)] parameters.

Based on the above discussion, it is concluded that, while plant operators might not have had as accurate a picture of reactor and reactor coolant conditions as they would have with analysis of an RCS liquid sample, they would have had sufficient information to allow continuation of accident mitigation and recovery activities. Therefore, the inability to obtain RCS samples by the above paths would not have had a significant affect on the ability to mitigate and recover from any postulated accident. Thus, this event has in no way affected the health and safety of the public.

#### V. <u>Corrective Actions</u>

A. Immediate Corrective Actions:

- 1. Design changes were implemented to remove diodes from the seven solenoid valves on each unit.
- 2. Class I solenoid valves having diodes in post-accident harsh environments will be reviewed to ensure that no other secondary functions (nonsafety-related, but required to be operable in a post-

۸ ۰

• ۰ ۲ 

· · · · \* 'n . .

# LICENSE EVENT REPORT (LER) TEXT CONTINUATION

Ψ.,

4

ι.

ź

				н е		
FACI	LITY NAME (1)	•	-	DOCKET NUMBER (2)	LER NUMBER (6) YEAR SEQUENTIAL REVISION	PAGE (3)
	DIABL	O CA	NYON UNIT 1	015101010121715	92 - 01216 - 011	8 05 9
TEXT	(17)					
			· · · · · · · · · · · · · · · · · · ·		- <b>1</b>	•
			accident, harsh environme	nt) nave been overlo	океа.	•
	•		3. A review was performed t the RCS hotleg, RHR outl paths) and the external Class II systems/subsyst accident harsh environme	hat confirmed that t et, containment air, hydrogen recombiners ems required to be o nt.	he PASS (specificall and sample return (BB)(RCB) are the o perable in a post-	y nly
2	£	•	4. A review will be conduct and external hydrogen re and then to assure that post-accident harsh envi	ed to identify all c combiner flow paths these components wil ronments.	omponents in the PAS needed to be operabl l remain operable in	S e
		Β.	Corrective Actions to Preve	nt Recurrence:		
		а <sup>т</sup> Н	Substantial additional deta would be expected to preclue addition, the following act	il in current design de similar events in ions have been taken	processes and pract the future. In :	ices
			<ol> <li>DCM S-11, "Nuclear Steam M-28 for the PASS, now s to operate in a post-acc</li> </ol>	Supply Sample Syste tates that portions ident harsh environm	m," which replaced D of the PASS are requ ent.	CM ired
		Ŧ	<ol> <li>In response to previousl PG&amp;E's new DCM T-23,"Mis precautionary notes rega environments. Also, the to include a note regard environment.</li> </ol>	y identified diode i cellaneous Electrica rding the use of dio electrical design d ing the use of diode	ssues (see Section V 1 Devices," now incl des in harsh rawing has been revi s in a harsh	I), udes sed
	VI.	<u>Add</u>	itional Information			
		Α.	Failed Components:		•	تر
			None.		· · · ·	<b>1</b> .
		B.	Previous LERs on Similar Pro	oblems:		÷
			LER 1-88-028-01 "Entry Inte Four Main Steam Isolation Va Environmental Qualification	o Technical Specifica alves Were Inoperable of Electrical Connec	ation 3.0.3 When Two e due to Inadequate ctions"	of
	•	-	The root cause of this event surge suppressor used within (SB)(FCV) solenoid control addressed in EQ files. The valves were required to actu than failing to a safety pos environmentally qualified C	t was personnel error n the main steam iso valves electrical con MSIVs were unique in uate to achieve thein sition. Corrective a lass I components out	r, cognitive, in that lation valve (MSIV) nnections was not n that the solenoid r safety position rat actions were limited tside containment	t the ther to

6006S/85K

•

, s.

,

# LICENS EVENT REPORT (LER) TEXT CENTINUATION

FACILITY NAME (1)	DOCKET NUHBER (2)		L	ER NUMBER	(6)		ŀ	PAGE (	3)
		YEAR	*	SEQUENTIAL NUMBER		REVISION NUMBER			
DIABLO CANYON UNIT 1	0 5 0 0 0 2 7 5	92	_	0 2 6	-	0 1	9	OF	9
TEXT (17)		~							

required to actuate to achieve a safety position and did not extend to any secondary actions that components might be required to take following achievement of the safety position. Therefore, the corrective actions would not have prevented the events described in this LER.

LER 2-92-005-01 "Use of Environmentally Unqualified Surge Suppression Diodes in the Auxiliary Building Ventilation System due to Personnel Error"

The root cause of this event was personnel error, in that the effects of diode failure were considered only in regards with the damper fail-safe design. This resulted in an incomplete analysis that allowed the subject diodes to be excluded from the EQ program. Corrective actions taken included a review of solenoid valve installations required to be environmentally qualified under PG&E's 10 CFR 50.49 program, addition of precautionary notes regarding the future use of surge suppression diodes, and issuing a lessons learned memorandum to design engineering. The corrective actions for LER 2-92-005 are still ongoing, and have been reassessed in conjunction with this LER.

5006S/85K ·

74 84

\* \* .a. ,

I

\*

۴