



NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

Arvin E. Upton, Esquire
LeBoeuf, Lamb, Leiby & MacRae
1757 N Street, N. W.
Washington, D. C. 20036

Anthony Z. Roisman, Esquire
Roisman, Kessler and Cashdan
1025 15th Street, N. W.
5th Floor
Washington, D. C. 20005


Mr. Eugene G. Saloga, Applicant Coordinator
Nine Mile Point Energy Information Center
P. O. Box 81
Lycoming, New York 13093

50-220

Docket File
NRC PDR
Local PDR
NRR Rdg
ORB#3 Rdg
E. G. Case
V. Stello
K. R. Goller
D. Eisenhut
A. Schwencer
D. Davis
G. Lear
R. Reid

L. Shao
R. Baer
W. Butler
B. Grimes
Project Manager
OELD
OI&E (3)
C. Parrish
NRC Participants
ACRS (16)
T. B. Abernathy
J. R. Buchanan
D. Thompson

*MEMO
4
RB*



DISTRIBUTION:
See attached list

JUL 6 1977

MEMORANDUM FOR: G. Lear, Chief, Operating Reactors Branch #3, DOR
FROM: S. J. Nowicki, Project Manager, Operating Reactors Branch #3, DOR
SUBJECT: MEETING ON NINE MILE POINT UNIT NO. 1 FEEDWATER NOZZLE INSPECTION AND REPAIR, JUNE 3, 1977

Introduction

A meeting was held on June 3, 1977 with representatives of Niagara Mohawk Power Corporation (NMPC) and NRC to discuss the results of the Feedwater Nozzle Inspection and Repair program completed by NMPC during their current refueling outage at Nine Mile Point Unit No. 1 (NMP-1). NMPC was asked to address five basic questions included in enclosure 1. NMPC provided a written outline (enclosure 2) of their presentation. Their presentation addressed all of the five questions presented by the staff. The staff requested and received several documents used by NMPC during their presentation. These documents listed in enclosure 3 were transmitted to the DOR engineering branch for final review of the nozzle reinforcement calculation.

After we receive the NMPC written report, we will need to set a requirement for a reinspection interval to assure that cracks do not reappear in the deep grindouts.

A list of the attendees is given in enclosure 4.

Original signed by

Stanley J. Nowicki, Project Manager
Operating Reactors Branch #3
Division of Operating Reactors

Enclosures:

1. Feedwater Nozzle and Control Rod Drive Return Line Nozzle Inspection Program Questions
2. Outline of presentation
3. Documents used by NMPC in their presentation

not required since conclusions were removed EJM 7/5/77

*SEE PREVIOUS YELLOW FOR CONCURRENCE

OFFICE >	ORB#2	EB	ORB#3		
SURNAME >	*RSnaider	NRandall	SNowicki		
DATE >	6/ 28 - 1977	7/ 1 1977	7/ 5 1977		

Faint, mostly illegible text, likely a header or introductory paragraph.

Main body of faint, illegible text.

Shorter block of faint, illegible text.

Line of faint, illegible text.

Section header or separator line.

Text block, possibly a list or specific details.

Text block on the right side, possibly a signature area.

Handwritten signatures and notes, including a large 'X' mark.

Form fields at the bottom of the page, mostly blank or with faint text.

DISTRIBUTION:
See attached list

MEMORANDUM FOR: G. Lear, Chief, Operating Reactors Branch #3, DOR
FROM: S. J. Nowicki, Project Manager, Operating Reactors Branch #3, DOR
SUBJECT: MEETING ON NINE MILE POINT UNIT NO. 1 FEEDWATER NOZZLE INSPECTION AND REPAIR, JUNE 3, 1977

Introduction

A meeting was held on June 3, 1977 with representatives of Niagara Mohawk Power Corporation (NMPC) and NRC to discuss the results of the Feedwater Nozzle Inspection and Repair program completed by NMPC during their current refueling outage at Nine Mile Point Unit No. 1 (NMP-1). NMPC was asked to address five basic questions included in enclosure 1. NMPC provided a written outline (enclosure 2) of their presentation. Their presentation addressed all of the five questions presented by the staff and the answers are acceptable. The staff requested and received several documents used by NMPC during their presentation. These documents listed in enclosure 3 were transmitted to the DOR engineering branch for final review of the nozzle reinforcement calculation.

As a result of our review of the Feedwater Nozzle Inspection and Control Rod Drive Return Line Nozzle Inspection program we agree with NMPC's findings that the inspection and repair program does not involve an unreviewed safety question.

A list of the attendees is given in enclosure 4.

Stanley J. Nowicki, Project Manager
Operating Reactors Branch #3
Division of Operating Reactors

Enclosures:

1. Feedwater Nozzle and Control Rod Drive Return Line Nozzle Inspection Program Questions
2. Outline of presentation
3. Documents used by NMPC in their presentation

OFFICE	ORB#2	EB	ORB#3			
SURNAME	RSnaider	NRandaT	SNowicki:acr			
DATE	6/ 28 /77	6/ /77	6/ /77			

SECRET

MEMORANDUM FOR THE DIRECTOR, FBI

DATE: 10/15/54

TO: SAC, NEW YORK

NY 100-100000

Re: [Illegible text]

[Illegible text]

[Illegible text]

[Illegible text]

[Illegible text]

[Illegible text]

ENCLOSURE 1

JUNE 3, 1977 MEETING
FEEDWATER NOZZLE AND CONTROL ROD DRIVE RETURN
LINE NOZZLE INSPECTION PROGRAM FOR NINE MILE POINT UNIT NO. 1

Meeting Purpose:

To discuss results of FWN and CRD return line nozzle inspection and repair program performed during spring outage of 1977.

Questions to be Answered:

1. What effect has deep crack removal had on nozzle integrity?
 - a. Has the reinforcement limit been exceeded?
 - b. What are the details of final nozzle configuration?
 - c. What, if any, fatigue analysis has been done on existing nozzles?
 - d. Will deep cavities interfere with sparger operation?
2. What discussion can be presented concerning operation of new sparger design?
 - a. Will new sparger inhibit any new propagation of cracks?
3. Why did NMPC think that the deep cracks in the SE & SW nozzle had been removed only to find them later? Is there assurance that other cracks have been completely removed?
4. What results have been obtained for future UT exams? Anything of value learned?
5. What were results of CRD return line nozzle inspection? How large an area was actually examined? What are results?



FEEDWATER NOZZLE PROGRAMI. Historical Outline

- A. All old spargers removed
 - 1. Rectangular box design
 - 2. No evidence of damage or failure
 - 3. Preload of arms was apparently still effective
- B. SE nozzle PT'd and UT'd with clad in place. Only clad portion of nozzle was PT'd. See Table 1 for results.
- C. Clad plus nominal 3/16-inch base metal removed.
- D. All nozzles PT'd after machining completed. See Table 1 for results.
- E. Defects ground out. Blending was deferred until later time after sparger fitup.
- F. Spargers were fit up with dummy thermal sleeves.
- G. Sparger parts final machined and thermal sleeves welded on.
- H. In parallel with G, above, nozzle defect cavities were ground to obtain required blend.
- I. Final acceptance PT exam was performed.



J. Spargers trial fit with thermal sleeves and flow shrouds in place.

K. Sparger thermal sleeves deformed to elliptical shape, piston rings installed.

L. Spargers installed.

II. Final Machined Nozzle Configuration

III. Evaluation of Repair Cavities - See Table 2

IV. Final Installed Sparger Configuration

V. Control Rod Drive Nozzle Examination



TABLE 1
SUMMARY OF EXAMINATION RESULTS

A. Before Clad Removal Machining

	<u>SE</u>	<u>SW</u>	<u>NE</u>	<u>NW</u>
Number of significant linear indications -	Over 25	NA	NA	NA

Note: Only clad portion of nozzle was examined.

B. After Clad Removal Machining

	<u>SE</u>	<u>SW</u>	<u>NE</u>	<u>NW</u>
Number of linear indications -	5	1	0	0

C. Final Cavity Sizes after Defect Removal

	<u>SE</u>	<u>SW</u>	<u>NE</u>	<u>NW</u>
Number of cavities -	4	1	0	0
Maximum length of cavity -	10.62	9.62	---	---
Maximum depth of cavity -	1.47	1.30	---	---



TABLE 2

EVALUATION OF DEFECT CAVITIESCriteria

Cavities are acceptable per Section XI, IWB-4300, provided:

- Vessel and nozzle minimum wall thicknesses are met.
- Nozzle reinforcement requirements are met.
- Cavities are blended such that the fatigue life of the nozzle is acceptable.

ResultsA. Nozzle Wall Thickness

- No cavities which infringe on vessel wall.
- Minimum nozzle wall thicknesses for worst defect is ≥ 3.0 in.
Minimum required thickness is 0.3 in.

B. Nozzle Reinforcement

	<u>Required Area (in²)</u>	<u>Available Area (in²)</u>	<u>Excess (in²)</u>
Before clad removal	55.1	78.8	23.7
After removal of clad and 1/4" base metal	57.7	75.8	18.1
Area available <u>per side</u> of nozzle for defect removal (in ²) -			9.05
Largest cavity area in any plane (in ²) -			<u>6.50</u>
		Excess	2.55



C. Blending Requirements

Blend all cavities smoothly into surrounding base metal. Main criteria is that radius at bottom of cavity be \geq depth of cavity.

For largest cavities, blend results are:

	<u>SE</u>	<u>SW</u>
Depth (in.) -	1.47	1.30
Minimum required radius (in.) -	1.47	1.30
Actual minimum radius (in.) -	1.50	1.50

Conclusion: All requirements are met.

NOTE:

1. Worst cavity locations are in nozzle bore, not in blend radius where peak stresses occur. (These peak stresses were used for analysis.) Actual peak stresses at location of deepest cavity are no more than 80% of values in blend radius area.
2. Average primary hoop stress due to pressure at location of maximum defects is \sim 5300 psi.



ENCLOSURE 3

DRAWINGS AND DOCUMENTS TRANSMITTED DURING
THE JUNE 3, 1977 MEETING

<u>Document</u>	<u>Number</u>	<u>Title</u>
1. MPR Drawing	SK-1083-60-526 Sheet 1, Rev o	Defect Removal Evaluation Nine Mile Point Unit No. 1 FW Nozzle (S. W. Nozzle)
2. MPR Drawing	SK-1083-60-525 Sheet 1, Rev 1	Defect Removal Evaluation Nine Mile Point Unit No. 1 SE. FW Nozzle
3. MPR Drawing	1083-60-02 Rev F Sheets 1 & 2	Feedwater Sparger Details Assembly & Installation
4. Xerox at E-231-566		Feedwater Nozzle Assembly
5. Hand Drawing	From John Johnson MPR To Dick Wood NMPC	Contour Geometry for Crack at 1 O'clock in SE Nozzle
6. Inspection Report	4577-050 6/1/77 13 pages	Measure and documentation the final configuration of the Nozzle after blending



10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

ENCLOSURE 4

ATTENDEES
JUNE 3, 1977 MEETING

<u>Name</u>	<u>Organization</u>
S. J. Nowicki	NRC
R. E. Johnson	NRC
G. A. Walton	NRC
R. P. Snaider	NRC
R. W. Klecker	NRC
J. Crooks	NRC
F. Clemenson	NRC
W. Hazelton	NRC
G. Lear	NRC
R. M. Wood	Niagara Mohawk Power Corp.
Bill D'Angelo	Niagara Mohawk Power Corp.
T. V. Perkins	Niagara Mohawk Power Corp.
John Johnson	MPR Assoc. Inc.
W. R. Schmidt	MPR Assoc. Inc.
R. E. Schaffstall	GE
Frank Hill	Combustion Engineering
Jim Bass	Combustion Engineering

