

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

TO: MR. GEORGE LEAR

FROM: NIAGARA MOHAWK POWER CO.
SYRACUSE, NEW YORK
MR. GERALD K. RHODE

DATE OF DOCUMENT
5/14/76

DATE RECEIVED
5/18/76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP INPUT FORM

NUMBER OF COPIES RECEIVED
ONE SIGNED

DESCRIPTION

LTR. W/ATTACHED RE OUR 4/12/76 LTR.....
FURNISHING REQUESTED INFO. RE POTENTIAL
CRACKING IN REACTOR FEEDWATER NOZZLE BLEND
RADII.

ENCLOSURE

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME:

ANINE MILE POINT #1

SAFETY

FOR ACTION/INFORMATION

ENVIRO

5/20/76

RJL

ASSIGNED AD :

BRANCH CHIEF :

PROJECT MANAGER:

LIC. ASST. :

LEAR (6)

PARRISH

ASSIGNED AD :

BRANCH CHIEF :

PROJECT MANAGER :

LIC. ASST. :

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E

O&E

GOSSICK & STAFF

MIPC

CASE

HANAUER

HARLESS

SYSTEMS SAFETY

HEINEMAN

SCHROEDER

ENGINEERING

MACCARY

KNIGHT

SIKWEIL

PAWLICKI

PLANT SYSTEMS

TEDESCO

BENAROYA

LAIMAS

IPPOLITO

OPERATING TECH

EISENHUT

SHAO

BAER

SCHWENCER

GRIMES

ENVIRO TECH

ERNST

BALLARD

SPANGLER

SITE TECH

GANNILL

STEPP

HULMAN

PROJECT MANAGEMENT

BOYD

P. COLLINS

HOUSTON

PETERSON

MELTZ

HELTJES

SKOVHOLT

REACTOR SAFETY

ROSS

NOVAK

ROSZTOCZY

CHECK

AT & I

SALTZMAN

RUTBERG

SITE SAFETY & ENVIRO

ANALYSIS

DENTON & MULLER

SITE ANALYSIS

VOLLMER

BUNCH

J. COLLINS

KREGER

EXTERNAL DISTRIBUTION

LPDR:

TIC

NSIC

ASLB

ACRS/6 HOLDING/SENCE

NATL LAB

REG. V-IE

LA PDR

CONSULTANTS

BROOKHAVEN NATL LAB

ULRIKSON (ORNL)

CONTROL NUMBER

74967

100-100

100-100

100-100

100-100

100-100

.....

100-100

100-100

()

100-100

100-100

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 14, 1976



Director of Nuclear Reactor Regulation
Attn: Mr. George Lear, Chief
Operating Reactors Branch #3
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Re: Nine Mile Point Unit 1
Docket No. 50-220
DPR-63

Dear Mr. Lear:

Your letter dated April 12, 1976 requested information regarding potential cracking in reactor feedwater nozzle blend radii at Nine Mile Point Unit 1. The attached information answers the questions contained in your letter.


Very truly yours,

NIAGARA MOHAWK POWER CORPORATION



GERALD K. RHODE
Vice President - Engineering


Regulatory Docket File



GKH/sz

Attachment

4967



Niagara Mohawk Power Corporation
Information Concerning Potential Feedwater Nozzle Cracking
Nine Mile Point Unit 1

The following numbered items refer to questions contained in a letter from Mr. George Lear (Commission) to Mr. Gerald K. Rhode (Niagara Mohawk) dated April 12, 1976.


Question 1:

If inspection(s) of feedwater nozzle blend radii has (have) been accomplished, supply the following information:

- (a) Date of inspection(s)
- (b) Inspection method used
- (c) Inspection results and subsequent actions - number of cracks found; number of cracks which penetrated the cladding into the base metal; maximum depth of cracks; general location of worst cracking around each nozzle; method used to remove cracks; cross-sectional area of reinforcement removed at the worst grind-out location; subsequent inspections and results.
- (d) If inspection report(s) has (have) been previously submitted to the NRC containing the desired information of (a), (b), and (c), provide reference to the report(s) in lieu of the information in (a), (b), and (c).

Response:

- (a) Ultrasonic examinations of reactor feedwater nozzles were performed on April 4, 1976 and April 9, 1976.
- (b) Ultrasonic examination methods were used. The examination on April 4 employed a developmental technique using a 60 degree angle beam from the reactor vessel outer wall. All four feedwater nozzles were examined. On April 9, the southeast nozzle was re-examined, using a compound angle beam shear wave technique from the feedwater nozzle outside the vessel.
- (c) The April 4 examination of the southeast feedwater nozzle revealed two indications at the clad-nozzle interface which were reportable in accordance with the test procedures. Five subsurface indications were found in the other three nozzles; these indications were interpreted as base metal inclusions. The April 9 re-examination of the southeast nozzle revealed no reportable indications.
- (d) Not applicable.



Question 2:

If no inspection of feedwater nozzle blend radii has been conducted, provide date inspection is planned and date of next planned refueling outage.

Response:

Not applicable.

Question 3:

If inspection(s) and repair(s) has (have) been undertaken, provide date of next planned inspection.

Response:


The next inspection is planned during the Spring 1977 refueling outage.

Question 4:

Provide the number of startup/shutdown cycles to the date of the inspection, if already accomplished, and the number of cycles since such inspection. If no inspection has been conducted, provide the estimated number of cycles at the planned inspection date. A startup/shutdown cycle is defined as a power increase from zero and subsequent return to zero.

Response:

One-hundred (100) startup/shutdown cycles occurred from initial reactor operation to the ultrasonic examination performed on April 4. Subsequent to that examination, one and one-half (1 1/2) cycles have occurred.




Question 5:

Describe actions taken or planned to minimize cold, intermittent feedwater flow to the reactor pressure vessel. Include changes in operating procedures and any redesign of feedwater heaters, pumps, flow control valves, piping etc.

Response:

A principal cause of cold intermittent feedwater flow to the reactor vessel is the "jogging" of feedwater pumps during plant startups. This practice is not used at Nine Mile Point Unit 1. During reactor startups efforts are made to maximize the steaming rate. The various drains to the condenser hotwell are opened as early as possible. These practices maximize the rate of feedwater flow, thus avoiding rapid introduction of cold feedwater to the hot nozzles. During hot standby operation the low feedwater flow condition is avoided. Maintaining feedwater flow avoids potential thermal transients to the nozzles associated with increasing cold feedwater flow from the low flow condition.



Question 6:

Describe reactor pressure vessel pressure-temperature limits for operating conditions and especially for the inservice-hydrostatic and leak tests.

Response:

Reactor pressure vessel minimum temperature limits as a function of reactor internal pressure have been calculated for hydrostatic leak tests and power operation based on postulated feedwater nozzle flaws, as discussed below. Operating procedures are being developed to implement these limits, which are shown in Figure 1.

Minimum pressurization temperatures were calculated using the criteria of Appendix G of Section III of the ASME Boiler and Pressure Vessel Code, (1974 Edition, Winter 1975 Addenda) and the following conservative bases:

1. A postulated flaw size of 2-inches deep was assumed. This value is slightly greater than the $1/4 T$ reference flaw size recommended by the Code and is significantly greater than would be expected based on crack growth analyses and ultrasonic examinations.
2. The A336 nozzle forging material was assumed to have an RT_{NDT} of $+40^{\circ}F$. This value is the maximum value permitted by the vessel procurement specification and is greater than would be expected for this forging material, particularly in the region from the nozzle surface to the $1/4 T$ point -- the location of the postulated flaw.
3. Pressure stresses and stress intensity factor, K , were determined using data presented in Welding Research Council (WRC) Bulletin 175, "PVRC Recommendations on Toughness Requirements for Ferritic Materials." Figure A5-1, for a 2:1 bi-axial stress field. (These data are more conservative than those recommended in WRC 175 for nozzle corner flaws.)
4. In applying the criteria of Appendix G of Section III, it was conservatively assumed that the total peak pressure stress is primary, while in fact, the total pressure stress includes secondary and peak stresses as well as primary stresses.





FIGURE 1

MINIMUM REACTOR VESSEL TEMPERATURE
FOR HYDROSTATIC TESTING AND HEATUP OR COOLDOWN



* Minimum temperature shall be 40 F higher when the core is critical.

