

April 4, 1979

Mr. Boyce H. Grier  
Director  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA. 19406


RE: Docket No. 50-220  
LER 79-03

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station #1 Technical Specification 6.9.2 b.(2), we hereby submit Licensee Event Report, LER 79-03. The events reported will be further summarized in the periodic test report required by 10 CFR 50, Appendix J Section V.B.3 and Technical Specification Section 6.9.3e.

The events reported occurred when the Station was shutdown for refueling and overhaul. Repairs will be completed during the outage and the results of retest will be included in the referenced summary report.

Very truly yours,

  
R.R. Schneider  
Vice President -  
Electric Production

Attachment (3 copies)

cc: Director, Office of I&E (30 copies)  
Director, Office of MIPC (3 copies)

7904100300

Asst  
S/H

5

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	N	Y	N	M	P	1	0	0	-	0	0	0	0	0	0	0	0	4	1	1	1	1	4	5	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	57	58
LICENSEE CODE						LICENSE NUMBER						LICENSE TYPE						CAT 58							

01	L	0	5	0	0	0	2	2	0	0	3	1	0	7	9	0	4	0	4	7	9				
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80			
CON'T		REPORT SOURCE						DOCKET NUMBER						EVENT DATE						REPORT DATE					

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During periodic Type C Leakage Test, found the following leaking in

03 | excess of Technical Specification Criteria for one isolation valve:

04 | IV 01-01, IV 201.7-01, IV 201.7-10, IV 201.2-71, IV 201-31. At this report

05 | it was not established that the redundant valve to each of these was

06 | either within or above criteria. Repairs are in progress.

07 |

08 |

09	C	D	E	X	V	A	L	V	E	X	H	D	
7	8	9	10	11	12	13	14	15	16	17	18	19	20
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE

17	7	8	0	0	3	0	3	L	0	
7	8	9	10	11	12	13	14	15	16	
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The bottom guide pad of the main poppet on IV 01-01 (MSIV) had worn and

11 | caused valve stem misalignment. This caused excessive wear on one pilot

12 | guide lug which prevented the proper seating of the pilot valve. Cause

13 | and correction for other valve leakage is not available at this time.

14 |

15	H	0	0	0	NA	B		
7	8	9	10	11	12	13		
FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY	DISCOVERY DESCRIPTION

16	Z	Z	NA	NA
7	8	9	10	11
ACTIVITY CONTENT RELEASED		AMOUNT OF ACTIVITY		LOCATION OF RELEASE

17	0	0	0	Z	NA
7	8	9	10	11	12
PERSONNEL EXPOSURES NUMBER		TYPE		DESCRIPTION	

18	0	0	0	NA
7	8	9	10	11
PERSONNEL INJURIES NUMBER		DESCRIPTION		

19	Z	NA
7	8	9
LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION

20	N	NA
7	8	9
ISSUED DESCRIPTION		PUBLICITY

7904100302