

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912040277 DOC. DATE: 79/11/28 NOTARIZED: NO DOCKET #
 FACIL: 50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220
 AUTH. NAME: AUTHOR AFFILIATION
 DIS. D.: Niagara Mohawk Power Corp.
 RECIP. NAME: RECIPIENT AFFILIATION
 IPPOLITO, T.A. Operating Reactors Branch 3

SUBJECT: Forwards results of feedwater & control rod drive nozzles
 insps performed during Spring 1979 refueling outage. No
 reportable indications of cracking found.

DISTRIBUTION CODE: A024S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: BWR Feedwater Nozzles/Spargers for Control Rod Drive Retu

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
INTERNAL:	1 REG FILE	1	10 W HAZELTON	1
	11 R SNAIDER	1	12 J ZUDANS	1
	13 S MACKAY	1	14 R JOHNSON	1
	15 R KECKER	1	16 AD/ENGR	1
	17 R MATTO	1	18 M HUM	1
	19 P RANDALL	1	2 NRC PDR	1
	20 MECH ENG BR	1	21 MATL ENG BR	1
	22 PROGRAM SUPP	1	23 I. & E	2
	3 NSIC	1	4 S HANAUER	1
	5 DIRECTOR DOR	1	6 AD/EP DOR	1
	7 AD/SE DOR	1	8 ENGR BR	1
	9 PLANT SYS BR	1		
EXTERNAL:	25 ACRS	16		16

DEC 5 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 40 ENCL 0

cap
1/1/74

6707

3

NY NIAGARA
NM MOHAWK

Donald P. Dise
Vice President
Engineering

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

November 28, 1979

Director of Nuclear Reactor Regulation
Attn: Mr. Thomas A. Ippolito, Chief
Operating Reactors Branch #3
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Re: Nine Mile Point Unit #1
Docket No. 50-220
DPR-63


Gentlemen:

Pursuant to our letter of April 26, 1978, provided herewith are the results of our inspection for feedwater and control rod drive nozzles performed during the spring 1979 refueling outage.

Ultrasonic examinations were performed on the feedwater nozzles. Ultrasonic examinations were performed on the nozzle to safe-end and safe-end to pipe weld of the control rod drive hydraulic return nozzle. No reportable indications of cracking were found during these inspections. In addition, an underwater visual examination of the feedwater spargers did not reveal any indications of cracking.

Very truly yours,

NIAGARA MOHAWK POWER CORPORATION


Donald P. Dise,
Vice President, Engineering

MGM:jk

A024
S
1/0

P 7912040 277



.....