

# UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I

631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

JAN 2 1 1980

Niagara Mohawk Power Corporation ATTN: Mr. G. K. Rhode Vice President System Project Management 300 Erie Boulevard, West Syracuse, New York 13202

Gentlemen:

The enclosed IE Bulletin No. 80-02 is forwarded to you for action. A written response is required. If you desire additional information regarding this matter, please contact this office.

Sincerely,

Boyce H. Grier

Enclosures:

I. IE Bulletin No. 80-02

2. List of Recently Issued IE Bulletins

CONTACT: S. D. Ebneter

(215-337-5283)

cc w/encls:

Eugene B. Thomas, Jr., Esquire

.

• 4 • • •

**ENCLOSURE 1** 

SSINS No.: 6820 Accession No.: 7912190653

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

IE Bulletin No. 80-02 Date: January 21, 1980 Page 1 of 2

### INADEQUATE QUALITY ASSURANCE FOR NUCLEAR SUPPLIED EQUIPMENT

#### <u>Description of Circumstances:</u>

The Marvin Engineering Company (MEC) of Inglewood, California was the subject of a special NRC inspection conducted on September 18-21, 1979 to evaluate their overall QA and QC programs which had come under severe criticism by a former Marvin Engineering employee. The special inspection was judged necessary since the Marvin Engineering Company was a known subcontractor and supplier to General Electric of BWR reactor internal feedwater spargers and feedwater thermal sleeves. The results of the NRC's inspection established that serious deficiencies exist in the implementation of the MEC quality assurance program relative to the manufacture of these components. During this inspection, twenty-seven deviations from applicable codes, and contractual and regulatory requirements were documented in the areas of material identification and control, process control, welding and nondestructive examination.

#### Corrective Action

The Marvin Engineering Company has been issued the NRC's detailed inspection report of the Company, and given 30 days to inform the NRC how the deviations discussed in the report will be corrected and preventive action taken.

#### Action To Be Taken

All BWR licensees and construction permit holders shall supply the following information within 90 days for operating plants and 120 days for plants under construction.

- 1.a. Have reactor feedwater spargers and thermal sleeves manufactured and/or fabricated by the Marvin Engineering Company been purchased and/or installed in your facility? Since Marvin Engineering is principally a subcontracting Company, determine if your equipment originated with the Marvin Company and was eventually supplied to your facility through another contractor/supplier.
- 1.b. Provide a description of this equipment to include its purchase date and its design function during both normal and accident conditions.

. • ι *i*. • •

Enclosure 1

IE Bulletin No. 80-02 Date: January 21, 1980 · Page 2 of 2

- 2. For each piece of identified equipment, provide the performance history associated with its usage. This should include the cause of any failures or malfunctions and the frequency of such events.
- 3. Provide information on the suppliers and receiver's QA/QC program in effect at the time of purchase. This information should be discussed in terms of it providing sufficient bases for judging that the integrity of the equipment is sufficient to permit plant operation during normal and accident conditions.

Approved by GAO, B180225 (R0072); clearance expires 7-31-80. Approval was given under a blanket clearance specifically for identified generic problems.

. . . at . • . •

## **ENCLOSURE 2**

IE Bulletin No. 80-02 Date: January 21, 1980 Page 1 of 1

#### RECENTLY ISSUED IE BULLETINS

| Bulletin<br>No.   | Subject  | Date Issued | Issued To  |
|-------------------|--|-------------|--|
| 79-17<br>(Rev. 1) | Pipe Cracks in Stagnant<br>Borated Water Systems<br>at PWR Plant                               | 10/29/79    | All PWRs with an Operating License (OL) (for Action). All other Power Reactor Facilities with an OL or Construction CP Permit (CP) (for Information) |
| 79-25             | Failures of Westinghouse<br>BFD Relays in Safety-<br>Related Systems                           | 11/2/79     | All Power Reactor<br>Facilities with an<br>OL or CP (for Action)   |
| 79-02<br>(Rev. 2) | Pipe Base Plate Designs<br>Using Concrete Expansion<br>Bolts                                   |             | All Power Reactor<br>Facilities with an<br>OL or CP  |
| 79-26             | Boron Loss From BWR<br>Control Blades  | 11/20/79    | All BWR Power Reactor<br>Facilities with an<br>OL  |
| 79-27             | Loss of Non-Class-1-E<br>Instrumentation and Con-<br>trol Power System Bus<br>During Operation | 11/30/79    | All Power Reactor Facilities with an OL and those nearing Licensing (for Action) All Power Reactor Facilities with a CP (for Information).           |
| 79-28             | Possible Malfunction<br>of NAMCO Model EA180<br>Limit Switches at<br>Elevated Temperatures     | 12/7/79     | All Power Reactor<br>Facilities with an<br>OL or CP  |
| 79-01B            | Environmental Quali-<br>fication of Class IE<br>Equipment                                      | 1/14/80     | All Power Reactors<br>with an OL except<br>SEP Plants  |
| 80-01             | Operability of ADS Valve<br>Pneumatic Supply   | 1/14/80     | All BWRs with an OL  |

h h

.

•

T.

•