

NINE MILE POINT NUCLEAR STATION / P.O. BOX 32 LYCOMING, NEW YORK 13093 / TELEPHONE (315) 343-2110

January 13, 1981

Mr. Boyce H. Grier, Director
United States Nuclear Regulatory
Commission - Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

RE: Docket No. 50-220
LER 80-32

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit the following Licensee Event Report:

80-32 which is being submitted in accordance with Section 6.9.2b2, Conditions Leading to Operation in a Degraded Mode Permitted by a Limiting Condition for Operation or Plant Shutdown Required by a Limiting Condition for Operation.

This report was completed in the format designated in NUREG-0161, dated July 1977.

Very truly yours,

Thomas E. Lempges
Thomas E. Lempges
Vice President
Nuclear Generation

TEL:jl
Attachments (3 copies)
cc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)

DISTRIBUTION SERVICES UNIT

1981 FEB 9 PM 1 32

U.S. NUC. REG. COM. DIST. DIVISION SERVICES BRANCH

102100632

S

A002
A 5/11

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | Y | N | M | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | 7 | 1 | 2 | 1 | 6 | 8 | 0 | 8 | 0 | 1 | 1 | 6 | 8 | 1 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | During normal operation, while performing the Emergency Ventilation System (Standby Gas
03 | Treatment) HEPA filter cold D.O.P. surveillance test, one filter bank in #11 branch
04 | produced an unacceptable efficiency of 8% leakage. The efficiency required by station
05 | tech specs is less than 1% bypass leakage. This had no significant safety or environ-
06 | mental effect since the overall branch efficiency was acceptable and the alternate re-
07 | dundant system was proven operable. All other testing involved provided acceptable
08 | results.

09 | SYSTEM CODE | S | C | 11 | CAUSE CODE | X | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | F | I | L | T | E | R | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | Inspection revealed that the filter sealing gasket was defective. Efforts to reseal
11 | the gasket surface were unsuccessful so a new filter unit was installed. Test results
12 | pf the new filter were acceptable. Surveillance testing on this system continues on
13 | a regular basis or as certain conditions necessitate as described in Technical
14 | Specifications.

15 | FACILITY STATUS | E | 28 | % POWER | 0 | 8 | 1 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | SURVEILLANCE TESTING | 32

16 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36

17 | PERSONNEL EXPOSURES | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39

18 | PERSONNEL INJURIES | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41

19 | LOSS OF OR DAMAGE TO FACILITY | Z | 42 | DESCRIPTION | N/A | 43

20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | N/A | 45